



**JUNOS[™]e Software
for E Series[™] Broadband Services Routers**

Release Notes

Release 10.3.1

Juniper Networks, Inc.
1194 North Mathilda Avenue
Sunnyvale, CA 94089
USA
408-745-2000
www.juniper.net

Published: 2010-04-26

Juniper Networks, the Juniper Networks logo, JUNOS, NetScreen, ScreenOS, and Steel-Belted Radius are registered trademarks of Juniper Networks, Inc. in the United States and other countries. JUNOSe is a trademark of Juniper Networks, Inc. All other trademarks, service marks, registered trademarks, or registered service marks are the property of their respective owners.

Juniper Networks assumes no responsibility for any inaccuracies in this document. Juniper Networks reserves the right to change, modify, transfer, or otherwise revise this publication without notice.

Products made or sold by Juniper Networks (including the ERX310, ERX705, ERX710, ERX1410, ERX1440, M5, M7i, M10, M10i, M20, M40, M40e, M160, M320, and T320 routers, T640 routing node, and the JUNOS, JUNOSe, and SDX-300 software) or components thereof might be covered by one or more of the following patents that are owned by or licensed to Juniper Networks: U.S. Patent Nos. 5,473,599, 5,905,725, 5,909,440, 6,192,051, 6,333,650, 6,359,479, 6,406,312, 6,429,706, 6,459,579, 6,493,347, 6,538,518, 6,538,899, 6,552,918, 6,567,902, 6,578,186, and 6,590,785.

Copyright © 2010, Juniper Networks, Inc.
All rights reserved. Printed in USA.

JUNOSe™ Software for E Series™ Broadband Services Routers Release Notes, Release 10.3.1

Writing: Subash Babu Asokan, Krupa Chandrashekar, Megha Shaseendran, Pallavi Madhusudhan, Namrata Mehta, Diane Florio, Brian Wesley Simmons, Fran Singer, Sairam V

Editing: Ben Mann, Krishnaveni Venkatesan

Cover Design: Edmonds Design

Revision History
April 2010—FRS JUNOSe 10.3.1

The information in this document is current as of the date listed in the revision history.

Software License

The terms and conditions for using this software are described in the software license contained in the acknowledgment to your purchase order or, to the extent applicable, to any reseller agreement or end-user purchase agreement executed between you and Juniper Networks. By using this software, you indicate that you understand and agree to be bound by those terms and conditions.

Generally speaking, the software license restricts the manner in which you are permitted to use the software and may contain prohibitions against certain uses. The software license may state conditions under which the license is automatically terminated. You should consult the license for further details.

For complete product documentation, please see the Juniper Networks Web site at www.juniper.net/techpubs.

END USER LICENSE AGREEMENT

READ THIS END USER LICENSE AGREEMENT ("AGREEMENT") BEFORE DOWNLOADING, INSTALLING, OR USING THE SOFTWARE. BY DOWNLOADING, INSTALLING, OR USING THE SOFTWARE OR OTHERWISE EXPRESSING YOUR AGREEMENT TO THE TERMS CONTAINED HEREIN, YOU (AS CUSTOMER OR IF YOU ARE NOT THE CUSTOMER, AS A REPRESENTATIVE/AGENT AUTHORIZED TO BIND THE CUSTOMER) CONSENT TO BE BOUND BY THIS AGREEMENT. IF YOU DO NOT OR CANNOT AGREE TO THE TERMS CONTAINED HEREIN, THEN (A) DO NOT DOWNLOAD, INSTALL, OR USE THE SOFTWARE, AND (B) YOU MAY CONTACT JUNIPER NETWORKS REGARDING LICENSE TERMS.

1. **The Parties.** The parties to this Agreement are (i) Juniper Networks, Inc. (if the Customer's principal office is located in the Americas) or Juniper Networks (Cayman) Limited (if the Customer's principal office is located outside the Americas) (such applicable entity being referred to herein as "Juniper"), and (ii) the person or organization that originally purchased from Juniper or an authorized Juniper reseller the applicable license(s) for use of the Software ("Customer") (collectively, the "Parties").
2. **The Software.** In this Agreement, "Software" means the program modules and features of the Juniper or Juniper-supplied software, for which Customer has paid the applicable license or support fees to Juniper or an authorized Juniper reseller, or which was embedded by Juniper in equipment which Customer purchased from Juniper or an authorized Juniper reseller. "Software" also includes updates, upgrades and new releases of such software. "Embedded Software" means Software which Juniper has embedded in or loaded onto the Juniper equipment and any updates, upgrades, additions or replacements which are subsequently embedded in or loaded onto the equipment.
3. **License Grant.** Subject to payment of the applicable fees and the limitations and restrictions set forth herein, Juniper grants to Customer a non-exclusive and non-transferable license, without right to sublicense, to use the Software, in executable form only, subject to the following use restrictions:
 - a. Customer shall use Embedded Software solely as embedded in, and for execution on, Juniper equipment originally purchased by Customer from Juniper or an authorized Juniper reseller.
 - b. Customer shall use the Software on a single hardware chassis having a single processing unit, or as many chassis or processing units for which Customer has paid the applicable license fees; provided, however, with respect to the Steel-Belted Radius or Odyssey Access Client software only, Customer shall use such Software on a single computer containing a single physical random access memory space and containing any number of processors. Use of the Steel-Belted Radius or IMS AAA software on multiple computers or virtual machines (e.g., Solaris zones) requires multiple licenses, regardless of whether such computers or virtualizations are physically contained on a single chassis.
 - c. Product purchase documents, paper or electronic user documentation, and/or the particular licenses purchased by Customer may specify limits to Customer's use of the Software. Such limits may restrict use to a maximum number of seats, registered endpoints, concurrent users, sessions, calls, connections, subscribers, clusters, nodes, realms, devices, links, ports or transactions, or require the purchase of separate licenses to use particular features, functionalities, services, applications, operations, or capabilities, or provide throughput, performance, configuration, bandwidth, interface, processing, temporal, or geographical limits. In addition, such limits may restrict the use of the Software to managing certain kinds of networks or require the Software to be used only in conjunction with other specific Software. Customer's use of the Software shall be subject to all such limitations and purchase of all applicable licenses.
 - d. For any trial copy of the Software, Customer's right to use the Software expires 30 days after download, installation or use of the Software. Customer may operate the Software after the 30-day trial period only if Customer pays for a license to do so. Customer may not extend or create an additional trial period by re-installing the Software after the 30-day trial period.

- e. The Global Enterprise Edition of the Steel-Belted Radius software may be used by Customer only to manage access to Customer's enterprise network. Specifically, service provider customers are expressly prohibited from using the Global Enterprise Edition of the Steel-Belted Radius software to support any commercial network access services.

The foregoing license is not transferable or assignable by Customer. No license is granted herein to any user who did not originally purchase the applicable license(s) for the Software from Juniper or an authorized Juniper reseller.

4. **Use Prohibitions.** Notwithstanding the foregoing, the license provided herein does not permit the Customer to, and Customer agrees not to and shall not: (a) modify, unbundle, reverse engineer, or create derivative works based on the Software; (b) make unauthorized copies of the Software (except as necessary for backup purposes); (c) rent, sell, transfer, or grant any rights in and to any copy of the Software, in any form, to any third party; (d) remove any proprietary notices, labels, or marks on or in any copy of the Software or any product in which the Software is embedded; (e) distribute any copy of the Software to any third party, including as may be embedded in Juniper equipment sold in the secondhand market; (f) use any 'locked' or key-restricted feature, function, service, application, operation, or capability without first purchasing the applicable license(s) and obtaining a valid key from Juniper, even if such feature, function, service, application, operation, or capability is enabled without a key; (g) distribute any key for the Software provided by Juniper to any third party; (h) use the Software in any manner that extends or is broader than the uses purchased by Customer from Juniper or an authorized Juniper reseller; (i) use Embedded Software on non-Juniper equipment; (j) use Embedded Software (or make it available for use) on Juniper equipment that the Customer did not originally purchase from Juniper or an authorized Juniper reseller; (k) disclose the results of testing or benchmarking of the Software to any third party without the prior written consent of Juniper; or (l) use the Software in any manner other than as expressly provided herein.
5. **Audit.** Customer shall maintain accurate records as necessary to verify compliance with this Agreement. Upon request by Juniper, Customer shall furnish such records to Juniper and certify its compliance with this Agreement.
6. **Confidentiality.** The Parties agree that aspects of the Software and associated documentation are the confidential property of Juniper. As such, Customer shall exercise all reasonable commercial efforts to maintain the Software and associated documentation in confidence, which at a minimum includes restricting access to the Software to Customer employees and contractors having a need to use the Software for Customer's internal business purposes.
7. **Ownership.** Juniper and Juniper's licensors, respectively, retain ownership of all right, title, and interest (including copyright) in and to the Software, associated documentation, and all copies of the Software. Nothing in this Agreement constitutes a transfer or conveyance of any right, title, or interest in the Software or associated documentation, or a sale of the Software, associated documentation, or copies of the Software.
8. **Warranty, Limitation of Liability, Disclaimer of Warranty.** The warranty applicable to the Software shall be as set forth in the warranty statement that accompanies the Software (the "Warranty Statement"). Nothing in this Agreement shall give rise to any obligation to support the Software. Support services may be purchased separately. Any such support shall be governed by a separate, written support services agreement. TO THE MAXIMUM EXTENT PERMITTED BY LAW, JUNIPER SHALL NOT BE LIABLE FOR ANY LOST PROFITS, LOSS OF DATA, OR COSTS OR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES, OR FOR ANY SPECIAL, INDIRECT, OR CONSEQUENTIAL DAMAGES ARISING OUT OF THIS AGREEMENT, THE SOFTWARE, OR ANY JUNIPER OR JUNIPER-SUPPLIED SOFTWARE. IN NO EVENT SHALL JUNIPER BE LIABLE FOR DAMAGES ARISING FROM UNAUTHORIZED OR IMPROPER USE OF ANY JUNIPER OR JUNIPER-SUPPLIED SOFTWARE. EXCEPT AS EXPRESSLY PROVIDED IN THE WARRANTY STATEMENT TO THE EXTENT PERMITTED BY LAW, JUNIPER DISCLAIMS ANY AND ALL WARRANTIES IN AND TO THE SOFTWARE (WHETHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE), INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NONINFRINGEMENT. IN NO EVENT DOES JUNIPER WARRANT THAT THE SOFTWARE, OR ANY EQUIPMENT OR NETWORK RUNNING THE SOFTWARE, WILL OPERATE WITHOUT ERROR OR INTERRUPTION, OR WILL BE FREE OF VULNERABILITY TO INTRUSION OR ATTACK. In no event shall Juniper's or its suppliers' or licensors' liability to Customer, whether in contract, tort (including negligence), breach of warranty, or otherwise, exceed the price paid by Customer for the Software that gave rise to the claim, or if the Software is embedded in another Juniper product, the price paid by Customer for such other product. Customer acknowledges and agrees that Juniper has set its prices and entered into this Agreement in reliance upon the disclaimers of warranty and the limitations of liability set forth herein, that the same reflect an allocation of risk between the Parties (including the risk that a contract remedy may fail of its essential purpose and cause consequential loss), and that the same form an essential basis of the bargain between the Parties.
9. **Termination.** Any breach of this Agreement or failure by Customer to pay any applicable fees due shall result in automatic termination of the license granted herein. Upon such termination, Customer shall destroy or return to Juniper all copies of the Software and related documentation in Customer's possession or control.
10. **Taxes.** All license fees payable under this agreement are exclusive of tax. Customer shall be responsible for paying Taxes arising from the purchase of the license, or importation or use of the Software. If applicable, valid exemption documentation for each taxing jurisdiction shall be provided to Juniper prior to invoicing, and Customer shall promptly notify Juniper if their exemption is revoked or modified. All payments made by Customer shall be net of any applicable withholding tax. Customer will provide reasonable assistance to Juniper in connection with such withholding taxes by promptly: providing Juniper with valid tax receipts and other required documentation showing Customer's payment of any withholding taxes; completing appropriate applications that would reduce the amount of withholding tax to be paid; and notifying and assisting Juniper in any audit or tax proceeding related to transactions hereunder. Customer shall comply with all applicable tax laws and regulations, and Customer will promptly pay or reimburse Juniper for all costs and damages related to any liability incurred by Juniper as a result of Customer's non-compliance or delay with its responsibilities herein. Customer's obligations under this Section shall survive termination or expiration of this Agreement.
11. **Export.** Customer agrees to comply with all applicable export laws and restrictions and regulations of any United States and any applicable foreign agency or authority, and not to export or re-export the Software or any direct product thereof in violation of any such restrictions, laws or regulations, or without all necessary approvals. Customer shall be liable for any such violations. The version of the Software supplied to Customer may contain encryption or other capabilities restricting Customer's ability to export the Software without an export license.
12. **Commercial Computer Software.** The Software is "commercial computer software" and is provided with restricted rights. Use, duplication, or disclosure by the United States government is subject to restrictions set forth in this Agreement and as provided in DFARS 227.7201 through 227.7202-4, FAR 12.212, FAR 27.405(b)(2), FAR 52.227-19, or FAR 52.227-14(ALT III) as applicable.
13. **Interface Information.** To the extent required by applicable law, and at Customer's written request, Juniper shall provide Customer with the interface information needed to achieve interoperability between the Software and another independently created program, on payment of applicable fee, if any. Customer shall observe strict obligations of confidentiality with respect to such information and shall use such information in compliance with any applicable terms and conditions upon which Juniper makes such information available.
14. **Third Party Software.** Any licensor of Juniper whose software is embedded in the Software and any supplier of Juniper whose products or technology are embedded in (or services are accessed by) the Software shall be a third party beneficiary with respect to this Agreement, and such licensor or vendor shall have the right to enforce this Agreement in its own name as if it were Juniper. In addition, certain third party software may be provided with the Software and is subject to the accompanying license(s), if any, of its respective owner(s). To the extent portions of the Software are distributed under and subject to open source licenses obligating Juniper to make the source code for such portions publicly available (such as the GNU General Public License ("GPL") or the GNU Library General Public License ("LGPL")), Juniper will make such source code portions (including Juniper

modifications, as appropriate) available upon request for a period of up to three years from the date of distribution. Such request can be made in writing to Juniper Networks, Inc., 1194 N. Mathilda Ave., Sunnyvale, CA 94089, ATTN: General Counsel. You may obtain a copy of the GPL at <http://www.gnu.org/licenses/gpl.html>, and a copy of the LGPL at <http://www.gnu.org/licenses/lgpl.html>.

15. **Miscellaneous.** This Agreement shall be governed by the laws of the State of California without reference to its conflicts of laws principles. The provisions of the U.N. Convention for the International Sale of Goods shall not apply to this Agreement. For any disputes arising under this Agreement, the Parties hereby consent to the personal and exclusive jurisdiction of, and venue in, the state and federal courts within Santa Clara County, California. This Agreement constitutes the entire and sole agreement between Juniper and the Customer with respect to the Software, and supersedes all prior and contemporaneous agreements relating to the Software, whether oral or written (including any inconsistent terms contained in a purchase order), except that the terms of a separate written agreement executed by an authorized Juniper representative and Customer shall govern to the extent such terms are inconsistent or conflict with terms contained herein. No modification to this Agreement nor any waiver of any rights hereunder shall be effective unless expressly assented to in writing by the party to be charged. If any portion of this Agreement is held invalid, the Parties agree that such invalidity shall not affect the validity of the remainder of this Agreement. This Agreement and associated documentation has been written in the English language, and the Parties agree that the English version will govern. (For Canada: Les parties aux présentes confirment leur volonté que cette convention de même que tous les documents y compris tout avis qui s'y rattache, soient rédigés en langue anglaise. (Translation: The parties confirm that this Agreement and all related documentation is and will be in the English language)).

Table of Contents

Release 10.3.1	1
Release Installation	1
Upgrading to Release 5.3.0 or a Higher-Numbered Release	1
Upgrading from Release 5.1.1 or Lower-Numbered Releases to Release 6.x.x or Higher-Numbered Releases	2
Moving Line Modules Between Releases	2
SRP Module Memory Requirements	3
Hardware and Software Compatibility	3
Requesting Technical Support	3
Self-Help Online Tools and Resources	3
Opening a Case with JTAC	4
Release Overview	4
Before You Start	5
Release Highlights	7
Early Field Trial Features	7
DHCP	7
SDX Software and SRC Software	8
Unified ISSU	8
Unsupported Features	8
E120 Router and E320 Router	8
Multicast	9
Policy Management	9
Stateful SRP Switchover (High Availability)	9
Release Software Protocols	9
Core Routing Stack	9
Network Management Protocols	10
Routing Protocols	10
Multiprotocol Label Switching (MPLS)	10
Layer 2 Protocols	10
Security Protocols	11
SRC Software and SDX Software Compatibility Matrix	11
Known Behavior	12
AAA	12
ATM	12
BGP	12
BGP/MPLS VPNs	13
B-RAS	13
CLI	13
DHCP	17
DHCP External Server	17
Dynamic Interfaces	18
Ethernet	19
Flash	20
GRE	20

Hardware	20
HDLC	21
IP	21
IPSec	23
IS-IS	23
L2TP	24
Line Module Redundancy	25
MLPPP	25
MPLS	25
Multicast	26
Packet Mirroring	26
Policy Management	26
PPP	28
PPPoE	28
QoS	28
RADIUS	29
SNMP	29
SSH	30
Stateful SRP Switchover (High Availability)	30
Subscriber Interfaces	32
System	32
System Logging	33
Tunneling	33
Known Problems and Limitations	34
ANCP	34
ATM	34
BFD	35
Bridged Ethernet	36
CLI	36
DHCP	36
DHCP External Server	36
DoS Protection	37
Ethernet	37
File System	37
Forwarding	37
ICR	39
IGMP	39
IP	40
IPSec	41
IS-IS	41
L2TP	41
MLD	42
MLPPP	42
Mobile IP	42
MPLS	43
Netflow	44
Policy Management	44
PPPoE	45
QoS	45
Service Manager	47
SNMP	48
SONET	48
SRC Software and SDX Software	48
Stateful SRP Switchover (High Availability) and IP Tunnels	48

Subscriber Management	49
System	50
System Logging	50
TCP	50
Unified ISSU	51
Resolved Known Problems	52
AAA	52
ARP	52
ATM	52
BFD	52
CLI	53
DHCP	53
DHCP External Server	53
DHCP Relay	53
DoS	54
Ethernet	54
Forwarding	54
Hardware	55
HTTP Server	56
IGMP	56
IP	56
IPv6	56
IS-IS	56
L2TP	57
MPLS	57
Multicast	57
Netflow	57
OSPF	57
PPPoE	57
Policy Management	58
QoS	58
RSVP-TE	58
Service Manager	58
SNMP	58
SRC Software and SDX Software	59
System Logging	59
Errata	60

Appendix A	System Maximums	65
ERX310, ERX7xx, and ERX14xx System Maximums		66
General System Maximums		66
Physical and Logical Density Maximums		67
Link Layer Maximums		70
Routing Protocol Maximums		75
Policy and QoS Maximums		79
Tunneling Maximums		82
Subscriber Management Maximums		84
E120 and E320 System Maximums		87
General System Maximums		87
Physical and Logical Density Maximums		88
Link Layer Maximums		90
Routing Protocol Maximums		96
Policy and QoS Maximums		99
Tunneling Maximums		103

	Subscriber Management Maximums.....	105
Appendix B	Module Name Cross-Reference Information	107
	Module Name Cross-Reference Information.....	107
Appendix C	Transferring DSL Line Rate Information from an Access Node to SRC Software	109
	Configuring the SRC Client to Retrieve DSL Information from Access Nodes.....	109
	Monitoring the Status of Transfer of Updated DSL Line Rate Parameters to the COPS Server	112
	JUNOSe Command Reference Guide Update.....	113
	sscc update-policy-request enable	113

Release 10.3.1

Release Installation

Complete procedures for installing the system software are available in *JUNOS System Basics Configuration Guide, Chapter 3, Installing JUNOS Software*.

New software releases are available for download from the Juniper Networks website at <http://www.juniper.net/customers/support>. You can use the downloaded image bundle to create your own software CDs.

Before upgrading to a new version of software, save your router's running configuration to a .cnf file or .scr file. If you subsequently need to downgrade for any reason, you can restore the earlier software version.



NOTE: When you upgrade the software on a router that has a large number of interfaces configured, the router might appear to be unresponsive for several minutes. This condition is normal; allow the process to continue uninterrupted.

Upgrading to Release 5.3.0 or a Higher-Numbered Release

When you upgrade from a lower-numbered release to Release 5.3.0 or a higher-numbered release, the higher release might not load if you issue the **boot system** command from Boot mode while the lower-numbered software is running on the router or if you insert a flash card running a higher-numbered release into a system running a lower numbered release. However, if you issue the **boot system** command from Global Configuration mode, the new software loads properly.

Upgrading from Release 5.1.1 or Lower-Numbered Releases to Release 6.x.x or Higher-Numbered Releases

Release 5.1.1 or lower-numbered releases support application images only up to 172 MB. To install larger application images for Release 6.0.0 and higher-numbered releases, you must first install Release 5.1.2 (or a higher-numbered 5.x.x release). This enables the system to support application images greater than 172 MB. For example, you cannot go from Release 5.1.1 to Release 7.2.0 without first upgrading to Release 5.1.2. See the following table for compatibility of releases.

JUNOSe Release	Highest Release Able to Load	Cannot Load	Maximum Application Image
5.1.1 or lower-numbered release	5.3.5p0-2 or the highest-numbered 5.x.x release	6.x.x or higher-numbered release	~ 172 MB
5.1.2 or higher-numbered release	No limitation	Not applicable	~ 234 MB
7.2.0 or higher-numbered release	No limitation	Not applicable	~ 256 MB

Your software upgrades may be available remotely through Telnet or FTP, or may be delivered on a new NVS card. Depending on how you access the software updates, there are two different procedures to follow. For more detailed information on installing software, and about NVS cards and SRP modules, see the following documents:

- *JUNOSe System Basics Configuration Guide, Chapter 6, Managing Modules*
- *Upgrading NVS Cards on SRP Modules in ERX Hardware Guide, Chapter 8, Maintaining ERX Routers*
- *Upgrading NVS Cards on SRP Modules in E120 and E320 Hardware Guide, Chapter 8, Maintaining the Router*

Moving Line Modules Between Releases

The Juniper Networks ERX1440 Broadband Services Router employs a 40-Gbps SRP module and a new midplane. Release 3.3.2 was the first software release to support the 40-Gbps SRP module and midplane. Before you can transfer a compatible line module from a Juniper Networks ERX705, ERX710, or ERX1410 Broadband Services Router to an ERX1440 router, you must first load Release 3.3.2 or a higher release onto the current router, and then reboot the router to load the release onto the line modules. If you then move any of those line modules to an ERX1440 router, that router is able to recognize the line module.

If you move a compatible line module from an ERX1440 router to an ERX705, ERX710, or ERX1410 router, the module loads properly in the new router regardless of the release.

SRP Module Memory Requirements

For Release 5.3.0 and higher-numbered software releases on ERX14xx models, ERX7xx models, and the Juniper Networks ERX310 Broadband Services Router, see *ERX Module Guide, Table 1, ERX Module Combinations*, for detailed information about memory requirements.

For Release 8.2.0 and higher-numbered software releases on Juniper Networks E120 and E320 Broadband Services Routers, see *E120 and E320 Module Guide, Table 1, Modules and IOAs*, for detailed information about memory requirements.

Hardware and Software Compatibility

For important information about hardware and software, see the document set as follows:

- Combinations of line modules to achieve line rate performance are in *JUNOS System Basics Configuration Guide, Chapter 6, Managing Modules*.
- Compatibility of ERX router modules with software releases is in *ERX Module Guide, Table 1, ERX Module Combinations*.
- Layer 2 and layer 3 protocols and applications supported by ERX router modules are in *ERX Module Guide, Appendix A, Module Protocol Support*.
- Compatibility of E120 router and E320 router modules with software releases is in *E120 and E320 Module Guide, Table 1, Modules and IOAs*.
- Layer 2 and layer 3 protocols and applications supported by IOAs on the E120 router and the E320 router are in *E120 and E320 Module Guide, Appendix A, IOA Protocol Support*.

Requesting Technical Support

Technical product support is available through the Juniper Networks Technical Assistance Center (JTAC). If you are a customer with an active J-Care or JNASC support contract, or are covered under warranty, and need post-sales technical support, you can access our tools and resources online or open a case with JTAC.

- **JTAC Policies**—For a complete understanding of our JTAC procedures and policies, review the *JTAC User Guide* located at <http://www.juniper.net/customers/support/downloads/710059.pdf>
- **Product Warranties**—For product warranty information, visit <http://www.juniper.net/support/warranty/>
- **JTAC Hours of Operation**—The JTAC centers have resources available 24 hours a day, 7 days a week, 365 days a year.

Self-Help Online Tools and Resources

For quick and easy problem resolution, Juniper Networks has designed an online self-service portal called the Customer Support Center (CSC) that provides you with the following features:

- Find CSC offerings:
<http://www.juniper.net/customers/support/>
- Search for known bugs:
<http://www2.juniper.net/kb/>
- Find product documentation:
<http://www.juniper.net/techpubs/>
- Find solutions and answer questions using our Knowledge Base:
<http://kb.juniper.net/>
- Download the latest versions of software and review release notes:
<http://www.juniper.net/customers/csc/software/>
- Search technical bulletins for relevant hardware and software notifications:
<https://www.juniper.net/alerts/>
- Join and participate in the Juniper Networks Community Forum:
<http://www.juniper.net/company/communities/>
- Open a case online in the CSC Case Manager:
<http://www.juniper.net/cm/>

To verify service entitlement by product serial number, use our Serial Number Entitlement (SNE) Tool located at
<https://tools.juniper.net/SerialNumberEntitlementSearch/>

Opening a Case with JTAC

You can open a case with JTAC on the Web or by telephone.

- Use the Case Manager tool in the CSC at
<http://www.juniper.net/cm/>
- Call 1-888-314-JTAC
(1-888-314-5822 – toll free in the USA, Canada, and Mexico)

For international or direct-dial options in countries without toll-free numbers, visit
<http://www.juniper.net/support/requesting-support.html>

Release Overview

These *Release Notes* cover Release 10.3.1 of the system software for the Juniper Networks E Series Broadband Services Routers and contain the following sections:

- Early Field Trial Features on page 7
- Unsupported Features on page 8
- Release Software Protocols on page 9
- SRC Software and SDX Software Compatibility Matrix on page 11

- Known Behavior on page 12
- Known Problems and Limitations on page 34
- Resolved Known Problems on page 52
- Errata on page 60
- *Appendix A, System Maximums*, on page 65
- *Appendix B, Module Name Cross-Reference Information* on page 107
- *Appendix C, Transferring DSL Line Rate Information from an Access Node to SRC Software*, on page 109

If the information in these *Release Notes* differs from the information found in the published documentation set, follow these *Release Notes*.

Before You Start

These *Release Notes* include information about the changes between Releases 10.3.0 and 10.3.1. Before you use your new software, read these *Release Notes* in their entirety, especially the section *Known Problems and Limitations*. You need the following documentation to fully understand all the features available in Release 10.3.1:

- These 10.3.1 Release Notes, which describe changes between Release 10.3.0 and Release 10.3.1
- The 10.3.0 Release Notes, which describe features available in Release 10.3.0.
- The 10.3.x documentation set, which provides detailed information about features available in Release 10.3.0

The 10.3.x documentation set consists of several manuals and is available only in electronic format. You can print your own documentation using the PDF and HTML formats available at the Juniper Networks Technical Documentation Web site at www.juniper.net/techpubs. Refer to the following table to help you decide which document to use.

Task	Document
Install the router	<i>ERX Hardware Guide</i> <i>E120 and E320 Hardware Guide</i>
Learn about modules	<i>ERX Module Guide</i> <i>ERX End-of-Life Module Guide</i> <i>E120 and E320 Module Guide</i>
Get up and running quickly	<i>E Series Installation Quick Start poster or ERX Quick Start Guide</i> <i>E120 and E320 Quick Start Guide</i>
Configure the router	<i>JUNOSe System Basics Configuration Guide</i>
Configure physical layer interfaces	<i>JUNOSe Physical Layer Configuration Guide</i>
Configure link layer interfaces	<i>JUNOSe Link Layer Configuration Guide</i>

Task	Document
Configure line module redundancy, stateful SRP switchover, unified ISSU, VRRP, and interchassis redundancy (ICR)	<i>JUNOSe Service Availability Configuration Guide</i>
Configure IP, IPv6 and Neighbor Discovery, and interior gateway protocols (RIP, OSPF, and IS-IS)	<i>JUNOSe IP, IPv6, and IGP Configuration Guide</i>
Configure IP routing services, including routing policies, NAT, J-Flow statistics, BFD, IPSec, digital certificates, and IP tunnels	<i>JUNOSe IP Services Configuration Guide</i>
Configure IP multicast routing and IPv6 multicast routing	<i>JUNOSe Multicast Routing Configuration Guide</i>
Configure BGP, MPLS, Layer 2 service, and related applications	<i>JUNOSe BGP and MPLS Configuration Guide</i>
Configure policy management	<i>JUNOSe Policy Management Configuration Guide</i>
Configure quality of service (QoS)	<i>JUNOSe Quality of Service Configuration Guide</i>
Configure remote access	<i>JUNOSe Broadband Access Configuration Guide</i>
Get specific information about commands	<i>JUNOSe Command Reference Guide A to M</i> <i>JUNOSe Command Reference Guide N to Z</i>
Monitor system events	<i>JUNOSe System Event Logging Reference Guide</i>
Look up definitions of terms used in JUNOSe technical documentation	<i>JUNOSe Glossary</i>

Release Highlights

Release 10.3.1 is a maintenance release.

Early Field Trial Features

The features described in this section are present in the code but have not yet been fully qualified by Juniper Networks. These features are available only for field test purposes in this release. If you use any of these features before they have been fully qualified, it is your responsibility to ensure that the feature operates correctly in your targeted configuration.

DHCP

- Support for DHCP External Server, DHCP Local Server, DHCP Relay, and DHCP Relay Proxy on POS Access Interfaces

The following packet over SONET (POS) module combinations on E Series routers now support configuration of the DHCP external server, DHCP local server, DHCP relay, and DHCP relay proxy applications, alone or in combination, when the POS module is the access interface:

- POS module combinations on the E120 router and the E320 router:
 - ES2 4G LM with ES2-S1 OC12-2 STM4 POS IOA
 - ES2 4G LM with ES2-S1 OC48 STM16 POS IOA
- POS module combinations on ERX14xx models, ERX7xx models, and the ERX310 router:
 - OCx/STMx POS line module with OC3-4 I/O module
 - OCx/STMx POS line modules with OC12/STM4 I/O module
 - OC48 line module with OC48 FRAME APS I/O module

In the current release, this feature is available for early field test purposes only.

You can configure DHCP external server, DHCP local server, DHCP relay, and DHCP relay proxy on these POS modules in either a virtual router (VR) or a VPN routing and forwarding instance (VRF).

As part of this feature, the **pos** keyword has been added to the existing **ip dhcp-local limit** command. To specify the maximum number of IP addresses that the DHCP local server application can supply to all POS access interfaces or to a specific POS access interface, in the range 0–96000, use the **ip dhcp-local limit** command with the new **pos** keyword. For example:

```
! Set the IP address limit for all POS access interfaces to 1000
host1(config)#ip dhcp-local limit pos 1000
! Set the IP address limit for the specified POS access interface to 2000
host1(config)#ip dhcp-local limit interface pos 5/0/0 2000
! Restore the IP address limit for all POS access interfaces to the default value,
! 48000
```

```
host1(config)#no ip dhcp-local limit pos
```

To display the maximum number of IP address leases available for POS access interfaces, use the existing **show ip dhcp-local limits** command. For example:

```
host1#show ip dhcp-local limits
```

```
*****
      DHCP Local Server Address Limits
ATM Limit      - 48000
VLAN Limit     - 48000
POS Limit      - 1000
Ethernet Limit - 48000
```

SDX Software and SRC Software

- Transfer of Calling Station ID to PDP
JUNOS Software now supports sending of the calling station ID to the Policy Decision Point (PDP) for a virtual router. To enable this, use the **sscc option send-calling-station-id** command in Global Configuration mode.

The following command has been modified in this release by the addition of the **send-calling-station-ID** keyword:

- **sscc option**

The output of the following command has been modified in this release:

- **show sssc option**

This feature is limited in this release to early field trial purposes only.

Unified ISSU

- Service Manager Support for Unified ISSU
Service Manager support for unified ISSU is limited in this release to early field trial purposes only.

Unsupported Features

The JUNOS Release 10.3.x documentation set describes some features that are present in the code but that have not yet been fully qualified by Juniper Networks. If you use any of these features before they have been fully qualified, it is your responsibility to ensure that the feature operates correctly in your targeted configuration.

The following features are present but unsupported in this release.

E120 Router and E320 Router

- The ES2 10G LM and ES2 10G Uplink LM do not support layer 2 statistics for VLANs.

- Subscriber Interfaces on the ES2 10G Uplink LM
You can configure dynamic subscriber interfaces and static subscriber interfaces on the ES2 10G Uplink LM using the CLI. However, configuring subscriber interfaces on the ES2 10G Uplink LM provides no benefit because access features such as per-subscriber QoS are unavailable on the module.

Multicast

- Unsupported IPv6 Data MDT Commands in CLI
The **ipv6 pim data-mdt** command and the **show ipv6 pim data-mdt** commands are unsupported in the current release.

The IPv6 PIM Data MDT Configuration mode is unsupported in this release. The following commands appear in IPv6 PIM Data MDT Configuration mode but are unsupported in the current release:

- | | |
|----------------------------------|------------------------------------|
| ■ ipv6 pim join-filter | ■ mdt-data-timeout |
| ■ ipv6 pim query-interval | ■ route map |
| ■ mdt-data-delay | ■ tunnel group-address-pool |
| ■ mdt-data-holdown | ■ tunnel source |

Policy Management

- External Parent Groups Unsupported on ES2 10G, ES2 10G Uplink, and ES2 10G ADV LMs
External parent groups are not supported on the ES2 10G, ES2 10G Uplink, and ES2 10G ADV LMs. If you create a policy that references an external parent group on these LMs, the system prevents you from attaching it to the LM interface and you receive an error message.

Stateful SRP Switchover (High Availability)

- Stateful SRP Switchover for Certain Applications
The stateful SRP switchover feature has not been qualified for the following applications:

Remote Access

- DHCP proxy client
- L2TP dialout

Release Software Protocols

The following list identifies the major software protocols supported in this release. For detailed information about any protocol, see the configuration guides.

Core Routing Stack

- Internet Protocol (IP) version 4 and version 6
- Transmission Control Protocol (TCP) for IPv4

- User Datagram Protocol (UDP) for IPv4 and IPv6

Network Management Protocols

- Simple Network Management Protocol (SNMP) versions 1, 2c, and 3

Routing Protocols

- Border Gateway Protocol (BGP-4)
- Distance Vector Multicast Routing Protocol (DVMRP)
- Internet Group Membership Protocol (IGMP)
- Intermediate System-to-Intermediate System (IS-IS)
- Layer 2 Virtual Private Networks (L2VPNs)
- Mobile IP
- Open Shortest Path First (OSPF) version 2 and version 3
- Protocol Independent Multicast Protocol (PIM), including PIM dense mode, PIM sparse mode, PIM dense-sparse mode, and PIM source-specific multicast
- Routing Information Protocol (RIP) version 2
- Virtual Private LAN Service (VPLS)
- Virtual Router Redundancy Protocol (VRRP)

Multiprotocol Label Switching (MPLS)

- Border Gateway Protocol (BGP-4)
- Label Distribution Protocol (LDP)
- Resource ReSerVation Protocol – Traffic Engineering Extensions (RSVP-TE)

Layer 2 Protocols

- Asynchronous Transfer Mode (ATM)
- Bridged Ethernet
- Bridged IP
- Cisco High-Level Data Link Control (Cisco HDLC)
- Ethernet
- Extensible Authentication Protocol (EAP)
- Frame Relay

- Layer 2 Tunneling Protocol (L2TP)
- Multilink Frame Relay (MLFR)
- Multilink Point-to-Point Protocol (MLPPP)
- Packet over SONET (POS)
- Point-to-Point Protocol (PPP)
- PPP over Ethernet (PPPoE)
- Transparent bridging

Security Protocols

- Internet Key Exchange (IKE)
- Internet Security Association and Key Management Protocol (ISAKMP)
- IP Authentication Header (AH)
- IP Encapsulating Security Payload (ESP)
- Network Address Translation (NAT)

SRC Software and SDX Software Compatibility Matrix

The SRC software offers the features of the SDX software on the C Series Controllers, a range of hardware platforms that use the Linux operating system. In contrast, the SDX software runs on Solaris workstations. The SRC software contains the features found in the associated SDX release plus additional features described in the *SRC Release Notes*.

The following table shows which versions of the SRC software and SDX software are compatible with specified versions of the JUNOS Software.

SRC Software Release	SDX Software Release	Tested with JUNOS Release
2.0.0	7.1.0	8.1.2, 8.2.2
2.1.0	Not applicable	9.1.0p0-1
3.0.0	Not applicable	9.0.0, 9.0.1, 9.1.1
3.1.0	Not applicable	9.2.0, 9.3.0, 10.0.0
3.2.0	Not applicable	10.1.0, 10.2.0, 10.3.0

For more detailed information about SRC software and SDX software compatibility with JUNOS releases, see the *SRC Release Notes*.

Known Behavior

This section briefly describes E Series router behavior and related issues. In some cases the behavior differs from non-E Series implementations; in others the behavior is included to emphasize how the router works.

AAA

- Although you can use the **max-sessions** command to configure a maximum of 32,000 outstanding authentication/authorization requests to a RADIUS server, AAA internal limits prevent the actual number of outstanding authentication/authorization requests from exceeding 9600. These internal AAA limits apply only to authentication/authorization requests and not to accounting requests.
- The JUNOS Software does not support accounting for ATM 1483 subscribers. The **atm1483** keyword for the **aaa accounting default** command is present in the CLI, but it is not supported.

ATM

- You cannot configure connection admission control (CAC) on an ATM interface on which you have created a bulk-configured virtual circuit (VC) range for use by a dynamic ATM 1483 subinterface. Conversely, you cannot create a bulk-configured VC range on an ATM interface on which you have configured CAC. The router rejects these configurations, which causes them to fail.

Configuring CAC and bulk-configured VCs on the same ATM interface was supported in previous JUNOS Software releases. As a result, if you are upgrading to the current JUNOS release from a lower-numbered release, configurations that use CAC and bulk configuration on the same ATM interface continue to work. However, we recommend that you disable CAC on these ATM interfaces to ensure continued compatibility with future JUNOS releases.

BGP

- The E Series router does not include the link-local IPv6 address in the next-hop field of an MP-BGP update message carrying IPv6 routing information over IPv4 transport. This behavior is compliant with RFC 2545 but might have interoperability issues with other implementations that depend on a link-local IPv6 address in the next-hop field on a directly connected external BGP peering.

Work-around: Enable EBGP multihop configuration on the remote (non-Juniper Networks) peer.

- The following message might be displayed under certain conditions:

```
bgpConnections (default,0.0.0.0): TCP error code xx (...) occurred while accepting inbound TCP connection
```

The message is generated when an unconfigured peer attempts to establish a TCP session with an E Series router and a valid route to the source address of the peer is absent from the router's routing table.

If a valid route exists in the routing table, the following message is displayed when an unconfigured peer attempts to establish a TCP session with an E Series router; X.X.X.X is the source address of the unconfigured peer:

```
NOTICE 08/29/2001 16:50:11 bgpConnections (default,X.X.X.X): Inbound
connection refused - no peer X.X.X.X configured in core
```

BGP/MPLS VPNs

- NAT does not function properly with secondary routing table lookup (fallback global) or global export mapping on the VRF.

B-RAS

- Pool groups are not supported; although the **ip local pool group** command appears in the CLI, it is not supported.
- If the router is under a heavy load, the **show profile** command might take longer than usual to execute.

Work-around: You can either delay examination of profiles until the router is less busy, or save a copy of the profile to a text file off the router.

CLI

- In Interface Configuration mode for a major interface, the CLI displays options for protocols that are not supported by that interface type.
- When you issue the **reload** command on an ERX310 router, the command might display a warning message that erroneously indicates that a synchronizing operation will be performed. Any references to synchronization that appear in command output or system messages do not apply to the ERX310 router, which does not support SRP module redundancy.
- The following commands have been deprecated in the JUNOS Software and might be removed completely in a future release. If a command has been deprecated for only a particular command mode, the table specifies any modes for which it is still available.

Deprecated Command	Command Mode	Preferred Command
aaa accounting interval	Global Configuration	aaa service accounting interval and aaa user accounting interval
cablelength short	Controller Configuration	
channel-group description	Controller Configuration	
channel-group shutdown	Controller Configuration	
channel-group snmp trap link-status	Controller Configuration	
channel-group timeslots	Controller Configuration	
classifier-list	Global Configuration	ip classifier-list
clock rate	Interface Configuration	

Deprecated Command	Command Mode	Preferred Command
color	Policy List Configuration	color in Classifier Group Configuration mode
controller e1	Global Configuration	
controller t1	Global Configuration	
description	Interface Configuration Still available in Controller Configuration and VRF Configuration modes	ip description
fdl	Controller Configuration	
fdl carrier	Controller Configuration	
fdl string	Controller Configuration	
fdl transmit	Controller Configuration	
filter	Policy List Configuration	filter in Classifier Group Configuration mode
forward next-hop	Policy List Configuration	forward next-hop in Classifier Group Configuration mode
forward next-interface	Policy List Configuration	forward interface in Classifier Group Configuration mode
hostname	Domain Map Tunnel Configuration Still available in Global Configuration mode	client-name
hssi description	Interface Configuration	
hssi force dte acknowledge	Interface Configuration	
hssi internal-clock	Interface Configuration	
ignore dcd	Interface Configuration	
ignore link-state-signals	Interface Configuration	
[no] ike cri	Global Configuration	[no] ipsec cri
interface hssi	Global Configuration	
invert tx clock	Global Configuration	
ip dhcp-local cable-modem	Global Configuration	set dhcp-relay with the strings docsis and pktc in the server-string mapping specification
ip mirror	Global Configuration	ip policy secure-input and ip policy secure-output; for E120 and E320 routers, you must use these commands because the ip mirror command has been removed from the CLI for those routers.
ip policy local-input	Interface Configuration, Profile Configuration	None

Deprecated Command	Command Mode	Preferred Command
[no] ipsec isakmp-policy rule	Global Configuration	[no] ipsec ike-policy-rule
ipv6 policy local-input	Interface Configuration, Profile Configuration	None
j1	Controller Configuration	
license l2tp-session	Global Configuration	None
lineCoding	Controller Configuration	
log	Policy List Configuration	log in Classifier Group Configuration mode
log severity debug dhcpLocalProtocolDecode	Global Configuration	log severity debug dhcpCapture
loopback	Domain Map Configuration Still available in Controller Configuration and Interface Configuration modes	local-interface
loopback remote { remote line fdl ansi remote line fdl bellcore remote line inband remote payload [fdl] [ansi] }	Controller Configuration	
mark	Policy List Configuration	mark in Classifier Group Configuration mode
mark-de	Policy List Configuration	mark-de in Classifier Group Configuration mode
mark-exp	Policy List Configuration	mark-exp in Classifier Group Configuration mode
mark-user-priority	Policy List Configuration	mark-user-priority in Classifier Group Configuration mode
mpls ldp discovery transport-address	Interface Configuration	This command has no effect in Interface Configuration mode. Now available in Global Configuration mode.
mpls topology-driven-lsp ip-interfaces	Global Configuration	ldp ip-forwarding
[no] next-hop	Policy List Configuration	forward next-hop in Classifier Group Configuration mode
[no] next-interface	Policy List Configuration	forward interface in Classifier Group Configuration mode
nrzi-encoding	Interface Configuration	
no ospf enable	Router Configuration	ospf shutdown
policy-list	Global Configuration	ip policy-list
radius disconnect client	Global Configuration The RADIUS Disconnect Configuration mode has been removed from the CLI.	subscriber disconnect

Deprecated Command	Command Mode	Preferred Command
rate-limit-profile	Policy List Configuration	rate-limit-profile in Classifier Group Configuration mode
remote-loopback	Controller Configuration	
show controllers t1/e1	User Exec, Privileged Exec	
show controllers t1 remote	User Exec, Privileged Exec	
show ike certificates	User Exec, Privileged Exec	show ipsec certificates
show ike configuration	User Exec, Privileged Exec	show ipsec ike-configuration
show ike identity	User Exec, Privileged Exec	show ipsec identity
show ike policy-rule	User Exec, Privileged Exec	show ipsec ike-policy-rule
show ike sa	User Exec, Privileged Exec	show ipsec ike-sa
show ip dhcp-external binding	Privileged Exec	show dhcp binding
show ip dhcp-external binding-id	Privileged Exec	show dhcp binding
show ip dhcp-local binding	Privileged Exec	show dhcp binding
show ip dynamic-interface-prefix	Privileged Exec, User Exec	None
show ip mirror interface	Privileged Exec	show secure policy-list
show license l2tp-session	User Exec, Privileged Exec	None
t1 lineCoding	Controller Configuration	None. This command never had any effect.
traffic-class	Policy List Configuration	traffic-class in Classifier Group Configuration mode
tunnel mpls autoroute announce bgp	Interface Configuration, Tunnel Profile Configuration	None
tunnel mpls label-dist	Interface Configuration, Tunnel Profile Configuration	None
unframed	Controller Configuration	
user-packet-class	Policy List Configuration	user-packet-class in Classifier Group Configuration mode
virtual-router	Domain Map Configuration Still available in Privileged Exec and Global Configuration modes	router-name
yellow	Controller Configuration	

The router displays a notice when you issue the command manually. If the command is in a script, the router automatically maps the deprecated command to the preferred command. If the deprecated command no longer has a function, then that command has no effect when you run a script containing the command.

- The **show configuration** command normally takes a long time to finish for extremely large configurations. If you specify a search string (with the **begin**, **exclude**, or **include** options) with the command for a string that is not present in the configuration, then the CLI session appears to be busy for a prolonged period. The CLI filtering feature for **show** commands does not speed up execution of the command.

DHCP

- Configuring authentication on the DHCP local server requires that you first disable the DHCP local server for standalone mode. Doing so removes your entire DHCP local server configuration. Therefore, if you want to configure authentication, do so before you have otherwise configured the DHCP local server.
- When you upgrade from a release numbered lower than Release 7.1.0, all DHCP host routes previously stored in NVS are deleted. After the upgrade, DHCP clients must reacquire their IP addresses, which results in the new host routes being correctly stored in NVS.

DHCP External Server

- If you are using DHCP external server and a burst of client releases occurs during a unified ISSU, some of the client releases might not be processed. [Defect ID 180178]
- When the DHCP relay agent application and the DHCP external server application are configured in the same virtual router, using the **ip dhcp-external server-sync** command on an unnumbered IP interface does not function as expected. When you issue the **ip dhcp-external server-sync** command in this configuration to create subscriber state information based on lease renewals when the external DHCP server and the router are unsynchronized, the router does not forward the ACK request from the DHCP server to the client because there is no route. [Defect ID 88562]
- When a bound DHCP client on a dynamic subscriber interface extends its IP address lease by restarting the DHCP discovery process on its primary IP interface instead of by initiating the DHCP renewal process on its dynamic subscriber interface, the default behavior of the DHCP external server application to preserve the client's dynamic subscriber interface was changed in the following JUNOSe releases to delete and re-create the client's dynamic subscriber interface:
 - Release 7.2.4p0-4 and all higher-numbered 7.2.x releases and patch releases
 - Release 7.3.4 and all higher-numbered 7.3.x releases and patch releases
 - Release 8.0.4 and all higher-numbered 8.0.x releases and patch releases
 - Release 8.1.2 and all higher-numbered 8.1.x releases and patch releases
 - Release 8.2.3 and all 8.2.3 patch releases
 - Release 9.0.0 and all 9.0.0 patch releases

- Release 9.0.1 and all 9.0.1 patch releases
- Release 9.1.0 and all 9.1.0 patch releases

If you are upgrading the JUNOSe Software on the router from any of these releases, you must explicitly issue the **ip dhcp-external recreate-subscriber-interface** command to configure the router to continue to delete and re-create the DHCP client's dynamic subscriber interface.



NOTE: The DHCP external server application is unsupported in JUNOSe Release 8.2.1 and JUNOSe Release 8.2.2.

- DHCP external server may not be able to bind all DHCP clients when all of the following conditions exist:
 - DHCP external server and either DHCP relay or relay proxy are configured in separate virtual routers on an E320 router.
 - The client-facing and server-facing interfaces for DHCP external server and either DHCP relay or relay proxy are configured on the same ES2 4G LM.
 - DHCP external server is configured to create dynamic subscriber interfaces.

When these three conditions exist simultaneously, the ES2 4G LM may not be able to successfully process all DHCP packets. Although all clients may get bounded in DHCP relay or relay proxy, some clients may not get bounded in DHCP external server. (In a production environment it is highly unlikely for conditions 1 and 2 to exist because stand-alone DHCP external server is normally configured for a DHCP relay in a different chassis.)

Work-around: You can eliminate this issue by modifying any one of these conditions. For example, this issue does not exist with any of the following configuration modifications:

- Configure DHCP external server and either DHCP relay or relay proxy in the same virtual router.
- Configure the client-facing and server-facing interfaces for DHCP external server and either DHCP relay or relay proxy on the same ES2 10G LM instead of the same ES2 4G LM.
- Configure the client-facing and server-facing interfaces for DHCP external server and either DHCP relay or relay proxy on separate ES2 4G LMs.

Dynamic Interfaces

- Dynamic IPv6 interfaces over static PPP interfaces are not supported.

Ethernet

- The hashing algorithm that selects the LAG member link is associated with the IP address of the subscriber client to support QoS. Consequently, a particular flow is always hashed to the same link. When a member link is removed from a LAG bundle, traffic rate is disrupted and traffic flow is reduced. When the link goes down and then comes back up, the traffic flow is automatically redistributed.
- When counting bits per second on a Fast Ethernet or Gigabit Ethernet interface, an E Series router includes 12 bytes for interpacket gap, 7 bytes for preamble, and 1 byte for start frame delimiter, for a total of 20 bytes (160 bits) per packet more than some non-E Series routers. This value therefore shows the total bandwidth utilization on the interface, including both data and overhead.
- To bridge unicast known-DA packets at line rate on both 2-Gbps ports of the GE-2 line module or the GE-HDE module when paired with the GE-2 SFP I/O module, the minimum packet size must be at least 144 bytes.

When installed in the ERX1440 router, the GE-2 module delivers full bandwidth of 4 GB per line module (2 GB at the ingress and 2 GB at the egress) only when installed in slot 2 or slot 4, and when the SRP-40G+ module is used in the router. When installed in any other ERX1440 slot, the GE-2 module delivers a maximum bandwidth of 2 GB per line module (1 GB maximum at the ingress and 1 GB maximum at the egress). Therefore, of the maximum 24 possible ports for the module in an ERX1440 chassis (that is, two ports in each of 12 slots), full bandwidth is delivered only on a maximum of four ports (those in slots 2 and 4).

When installed in the ERX1440 router, the GE-HDE line module delivers full bandwidth of 4 GB per line module (2 GB at the ingress and 2 GB at the egress) only when installed in slot 2 or slot 4, and when the SRP-40G+ module is used in the router. When installed in any other ERX1440 slot, the GE-HDE module delivers a maximum bandwidth of 2 GB per line module (1 GB maximum at the ingress and 1 GB maximum at the egress). Therefore, of the maximum 96 possible ports for the module in an ERX1440 chassis (that is, 8 ports in each of 12 slots), full bandwidth is delivered only on a maximum of 16 ports (those in slots 2 and 4).

When the GE-2 line module or the GE-HDE line module is installed in either the ERX1440 router or the ERX310 router and both ports are active, line rate performance is achieved only with packets that are 174 bytes or larger. The line module might not achieve line rate with packets that are smaller than 174 bytes.

- Support for the 0x9200 S-VLAN Ethertype has been removed. You can no longer specify the **9200** option with the **svlan ethertype** command.

When you upgrade to Release 7.1.0 or higher-numbered release, the software automatically transfers existing configurations that use the 0x9200 Ethertype to the 0x88a8 Ethertype.

- The **show interface gigabitEthernet** command output does not display the following line of output for Gigabit Ethernet modules that do not support SFPs, such as the GE Single Mode I/O module and GE I/O Multi Mode I/O modules:

Primary/Secondary link signal detected
 Primary/Secondary link signal not detected

Flash

- Flash cards manufactured by Wintec are present on some currently deployed routers. When you upgrade the JUNOSe Software on such routers, the firmware on the flash card controller is automatically updated during diagnostics. During this reboot, the software runs an integrity check on the file system to verify that the firmware update did not corrupt the contents of the flash card. This integrity check is an expected side effect of the enhanced firmware available in this release. The integrity check does not indicate a problem with the flash card or its contents.

GRE

- When you shut down the only outgoing IP interface to the IP destinations of GRE/IP tunnels, the tunnels remain in the up state rather than transitioning to down. As a consequence, all IP routes that use these tunnels as next hops also remain in the routing table.

Hardware

- SRP modules with only 1 GB of memory do not work reliably in ERX7xx and ERX14xx routers running JUNOSe Release 8.1.0 or higher, and may experience system resets due to an out of memory condition. However, the ERX310 router still supports 1 GB of memory in the SRP-SE10 module.

Work-around: Upgrade your SRP module memory to 2 GB for all ERX7xx and ERX14xx routers running JUNOSe Release 8.1.0 or higher.

- Do not include a **not protocol** clause in any classifier control list for policies attached to an interface on an ES2 10G Uplink LM. The **not protocol** functionality is not available for this module.
- The ES2 10G LM and the ES2 10G Uplink LM do not support VLAN statistics in the current release.
- PCMCIA NVS Card Caution



CAUTION: Before you insert or remove PCMCIA NVS (flash) cards from a running router, we strongly recommend that you halt the SRP module or shut down the router. Failure to do this can result in file corruption in one or both cards.

- The 4XOC3 APS MULTIMODE and 4XOC3 APS SINGLE MODE I/O modules are incompatible with the following versions of the OCx/STMx ATM and OCx/STMx POS line modules:
 - OCx/STMx ATM line modules with assembly numbers 350-00039-xx, 350-80039-xx, and 350-90039-xx
 - OCx/STMx POS line modules with assembly number 350-10039-xx

- When you configure 1:5 line module redundancy by using either the 4XOC3 APS MULTIMODE or 4XOC3 APS SINGLE MODE I/O module, the spare R-Mid OCX I/O module you install must have assembly number 350-00094-01 Rev. A01 or later. Spare R-Mid OCX I/O modules with an earlier assembly number are not supported for 1:5 redundancy configurations that use either the 4XOC3 APS MULTIMODE or 4XOC3 APS SINGLE MODE I/O module.
- There is a very small chance that some line modules can have an improperly modified keying block that prevents the module from proper seating in the top slot of an older ERX7xx chassis or a preproduction ERX310 chassis. For example, this problem has been observed for an OCx/STMx module in slot 2 of an early-test ERX310 chassis.

Work-around: Remove the keying block to insert the module into the top slot, or insert the module into a different slot.

HDLC

- By design, on the cOC12/STM4 module you cannot delete a serial interface while data for the interface is still enqueued. The enqueued data can drain only when the interface is operationally up. Therefore you must ensure that the interface is operationally up before you delete it. For example, if you have issued the **shutdown** command for the interface before you try to delete the interface, issue the **no shutdown** command, then delete the interface.

IP

- When you upgrade from certain releases to JUNOS Release 9.2.0p1-0 or higher-numbered releases, descriptions configured for IP interfaces or IP subinterfaces are not retained across the upgrade when the descriptions are shorter than 9 characters in length. Additionally, VRF descriptions are not retained across the upgrade when the combined length of the VRF description and the VRF name is shorter than 9 characters. This behavior is seen during upgrades using a reload, stateful SRP switchover, or unified ISSU. Upgrades from the following releases are affected by this behavior:
 - 7.x.x
 - 8.0.x
 - 8.1.x, 8.2.x, and 9.x.x builds created before July 23, 2008

Examples of descriptions that are not retained across the upgrade:

```
host1(config-if)#ip description 12345678
```

```
host1(config)#ip vrf 123
host1(config-vrf)#description 45678
```

Examples of descriptions that are retained across the upgrade:

```
host1(config-if)#ip description longdescription
```

```
host1(config)#ip vrf longername
host1(config-vrf)#description 45678
```

```
host1(config)#ip vrf 123
host1(config-vrf)#description longdescription
```

Work-around: Before you upgrade from an affected release to JUNOSe Release 9.2.0p1-0 or higher-numbered releases, ensure that you do the following:

- Change IP interface and subinterface descriptions to 9 or more characters.
- Change VRF descriptions, VRF names, or both so that the combination of associated VRF names and descriptions consists of 9 or more characters.
- The **ip tcp adjust-mss** command, which modifies the maximum segment size for TCP SYN packets traveling through the interface, is not supported on the ES2 10G LM or ES2 10G Uplink LM.
- If you have enabled ipInterface logging at a priority of debug, the acknowledgment that an interface has been deleted from the line modules can return to the SRP module after the layers beneath IP have deleted their interfaces. Consequently, the original name of the interface cannot be resolved or displayed in the log, and the system instead displays the ifIndex of the IP interface. This behavior has no functional effect other than that the log is misleading. However, previous log events indicate that the interface deletion was beginning.
- When you want to use a configuration script to configure IP shared interfaces that reference a physical interface, you must issue the **service show configuration format 2** command before you generate the script. If the default **show configuration** format (format 1) is enabled instead, the generated script cannot properly configure the IP shared interfaces because they are created before the physical interfaces. To properly configure the shared interfaces in this event, run the generated format 1 script twice.
- When you issue the **show ip forwarding-table** command for a particular slot, it is normal and appropriate behavior when the Status field indicates Valid while the Load Errors field is increasing daily for that VR. The Load Errors field records any failed routing table distribution attempt as an error. Attempts can fail for many reasons during normal operation; a failed attempt does not necessarily indicate a problem. It is normal to see many load errors per day. If the Status field indicates Invalid, then the routing table distribution has failed constantly for that VR and a real problem exists. You might occasionally see a status of Updating. However, if the Status field always indicates Updating, then again the routing table distribution has failed constantly for that VR, and a real problem exists.
- The enhancement to the CLI to support unnumbered reference to any kind of interface rather than just loopback interfaces has consequences such as the following: [Defect ID 47743]
 - If the references to shared interfaces appear in the **show configuration** output before the configuration for the interfaces they refer to, trying to restore such a configuration with a script generated from **show configuration** generates errors like the following:

```
% Error, line 3929:
```

```
host1(config-if)#ip share-interface FastEthernet 3/0.2
% No such interface
```

- Unnumbered interfaces that refer to nonloopback interfaces (for example, **ip unnumbered fastEthernet 3/0.2**) and that appear in the **show configuration** output before the interface referred to might generate similar no such interface errors.

Work-around: Run the script twice.

IPSec

- When you shut down the only outgoing IP interface to the IP destinations of IPSec tunnels, the tunnels remain in the up state rather than transitioning to down. As a consequence, all IP routes that use these tunnels as next hops also remain in the routing table. You can use dead keepalive detection (DPD) to avoid this situation. DPD must be active, which requires both IPSec tunnel endpoints to support DPD.
- During a warm restart after a system failover, the SRP module can take several minutes to resume the normal exchange of UDP/IP packets to applications. During this restart time, the E Series router does not send or receive dead peer detection (DPD) keepalives, which are used to verify connectivity between the router and its peers. The length of the restart time depends on the number of interfaces—if the restart time is too long, remote peers might determine that the connection from them to the E Series router is broken and then shut down an IPSec tunnel that has DPD enabled. In the worst case, all IPSec tunnels might be shut down. [Defect ID 65132]

IS-IS

- When IS-IS is configured on a static PPP interface, the IS-IS neighbor does not come up if you remove the IP address from the interface and then add the IP address back to the interface.

Work-around: When you remove and add back the IP address, you must also remove the IS-IS configuration from the interface and then add the configuration back to the interface by issuing the **no router isis** and **router isis** commands.

- When you run IS-IS on back-to-back virtual routers (VRs) in an IS-IS-over-bridged-Ethernet configuration and do not configure different IS-IS priority levels on each VR, a situation can occur in which both VRs elect themselves as the designated intermediate system (DIS) for the same network segment.

This situation occurs because the router uses the same MAC address on all bridged Ethernet interfaces by default. When both VRs have the same (that is, the default) IS-IS priority level, the router must use the MAC address assigned to each interface to determine which router becomes the DIS. Because each interface in an IS-IS-over-bridged-Ethernet configuration uses the same MAC address, however, the router cannot properly designate the DIS for the network segment. As a result, both VRs elect themselves as the DIS for the same network segment, and the configuration fails. [Defect ID 72367]

Work-around: To ensure proper election of the DIS when you configure IS-IS over bridged Ethernet for back-to-back VRs, we recommend that you use the **isis network point-to-point** command in Interface Configuration mode to configure IS-IS to operate using point-to-point (P2P) connections on a broadcast circuit when only two routers (or, in this case, two VRs) are on the circuit. Issuing this command tears down the current existing IS-IS adjacency in that link and reestablishes a new adjacency.

L2TP

- L2TP peer resynchronization enables an L2TP failed endpoint to resynchronize with its peer non-failed endpoint. The JUNOS Software supports failover protocol and silent failover peer resynchronization methods. If you configure the silent failover method, you must keep the following considerations in mind:
 - PPP keepalives—To ensure resynchronization of the session database, PPP keepalives must be enabled on the L2TP data path. Without PPP keepalives, silent failover might disconnect an established session if there is no user traffic during failover recovery.
 - Asymmetric routes on different line modules—Asymmetric routes whose receive and transmit paths use I/O paths on different line modules can result in improperly handled line module control packets. If your network does include this type of asymmetric route, tunnels using these routes might fail to recover properly.
- NAT dynamic translation generation affects the LNS session creation time. When NAT dynamic translations and LNS sessions are created simultaneously, NAT dominates the CPU cycles of the tunnel-service module, resulting in a delay in the LNS session creation rate. The LNS session creation rate returns to its normal rate when NAT dynamic translations are no longer being generated. [Defect ID 53191]

Work-around: When signaling performance must be optimal, avoid the simultaneous configuration of NAT and LNS.

- If you create an L2TP destination profile *profileName*, establish tunnels with the profile, and then remove the profile, you cannot subsequently create another destination profile using that same *profileName* until all the tunnels drain from the previous instance of this destination profile. If you do not wait, the E Series router displays a message similar to the following:

```
l2tp: Discarding incoming sccrq from vr default, remote address 192.168.100.1 -
no destination profile.
```

If you do not want to wait for the tunnels to drain, use a different name for the destination profile. [Defect ID 32973]

Line Module Redundancy

- On E120 routers and E320 routers, redundant IOAs have a temperature sensor, and the **show environment all** command lists the temperature of IOAs in their associated slots.

On ERX routers, redundant I/O modules do not have a temperature sensor. Therefore, the **show environment all** command output lists the primary I/O module temperature in the slot of the line module that is responsible for the I/O module.

- When you install an ES2-S1 Redundancy IOA with a hardware revision number of -02 or less in slot 0 or slot 11 of the E320 router or in slot 0 or the E120 router, do not install an OCx/STMx ATM IOA or an OCx/STMx POS IOA in the lower (E320) or left (E120) adapter bay of slot 1 or slot 12. When the spare line module is controlling another slot and you revert back to the primary line module, the ATM or POS IOAs can become unusable or cause the line module to reset. [Defect ID 69760]

Work-around: This problem is not present for ES2-S1 Redundancy IOAs with a hardware revision number of -03 or higher.

MLPPP

- Do not configure both MLPPP fragmentation (with the **ppp fragmentation** command) and IP fragmentation of L2TP packets (with the **ip mtu** command) on the same interface. Instead, you must choose only one of the fragmentation configurations by setting it to the necessary value and set the other fragmentation configuration to the maximum allowable value.

MPLS

- Martini circuits configured on the ES2 10G LM act as true layer 2 tunnels, without modifying the layer 2 headers. For this reason, Martini VLAN retagging is not currently supported.
- If you are upgrading to Release 7.1.0 or a higher-numbered release from a release numbered lower than Release 7.1.0, and have inter-AS option B or C configurations, you must explicitly configure MPLS on all inter-AS links, as in the following example:

```
host1#configure terminal
host1(config)#interface fastEthernet 2/0
host1(config-if)#ip address ...
host1(config-if)#mpls
```

If you do not explicitly configure MPLS on the links, the inter-AS feature will not work properly.

Multicast

- The **ip dipe sg-cache-miss** and **ipv6 dipe** commands are not intended or supported for customer use, although they are visible in the User Exec and Privileged Exec modes respectively. These commands are intended to be used in a Juniper Networks internal lab environment for testing without a traffic generator.
- Do not configure a multicast group with more than 10,219 outgoing interfaces (OIFS) on the same ES2 10G LM. [Defect ID 81768]

Packet Mirroring

- The ES2 10G LM supports the packet mirroring feature when the module is paired with the ES2-S2 10GE PR IOA, the ES2-S1 GE-8 IOA, or the ES2-S3 GE-20 IOA. When you use the ES2 10G LM with these IOAs, CLI-based interface-specific mirroring is not supported.
- When both interface-specific mirroring and user-specific mirroring are configured on the same interface, the interface-specific secure policies take precedence. The interface-specific secure policies, which you manually attach using the CLI, override and remove any existing secure policies that were attached by a trigger action. If the interface-specific secure policies are subsequently deleted, the original trigger-based secure policies are not restored.
- Typically, when configuring packet mirroring, you configure a static route to reach the analyzer device through the analyzer port. If the analyzer port is an IP-over-Ethernet interface, you must also configure a static Address Resolution Protocol (ARP) entry to reach the analyzer device. However, because only a single static ARP entry can be installed for a given address at any given time, when you are using equal-cost multipath (ECMP) links to connect to the analyzer device, the static ARP configuration does not provide failover if the link being selected fails or is disconnected. Therefore, to provide continued connectivity if the link fails when using ECMP, enable the **ip proxy-arp unrestricted** command on the next-hop router for each ECMP interface. As a result, when the link fails, the router sends an ARP request to identify the MAC address of the analyzer device and gets a response over the new link.

Policy Management

- The ES2 10G LM does not support the deprecated **next-hop** command.
- You cannot configure classifier lists that reference multiple fields for a VLAN policy list on the ES2 10G Uplink LM or the ES2 10G LM, with the exception of traffic-class and color. The system incorrectly classifies VLAN policies that classify using multiple fields. For example, an invalid policy list that references multiple fields uses both color and user-packet-class, or one classifier list using color and another using user-packet-class.
- In rare cases, some policy configurations that use CAM hardware classifiers from releases earlier than Release 7.1.0 can fail because they exceed the total hardware classifier entry size of 128 bits that was introduced in Release 7.1.0. For more information and examples of previous configurations, see *JUNOS Policy Management Configuration Guide, Chapter 8, Policy Resources*.

- Multiple Forwarding Solution Rules for a Single Classifier List in a Policy
Before Release 5.2.0, it was possible to configure a policy with multiple rules that specified forwarding solutions where all of these rules were associated with a single classifier list. This typically was a configuration error, but the CLI accepted it. Beginning with Release 5.2.0, the CLI no longer accepts this configuration.
- Multiple forwarding rules behavior for releases numbered lower than Release 5.2.0:
 - If multiple forward or filter rules were configured to reference the same classifier list in a single policy, then all rules except the first rule configured were marked as eclipsed in the **show policy** command display. Next-interface and next-hop rules were treated in the same manner. The eclipsed rules were not applied.
 - If a policy were configured with one rule from the [forward, filter] pair and one rule from the [next-hop, next-interface] pair, and if both rules referenced the same classifier list, then no visible eclipsed marking occurred. However, these two rules were mutually exclusive, and only one of them defined the forwarding behavior. The rule action that was applied was in the order (from highest to lowest preference): next interface, filter, next hop, forward. The applied rule was the rule whose behavior was seen by forwarded packets.

For example, if a policy had both a next-interface and a filter rule, then the next interface was applied. If a policy had a next-hop and a filter rule, then the filter rule was applied.

- Multiple forwarding rules behavior for Release 5.2.0 and higher-numbered releases:

Beginning with Release 5.2.0, the multiple rules behavior is designed so that when a forwarding solution conflict occurs within a policy, such as those described earlier, the second forwarding solution overwrites the preceding solution. That is, the last forwarding rule configured for the given classifier list within a policy is the forwarding behavior that is used. Also, a warning message is now displayed when this type of conflict occurs.

Example 1—In this example, the filter rule action overwrites the forward rule, and is therefore applied.

```
host1(config)#policy-list wstPolicyList
host1(config-policy-list)#forward classifier-group svaleClacl1
host1(config-policy-list)#filter classifier-group svaleClacl1
WARNING: This rule has replaced a previously configured rule.
host1(config-policy-list)#exit
host1(config)#
```

Example 2—In this example, three forwarding solution conflicts result in rules being overwritten. The filter rule is the last rule configured, and is therefore applied.

```
host1(config)#policy-list bostTwo
host1(config-policy-list)#forward classifier-group clacl5
```

```

host1(config-policy-list)#next-hop 1.1.1.1 classifier-group clacl5
WARNING: This rule has replaced a previously configured rule.
host1(config-policy-list)#next-interface atm 1/0.0 classifier-group clacl5
WARNING: This rule has replaced a previously configured rule.
host1(config-policy-list)#filter classifier-group clacl5
WARNING: This rule has replaced a previously configured rule.
host1(config-policy-list)#exit
host1(config)#

```



NOTE: When you upgrade the nonvolatile memory to Release 5.2.0 or later, the upgrade removes eclipsed rules and rules whose behavior was not applied in the previous release. This removal ensures that the postupgrade forwarding behavior is the same as the preupgrade behavior.

NOTE: If you upgrade to Release 5.2.0 or later and then configure your router using a script generated before Release 5.2.0, the postupgrade and preupgrade forwarding behaviors might not be the same. The new Release 5.2.0 configuration behavior is applied—the last policy rule configured for a given classifier list that specifies a forwarding behavior is the only rule remaining.

PPP

- The GE-2 line module does not support dynamic IP interfaces over static PPP interfaces when the PPPoE subinterface is also static. The OC3/STM1 GE/FE line module does not support dynamic IP interfaces over static PPP interfaces when the ATM interface column is also static.

PPPoE

- On the ES2 4G LM, ES2 10G LM, and ES2 10G Uplink LM, data packets for PPPoE are not counted at the PPPoE interface. Instead, PPPoE data packets are counted at the PPP interface that sits on the PPPoE interface. Use the **show ppp interface** command to display the data packets. Control packets for PPPoE are counted at the PPPoE interface; use the **show pppoe interface** command to display the control packets.

QoS

- In JUNOS Releases 7.1.x, 7.2.x, and 7.3.x, you can attach a QoS profile to Ethernet interfaces that are configured in a link aggregation group (LAG) interface. However, beginning with JUNOS Release 8.0.1, you can attach a QoS profile directly to the LAG interface. As of JUNOS Release 8.0.1, the software restricts you from attaching a QoS profile to any Ethernet interfaces that are members of a LAG. [Defect ID 84632]

Work-around: Prior to upgrading from JUNOS Releases 7.1.x, 7.2.x, or 7.3.x to JUNOS Release 8.0.x or higher-numbered releases, remove the QoS profile from the Ethernet interface. When you have successfully upgraded to JUNOS Release 8.0.x or higher-numbered releases, reattach the QoS profile to the LAG interface.

- In Release 7.2.0 and higher-numbered releases, you can configure the simple shared shaper to select scheduler nodes in a named traffic-class group as active constituents.

By default, simple implicit shared shapers activate scheduler nodes in named traffic-class groups. The implicit constituent selection process is now the same for both simple and compound shared shapers.

This is a change in default behavior. For releases before Release 7.2.0, you could not configure scheduler nodes as active constituents of the simple shared shaper, except for the best-effort node.

To recover the default behavior available before Release 7.2.0, or to select active constituents that are different, use simple explicit shared shapers to select best-effort nodes only.

- When you are configuring compound shared shaping using explicit constituents and you explicitly specify both a scheduler node and a queue stacked above the node as constituents of the shared shaper, the system selects the scheduler node (but not the queue) as the constituent.

RADIUS

- JUNOS Software provides extended commands for configuring the formats of the RADIUS NAS-Port attribute (attribute 5) and the RADIUS Calling-Station-ID attribute (attribute 31) when the physical port value is greater than 7.

When the physical port value is greater than 7:

- An incorrectly configured NAS-Port attribute format results if you use either the **radius nas-port-format 0ssssppp** or **radius nas-port-format ssss0ppp** command.
- An incorrectly configured Calling-Station-ID attribute results if you use either the **radius calling-station-format fixed-format** command or the **radius calling-station-format fixed-format-adapter-embedded** command.

Work-around: Use the following commands on routers that have line modules with more than 7 physical ports:

- To configure the NAS-Port attribute format, use the **radius nas-port-format extended [atm | ethernet]** command.
- To configure the Calling-Station-ID attribute format, use the **radius calling-station-format fixed-format-adapter-new-field** command.

SNMP

- SNMP MIBs
Information about all the SNMP MIBs (both standard and proprietary) that the router supports in this release is available in the MIB directory in the SW_Image_CD-2 folder of the JUNOS Software image bundle, which you downloaded from the Juniper Networks website, that contains the release file for E120 and E320 routers. .

- Some Juniper Networks SNMPv1-formatted traps contain an incorrect object identifier (OID) in the SNMPv1-Trap-PDU enterprise field. An SNMPv2 trap is typically identified by an OID that ends in the form ...x.y.z.0.n. This OID appears, in full, as the value of the snmpTrapOID.0 object in the varbind list of an SNMPv2-formatted trap. In the corresponding SNMPv1-formatted trap, this OID is broken down into subcomponents that fill the SNMPv1-Trap-PDU enterprise field (...x.y.z) and specific trap number field (n); the zero is unused.

The SNMPv1-formatted versions of the following Juniper Networks traps incorrectly contain ...x.y.z.0 in the SNMPv1-Trap-PDU enterprise field. That is, a zero is mistakenly appended to the correct enterprise OID value.

Trap Name	Expected Enterprise OID	Enterprise OID Sent by SNMP Agent
junidApsEventSwitchover	.1.3.6.1.4.1.4874.3.2.2.1.2	.1.3.6.1.4.1.4874.3.2.2.1.2.0
junidApsEventModeMismatch	.1.3.6.1.4.1.4874.3.2.2.1.2	.1.3.6.1.4.1.4874.3.2.2.1.2.0
junidApsEventChannelMismatch	.1.3.6.1.4.1.4874.3.2.2.1.2	.1.3.6.1.4.1.4874.3.2.2.1.2.0
junidApsEventPSBF	.1.3.6.1.4.1.4874.3.2.2.1.2	.1.3.6.1.4.1.4874.3.2.2.1.2.0
junidApsEventFEPLF	.1.3.6.1.4.1.4874.3.2.2.1.2	.1.3.6.1.4.1.4874.3.2.2.1.2.0
juniAddressPoolHighAddrUtil	.1.3.6.1.4.1.4874.2.2.21.3	.1.3.6.1.4.1.4874.2.2.21.3.0
juniAddressPoolAbatedAddrUtil	.1.3.6.1.4.1.4874.2.2.21.3	.1.3.6.1.4.1.4874.2.2.21.3.0
juniAddressPoolNoAddresses	.1.3.6.1.4.1.4874.2.2.21.3	.1.3.6.1.4.1.4874.2.2.21.3.0
juniDhcpLocalServerPoolHighAddrUtil	.1.3.6.1.4.1.4874.2.2.22.3	.1.3.6.1.4.1.4874.2.2.22.3.0
juniDhcpLocalServerPoolAbatedAddrUtil	.1.3.6.1.4.1.4874.2.2.22.3	.1.3.6.1.4.1.4874.2.2.22.3.0
juniDhcpLocalServerPoolNoAddresses	.1.3.6.1.4.1.4874.2.2.22.3	.1.3.6.1.4.1.4874.2.2.22.3.0
pimNeighborLoss	.1.3.6.1.3.61.1	.1.3.6.1.3.61.1.0

Work-around: Use the OIDs that the SNMP agent sends.

SSH

- If the SRP module restarts when SSH is configured in a VR other than default, SSH can sometimes become disabled. This happens if SSH attempts to bind with a VR before the VR comes back up after the restart. In this event, a warning message is generated to alert you to the fact that SSH is disabled in that VR. You must manually re-enable SSH either by accessing the console VTY or creating a Telnet session to the router.

Stateful SRP Switchover (High Availability)

- Additional processing is required to maintain and mirror the necessary state information that enables subscriber sessions to stay up across an SRP failover. As a result, the performance of other control plane functions is reduced. Specifically, call setup rates are lower than in previous releases.



NOTE: Rapid call setup rates are most important following an outage that causes all subscribers to drop, because many of the dropped subscribers will immediately attempt to reconnect. This type of outage occurs far less frequently with stateful SRP switchover.

We have ongoing development activities to characterize and improve call setup rates in future releases.

- Stateful SRP switchover remains inactive for 20 minutes after an initial cold-start or cold-restart of the router. This delay enables the system to reach a stable configuration before starting stateful SRP switchover.

If you want to override the 20-minute timer, turn high availability off by using the **mode file-system-synchronization** command, and then on again by using the **mode high-availability** command.

- When IP tunnels are configured on a router enabled for stateful SRP switchover, and the Service Module (SM) carrying these tunnels is reloaded, stateful SRP switchover transitions to the pending state. Stateful SRP switchover remains in the pending state for 10 minutes following the successful reloading of the SM. This amount of time allows for IP tunnel relocation and for the tunnels to become operational again on the SM. If an SRP switchover occurs while in the pending state, the router performs a cold restart.

Work-around: None.

- After a stateful SRP switchover, each layer of the interface columns must reconstruct its interfaces from the mirrored information. While the interfaces are being reconstructed the SRP module cannot send or receive frames, including the protocol frames that signal graceful restart behavior with OSPF and IS-IS peers. If the configured hold time is too short, peers might mistakenly declare the adjacency down during the time in which the graceful restart is taking place. [Defect ID 65132]

Work-around: Increase the hold time to provide sufficient time for interface synchronization before the peers declare the adjacency down.

- For OSPF, use the **ip ospf dead-interval** command to set the hold time. We recommend that you use Bidirectional Forwarding Detection (BFD) with a longer OSPF dead interval to achieve fast failure detection.
- For IS-IS, use the **isis hello-interval** and **isis hello-multiplier** commands to set the hold time.

We recommend the following hold times for each protocol, based on the number of interfaces.

Interface Count	Recommended Hold Time for OSPF	Recommended Hold Time for IS-IS
16000 or less	80 seconds	50 seconds
16001 to 32000	87 seconds	55 seconds
32001 to 48000	90 seconds	70 seconds

Subscriber Interfaces

- MAC address validation is not supported on either of the following:
 - Packet-triggered subscriber interfaces that are created dynamically
 - Packet-triggered subscriber interfaces that are managed on the primary IP interface

A packet-triggered subscriber interface is created when the router receives a packet with an IP source address that does not match any entries in the demultiplexer table. When the router detects an unmatched packet, it generates a trigger event that determines whether to create a dynamic subscriber interface or configure an existing interface. To configure packet detection on the router, use the **ip auto-detect ip-subscriber** command.

System

- ERX routers display different behavior from E120 routers and E320 routers when reporting modules as inactive.

ERX routers report a module as inactive when either:

- The I/O module is not present
- The primary line module is fully booted and ready to resume operation. In this case, the standby is currently providing services.

E120 routers and E320 routers report a module as inactive when either:

- The primary line module has no IOAs.
- The primary line module has IOAs, but they have failed diagnostics.
- The standby line module has taken over for the primary line module, and has control of the IOAs.

Because E120 and E320 routers can accommodate up to two IOAs per slot, at least one IOA must be online. If the second IOA fails, the line module is still online, but does not use both IOAs. You can ensure that every module is up and active in the system and not in a failed state by issuing the **show version all** command.

- In a router with a redundancy group that does not span quadrants (for example, a three-slot redundancy group that spans slots 0, 1, and 2 in an ERX1410 chassis), the potential bandwidth of the redundant module is erroneously included in the quadrant bandwidth calculation. The **show utilization** command might indicate that the bandwidth is exceeded for modules in that group. [Defect ID 31034]
- When you copy the running configuration to NVS, the E Series router verifies whether it has available space equal to at least twice the size of the .cnf file. If the space is insufficient, you cannot complete the copy. [Defect ID 40655]

Work-around: Make sufficient space on the NVS by deleting .rel or .cnf files.

- You cannot delete the ipInterface log after you delete the corresponding IP interface. This does not prevent you from adding filters to other interfaces, nor does it prevent you from adding a filter to the same interface if you re-create it after deletion. [Defect ID 34842/45063]

Work-around: Remove the filter before you remove the interface. Alternatively, if you remove the interface first, then you must remove all filters associated with all IP interfaces.

System Logging

- If you enable engineering logs and set the control network logs to a level of notice or lower (down from the default of error), you might see erroneous controlNetwork log messages like the following that are generated because SNMP polling on line modules (correctly) detects no fabric: [Defect ID 43168]

NOTICE 09/01/2002 18:47:52 CEST controlNetwork (slot 11): Control Bus Master slave error 0x5 while accessing slot

Tunneling

- When you configure the GE-2 line module, the GE-HDE line module, or the ES2-S1 GE-4 IOA to operate as a shared tunnel-server module, the available bandwidth for tunnel services is limited to 0.5 Gbps per module.
- In releases numbered lower than Release 7.3.0, a dynamic tunnel-server port was located on port 8 of the GE-HDE line module and GE-8 I/O module.

In Release 7.3.0 and higher-numbered releases, the dynamic tunnel-server port is located on port 9. When you upgrade to Release 7.3.0, any existing tunnel-server port configurations move from port 8 to port 9.

Known Problems and Limitations

This section identifies the known problems and limitations in this release. For more information about known problems that were discovered at customer sites, you can log in to the JUNOS Knowledge Base at <https://www2.juniper.net/kb/>, enter the defect ID number in the Search by Keyword field, and click Search.

ANCP

- On an E320 router that has established 3000 ANCP adjacencies with a client and traffic is initiated, the following behavior occurs sporadically: All existing Telnet sessions are disconnected and no new Telnet sessions can be established for several minutes. [Defect ID 83872]

ATM

- When 16,000 PPPoA interfaces are configured on an OCx/STMx ATM line module paired with an OC3-4 I/O module in an ERX14xx model, ERX7xx model, or ERX310 router, Ping traffic passing through the line module on the restarting router experiences an outage of 103 seconds, which is beyond the maximum limit, after a unified ISSU from JUNOS Release 9.2.0p1-0 to 9.3.0b0-12. This outage does not occur when the same configuration is applied on a Gigabit Ethernet interface. [Defect ID 179794]

- When you reload an ATM line module that is configured with NBMA circuits as passive OSPF interfaces and that has established OSPF adjacencies and IBGP peers (configured on Gigabit Ethernet interfaces), the transmission of OSPF hello packets might be affected until all the NBMA interfaces have initialized. [Defect ID 46157]

Work-around: Either remove the passive OSPF interface statements on the NBMA interfaces, or statically configure the OSPF cost on the NBMA interfaces.

- When a mirror rule that triggers on username is employed for packet mirroring of dynamic IP subscribers over ATM, removal of the rule does not disable packet mirroring. [Defect ID 175356]

Work-around: Use a mirror rule that triggers on account session ID rather than on username.

- The ATM peak cell rate (PCR) does not appear in the L2TP Calling Number AVP for the first PPP session when the ATM shaping parameters were configured by RADIUS return attributes. [Defect ID 60933]
- When you issue the **no atm atm1483 auto-configure** *upperInterfaceType* **lockout-time** command in Profile Configuration mode, the lockout time range does not revert to the default values. [Defect ID 66544]
- When one or more ATM1483 attributes appears in a profile, the **show configuration include-defaults** command fails to display the default values for all possible ATM1483 attributes. [Defect ID 67157]
- The output of the **show atm arp** command displays only 4096 entries when the line module is configured with more than 4096 NBMA ARP entries. [Defect ID 68849]

- When you use the **no-authenticate** keyword with the **subscriber** command to prevent subscriber authentication so that the subscriber information can be used for DHCP option 82, suboption 2, the SRP module can reset. This issue does not occur when you use the **no-authenticate** keyword with the **subscriber** command as a way to perform a RADIUS configuration. [Defect ID 69865]
- When you perform an `snmpWalk` on the `juniAtmSubIfVccTable`, a response is received for only a few of the total configured ATM subinterfaces when both of the following are true: the router has a line module that has some ATM-related configuration and the line module is in the disabled state. [Defect ID 80020]
- The **baseline interface atm** command fails for a VCD assigned by the router to F4 OAM circuits. [Defect ID 174482]
- Unified ISSU is not supported when ILMI is configured on ATM interfaces. [Defect ID 176007/177297/177122]
- ATM line modules reset after unified ISSU completes at the LAC when an MLPPP bundle with three links are tunneled to the LNS. [Defect ID 178821]
- For PPPoE, the AAL5 `inPacket Discards` counter might increment erroneously during call setup when a packet is passed directly to PPPoE for negotiation rather than being discarded. [Defect ID 51757]

Work-around: Incremental `InPacketDiscards` during call setup do not necessarily indicate a problem. However, we recommend you investigate an excessive count because that might indicate a connection that cannot be successfully brought up for some reason, such as RADIUS denials or improper configuration.

- The `inPacketOctetDiscards` counter in the output of the **show atm vc atm interface vcd** command includes both `inBytesDropped` and `inBytesUnknownProtocol` statistics. The `inBytesUnknownProtocol` statistics should be displayed by a separate counter.

At the major interface level, the `inPacketDiscards` counter includes both `inPacketsDropped` and `inPacketUnknownProtocol` statistics. The `inPacketUnknownProtocol` statistics should be displayed by a separate counter. [Defect ID 44286]

- When you configure an ATM PVC where PCR = SCR and maximum burst size is zero, the CLI returns an error indicating the burst size is invalid and it does not create the VC. [Defect ID 58357]

Work-around: Configure a CBR or a UBR plus PCR to create the circuit with the same parameters, depending on the desired priority for the traffic. CBR has a high priority and UBR plus PCR has a medium priority.

BFD

- After you have shut down the interface to the next hop (for the route that is used to establish the BFD session), output for the **show bfd session** command erroneously indicates the shutdown interface as Management Interface (FastEthernet 6/0). [Defect ID 174271]

Bridged Ethernet

- The CLI erroneously permits you to configure **bridge1483** encapsulation over AAL5MUX IP even though that configuration is not supported. [Defect ID 35013]

CLI

- When you issue a **run show ppp** command, the CLI changes the configuration level of the command line to Global Configuration mode rather than remaining at the level from which you issued the command. [Defect ID 52165]

Work-around: Reissue the commands necessary to reenter the desired mode.

- The **logout subscribers all** command may not log out all of the DHCP subscribers. Although the bindings and DHCP addresses are cleared, the **show subscribers summary** command may display some of the DHCP subscribers. [Defect ID 180176]

Work-around: Try using the **dhcp delete-binding all** command. If this does not clear the subscribers, you may want to reload the line module to avoid further issues.

DHCP

- DHCP packets are not forwarded to the DHCP server over dynamically created interfaces when all of the following are true: [Defect ID 180343]
 - DHCP relay or DHCP relay proxy is configured on the router.
 - The client-facing interfaces are created dynamically using bridged Ethernet over static ATM PVCs.
 - The **ip auto-detect ip-subscriber** command is configured to enable packet detection (packet triggering) and to trigger creation of dynamic subscriber interfaces.

Work-around: To avoid this defect, do all of the following:

- Do not use the **ip auto-detect ip-subscriber** command to enable packet triggering and to create dynamic subscriber interfaces
- Ensure that DHCP external server is configured in the virtual router.
- Ensure that the **set dhcp relay inhibit-access-route-creation** command is configured in the virtual router to prevent DHCP relay from installing host routes by default.

DHCP External Server

- With the unique client ID option enabled, when two clients with the same MAC address or client ID are on an interface (where one client is connected over a router and relay and the other client is connected directly), sending a release request from one of the clients might terminate another client. [Defect ID 179759]

- The DHCP renew counter and release counter (displayed with the **show ip dhcp-external statistics** command) are doubled rather than incremented for each renew and release sent. [Defect ID 78802]
- When DHCP clients on an S-VLAN over bridged Ethernet stack configuration send a decline message to a router that has DHCP relay and DHCP external server configured in the same VR, the clients bindings are not removed from the DHCP external server. [Defect ID 87086]
- When DHCP relay and DHCP external server are configured in the same VR with server-sync enabled, bindings are not created in the DHCP external server when DHCP clients on an ATM bulk configuration interface stack and dynamic VLAN over Ethernet stack sends a renew message. [Defect ID 87087]
- DHCP NAK packets are sent from a different VLAN than the one on which the renew request is received on a router that is configured with dynamic VLANs, DHCP local server, and automatically created dynamic subscriber interfaces. This behavior occurs only after a link flap has taken place. [Defect ID 87062]

DoS Protection

- A Telnet session closes when sending ipLocalBGP protocol traffic at a rate in the range 4096–4200 packets per second (pps) with suspicious control flow detection enabled. [Defect ID 81974]

Work-around: When the traffic drops below 4096 pps, open a new Telnet session.

Ethernet

- When autonegotiation is enabled on Gigabit Ethernet interfaces with the **speed automatically negotiate** command, issuing the **link selection** command logs out subscribers. [Defect ID 87185]

Work-around: Use the following commands to enable auto link selection (GE port redundancy) and to switch from one port to the other port:

```
(config-if)#no link selection
(config-if)#link failover force
```

File System

- When the primary SRP module is running JUNOS Release 7.2.0 or higher-numbered release and the standby SRP module is running a release numbered lower than Release 7.2.0 (as in a downgrade situation), you cannot display the files for the standby SRP module. [Defect ID 74104]

Forwarding

- The DoS protection egress rate is not accurate for the ES2 10G LM or the ES2 10G Uplink LM. [Defect ID 86925]

- When performing MAC validation to match subscriber demux entries with ARP host entries, the ES2 10G LM does an exact match, rather than a longest prefix match. The subscriber demux entry source address must be a /32 value matching the IP address of an ARP entry in order to validate the MAC address against that ARP entry. [Defect ID 79641]
- When PPPoE over LAG is configured on an interface, and you re-execute the PPPoE-over-LAG configuration before you delete the previous configuration, the ES2 10G LM line module resets. [Defect ID 179639]

Work-around: Before you can re-execute the PPPoE-over-LAG configuration, delete the existing PPPoE-over-LAG configuration.

- VPLS forwarding does not function properly when any of the following conditions occur: [Defect ID 79856]
 - MLPPP interfaces are used
 - L2TP is used with sequence numbers enabled
 - GRE is used with sequence numbers enabled
- Specifying S-VLAN ranges that partially overlap does not work. [Defect ID 81886/81918]

For example, the following configuration fails because S-VLAN 22 falls within the previously specified S-VLAN range of 21–23.

```
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 21 23 401 426
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 21 23 427 712
host1(config-if)#vlan bulk-config BulkCezarCng2 svlan-range 22 22 101 110
```

Work-around: You can do either of the following to avoid this problem.

- Specify each S-VLAN within the partially overlapping range as individual S-VLANs, as in the following example:

```
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 21 21 401 426
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 22 22 401 426
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 23 23 401 426
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 21 21 427 712
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 22 22 427 712
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 23 23 427 712
host1(config-if)#vlan bulk-config BulkCezarCng2 svlan-range 22 22 101 110
```

- Use fully overlapping ranges rather than partially overlapping ranges, as in the following example:

```
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 21 23 401 426
host1(config-if)#vlan bulk-config BulkDHCPcng1 svlan-range 21 23 427 712
host1(config-if)#vlan bulk-config BulkCezarCng2 svlan-range 21 23 101 110
```

- When you attach certain hierarchical policies to subinterfaces as input policies, secondary input policies, and output policies, incoming traffic loss can occur when the number of subinterfaces to which the policies are attached exceeds 4600. [Defect ID 86741]

- Ethernet statistics are incorrectly displayed for virtual port 8 of the ES2-S1 GE-8 IOA when that module is paired with the ES2 10G LM or the ES2 10G Uplink LM. [Defect ID 174784]
- The ES2 10G LM does not support framed routes configured for dynamic subscriber interfaces. [Defect ID 83154]
- A memory leak of about two percent can occur on the ES2 10G LM and result in a module reset when a large number of successive SRP switchovers take place with active DHCP clients. [Defect ID 86245]
- On the ES2 10G LM, a VLAN ID of 0 assigned to an interface can prevent packets from being properly forwarded. [Defect ID 176125]

ICR

- When you configure ICR settings using a CLI macro, ICR commands are run in quick succession. Sometimes, in such a scenario, the active SRP module resets if the event that causes the change of state of the VRRP instance reaches the ICR application before the ICR partition has been created. [Defect ID 184095]

Work-around: To avoid this problem, add an additional delay of one second using the **sleep** command in the macro, before the **ip vrrp vrid enable** command that is written in the macro to enable VRRP instance.

For example, consider a macro that contains the following commands:

```
ip vrrp vrid enable
ip vrrp vrid icr-partition partitionId
```

Modify the macro, as follows, to add a delay of one second before the VRRP instance ID is enabled on the router and a delay of another second before the ICR partition that corresponds to the VRRP instance is created:

```
sleep 1
ip vrrp vrid enable
sleep 1
ip vrrp vrid icr-partition partitionId
```

- If you saved the running configuration of the router as a script file (.scr) and execute the script to apply the settings on the router, ICR partition configuration commands in the .scr file might fail to add group members to the partition. This problem happens when the subscriber configuration in the .scr file is placed before the ICR partition configuration. However, this problem does not occur if you used a system configuration (.cnf) file to set up the router. [Defect ID 183913]

IGMP

- IGMPv3 proxy is not supported. [Defect ID 46038]
- The default value for the IGMPv3 proxy unsolicited report interval timer should be 1 second rather than 10 seconds (the value for v2). [Defect ID 46040]

- The E Series router IGMPv3 proxy does not operate correctly in the presence of IGMPv2 queriers. [Defect ID 46039/46045]

Work-around: If an IGMPv2 router is present on the network, do not configure version 3 with the **ip igmp-proxy version** command on that network interface. (Version 2 is the default.)

- When more than about 100,000 mapped OIF entries are configured on a virtual router, issuing the **no virtual router** command for this and other virtual routers does not delete all the virtual routers within the deletion timeout interval (3 minutes). The virtual routers do eventually delete after this timeout. [Defect ID 63882]
- The E Series router does not log a warning when it receives an IGMPv2 query but is not configured to use IGMPv2 on the interface. [Defect ID 46046]

IP

- The ES2 4G LM can reset during a unified ISSU after you issue the **issu start** command on a router configured with 8000 dynamic VCs and 8000 packet-triggered dynamic subscriber interfaces. [Defect ID 86761]
- If you have a large configuration on a hybrid module combination (OC3/STM-1 GE/FE line module with the OC3-2 GE APS I/O module), boot from NVS, and issue the **slot erase** command before booting has completed, the line module resets. [Defect ID 64104]

Work-around: To recover from the error, issue the **slot reload** command anytime after the module begins to reset.

- Deleting a VRF with 32,000 static subscriber interfaces fails to complete. [Defect ID 82670]

Work-around: Use a macro to delete all static subscriber interfaces before you delete a VRF.

- IP interface statistics become inconsistent when a slot is reset, because some traffic (such as control traffic) might be destined for the SRP module and is therefore counted elsewhere. [Defect ID 26697]
- The **ip route permanent** command does not work properly. [Defect ID 34303]

Work-around: Issue the **ip alwaysup** command to prevent the route from being removed from the IP routing table after the interface is shut down.

- Traffic statistics for dynamic subscriber interfaces associated with Mobile IP subscribers are not maintained as the subscribers move between Mobile IP nodes. Consequently the reported interface statistics are only the values accumulated since the last time a mobile node moved. [Defect ID 174509]
- When a router configured with PIM on a virtual router undergoes multiple warm restarts, the router subsequently hangs when an IP profile is configured. [Defect ID 176470]

- Logical port 20 on the ES2-S3 GE-20 IOA is reserved for the hardware multicast packet replication feature. Logical port 20 and the hardware multicast replication feature are not supported on the ES2-S3 GE-20 IOA in this release. [Defect ID 84727]
- When you change the demultiplexer type on a primary interface that has 1024 demultiplexer table entries, the ICC ping threshold times out due to the removal of the old entries and the addition of the new ones. [Defect ID 182218]
- After an SRP stateful switchover completes on an ERX1410 router configured with a single VPN routing and forwarding instance (VRF) and Network Address Translation (NAT), the SRP module that becomes active after the switchover resets. [Defect ID 180058]

IPSec

- When the LAC-to-LNS data path runs over an MPLS tunnel and the MPLS tunnel originates or terminates at the LAC on an ES2 10G LM or an ES2 10G Uplink LM, the L2TP data traffic that originated or terminated at the LAC is discarded. [Defect ID 87260]
- In a network where you use the tunnel signalling command to specify that the security parameters and keys are configured manually for IPSec tunnels between VRs, the line modules reset when you delete and then re-create the IPSec tunnels. If you attempt to configure the tunnels again after the modules come back up, the line modules reset again.

Work-around: Configure the IPSec tunnels to use ISASKMP/IKE to negotiate SA and establish keys. [Defect ID 178304]

- IPSec tunnels created over Fast Ethernet interfaces fail to come up. [Defect ID 179256]

Work-around: After you create the tunnel, bounce the tunnel interface by issuing the **shutdown/no shutdown** command sequence. The tunnel comes up successfully.

IS-IS

- On a router configured with IS-IS and BFD, using the **redundancy force srp** command to force an SRP switchover sometimes brings down IS-IS and BFD. [Defect ID 179287]
- IS-IS graceful restart (nonstop forwarding) does not work on the broadcast interface when the restarting router is the designated intermediate system (DIS). Graceful restart works properly when the restarting router is not the DIS. [Defect ID 61496]

L2TP

- After a unified ISSU completes on a router functioning as an L2TP access concentrator (LAC), traffic outages occur on the L2TP network server (LNS)-facing interface at the LAC in a configuration with 16,000 or 32,000 L2TP sessions over 500 tunnels. [Defect ID 180147]

MLD

- MLDv2 proxy is not supported. [Defect ID 46038]
- The E Series router MLDv2 proxy does not operate correctly in the presence of MLDv1 queriers. [Defect ID 46039/46045]

Work-around: If an MLDv1 router is present on the network, configure version 1 with the **ipv6 mld-proxy version** command on that network interface. (Version 2 is the default.)

- The default value for the MLDv2 proxy unsolicited report interval timer should be 1 second rather than 10 seconds (the value for v1). [Defect ID 46040]
- The E Series router does not log a warning when it receives an MLDv1 query but is not configured to use MLDv1 on the interface. [Defect ID 46046]

MLPPP

- Failure to meet all of the following conditions for fragmented packets can result in an incorrect operation during packet classification of the resulting reassembled packet: [Defect ID 50111]
 - The initial fragment of a packet must either contain the entire MLPPP packet or be greater than 128 bytes.
 - The fragment size of the peer must not be lower than 128 bytes.
 - The initial fragment of a packet must be larger than subsequent fragments of that packet.

Mobile IP

- The **clear ip mobile binding nai @realm** command does not work. [Defect ID 178652]

Work-around: Use the following version of the command instead:

```
clear ip mobile binding nai user@realm
```

- The **@realm** variable and the **@** keyword alone do not work for the **show ip mobile binding** command. [Defect ID 178653]

Work-around: You can use the **user@realm** syntax instead to display the binding for a specific user, as in this example:

```
host1#show ip mobile binding nai xyz@example.com
```

Alternatively, you can display the entire Mobile IP binding table by issuing the **show ip mobile binding** command without additional options.

- The setup rate for Mobile IP client sessions decreases when you repeatedly bring a large number of sessions down and back up. [Defect ID 178760]

- When mobility bindings are present and you delete the Mobile IP home agent with the **no virtual router** command, Mobile IP sends a RADIUS Acct-Stop message with no accounting statistics for the subscribers. [Defect ID 179081]

Work-around: Issue the **clear ip mobile binding all** command before you issue the **no virtual router** command. The **clear** command clears all the MIP subscribers and sends a RADIUS Acct-Stop message with the appropriate accounting statistics for the subscribers.

MPLS

- When MPLS and IS-IS are configured on Ethernet interfaces, you cannot delete the interface after the IP address is removed. This issue is not a problem on Ethernet VLAN interfaces. [Defect ID 66813]

Work-around: Issue the **no mpls** command to disable MPLS, then delete the interface.

- You cannot use an underscore character (`_`) in an MPLS tunnel name. [Defect ID 31291]
- If LSPs are announced into IS-IS, then the IS-IS routes cannot be used for multicast RPF checks, because LSPs are unidirectional. [Defect ID 28526]

Work-around: Configure static RPF routes with native hops when LSPs are autoroute announced to IGP.

- When the IPv4 explicit null label appears anywhere other than at the bottom of the label stack, TTL expiration for this label is not handled correctly. As a result, the **traceroute** command does not work correctly for LSPs that have the IPv4 explicit null label anywhere other than at the bottom of the label stack. [Defect ID 76037]
- When you upgrade the router to JUNOS Release 7.1.0 or a higher-numbered release from a release numbered lower than Release 7.1.0, remote ATM layer 2 over MPLS circuits (also known as MPLS shim interfaces) that use Martini encapsulation are erroneously signaled with the control word attribute setting “Control word is not preferred by default”. Because control words are required for these MPLS shim interfaces, these circuits should instead be signaled with the setting “Control word is preferred by default”. [Defect ID 87048]

Work-around: To reinstate the proper setting (“Control word is preferred by default”), remove the MPLS shim interface from the ATM subinterface and then reconfigure it.

- When you issue a **traceroute** or **trace mpls** command to trace the paths of router packets over MPLS interfaces on an ES2 10G LM or ES2 10G Uplink LM, the results include an extra unknown host. [Defect ID 174537]

Netflow

- Flow sampling stops after a cold switchover on a router that is configured with 16 VRs and 32 interfaces per VR, when all flows are passing through the configuration (32 flows per VR). [Defect ID 74477]

Work-around: After the cold switchover is completed, reissue the **ip flow-sampling-mode packet-interval 10** command on each VR, even though the command is present in the configuration.

- The OC3/STM1 GE/FE line module might reset after sending Ethernet traffic into a VPLS network in a test environment when Ethernet packets are flooded to remote VPLS bridges. [Defect ID 74540]

Policy Management

- On the E320 router, redirecting a large configuration with thousands of interfaces to a script file can take a long time, perhaps exceeding a half-hour depending on the configuration. [Defect ID 80429]
- When you attach a policy to an interface and the policy contains a classifier rule that is unsupported for that interface, the CLI generates a message and the policy is applied. However, if an existing policy is already attached to that interface, then support for the new policy is not checked and the invalid policy is applied to the interface without warning. The results of this attachment are not predictable. [Defect ID 83562]
- If you have removed the last rule in a policy list, the router generates a warning only after you exit Policy List Configuration mode. If you have removed the last policy rule and then added a classifier group before you exit Policy List Configuration mode, the router does not generate a warning about removing the last rule. [Defect ID 83834]
- When an MD-Port-Number value greater than 65,535 is sent to an E120 or E320 router by means of a CoA request, the value that is displayed in the UDP header of mirrored packets is the actual value minus 65,536. For example, an MD-Port-Number of 65,540 is displayed in the mirrored packet as 4. [Defect ID 84712]
- On the E120 and E320 routers, when a mirror rule is deleted after a CoA request is sent with Juniper-LI-Action set to No-Action, the existing mirroring session is not disabled. [Defect ID 84826]
- No logs are created if you use the **policy-list** option with the **log severity severityValue policyMgrPacketLog policy-list policyListName** command when logging policyMgrPacketLog events. [Defect ID 87203]
- When you reload the slot holding a GE-2 or GE-HDE line module and you have configured more than about 2000 policies with rate limiting on that module, the drop count becomes more than expected. This unexpected drop count does not occur when you create the same configuration after you reload the router to the factory-default configuration. [Defect ID 175696]

- On E320 line modules that support secure policies, the SRP module enables you to configure more than 1022 secure policies per module. [Defect ID 175756/180360]

Work-around: To avoid potential performance issues, we recommend that you do not configure more than 1022 secure policies per module.

- Unified in-service software upgrade (unified ISSU) is not supported on an E120 or E320 router if a hierarchical policy is attached to an external parent group. [Defect ID 177478]
- When you enter the **no ip policy-parameter hierarchical** *parameterName* command or **no ipv6 policy-parameter hierarchical** *parameterName* command for a hierarchical policy-parameter type in Interface Configuration mode, the explicit reference of the parameter is removed successfully from the interface. However, the Referenced by interfaces field in the output of the **show policy-parameter** command does not change from the previously configured value to implicit. [Defect ID 183957]

Work-around: To correct this problem, remove the entire interface configuration.

- When you modify a rate-limit profile in Global Configuration mode after the system is in a scaled state, changes to the rate-limit profile fail owing to lack of adequate policy resources. However, the changed value of the rate-limit profile is displayed in the output of the **show rate-limit profile** command. [Defect ID 184107]

PPPoE

- The E Series router erroneously accepts a PADI with a payload length of 0 instead of rejecting it and incrementing the PPPoE Invalid PAD packet length counter. [Defect ID 48356]

QoS

- You cannot paste a **load-rebalance** command string that uses the **percent** option into a console or Telnet session from **show configuration** output because the output displays the % sign rather than the **percent** keyword that was submitted with the command and the percent sign is not recognized by the CLI. [Defect ID 81705]

- The router cannot resolve inconsistent requests caused by two QoS profiles that modify the same scheduler property inconsistently. [Defect ID 61485]

Work-around: Avoid using two QoS profiles that modify the same scheduler property inconsistently, such as setting different values for the shaping rate for the same S-VLAN node.

- When you perform an SNMP walk of the `juniQosQueueStatistics` MIB, a timeout of up to 5 minutes ensues, during which the SRP module CPU utilization goes to 100 percent. [Defect ID 62252]

- The compound shared shaping feature does not work properly on egress forwarding ASIC 2 (EFA2)-based ATM line modules when the shared shaper is queue-controlled as opposed to node-controlled. In a node-controlled configuration, in which you configure the shared-shaping rate on the best-effort scheduler node for the logical interface, integration of the EFA2 and ATM segmentation and reassembly (SAR) schedulers functions properly. However, in a queue-controlled configuration, in which you configure the shared-shaping rate on the best-effort queue for the logical interface, integration of the EFA2 and ATM SAR schedulers does not function properly. [Defect ID 69167]

Work-around: Use node-controlled compound shared shaping configured on the best-effort scheduler node with EFA2-based ATM line modules.

- Egress strict-priority packets may experience high latency on OC3/STM1 ATM interfaces associated with the LM if you have shaped the port rate to more than 148.5 Mbps. [Defect ID 80378]

Work-around: To ensure low strict-priority latency, shape the port rate to no more than 148.5 Mbps.

- An error message regarding the qos-parameter instance QosParameterDefinition is erroneously generated on an ERX1440 router when it is configured for L2C and QoS RAM and receives TLV 144 (DSL Type). The parameter instantiation actually functions properly. [Defect ID 80620]
- The CLI erroneously enables you to configure a QoS profile with the **ethernet node group** command. [Defect ID 80861]
- The dynamic shaping rate calculated by the simple shared shaper can vary because of the variation in the enqueue rate of the constituent queues. Even when the offered load is constant, the mechanism that calculates the enqueue rate introduces a slight variation, introducing a slight variation in the calculated dynamic shaping rate. [Defect ID 80938]
- On a router that has both an ES2 10G LM and an ES2 4G LM installed, the byte count reported by the **show fabric-queue egress-slot** command is incorrect. The reported packet count is correct. [Defect ID 80965]
- On the E120 and E320 routers, you cannot attach QoS profiles to L2TP tunnels by means of the CLI because the CLI does not pass the router ID to QoS. [Defect ID 81516]
- PPP sessions may be dropped if you change the shaping rate in a QoS profile that affects thousands of circuits while QoS traffic affected by the profile is being forwarded. [Defect ID 82950]

Work-around: Do not change the shaping rate in a QoS profile that affects thousands of circuits while QoS traffic is using the profile.

- Egress traffic may be dropped on OC12/STM4 ATM interfaces if you have shaped the port rate to more than 542 Mbps. [Defect ID 83785]

Work-around: Do not exceed a shaped port rate of 542 Mbps.

- Incorrect output is sent to the CLI the first time you enter Global Configuration mode or issue the **show subscribers** command after viewing the VLAN subinterface over which a subscriber is connected. [Defect ID 84507]
- When QoS resources such as failure nodes and statistics bins are exhausted because of insufficient memory available on the line module, the failures are properly logged, but additional log messages are generated every 10 minutes that report zero failures. [Defect ID 85105]
- The **no qos-parameter-define definition** command does not delete the specified QoS parameter definition. [Defect ID 176844]

Work-around: Remove the interface and add the desired QoS parameters when you re-create the interface instead of deleting the definition.

- When 32,000 subscribers with 128,000 QoS queues are brought up on an ES2 10G or ES2 10G ADV LM, the LM resets if you modify the QoS profile that contains the best-effort IP or VLAN node rule, which references a scheduler profile configured with shared shaping rate, to a scheduler profile configured with legacy shaping rate. [Defect ID 183291]

Work-around: To avoid this problem, apply shared shaping on the best-effort queue, instead of on the best-effort node.

- Simple shared shaping does not function correctly when it is used for 32,000 subscribers on an ES2 10G ADV LM. However, when you change the shaper to compound shared shaping, it works properly. Also, simple shared shaping does not function correctly for 16,000 subscribers on an ES2 10G ADV LM. [Defect ID 183512]
- When you configure an E120 or E320 router with an ES2 10G ADV LM as a LAC on one side of an L2TP tunnel and as a LNS to receive packets from the LAC on the other side of the tunnel, use RADIUS servers for authentication of subscribers on both sides of the tunnel, and attempt to bring up 16,000 subscribers on the L2TP tunnel, the LM that has subscribers on the LAC side of the tunnel resets when approximately 8000 logged-in subscribers are logged out and try to reestablish the connection. [Defect ID 184118]

Service Manager

- After you activate an independent IPv6 service and issue either of the following commands on the default virtual router or any other virtual router, except the one on which the subscriber session is active, no output is displayed in the CLI interface: [Defect ID 181929]
 - **show service-management subscriber-session** *subscriberName* interface *interfaceType* *interfaceSpecifier*
 - **show service-management subscriber-session** *subscriberName* interface *interfaceType* *interfaceSpecifier* **service-session** *serviceName*

This problem also occurs when a subscriber is authenticated using a RADIUS server for a combined IPv4 and IPv6 service in a dual stack.

Work-around: To avoid this problem, use the **show service-management owner-session *ownerName ownerId*** command to display subscriber session information based on the session owner, instead of the **show service-management subscriber-session *subscriberName interfaceType*** command to display details on subscriber sessions.

SNMP

- When you configure the router with an address pool that has two IP address ranges, only the range that you configured first is available via the MIB. [Defect ID 61232]

SONET

- You cannot use the highest sensitivity bit-error rate setting (a value of 9) associated with APS/MSP alarm when you issue the **threshold sd-ber** command to configure a cOCx/STMx line module with cOC12-APS-capable IOAs. [Defect ID 72861]

Work-around: Use only a value in the range 5–8 when you issue the **threshold sd-ber** command for this module combination, as in the following example:

```
host1(config)#controller sonet 2/1
host1(config-controll)#aps group boston
host1(config-controll)#aps protect
host1(config-controller)#threshold sd-ber 6
```

SRC Software and SDX Software

- The SRC client does not prevent you from changing the name of the router while the client is connected to the SAE, resulting in SAE issues such as lost IP addresses and stale users. [Defect ID 77102]

Work-around: To change the router name while the SRC client is connected to the SAE, shut down the SRC client, change the name, then re-enable the SRC client.

- When multiple IPv6 interfaces are configured with policies attached from SRC, only some of the IPv6 interfaces have the policies attached. [Defect ID 179498]
- Changing the SSCC status (enable/disable) while IPv6 interfaces are configured might cause the SRP to reset. [Defect ID 179537]

Stateful SRP Switchover (High Availability) and IP Tunnels

- When you issue **show** commands as soon as the CLI is available after a stateful SRP switchover, the commands can hang until the warm restart is completed. [Defect ID 85306]
- A packet loss sometimes occurs during stateful SRP switchover when you use the **ping** command on a router that is configured for OSPF graceful restart, and is connected to a helper router in the OSPF IPv6 broadcast network and another helper router in the OSPF IPv6 backbone area. [Defect ID 181470]
 - ERX7xx model, ERX14xx model, or ERX310 router:

- ❑ When you use the **ping** command with the IPv6 address of the helper router in the multicast area as the destination address and the loopback address of the helper router in the backbone area as the source address, a packet loss of 2 seconds occurs for the first stateful SRP switchover. However, no packet loss occurs for successive stateful SRP switchovers.
- ❑ When you use the **ping** command with the IPv6 address of the helper router in the broadcast network as the destination address and no source address when stateful SRP switchover is performed the first time, an identical packet loss occurs. In this case too, no packet loss occurs during subsequent switchovers.
- E120 router or E320 router
 - ❑ When you use the **ping** command with the IPv6 address of the helper router in the broadcast network as the destination address and the loopback address of the helper router in the backbone area as the source address, no packet loss occurs.
 - ❑ When you use the **ping** command with the IPv6 address of the helper router in the multicast area as the destination address and no source address, a packet loss of 1–2 seconds sometimes occurs during stateful SRP switchovers.

Subscriber Management

- When a dynamic GRE tunnel interface for Mobile IP relocates between SM modules because the original SM reloads, Mobile IP deletes the relocated tunnel interface. [Defect ID 178399]
- When a subscriber has subscribed for a service, service session accounting records always contains a default Acct-Terminate-Cause value of 10. This value remains unchanged even after you use the **terminate-code** command to configure a custom mapping between application terminate reasons and RADIUS Acct-Terminate-Cause attributes. [Defect ID 181043]
- Dynamic subscriber interfaces continue to remain in the down or not present operational state in either of the following scenarios: [Defect ID 81269]
 - If you configured a dynamic interface column, such as a dynamic bridged Ethernet interface, dynamic VLAN interface, or an ATM interface, and when any one of the following conditions is satisfied:
 - ❑ The major interface is bounced (shut down and reenabled)
 - ❑ The major interface is shut down, which cause the dynamic VLAN interfaces to be removed
 - ❑ The physical link goes down and comes back up
 - ❑ The line module is removed and reinserted
 - If you configured a static interface column and removed the major interface

These scenarios might occur if you administratively issue the **shutdown** and **no shutdown** commands on the major interface in which the dynamic interface column is configured.

Work-around: Use the **no interface ip** *ipAddress* command to remove the dynamic subscriber interfaces. Although you can use the **dhcp delete-binding** command to remove the DHCP binding and the dynamic subscriber interfaces, the DHCP client does not detect the binding removal and retains the lease.

System

- You cannot use a configuration script to boot the E320 router. [Defect ID 80304]
- If you hot swap an IOA and then remove it again before that IOA's OK or FAIL LED is illuminated, the associated line module can reset. [Defect ID 177313/177267]

Work-around: Ensure that you firmly insert the IOA into the chassis when you hot swap IOAs. Do not attempt a second hot swap of an IOA that has not indicated that it completed the first hot swap cycle. You can remove the IOA when either its OK or FAIL LED is illuminated.

- If your router is in Manual Commit mode, then you must issue the **write memory** command before you perform an SRP module switch or a manual reload. You must do this even when you have made no changes to the system configuration and the file systems are synchronized. [Defect ID 44469]

System Logging

- The **show configuration category management syslog virtual-router default** command incorrectly displays logs for multiple syslog destinations when you add a log to only one syslog destination. The **show log configuration** command shows the correct configuration. [Defect ID 84082]

TCP

- The SRP module resets in any of the following circumstances on an E320 router that has a line module configured with 5000 ANCP adjacencies: [Defect ID 176916]
 - When you issue the **issu initialization** command from the console and then reload the line module from a Telnet session.
 - When the client that has the 5000 ANCP clients resets or an intermediate switch resets.
 - When you reload the line module.

Unified ISSU

- ATM line modules might reset after a unified ISSU when you attempt to add memory to a VLAN subinterface in a large bridged Ethernet configuration. [Defect ID 178798]
- Under certain conditions, a unified ISSU from JUNOS Release 9.2.0p1-0 to the current release fails, and causes the SRP module and the ES2 4G LM to reset. [Defect ID 179975]
- When any of the subsystems is excluded for a JUNOS release, a unified ISSU to that release fails to apply conversion code to all of the line modules. As a result, the line modules reset when they come up with that release. [Defect ID 179595]

Work-around: To prevent the exclusion of a subsystem file from the release, do the following before you upgrade to a new JUNOS release that supports unified ISSU:

1. Issue the **show subsystems file *fileName.rel*** command, where *fileName* is the name of the software release file, to determine whether any of the subsystem files are excluded from the release.
2. For each subsystem file that is excluded, issue the **no exclude-subsystem *subsystemName*** command to remove the exclusion for the specified subsystem file.

If you copied the software release to the router before removing the subsystem file from the exclusion list, you must copy the release to the router again to ensure that all subsystem files are included in the release.

- Unified ISSU is not supported with 8000 bridged Ethernet interfaces on an OC3/STM1 GE/FE ATM line module. [Defect ID 178809/178811/178797/179547]

Resolved Known Problems

The following problems were reported open in Release 10.3.0 and have been resolved in this release. For more information about particular resolved problems, you can log in to the JUNOS Knowledge Base at <https://www2.juniper.net/kb/>, enter the defect ID number in the Search by Keyword field, and click Search.

AAA

- The E Series router erroneously accepts two subscribers with the same IP address instead of denying access to the second subscriber. [Defect ID 176260]

ARP

- The **show arp** command does not populate the ARP entry after issuing the **clear arp interfaceSpecifier** command. [Defect ID 177685]
- ES2 4G LM reset type: panic message. Node already on free list free list ptr = 0x0238e8e4; file: statics.cc line: 413 [Defect ID 90120]
- GE line card reset type: processor exception 0x300 ; pc: 0x2a2210 - Arp::timerTick(unsigned long) [Defect ID 89849]

ATM

- After you upgrade the router from 7-0-x to 9-1-x release the ATM subinterface configuration change. [Defect ID 89456]
- After upgrading port showing “cannot get operational” status on aal5 interface (hardware not present) [Defect ID 90068]
- SRP reset type: panic; file: apterLocation.cc; line: 179; task: snmp_Data_1. [Defect ID 90202]
- After you run the **redundancy revert** command, most of the PPPoE subscribers do not come up on the line module. [Defect ID 183791]

BFD

- bfdSessPerfSessUpCount MIB counts both Up and Down states [Defect ID 89783]
- bfdSessUpTime MIB is displaying the value in Time Ticks of the ticks elapsed since the last time the bfd session came up. bfdPerfLastSessDownTime MIB is displaying the difference value in Time Ticks between the last bfdSession Up time and the last bfdSession Down time. Both these values are incorrect as per the RFC. [Defect ID 89795]

CLI

- SIT_11.0.0b0-6: SRP Crash: reset type: panic arg (0x6) file: osPool.cc line: 1290 task: IpSubscriberMana [Defect ID 184506]
- When you attempt to access the router through telnet or the CLI, the router is unavailable. However, the router responds to SNMP messages. [Defect ID 82970]
- SRP crash: reset type: exception 0x300 (data access: protection violation (write attempt))task: telC42083 [Defect ID 73380]
- After creating a secure classifier list, the CLI session stops operating when executing a **show classifier-list** command. [Defect ID 86165]
- SRP reset type: panic arg (0x30000004); file: 2tpEngineSlot.cc; task: l2tp [Defect ID 90034]
- When you use the **no t1 yellow detect** command from the CLI, yellow alarms were detected on the interface resulting in some of the interfaces going down. [Defect ID 89660]

DHCP

- DHCP server deletes binding when the release is received with different IP addresses. [Defect ID 184484]
- DhcpBasePlugIn::receivePacket() debugs displayed on line module for every DHCP packet received. [Defect ID 89934]
- SRP module reset with panic task: dhcpBackend.cc line: 2684 task: dhcpRelay_dhcpRe. [Defect ID 89754]
- SRP module reset with panic task: dhcpRelay_dhcpRe file: dhcpRelay.cc DhcpRelay::addRouteWorker. [Defect ID 89803]
- SRP reset type: processor exception 0x300 task: dhcpRelay_dhcpRe doMacAddressChange [Defect ID 90059]
- SRP reset type: panic file: dhcpRelay.cc task: dhcpRelay_dhcpRe deleteMsnvRoutesWorker [Defect ID 90095]

DHCP External Server

- DhcpExternal ServerSync Renew/rebind requests with no ack/nak clears the client bindings after 20 seconds. [Defect ID 184206]
- SRP reset type exception 0x300 task: dhcpExternal pc-DhcpExternal::clientExpireTableErase() [Defect ID 89975]

DHCP Relay

- SRP crash - reset type: panic task: dhcpRelay_dhcpRe file: dhcpRelay.cc line: 11249 [Defect ID 90123]

DoS

- DoS-protection-group configuration for IpLocalLspPing is not working as expected. [Defect ID 88877]

Ethernet

- When you remove the IP address of a LAG bundle on an ES2 10G LM or an ES2 10G ADV LM, which is configured with a Gigabit Ethernet physical interface as the member interface and assigned an IP address and subnet mask, the line module resets during the time of deletion of the IP address. This problem occurs if you enabled a VRRP instance identifier (VRID), assigned an IP address with the VRID, and configured the VRRP advertisement interval time for the LAG bundle. [Defect ID 181116]
- In the Gigabit Ethernet line modules, the CPU usage increase after upgrade to 9.1.2 due to ISSU changes. [Defect ID 89846]
- In some conditions if a PPPoE subinterface exists in the same VLAN, DSI cannot be created. [Defect ID 89824]
- Failure of PPPoE interfaces creation on LM10A. [Defect ID 89809]

Forwarding

- LM10A or LM10+ crashes when removing merge policies; file: aptationLayer.cc; line: 7515; task: scheduler. [Defect ID 185102]
- Memory Leak observed in NWT LAB when flapping DHCP and PPPoE subscribers on LM10. [Defect ID 185871]
- After every PPPoE session disconnect and reconnect, a Memory Leak was observed on the ES2 10G LM indicating that there is one luInstructions:nextHop forty byte objects that consumes the memory. [Defect ID 89816]
- Multicast admission bandwidth in adaptive mode blocking multicast streams [Defect ID 87822]
- Packets with router alert IP option configured are sent to SRP though the source addresses in the packets are not local and the associated protocol is disabled. [Defect ID 88859]
- When you configure IP policy-lists having external parent-groups on IP interfaces, and use hierarchical policing within interface groups, you may face incorrect parent-group references. [Defect ID 89850]
- The E series router sends transit packets having unordered sequence numbers through the GRE tunnel. [Defect ID 89518]
- After the LAG member link flaps VLAN subinterfaces are not created on ES2 10G LM LAG in the svlan-range in the bulk configuration. [Defect ID 89708]
- Create a mechanism to detect invalid op-code for SRAM errors and log it. [Defect ID 89878]

- Few COA-ACK packets sent from the ERX router are missing under control-plane load. [Defect ID 89788]
- Unable to send message type X to address (15a15 0) because ICC returned error code Y log message not clear. [Defect ID 89524]
- The core dump analysis on ES2 10G LM indicated that lulnstructions:nextHop seventy two byte objects consumed the memory. [Defect ID 89550]
- Recovery for single-bit and double-bit ECC errors. [Defect ID 90242]
- ES2 10G LM experiencing memory leak in KTREE on LM10. [Defect ID 90088]
- LM10 leak in 24Byte STL pool object caused by rate-limits (Hw2LuTokenBucketNhDescriptorArrayFtii) [Defect ID 90155]
- EMEA:LM10 Reset: type: exception 0x700 (program); Ir: Ktree::TwoWayBlockBase::adoptNextNode(bool, Ktree::Node * [Defect ID 90285]
- The **show ip interface** command incorrectly displayed additional packets being forwarded because the policy stats were not being initialized in the egress FC. [Defect ID 90062]

Hardware

- **show configuration** commands disappear when removing hardware. [Defect ID 89679]
- Gigabit Ethernet interface in failed state where link is down but interface is up. [Defect ID 89942]
- After a unified ISSU, the Gigabit Ethernet interface dropped a few egress packets on some ports and sometimes dropped all egress packets on one port. [Defect ID 89756]
- ES2 10G LM has 100 percent CPU due to Ethernet. [Defect ID 88089]
- After the LAG member link flaps VLAN subinterfaces are not created on LAG in the svlan-range in the bulk configuration. [Defect ID 89656]
- Running one UT3 port without a timing source may affect (FR LMI and PPP flaps) different ports on slot. [Defect ID 89748]
- Need to remove the SRAM Cell tests from the regression diags and add to POST. [Defect ID 89785]
- Memory leak on E-Series line modules in application os:ICC. [Defect ID 89747]
- The ERX router did not respond to ingress L2TP control packets during warm-restart. [Defect ID 89751]
- Implement credit based mechansim for Global recirculation SRA panic. [Defect ID 89877]

- SN for fan in show hard not updated when fan is swapped. [Defect ID 90008]
- LM10A experiencing memory leak in memory pool LuCodeBranch on LM10. [Defect ID 90249]
- LM10A experiences peak CPU Utilization of 100 % when a high priority event monopolizes the scheduler. Other applications cannot run because there are no buffers and this can result in an indefinite peak CPU Utilization of 100 % . [Defect ID 89879]

HTTP Server

- HTTP Server doesn't SYN + ACK any TCP SYN from clients when having high number of requests. [Defect ID 90152]

IGMP

- Discrepancy in SC and IC IGMP state because of excessive IGMP traffic. Need to modify IcmpMembershipEventQueue per virtual router to 32k. [Defect ID 89530/89532]
- The output of the **show ip traffic** command erroneously displays IGMP packets on ES2 10G LM, as multicast packets. [Defect ID 90041]

IP

- High CPU utilization. [Defect ID 90081]
- When you upgrade the router to 9.1.2p0-3, IP interfaces are created slowly. [Defect ID 89665]
- The output of the **show ipv6 interface** command displays incorrect IP operational speed for TenGig field. [Defect ID 89706]

IPv6

- When an IPv6 client that is connected to the requesting router using a PPP link is delegated a prefix by the DHCPv6 server, the client binding is not removed when the PPP session terminates and is retained until the lease time expires. As a result, when the same PPP client logs in again and sends a DHCPv6 SOLICIT request to the DHCPv6 server, the SOLICIT request is ignored if the prefix or the local address pool returned by the RADIUS server is different from the prefix or pool that was returned by the RADIUS server for the previous login session, and the existing binding is retained untouched. If RADIUS returns the same prefix or pool information as the previous login session, the DHCPv6 advertise message is returned to the client. This behavior is expected and occurs because the DHCPv6 server does not create a new client binding until the old binding is removed when the lease time expires. [Defect 182020]

IS-IS

- 'ldpGeneral:rsLdpTopologyDriven.cc:519:addRoute:a.b.c.d not found' severity level is incorrectly set to NOTICE [Defect ID 89882]

- The multiple ERX routers failed to invalidate the next-hop for iBGP Next-hops [Defect ID 89930]

L2TP

- L2TP over MPLS is not supported for the ES2 10G ADV LM. L2TP over MPLS is supported for the ES2 4G LM, ES2 10G Uplink LM, and ES2 10G LM in all possible module combinations. [Defect ID 85608]
- SRP reset type: panic; file: l2tpTunnel.cc; task: l2tp [Defect ID 89967]
- session-out-of-resource-result-code-override result code. [Defect ID 89825]

MPLS

- LM10 module reset with panic task: aptationLayer.cc line: 3038 task: scheduler. [Defect ID 89777]

Multicast

- Functions as designed. Reoptimization of routes with fast reroute does not happen after a failure unless you have configured a path option. [Defect ID 44317]

Netflow

- When you use the **ip fallback global** option to import a route to the destination, and then export a flow from a VRF, J-flow export does not function within VRF. [Defect ID 89623]

OSPF

- OSPF neighbor is jammed in loading state due to LSA installation failure. [Defect ID 89793]

PPPoE

- Old PPPoE subinterfaces cause subscriber connectivity problem. [Defect ID 89681]
- When you connect a PPPoE subscriber and then shutdown the interface from the CLI, PPPoE lockout is not activated on the server. Instead if you first log out the subscriber from the server using the **logout subscriber** command, PPPoE lockout is activated. [Defect ID 90044]
- When many PPPoE subscribers were attempting to reconnect on a line module, the RADIUS server experienced an outage. Some of the subscribers were unable to reconnect. Some subscribers received PADDRs but no PADS could be sent. [Defect ID 90216]
- When you change the configuration of a dynamic PPPoE subinterface, no warning message is displayed when you use the **no pppoe auto-configure** command. This results in the creation of multiple ghost PPP and IP subinterfaces. [Defect ID 90266]

Policy Management

- When an interface that the SRC software manages is removed, the static policy list continues to show references to the removed interface. [Defect ID 89239]
- When the services used inherit profile policies, deactivating one of the services, impacts the other services as well. [Defect ID 89587]

QoS

- If a scheduler profile is configured with shaping rate greater than oc3/oc12 port speed is attached at ATM port interface, then the implicit atm scheduler profile is used instead of user configured scheduler profile. [Defect ID 183595]
- 'bad if' logs reported when QoS Agent checks for L2TP client interface type [Defect ID 89711]
- Unable to display scheduler hierarchy or egress-queue rate for LM4 tunnel server ports. [Defect ID 89692]
- ES2 10G LM in slot 0 crashed - reset type: panic arg (0xda) file: templateRam.cc line: 305 [Defect ID 90093]
- QoS has a limit of 4 Gbps on tenGigabitEthernet interface for maximum rate. [Defect ID 90097]
- When you change or re-attach a qos-profile on an ATM interface, the minimum rate of the best effort traffic is displayed incorrectly to be a lower value. [Defect ID 89892]
- On E Series Routers that have not had any SRP switch or cold boot for over a year, SRP crashes because of a deadlock in QoS manager. [Defect ID 89997]

RSVP-TE

- Few RSVP LSP can be inactive after network churn. [Defect ID 89616]

Service Manager

- Large Acct-Session-Time value in Accounting-Stop with Service Manager macro are defined. [Defect ID 89728]
- Service Manager volume based service sessions do not expire. [Defect ID 89810]
- Service Manager triggers continuous PLR (protocolLayerRegistry) events resulting in peak SRP CPU utilization of 100%. Service activation for a subscriber also fails. [Defect ID 90282]

SNMP

- SNMP walk on IfTable causes SRP to stall causing watchdog reset with L2TP configuration. [Defect ID 185087]

- SNMP walk on the jniQosSvlanIdTablePortUid and jniQosSvlanIdTableSvlanId objects result in an infinite loop. [Defect ID 89357]

SRC Software and SDX Software

- Problem with re-attaching policies on SDX managed DSI interfaces after a line module reload. [Defect ID 87326]
- Slot-7 SRP reset type: processor exception 0x700 (program); task: sssClient_Data_1 [Defect ID 89863]
- Plugin initialization order causing invalid reference counts on the address mode indication of the interface. [Defect ID 89832]
- SRP Reset: exception 0x300 task: sssClient_Data_1 pc: SssClient::ReportStateMessage::append(...) [Defect ID 90043]
- SRP reset type: processor exception 0x300; task: sssClient_Data_2 [Defect ID 90218]

System Logging

- After stateful SRP switchover, the source of the syslog messages stored on the syslog server erroneously displays the IP address of the uplink interface instead of the IP address of the configured loopback interface. [Defect ID 89206]

Errata

This section identifies errors found in the JUNOSe documentation. These errors are corrected in subsequent releases of the affected documentation.

- The *Resolved Known Problems* section of the *JUNOSe 10.3.1 Release Notes*, which was bundled with the software with the published date of 2010-04-07, erroneously reported that the following defect IDs were fixed:

- 183913
- 184107
- 183512
- 184118

In fact, these defect IDs are still open. The latest version of the *JUNOSe 10.3.1 Release Notes*, available on the Web with the published date of 2010-04-26, contains an accurate classification of these defect IDs.

- The Link Layer Maximums table (for the E120 and E320 routers) in *Appendix A, System Maximums*, of the *JUNOSe Release Notes*, for the following releases incorrectly stated that the maximum number of Ethernet S-VLANs per ES2-S2 10GE PR IOA with an ES2 10G LM or ES2 10G Uplink LM was 32,768:

- Releases 10.2.0 and 10.2.1
- Release 10.3.0

The correct limit for Ethernet S-VLANs per ES2-S2 10GE PR IOA on these LMs in these releases is only 16,384. The increased scaling maximum of 32,768 Ethernet S-VLANs per ES2-S2 10GE PR IOA, in these releases, applies only to the ES2 10G ADV LM.

- The SRC Software and SDX Software section in the Subscriber Management Maximums table (for the ERX310, ERX7xx, and ERX14xx routers) in *Appendix A, System Maximums*, of the *JUNOSe Release Notes*, for the following releases incorrectly mentioned that the maximum number of SRC interfaces supported on all ERX routers was 48,000:

- Release 9.0.3
- Release 9.1.3
- Releases 9.2.2 and 9.2.3
- Releases 9.3.1 and 9.3.2
- Releases 10.0.1 and 10.0.2
- Releases 10.1.0, 10.1.1, and 10.1.2
- Releases 10.2.0 and 10.2.1

- Release 10.3.0

The correct maximum number of SRC interfaces supported on the different ERX routers is as follows:

- 16,000 interfaces on the ERX310 router
 - 32,000 interfaces on the ERX705 and ERX710 routers
 - 32,000 interfaces on the ERX1410 router
 - 48,000 interfaces on the ERX1440 router
- The General System Maximums table (for the ERX310, ERX7xx, and ERX14xx routers) in *Appendix A, System Maximums*, of the *JUNOSe Release Notes*, for the following releases incorrectly mentioned that the maximum number of SRC interfaces supported on all the ERX routers was 48,000:
 - Releases 9.0.0, 9.0.1, and 9.0.2
 - Releases 9.1.0, 9.1.1, and 9.1.2
 - Releases 9.2.0 and 9.2.1
 - Release 9.3.0
 - Release 10.0.0

The correct maximum number of SRC interfaces supported on the different ERX routers is as follows:

- 16,000 interfaces on the ERX310 router
 - 32,000 interfaces on the ERX705 and ERX710 routers
 - 32,000 interfaces on the ERX1410 router
 - 48,000 interfaces on the ERX1440 router
- The *ERX Module Guide* fails to include a *Module Name Cross-Reference Information* appendix. See *Appendix B, Module Name Cross-Reference Information*, in these Release Notes for a single table that lists the module label name, software display name, and the model number for each module for ERX routers.
 - In *JUNOSe System Basics Configuration Guide, Chapter 4, Configuring SNMP*, the *Monitoring Interface Tables* section contains a topic whose heading is incorrect. Although the heading is *show snmp group*, the information described in the topic relates to the **show snmp interfaces** command.

The correct heading for that section is *show snmp interfaces*. The field descriptions and usage guidelines for the **show snmp group** command are available in a separate section in the *Viewing SNMP Status* section of the same chapter.

- The *Monitoring Suspicious Control Flow* section in *JUNOS System Basics Configuration Guide, Chapter 7, Passwords and Security*, incorrectly contains a section titled *show snmp interfaces*. The section discusses commands to monitor suspicious control flows; the **show snmp interfaces** command is used to view SNMP status.

The **show snmp interfaces** command is described in detail in the *Monitoring Interface Tables* section in *Chapter 4, Configuring SNMP*. However, the heading of the topic in that section incorrectly reads *show snmp group*; the description is about the usage of the **show snmp interfaces** command.

- The *ICR Overview* section in *JUNOS 10.3.x Service Availability Configuration Guide, Chapter 6, Managing Interchassis Redundancy*, does not accurately describe how the ICR master partition functions. The following paragraph accurately describes how the ICR master partition functions:

The subscriber broadcasts a PPPoE Active Discovery Initiation (PADI) packet to both the master and backup router. Only the master router processes the packet and creates the subscriber session. When the master router fails, VRRP switchover occurs and the backup router becomes the new master router. PPPoE data that now shows up on the new master is dropped because a session was not created for the subscriber on the new master. Eventually, the PPP session on the client expires and the client session is re-created with the new master.

- The *ICR Overview* section in *JUNOS 10.3.x Service Availability Configuration Guide, Chapter 6, Managing Interchassis Redundancy*, does not accurately define an ICR partition. The following sentence accurately defines the ICR partition:

An ICR partition is a set of S-VLANs (and CVLANs) associated with a unique VRRP instance.

- The note in the *ICR Overview* section in *JUNOS 10.3.x Service Availability Configuration Guide, Chapter 6, Managing Interchassis Redundancy* does not accurately describe what service providers must do to enable subscriber traffic to reach all interfaces. The following note accurately describes what to do:



NOTE: While deploying ICR, service providers must ensure that the aggregation layer between the E Series router and access node (DSLAM) provides a broadcast domain per VLAN or per S-VLAN between active and backup routers. In the case of a direct connect model the access node must provide the broadcast domain per VLAN or per S-VLAN between the active and backup routers or instead provide an Ethernet switch such as EX Series Ethernet Switch between the access node and E Series router.

- The *ICR Scaling Considerations* section in *JUNOS 10.3.x Service Availability Configuration Guide, Chapter 6, Managing Interchassis Redundancy* incorrectly states that ICR supports 1:3 or 1:N subscriber redundancy.

ICR supports 1:1 subscriber redundancy only.

- The *Example: Configuring ICR Partitions That Group Subscribers by S-VLAN ID* section in *JUNOSe 10.3.x Service Availability Configuration Guide, Chapter 6, Managing Interchassis Redundancy* incorrectly uses the **control-subinterface** keyword in Step 4 of the procedures that describe how a master and backup ICR partition can be configured. The correct keyword is **control-interface**, which controls traffic on the range of subinterfaces of the master and backup partitions. The following example of the command used to control traffic on subinterface ranges of the master and backup partitions is correct:

```
host1 (config-if)#ip vrrp 1 icr-partition svlan-range 100 110 control-interface
```

- In *JUNOSe Service Availability Configuration Guide, Chapter 4, Configuring a Unified In-Service Software Upgrade*, the DHCP Relay Server row in the Application Support for Unified In-Service Software Upgrades table is incorrectly marked as unsupported for the unified ISSU operation. DHCP relay has supported unified ISSU since JUNOSe Release 9.2.0.
- The *DHCP Affected Behaviors* section in *JUNOSe Service Availability Configuration Guide, Chapter 4, Configuring a Unified In-Service Software Upgrade*, incorrectly contains the *DHCP Relay and DHCP Relay Proxy Prevent Unified ISSU* section, which indicates that the DHCP relay and DHCP relay proxy applications do not support unified ISSU.

Both the DHCP relay and relay proxy applications began supporting unified ISSU in JUNOSe Release 9.2.0. Therefore, you need not unconfigure these applications from all virtual routers to perform a unified ISSU operation for JUNOSe Release 9.2.0 and higher-numbered releases. DHCP relay proxy continues processing of DHCP release requests during the unified ISSU to maintain server-client synchronization.

- The note in the **timeout** command section in *JUNOSe Broadband Access Configuration Guide, Chapter 1, Configuring Remote Access* fails to mention that the router uses the backoff algorithm only for subscriber AAA accounting messages except Acct-On messages.
- In the JUNOSe documentation for Release 9.3.x, 10.x.x, and 11.0.x, the descriptions about support for DSL line rate information retrieval from access nodes for transmission to the SRC software, and the **sscc update-policy-request enable** command introduced by this feature are erroneously omitted. This feature was introduced in JUNOSe Release 9.3.0.

The information on this functionality and associated command is missing from the following guides in the JUNOSe documentation set:

- *JUNOSe Broadband Access Configuration Guide—Configuring the SRC Client* section in *Chapter 1, Configuring Remote Access*, and *Monitoring SRC Client Connection Status* section in *Chapter 2, Monitoring and Troubleshooting Remote Access*
- *JUNOSe Command Reference Guide N to Z*

See *Appendix C, Transferring DSL Line Rate Information from an Access Node to SRC Software*, in these *Release Notes* for detailed information.

- The syntax of the **show icr-partitions** command in the *JUNOS Command Reference Guide N to Z* incorrectly states the following:

```
show icr-partitions [ brief ] [ filter ]
```

The correct syntax for this command is as follows:

```
show icr-partitions [ backup | dormant | master | summary ] [ filter ]
```

where:

- **backup**—Displays the total number of backup ICR partitions configured on the router
 - **dormant**—Displays the total number of dormant ICR partitions configured on the router
 - **master**—Displays the total number of master ICR partitions configured on the router
 - **summary**—Displays a summary of all ICR partitions configured on the router
 - **filter**—Displays a filtered output using a combination of | (the UNIX pipe symbol), defined keywords, and a text string or regular expression
- The tables in the *Interface Types and Specifiers* section of *Chapter 1, Command Reference Topics*, in the *JUNOS Command Reference Guide* erroneously state that the maximum number of PPPoE subinterfaces per Ethernet (GE/FE) line module is 4094. The correct number for an ERX router is 8000 and for an E120 or E320 router, it is 16,000.

Appendix A

System Maximums

This appendix presents current system maximums for various E Series hardware configurations. An E Series router does not simultaneously support all maximum configurations.

For some entries, early field trial (EFT) values are presented in addition to supported values. These values have not been fully qualified by Juniper Networks and are mentioned only for field test purposes in this release. EFT values are enclosed within parentheses with an EFT designation; for example, (96,000 EFT).

Modules referred to in the tables are identified by their physical label. For module specifications, including their identifying labels, see *ERX Module Guide, Table 1, Module Combinations* and *E120 and E320 Module Guide, Table 1, Modules and IOAs*.

System Maximums for ERX310, ERX7xx, and ERX14xx	Section
General router values	General System Maximums on page 66
Physical layer values	Physical and Logical Density Maximums on page 67
Link layer values	Link Layer Maximums on page 70
Routing protocol and performance values	Routing Protocol Maximums on page 75
Policy and QoS values	Policy and QoS Maximums on page 79
Tunneling values	Tunneling Maximums on page 82
Subscriber management values	Subscriber Management Maximums on page 84

System Maximums for E120 and E320 Routers	Section
General router values	General System Maximums on page 87
Physical layer values	Physical and Logical Density Maximums on page 88
Link layer values	Link Layer Maximums on page 90
Routing protocol and performance values	Routing Protocol Maximums on page 96
Policy and QoS values	Policy and QoS Maximums on page 99
Tunneling values	Tunneling Maximums on page 103
Subscriber management values	Subscriber Management Maximums on page 105

ERX310, ERX7xx, and ERX14xx System Maximums

The following tables provide system maximums for the ERX310, ERX7xx, and ERX14xx routers.

General System Maximums

Table 1 lists some general system maximums for the ERX routers.

Table 1: General System Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Fabric size	10 Gbps	5 or 10 Gbps	10 Gbps	40 Gbps
Chassis per 7-foot rack	14	6	3	3
NTP clients	1000	1000	1000	1000
NTP servers	300	300	300	300
Sessions per chassis (simultaneous Telnet + FTP + SSH, in any combination)	30	30	30	30
Virtual routers per chassis	1000	1000	1000	1000
Virtual routers per line module ASIC	1000	1000	1000	1000
ICR Partitions per chassis	640	640	640	640
ICR Partitions per line module	64	64	64	64

Physical and Logical Density Maximums

Table 2 lists physical and logical density maximums for the ERX routers. The following notes are referred to in Table 2:

1. *Wire rate* indicates the port density that supports maximum (wire-rate) performance. *Oversubscribed* indicates the port density possible when you are willing to accept less than wire-rate performance by oversubscribing the available fabric bandwidth. The ERX310 and ERX1440 routers do not support oversubscription; port densities for these models indicate wire-rate performance.
2. When you pair the GE-2 or GE-HDE line module with the GE-2 SFP I/O module on the ERX1440 router, you can terminate up to 24 Gigabit Ethernet interfaces. Slots 2 and 4 on the ERX1440 router support two Gigabit Ethernet interfaces at wire rate; the remaining 10 slots support one Gigabit Ethernet interface at wire rate. On the ERX310 router, all four ports (active and redundant) are at wire rate.

For more information about bandwidth and line-rate considerations for the GE-2 line module or the GE-HDE line module and their corresponding I/O modules on E Series routers, see *JUNOSe Physical Layer Configuration Guide, Chapter 5, Configuring Ethernet Interfaces*.

3. When you pair the GE-HDE line module with the GE-8 I/O module on the ERX1440 router, you can terminate up to 96 Gigabit Ethernet interfaces. Slots 2 and 4 on the ERX1440 router support two Gigabit Ethernet interfaces at wire rate; the remaining 10 slots support one Gigabit Ethernet interface at wire rate. On the ERX310 router, only two Gigabit Ethernet interfaces per slot are at wire rate; therefore, only four Gigabit Ethernet interfaces are at wire rate for the entire router.

For more information about bandwidth and line-rate considerations for the GE-HDE line module and the GE-8 I/O module on E Series routers, see *JUNOSe Physical Layer Configuration Guide, Chapter 5, Configuring Ethernet Interfaces*.

4. The OC3/STM-1 GE/FE line module and OC3-2 GE APS I/O module combination does not support line rate for Gigabit Ethernet interfaces.

Table 2: Physical and Logical Density Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Physical density wire rate/oversubscribed				
(See Note 1 on page 67.)				
Channelized OC3 ports per chassis (cOC3 STM1 FO I/O modules)	8	16/20	32/48	48
Channelized OC12 ports per chassis (cOC12 STM4 FO I/O modules)	2	4/5	4/12	12
Channelized T3 ports per chassis (CT3/T3 12 I/O modules)	24	48/60	96/144	144
E3 (unchannelized) ports per chassis (CT3/T3 12 I/O modules)	24	48/60	96/144	144

Table 2: Physical and Logical Density Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Fast Ethernet (10/100) ports per chassis (FE-8 I/O and FE-8 SFP I/O modules)	16	32/40	32/96	96
Gigabit Ethernet ports per chassis (GE I/O modules)	2	4/5	4/12	12
Gigabit Ethernet ports per chassis (GE-2 SFP I/O modules) (See Note 2 on page 67.)	4	–	–	14/24
Gigabit Ethernet ports per chassis (GE-8 I/O modules) (See Note 3 on page 67.)	4/16	–	–	14/96
Gigabit Ethernet ports per chassis (OC3-2 GE APS I/O module) (See Note 4 on page 67.)	2	4/5	4/12	12
OC3/STM-1 ATM ports per chassis (OC3-4 I/O modules)	8	16/20	32/48	48
OC3/STM-1 ATM ports per chassis (OC3-2 GE APS I/O module)	4	10	24	24
OC3/STM-1 POS ports per chassis (OC3-4 I/O modules)	8	16/20	16/48	48
OC12/STM-4 ATM ports per chassis (OC12 STM4 I/O modules)	2	4/5	8/12	12
OC12/STM-4 POS ports per chassis (OC12 STM4 I/O modules)	2	4/5	4/12	12
OC48/STM16 POS ports per chassis (OC48 FRAME I/O modules); ERX1440 router only	–	–	–	2
T3 (unchannelized) ports per chassis (4xDS3 ATM I/O modules)	8	16/20	32/48	48
T3 (unchannelized) ports per chassis (CT3/T3 12 I/O modules)	24	48/60	96/144	144
Logical density per chassis				
Logical E1s per chassis	504	1260	3024	3024
Logical E3s per chassis	24	60	144	144
Logical fractional E1s (DS0) per chassis	4000	10,000	24,000	24,000
Logical fractional T1s (DS0) per chassis	4000	10,000	24,000	24,000
Logical OC3/STM1 per chassis	8	20	48	48
Logical OC12/STM4 per chassis	2	5	12	12
Logical OC48/STM16 per chassis (ERX1440 router only)	–	–	–	2
Logical T1s per chassis	672	1680	4032	4032
Logical T3s per chassis	24	60	144	144

Table 2: Physical and Logical Density Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Logical density per module combination (specified line module and all supported I/O modules)				
Logical E1s per cOCx/STMx F0 line module	252	252	252	252
	63 per OC3/STM1	63 per OC3/STM1	63 per OC3/STM1	63 per OC3/STM1
Logical E3s per COCX-F3 line module	12	12	12	12
Logical fractional E1s (DS0) per cOCx/STMx F0 line module	2000	2000	2000	2000
	500 per OC3/STM1	500 per OC3/STM1	500 per OC3/STM1	500 per OC3/STM1
Logical fractional T1s (DS0) per cOCx/STMx F0 line module	2000	2000	2000	2000
	500 per OC3/STM1	500 per OC3/STM1	500 per OC3/STM1	500 per OC3/STM1
Logical fractional T1s (DS0) per CT3/T3-F0 line module	1992	1992	1992	1992
	166 per T3	166 per T3	166 per T3	166 per T3
Logical fractional T3s (DS3) per COCX-F3 line module	12	12	12	12
Logical T1s per cOCx/STMx F0 line module	336	336	336	336
	84 per OC3/STM1	84 per OC3/STM1	84 per OC3/STM1	84 per OC3/STM1
Logical T1s per CT3/T3-F0 line module	336	336	336	336
	28 per T3	28 per T3	28 per T3	28 per T3
Logical T3s per COCX-F3 line module	12	12	12	12
Logical T3s per cOCx/STMx F0 line module	12	12	12	12
	3 per OC3/STM1	3 per OC3/STM1	3 per OC3/STM1	3 per OC3/STM1
Logical T3s per CT3/T3-F0	12	12	12	12
Logical T3s per OCx/STMx/DS3-ATM line module with 4xDS3 ATM I/O module	4	4	4	4

Link Layer Maximums

Table 3 lists link layer maximums for the ERX routers. The following notes are referred to in Table 3:

1. The ERX1440 router supports a maximum of 48,000 interface columns of all types combined. You can use either all dynamic interfaces or a combination of dynamic and static interfaces to achieve this maximum. For bridged Ethernet, IP network, and PPP interfaces, the ERX1440 router supports a maximum of 32,000 static major interfaces. Although the ERX1440 router supports a maximum of 48,000 static major interfaces for PPPoE, the PPPoE static limit is enforced at the subinterface level, which has a limit of 32,000.

The ERX705, ERX710, and ERX1410 routers support a maximum of 32,000 interfaces of all types combined; the ERX310 router supports a maximum of 16,000 interfaces of all types combined. For these routers, the interfaces can be any combination of dynamic or static.

The JUNOSe Software supports up to 10,000 PPP interfaces with EAP authentication negotiation configured. Performance and scalability is unchanged when EAP is not configured.

2. The total maximum number of Ethernet subinterfaces that can be active at any one time on an ERX310 router, an ERX7xx router, or an ERX14xx router is limited by the number of slots per chassis. Of this total, you can configure all single-tagged VLAN subinterfaces, all double-tagged S-VLAN subinterfaces, or a combination of both VLAN subinterfaces and S-VLAN subinterfaces to achieve this maximum.

Table 3: Link Layer Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
ARP entries per line module				
Dynamic ARP entries	32,768	32,768	32,768	32,768
Static ARP entries	32,768	32,768	32,768	32,768
Total ARP entries	32,768	32,768	32,768	32,768
ATM bulk configuration VC ranges per chassis				
	300	300	300	300
ATM bulk configuration VC ranges per line module				
	300	300	300	300
ATM bulk configuration total VCs per chassis				
	64,000	160,000	384,000	384,000
ATM bulk configuration total VCs per line module				
OCx/STMx/DS3-ATM	32,000	32,000	32,000	32,000
OC3/STM1 GE/FE	32,000	32,000	32,000	32,000

Table 3: Link Layer Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
ATM bulk configuration overriding profile assignments per chassis	100	100	100	100
ATM VCs per chassis (active/configured)	16,000/32,000	32,000/64,000	32,000/64,000	48,000/96,000
ATM VCs per line module				
OCx/STMx/DS3-ATM (active/configured)	8000/16,000	8000/16,000	8000/16,000	8000/16,000
OC3/STM1 GE/FE (active/configured)	8000/16,000	8000/16,000	8000/16,000	8000/16,000
ATM VCs per port				
OCx/STMx/DS3-ATM (active/configured)	8000/16,000	8000/16,000	8000/16,000	8000/16,000
OC3/STM1 GE/FE (active/configured)	8000/16,000	8000/16,000	8000/16,000	8000/16,000
ATM VC classes per chassis	100	100	100	100
ATM VP/VC addresses per line module				
OCx/STMx/DS3-ATM	20-bit	20-bit	20-bit	20-bit
OC3/STM1 GE/FE	20-bit	20-bit	20-bit	20-bit
ATM VP tunnels per port, all supported modules	256	256	256	256
Bridged Ethernet interfaces per chassis (See Note 1 on page 70.)	16,000	32,000	32,000	48,000
Bridged Ethernet interfaces per line module				
OCx/STMx/DS3-ATM	8192	8192	8192	8192
OC3/STM-1 GE/FE	8192	8192	8192	8192
Dynamic interfaces				
Active autosensed dynamic interface columns per chassis over static or dynamic (bulk) ATM1483 subinterfaces	16,000	32,000	32,000	48,000
Ethernet 802.3ad Link Aggregation				
Links per LAG (bundle)	8	8	8	8
LAGs (bundles) per chassis	64	64	64	64
Ethernet S-VLANs per chassis (See Note 2 on page 70.)	32,768	81,920	96,000	96,000

Table 3: Link Layer Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Ethernet S-VLANs per I/O module				
FE-8 I/O and FE-8 SFP I/O	16,384	16,384	16,384	16,384
GE I/O	16,384	16,384	16,384	16,384
GE-2 SFP I/O	16,384	–	–	16,384
GE-8 I/O	16,384	–	–	16,384
OC3-2 GE APS I/O	16,384	16,384	16,384	16,384
Ethernet VLANs per chassis				
(See Note 2 on page 70.)	32,768	81,920	96,000	96,000
Ethernet VLANs per I/O module (no more than 4096 VLANs per port)				
FE-8 I/O and FE-8 SFP I/O	8192	8192	8192	8192
GE I/O	4096	4096	4096	4096
GE-2 SFP I/O	8192	–	–	8192
GE-8 I/O	16,384	–	–	16,384
OC3-2 GE APS I/O	4096	4096	4096	4096
Ethernet VLAN bulk configuration VLAN ranges per chassis				
	300	300	300	300
Ethernet VLAN bulk configuration VLAN ranges per line module				
	300	300	300	300
Ethernet VLAN overriding profile assignments per chassis				
	200	200	200	200
Ethernet VRRP VRIDs per line module ASIC				
	800	800	800	800
Frame Relay virtual circuits per chassis				
	2000	5000	12,000	12,000
Frame Relay virtual circuits per line module				
COCX-F3	1000	1000	1000	1000
cOCx/STMx F0	1000	1000	1000	1000
OC48 (ERX1440 router only)	–	–	–	1000
Frame Relay virtual circuits per port				
COCX-F3	1000	1000	1000	1000
cOCx/STMx F0	1000	1000	1000	1000
OC48 (ERX1440 router only)	–	–	–	1000

Table 3: Link Layer Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
HDLC interfaces per chassis	4000	10,000	24,000	24,000
HDLC interfaces per line module				
COCX-F3	12	12	12	12
cOCx/STMx F0	2000	2000	2000	2000
CT3/T3 F0	1992	1992	1992	1992
OCx/STMx/DS-3 ATM	8000	8000	8000	8000
OCx/STMx POS	4	4	4	4
OC48 (ERX1440 router only)	–	–	–	1
MLFR bundles per chassis	5000	5000	5000	5000
MLFR bundles per line module	Bundles per line module are limited only by the availability of interface columns on the module. Because a bundle requires at least one interface column, the number of bundles cannot exceed the number of interface columns.			
MLPPP bundles per chassis	12,000	12,000	12,000	12,000
MLPPP bundles per line module	The maximum number of MLPPP bundles supported per line module is the <i>lesser</i> of the maximum number of MLPPP bundles supported per chassis or of the maximum number of interfaces supported on the line module. For more information, see the <i>JUNOS Link Layer Configuration Guide</i> .			
PPP interfaces per chassis (See Note 1 on page 70.)	16,000	32,000	32,000	48,000
PPP interfaces per line module				
COCX-F3	12	12	12	12
cOCx/STMx FO	2000	2000	2000	2000
GE/FE	8000	8000	8000	8000
GE-2	8000	–	–	8000
GE-HDE	8000	–	–	8000
OCx/STMx/DS-3 ATM	8000	8000	8000	8000
OC3/STM-1 GE/FE	8000	8000	8000	8000
OCx/STMx POS	4	4	4	4
OC48 (ERX1440 router only)	–	–	–	1

Table 3: Link Layer Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
PPP packet logging				
Aggregate dynamic and static PPP interfaces for which you can log PPP packets per chassis	32	32	32	32
PPPoE service name tables				
PPPoE service name tables per chassis	16	16	16	16
Service name tags per PPPoE service name table (including one empty service name tag)	17	17	17	17
PPPoE subinterfaces				
Subinterfaces per chassis (See Note 1 on page 70.)	16,000	32,000	32,000	48,000
Subinterfaces per GE/FE line module	8000	8000	8000	8000
Subinterfaces per GE-2 line module	8000	–	–	8000
Subinterfaces per GE-HDE line module	8000	–	–	8000
Subinterfaces per OCx/STMx/DS-3 ATM line module	8000	8000	8000	8000
Subinterfaces per OC3/STM-1 GE/FE line module	8000	8000	8000	8000
Transparent bridging and VPLS				
Bridge groups or VPLS instances per chassis	1024	1024	1024	1024
Bridge interfaces per line module in bridge groups or VPLS instances	8000	8000	8000	8000
Bridge interfaces per chassis in bridge groups or VPLS instances	16,000	32,000	32,000	32,000
Learned MAC address entries combined for all bridge groups and VPLS instances on a chassis	64,000	64,000	64,000	64,000

Routing Protocol Maximums

Table 4 lists routing protocol maximums for the ERX routers. The following notes are referred to in Table 4:

1. The total set of FTEs can be shared by interfaces, next hops, ECMP sets, VRs, and VRFs. Next-hop FTEs identify the next hop on multiaccess media, such as ATM multipoint, Ethernet, or bridged Ethernet. Each VR or VRF consumes three entries. Each interface, next hop, and ECMP set consumes a single entry. One FTE is reserved for internal use, and the system software limits the number of FTEs used by interfaces to a maximum of 32,000. The remaining FTEs can be shared across the other types.
2. The ERX1440 router supports a maximum of 48,000 interfaces of all types combined. You can use either all dynamic interfaces or a combination of dynamic and static interfaces to achieve this maximum. The ERX1440 router supports a maximum of 32,000 static PPP/PPPoE interfaces and a maximum of 36,500 static IP network interfaces. Bridged Ethernet does not enforce a limit so IP interfaces created on Bridged Ethernet can scale to the IP maximum of 36,500.

The ERX705, ERX710, and ERX1410 routers support a maximum of 32,000 IP network interfaces; the ERX310 router supports a maximum of 16,000 IP network interfaces. For all these models, the interfaces can be any combination of dynamic or static.

3. These values are subject to limitations on available SRP module memory, which varies according to your router configuration.
4. Depending on your configuration, the router may support more routing table entries or fewer routing table entries than this value. In any case, you can choose to limit the number of routes that can be added to the routing table on a per-VR or per-VRF basis by means of the **maximum routes** command.
5. The maximum number of ANCP adjacencies can be scaled over a maximum of 100 virtual routers. Fewer ANCP adjacencies can be scaled in configurations with more than 100 virtual routers.
6. This maximum is not valid for Frame Relay. The Frame Relay maximum is 1000 circuits over MPLS per line module, because only 1000 Frame Relay DLCIs are permitted per line module.
7. On the ERX1440 router, you can achieve 32,767 total Martini circuits over ATM or Ethernet interfaces. For all routers, the total Martini can be any combination of external inter-router circuits and internal circuits (local cross-connects).
8. There is no per-VR limit; all multicast routes can be on a single VR or present across multiple VRs.
9. The maximum number of interfaces can be achieved by any combination; for example, two streams each being replicated to 32,768 interfaces; 16,384 streams each being replicated four times; or any other combination.

- 10. Dynamic values represent typical limits that vary depending on configuration details and actual dynamic behavior. For dynamic values only, multiple server modules (SMs) in a chassis can improve the values as long as the multiple server modules are online and the number of virtual routers configured with NAT is greater than or equal to the number of server modules. If a server module fails, the load is redistributed to the remaining server modules, with a consequent reduction in aggregate capacity.
- 11. Static and dynamic translations occupy the same table; therefore, the number of static translation entries present in the table reduces the room for dynamic entries.

Table 4: Routing Protocol Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
BFD				
Sessions per line module	50	50	50	50
ECMP maximum paths to a destination				
BGP, IS-IS, MPLS, OSPF, RIP	16	16	16	16
IPv4 forwarding table entries (See Note 1 on page 75.)				
Chassis with only ASIC modules	1,048,576	1,048,576	1,048,576	1,048,576
IP network interfaces (IPv4 and IPv6)				
Per chassis (See Note 2 on page 75.)	16,000	32,000	32,000	48,000
Per line module ASIC	8000	8000	8000	8000
IPv4 routing protocol scaling and peering densities (See Note 3 on page 75.)				
Routing table entries (See Note 4 on page 75.)	500,000	500,000	500,000	500,000
ANCP Adjacency Scaling (See Note 5 on page 75.)	5000	5000	5000	5000
BGP-4 peering sessions	1000	1000	1000	1000
BGP-4 routes (NLRI)	1,500,000	1,500,000	1,500,000	1,500,000
IP next hops (egress FECs) on router with ASIC modules (used to represent the IP addresses of next-hop routers on Ethernet interfaces)	1,000,000	1,000,000	1,000,000	1,000,000
MPLS next hops (egress FECs) on router with ASIC modules only	500,000	500,000	500,000	500,000
MPLS forwarding entries	64,000	64,000	64,000	64,000

Table 4: Routing Protocol Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
IS-IS adjacencies	150	150	150	150
IS-IS routes	20,000	20,000	20,000	20,000
MPLS LDP LSPs	10,000	10,000	10,000	10,000
MPLS RSVP-TE LSPs	10,000	10,000	10,000	10,000
OSPF adjacencies	1000	1000	1000	1000
OSPF routes	25,000	25,000	25,000	25,000
IPv6 routing table entries (See Note 3 on page 75.)	50,000	50,000	50,000	50,000
J-Flow statistics				
J-Flow-enabled VRs and VRFs, in any combination	16	16	16	16
Sampled interfaces per VR or VRF	32	32	32	32
Total sampled Interfaces per chassis	512	512	512	512
Martini circuits for layer 2 services over MPLS				
Total Martini circuits per line module (See Note 6 on page 75.)	8000	8000	8000	8000
Total Martini circuits per chassis (See Note 7 on page 75.)	16,000	16,000	16,000	32,767
External Martini circuits per chassis	16,000	16,000	16,000	32,767
Internal Martini circuits (local cross-connects) per chassis	16,000	16,000	16,000	32,767
Mobile IP bindings per chassis	–	–	–	48,000
Multicast routes (IPv4 and IPv6)				
Forwarding entries [(S,G) pairs] per chassis (See Note 8 on page 75.)	16,384	16,384	16,384	16,384
Outgoing interfaces per chassis (See Note 9 on page 75.)	65,536	65,536	65,536	65,536
Network Address Translation (NAT)				
Static translations (simple or extended) per chassis	96,000	96,000	96,000	96,000
Dynamic simple translations (NAT) per SM (See Notes 10 and 11 on page 76.)	400,000	400,000	400,000	400,000
Dynamic extended translations (NAPT) per SM (See Notes 10 and 11 on page 76.)	200,000	200,000	200,000	200,000

Table 4: Routing Protocol Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Response Time Reporter simultaneous operations per VR	500	500	500	500
VRRP VRIDs per line module ASIC	See Ethernet VRRP VRIDs per line module ASIC on page 72.			

Policy and QoS Maximums

Table 5 lists policy and QoS maximums for the ERX routers. The following notes are referred to in Table 5:

1. The OC48 line module supports only 131,071 entries. The GE-2 and GE-HDE line modules support only 65,535 entries.
2. For line modules other than the GE-2, GE-HDE, and OC48/STM16 line modules, the router supports two sizes of policies: 8127 policies, each with a maximum of 32 classifiers, and 16,255 policies, each with a maximum of 16 classifiers. A combination of the two sizes of policies is also supported, in which case the total number of policies is between 8127 and 16,255, depending on the actual configuration.
3. The GE-2, GE-HDE, and OC48/STM16 line modules support CAM classifiers instead of hardware policy assignments. For most configurations, each classifier entry in a policy consumes one CAM entry. However, a policy that has only the default classifier consumes no CAM resources. Policies that use CAM hardware classifiers consume one interface attachment resource, regardless of the number of classifier entries in a policy.

Table 5: Policy and QoS Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
QoS queues per ASIC line module	49,000	49,000	49,000	49,000
QoS profiles configurable per chassis	1000	1000	1000	1000
QoS profile attachments per chassis	96,000	96,000	96,000	96,000
QoS profile attachments per ASIC line module	16,000	16,000	16,000	16,000
QoS shapers per line module	64,000	64,000	64,000	64,000
Classification rules per policy	512	512	512	512
Policy classification (CLACL) entries per line module (See Note 1 on page 79.)	256,000	256,000	256,000	256,000
Unique hardware policy assignments per line module for modules other than the GE-2, GE-HDE, and OC48/STM16 (See Note 2 on page 79.)	8127/16,255	8127/16,255	8127/16,255	8127/16,255

Table 5: Policy and QoS Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
CAM entries				
(See Note 3 on page 79.)				
GE-2	64,000	–	–	64,000
GE-HDE	64,000	–	–	64,000
OC48/STM16	–	–	–	128,000
Policy egress interface attachments per ASIC line module				
Combined IP and IPv6 interface attachments	8191	8191	8191	8191
Combined ATM, Frame Relay, GRE, L2TP (LNS only), MPLS, and VLAN interface attachments	8191	8191	8191	8191
Policy ingress interface attachments per ASIC line module				
Combined IP and IPv6 interface attachments on GE-2, GE-HDE, and OC-48/STM16 line modules	16,383	–	–	16,383
Combined IP and IPv6 interface attachments on all other line modules	16,000	16,000	16,000	16,000
Combined ATM, Frame Relay, GRE, L2TP (LNS only), MPLS, and VLAN interface attachments	8191	8191	8191	8191
Rate limiters				
Egress per ASIC line module	24,575	24,575	24,575	24,575
Ingress per ASIC line module	24,575	24,575	24,575	24,575
Policy statistics blocks				
Egress per ASIC line module	256,000	256,000	256,000	256,000
Ingress per ASIC line module	256,000	256,000	256,000	256,000
Parent groups per ASIC line module				
GE-2, GE-HDE, and OC3/OC12 ATM line modules (Egress and Ingress)	24,575	24,575	24,575	24,575
All other ASIC line modules (Egress and Ingress)	8191	8191	8191	8191
Software lookup blocks				
Per ASIC line module	16,383	16,383	16,383	16,383

Table 5: Policy and QoS Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Secure policies (for packet mirroring)				
Per ASIC line module	1022	1022	1022	1022
Per chassis	2400	2400	2400	2400

Tunneling Maximums

Table 6 lists tunneling maximums for the ERX routers. The following notes are referred to in Table 6:

1. The SM supports any combination of DVMRP, GRE, and L2TP tunnels up to a maximum of 8000 tunnels; however, no more than 4000 tunnels can be DVMRP or GRE tunnels in any combination. The ISM supports any combination of DVMRP, GRE, and L2TP tunnels over IPSec, up to a maximum of 5000 tunnels; however, no more than 4000 tunnels can be DVMRP or GRE tunnels.
2. You can have no more than 8000 L2TP/IPSec sessions per chassis.
3. For more information about supported L2TP sessions and tunnels, see *JUNOSe Broadband Access Configuration Guide, Chapter 11, L2TP Overview*.

Table 6: Tunneling Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
DVMRP (IP-in-IP) tunnels per chassis	4000	4000	4000	4000
DVMRP (IP-in-IP) tunnels per line module				
(See Note 1 on page 82.)				
GE-2 with shared tunnel-server ports provisioned	4000	–	–	4000
GE-HDE with shared tunnel-server ports provisioned	4000	–	–	4000
IPSec Service Module (DVMRP/IPSec tunnels)	4000	4000	4000	4000
Service Module (SM)	4000	4000	4000	4000
GRE tunnels per chassis	4000	4000	4000	4000
GRE tunnels per line module				
(See Note 1 on page 82.)				
GE-2 with shared tunnel-server ports provisioned	4000	–	–	4000
GE-HDE with shared tunnel-server ports provisioned	4000	–	–	4000
IPSec Service Module (GRE/IPSec tunnels)	4000	4000	4000	4000
Service Module (SM)	4000	4000	4000	4000
IPSec manual secure tunnels per chassis	256	256	256	256
IPSec transform sets per chassis	1000	1000	1000	1000
IPSec transforms per transform set	6	6	6	6
IPSec tunnels per chassis	10,000	10,000	10,000	20,000

Table 6: Tunneling Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
IPSec tunnels per IPSec Service Module	5000	5000	5000	5000
L2TP sessions per chassis (See Notes 2 and 3 on page 82.)	16,000	16,000	16,000	32,000
L2TP sessions per line module (See Notes 1 and 3 on page 82.)				
GE-2 with shared tunnel-server ports provisioned	8000	–	–	8000
GE-HDE with shared tunnel-server ports provisioned	8000	–	–	8000
IPSec Service Module (ISM; L2TP/IPSec sessions)	5000	5000	5000	5000
Service Module (SM)	16,000	16,000	16,000	16,000
L2TP tunnels per chassis	8000	8000	8000	8000
L2TP tunnels per line module (See Notes 1 and 3 on page 82.)				
GE-2 with shared tunnel-server ports provisioned	8000	–	–	8000
GE-HDE with shared tunnel-server ports provisioned	8000	–	–	8000
IPSec Service Module (L2TP/IPSec tunnels)	5000	5000	5000	5000
Service Module	8000	8000	8000	8000

Subscriber Management Maximums

Table 7 lists subscriber management maximums for the ERX routers. The following notes are referred to in Table 7:

1. DHCP relay proxy maintains a list of active DHCP clients up to a maximum of 100,000 clients per chassis for all virtual routers. DHCP relay does not maintain a list of DHCP clients.

DHCP relay proxy is notified of DHCP client deletions and subsequently deletes the client's host routes. In contrast, DHCP relay is not notified of DHCP client deletions, so the host routes for deleted clients remain in DHCP relay until you permanently delete them with the **set dhcp relay discard-access-routes** command. A maximum of 100,000 host routes for DHCP clients can be stored for all DHCP relay and DHCP relay proxy instances (that is, for all virtual routers).

2. The ERX1440 router supports a maximum of 48,000 interface columns of all types combined. You can use either all dynamic interfaces or a combination of dynamic and static interfaces to achieve this maximum. For bridged Ethernet, IP network, and PPP interfaces, the ERX1440 router supports a maximum of 32,000 static major interfaces. Although the ERX1440 router supports a maximum of 48,000 static major interfaces for PPPoE, the PPPoE static limit is enforced at the subinterface level, which has a limit of 32,000.

The ERX705, ERX710, and ERX1410 routers support a maximum of 32,000 interfaces of all types combined; the ERX310 router supports a maximum of 16,000 interfaces of all types combined. For these routers, the interfaces can be any combination of dynamic or static.

The JUNOSe Software supports up to 10,000 PPP interfaces with EAP authentication negotiation configured. Performance and scalability is unchanged when EAP is not configured.

3. For DHCPv6 local server, up to 32,000 subscribers and clients are supported on PPP/ATM and PPPoE/ATM with dynamic interfaces. Interface flapping tests have been qualified for 8000 subscribers and interfaces.

Table 7: Subscriber Management Maximums

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
DHCP external server clients (per chassis for all virtual routers; and per virtual router)	100,000	100,000	100,000	100,000
(See Note 1 on page 84.)				
DHCP local server				
(See Note 2 on page 84.)				
Client bindings per chassis	96,000	96,000	96,000	96,000
Client interfaces per chassis	16,000	32,000	32,000	48,000
Local address pools per virtual router	4000	4000	4000	4000
IP addresses per local address pool	32,000	32,000	32,000	32,000

Table 7: Subscriber Management Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
DHCPv6 local server				
Clients (See Note 3 on page 84.)	32,000	32,000	32,000	32,000
DHCP relay and relay proxy client (See Notes 1 and 2 on page 84.)				
DHCP client host routes for DHCP relay and DHCP relay proxy combined (per chassis for all virtual routers; and per virtual router)	100,000	100,000	100,000	100,000
DHCP relay proxy clients (per chassis for all virtual routers; and per virtual router)	100,000	100,000	100,000	100,000
Interfaces (per chassis for all virtual routers; and per virtual router)	16,000	32,000	32,000	48,000
Local authentication server				
Local user databases per chassis	100	100	100	100
Users per local user database	100	100	100	100
Users for all local user databases	100	100	100	100
RADIUS requests				
Concurrent RADIUS authentication requests	4000	4000	4000	32,000
Concurrent RADIUS accounting requests	4000	4000	4000	96,000
RADIUS route-download server downloaded routes per chassis	32,000	32,000	32,000	32,000
Service Manager				
Service definitions	2048	2048	2048	2048
Service sessions (active)	131,072	131,072	131,072	131,072
Active subscriber sessions	16,000	32,000	32,000	48,000
SRC Software and SDX Software				
COPS client instances	200	200	200	200
SRC clients	200	200	200	200
SRC interfaces	16,000	32,000	32,000	48,000

Table 7: Subscriber Management Maximums (continued)

Feature	ERX310	ERX705 and ERX710	ERX1410	ERX1440
Subscriber interfaces				
(See Note 2 on page 84.)				
Dynamic subscriber interfaces per chassis	16,000	32,000	32,000	48,000
Dynamic subscriber interfaces per line module	8000	8000	8000	8000
Static subscriber interfaces per chassis	16,000	32,000	32,000	48,000
Static subscriber interfaces per line module	8000	8000	8000	8000

E120 and E320 System Maximums

The following tables provide system maximums for the E120 router and the E320 router.

General System Maximums

Table 8 lists some general system maximums for the E120 router and the E320 router. The following notes are referred to in Table 8:

1. The maximum number applies to any combination of VRs and VRFs. The number of VRs and VRFs that you can configure depends on your configuration. You cannot achieve the maximum number if each VR and VRF instance is running a routing protocol.
2. The maximum of 3000 VRs and VRFs can be achieved only with the SRP-120 and SRP-320 modules, which have 4 GB of memory. The limits cannot be achieved with the SRP-100 module, which has 2 GB of memory.

Table 8: General System Maximums

Feature	E120	E320
Fabric size	120 Gbps	100 Gbps/320 Gbps
Chassis per 7-foot rack	6	3
NTP clients	1000	1000
NTP servers	300	300
Sessions per chassis (simultaneous Telnet + FTP + SSH, in any combination)	30	30
Virtual routers and VRFs per chassis, combined (See Notes 1 and 2 on page 87.)	3000	3000
Virtual routers and VRFs per line module, combined (See Notes 1 and 2 on page 87.)	3000	3000
ICR Partitions per chassis	640	640
ICR Partitions per line module	64	64

Physical and Logical Density Maximums

Table 9 lists physical and logical density maximums for the E120 router and the E320 router. The following notes are referred to in Table 9:

1. *Wire rate* indicates the port density that supports maximum (wire-rate) performance. *Oversubscribed* indicates the port density possible if you are willing to accept less than wire-rate performance by oversubscribing the available fabric bandwidth.
2. With a 120 Gbps configuration on the E120 router, you can install up to 6 combinations of ES2 10G Uplink LMs, ES2 10G LMs, or ES2 10G ADV LMs in slots numbered 0-5. You can install a maximum of 6 active ports and 6 redundant ports at any time.

With a 100 Gbps fabric configuration on the E320 router, you must install the ES2 10G Uplink LM, the ES2 10G LM, or the ES2 10G ADV LM in either of the E320 router turbo slots (2 and 4). When the ES2 10G Uplink LM, the ES2 10G LM, or the ES2 10G ADV LM is installed in slot 2 or slot 4, you cannot install another line module in slot 3 or slot 5. In this case, you can only install the ES2 4G LM in slots 0-1 and 6-11; therefore, the maximum number of ports and the forwarding performance per chassis is reduced for the IOAs that pair with the ES2 4G LM.

With a 320 Gbps fabric configuration on the E320 router, you can install up to 12 combinations of ES2 10G Uplink LMs, ES2 10G LMs, or ES2 10G ADV LMs in slots numbered 0-5 and 11-16. You can install a maximum of 12 active ports and 12 redundant ports at any time.

Table 9: Physical and Logical Density Maximums

Feature	E120	E320
Physical density wire rate/oversubscribed		
(See Note 1 on page 88.)		
10-Gigabit Ethernet ports per chassis (ES2-S1 10GE IOA)	6	12
10-Gigabit Ethernet ports per chassis (ES2-S2 10GE PR IOA)	6 + 6	12 + 12
(See Note 2 on page 88.)		
Gigabit Ethernet ports per chassis (ES2-S1 GE-4 IOAs)	24	48
Gigabit Ethernet ports per chassis (ES2-S1 GE-8 IOAs)	96	192
(See Note 2 on page 88.)		
Gigabit Ethernet ports per chassis (ES2-S3 GE-20 IOA)	120	240
(See Note 2 on page 88.)		
OC3/STM-1 ATM ports per chassis (ES2-S1 OC3-8 STM1 ATM IOAs)	96	192
OC12/STM-4 ATM ports per chassis (ES2-S1 OC12-2 STM4 ATM IOAs)	24	48

Table 9: Physical and Logical Density Maximums (continued)

Feature	E120	E320
OC12/STM-4 POS ports per chassis (ES2-S1 OC12-2 STM4 POS IOAs)	24	48
OC48/STM16 ports per chassis (ES2-S1 OC48 STM16 POS IOAs)	6	12
Logical density per chassis		
Logical OC3/STM1 per chassis	96	192
Logical OC12/STM4 per chassis	24	48
Logical OC48/STM16 per chassis	6	12

Link Layer Maximums

Table 10 lists link layer maximums for the E120 router and the E320 router. The following notes are referred to in Table 10:

1. On the ES2 10G LM, ES2 10G ADV LM, or ES2 10 G Uplink LM, you can have configurations with up to 100,000 static entries that support 100,000 DHCP relay proxy clients. You can have an additional 28,000 static or dynamic entries for network resources, such as RADIUS and DHCP servers. However, the total number of dynamic entries in the ARP table is still restricted to a maximum of 32,768 per line module.
2. On the E120 router, the SRP-120 and the SRP-320 support a maximum of 64,000 interfaces.

On the E320 router, the SRP-320 supports a maximum of 96,000 interfaces. The SRP-100 supports a maximum of 64,000 interfaces.

3. The E120 router supports a maximum of 64,000 interface columns of all types combined. The E320 router supports a maximum of 96,000 interface columns of all types combined. You can use all dynamic interfaces, or all static interfaces, or a combination of dynamic and static interfaces to achieve this maximum.

The JUNOSe Software supports up to 10,000 PPP interfaces with EAP authentication negotiation configured. Performance and scalability is unchanged when EAP is not configured.

4. The E120 router supports a maximum of 64,000 Ethernet subinterfaces that can be active at any one time. The E320 router supports a maximum of 96,000 Ethernet subinterfaces that can be active at any one time. Of this total, you can configure all single-tagged VLAN subinterfaces, all double-tagged S-VLAN subinterfaces, or a combination of both VLAN subinterfaces and S-VLAN subinterfaces to achieve this maximum.
5. The E120 router and the E320 router support 16,384 VLAN subinterfaces per slot on the ES2 4G LM and the ES2 10G LM, and 32,768 VLAN subinterfaces per slot on the ES2 10G ADV LM. On the E120 router, a maximum of 64,000 VLAN subinterfaces is supported per chassis. On the E320 router, a maximum of 96,000 VLAN subinterfaces is supported per chassis. You can use all dynamic interfaces, or all static interfaces, or a combination of dynamic and static interfaces to achieve this maximum.
6. For all LMs, no more than 16,384 S-VLANs are supported per port. The ES2 10G ADV LM supports 32,768 S-VLANs per module. All other LMs support only 16,384 S-VLANs per module.
7. For all LMs, no more than 4096 VLANs are supported per port. The ES2 10G ADV LM supports 32,768 VLANs per module. All other LMs support only 16,384 VLANs per module.
8. No more than 8192 VLAN major interfaces are supported per line module.

Table 10: Link Layer Maximums

Feature	E120	E320
ARP entries per line module		
Dynamic entries per LM	32,768	32,768
Static entries per ES2 4G LM	32,768	32,768
Static entries per ES2 10G LM, ES2 10G ADV LM, or ES2 10G Uplink LM (See Note 1 on page 90.)	128,000	128,000
Total entries per ES2 4G LM	32,768	32,768
Total entries per ES2 10G LM, ES2 10G ADV LM, or ES2 10G Uplink LM (See Note 1 on page 90.)	128,000	128,000
ATM bulk configuration VC ranges per chassis		
	300	1025
ATM bulk configuration VC ranges per line module		
	300	1025
ATM bulk configuration total VCs per chassis		
	192,000	384,000
ATM bulk configuration total VCs per line module		
ES2 4G LM and OCx/STMx ATM IOA	32,000	32,000
ATM bulk configuration overriding profile assignments per chassis		
	100	100
ATM VCs per chassis (See Note 2 on page 90.)		
	64,000	96,000
ATM VCs per line module		
ES2 4G LM and OCx/STMx ATM IOA	16,000	16,000
ATM VCs per port		
ES2 4G LM and OCx/STMx ATM IOA	16,000	16,000
ATM VC classes per chassis		
	100	100
ATM VP/VC addresses per line module		
ES2 4G LM and OCx/STMx ATM IOA	24-bit	24-bit
ATM VP tunnels per port, all supported modules		
	256	256

Table 10: Link Layer Maximums (continued)

Feature	E120	E320
Bridged Ethernet interfaces per chassis (See Notes 2 and 3 on page 90.)	64,000	96,000
Bridged Ethernet interfaces per line module (OCx/STMx ATM)	16,000	16,000
Dynamic interfaces		
Active autosensed dynamic interface columns per chassis over static or dynamic (bulk) ATM1483 subinterfaces (See Note 2 on page 90.)	64,000	96,000
Ethernet 802.3ad Link Aggregation		
Links per LAG (bundle)	8	8
LAGs (bundles) per chassis	64	64
Ethernet S-VLANs per chassis (See Notes 2, 4, and 5 on page 90.)	64,000	96,000
Ethernet S-VLANs per IOA (See Note 6 on page 90.)		
ES2-S1 GE-4 IOA (with ES2 4G LM)	16,384	16,384
ES2-S1 GE-8 IOA (with ES2 4G LM or ES2 10G LM)	16,384	16,384
ES2-S1 GE-8 IOA (with ES2 10G ADV LM)	32,768	32,768
ES2-S1 10GE IOA (with ES2 4G LM)	16,384	16,384
ES2-S2 10GE PR IOA (with ES2 10G LM or ES2 10G Uplink LM)	16,384	16,384
ES2-S2 10GE PR IOA (with ES2 10G ADV LM)	32,768	32,768
ES2-S3 GE-20 IOA (with ES2 10G LM)	16,384	16,384
ES2-S3 GE-20 IOA (with ES2 10G ADV LM)	32,768	32,768
Ethernet VLANs per chassis (See Notes 2, 4, and 5 on page 90.)	64,000	96,000

Table 10: Link Layer Maximums (continued)

Feature	E120	E320
Ethernet VLANs per IOA		
(See Note 7 on page 90.)		
ES2-S1 GE-4 IOA (with ES2 4G LM)	16,384	16,384
(See Note 5 on page 90.)		
ES2-S1 GE-8 IOA (with ES2 4G LM or ES2 10G LM)	16,384	16,384
(See Note 5 on page 90.)		
ES2-S1 GE-8 IOA (with ES2 10G ADV LM)	32,768	32,768
(See Note 5 on page 90.)		
ES2-S1 10GE IOA (with ES2 4G LM)	16,384	16,384
(See Note 5 on page 90.)		
ES2-S2 10GE PR IOA (with ES2 10G LM, ES2 10G ADV LM, or ES2 10G Uplink LM)	4096	4096
(See Note 5 on page 90.)		
ES2-S3 GE-20 IOA (with ES2 10G LM)	16,384	16,384
ES2-S3 GE-20 IOA (with ES2 10G ADV LM)	32,768	32,768
Ethernet VLAN major interfaces over Bridged Ethernet Interfaces, per IOA		
(See Note 8 on page 90.)		
ES2-S1 GE-4 IOA (with ES2 4G LM)	8192	8192
ES2-S1 GE-8 IOA (with ES2 4G LM, ES2 10G LM, or ES2 10G ADV LM)	8192	8192
ES2-S1 10GE IOA (with ES2 4G LM)	8192	8192
ES2-S2 10GE PR IOA (with ES2 10G LM, ES2 10G ADV LM, or ES2 10G Uplink LM)	4096	4096
ES2-S3 GE-20 IOA (with ES2 10G LM or ES2 10G ADV LM)	8192	8192
Ethernet VLAN bulk configuration VLAN ranges per chassis		
	1000	1000
Ethernet VLAN bulk configuration VLAN ranges per line module		
	500	500
Ethernet VLAN overriding profile assignments per chassis		
	200	200

Table 10: Link Layer Maximums (continued)

Feature	E120	E320
Ethernet VRRP VRIDs per line module	800	800
HDLC interfaces per chassis	24,000	24,000
HDLC interfaces per line module	8000	8000
MLPPP bundles per chassis	12,000	12,000
MLPPP bundles per line module	The maximum number of MLPPP bundles supported per line module is the <i>lesser</i> of the maximum number of MLPPP bundles supported per chassis or of the maximum number of interfaces supported on the line module. For more information, see the <i>JUNOSe Link Layer Configuration Guide</i> .	
PPP major interfaces per chassis (See Notes 2 and 3 on page 90.)	64,000	96,000
PPP major interfaces per line module (ignoring physical interface constraints)		
ES2 4G LM	16,000	16,000
ES2 10G LM	16,000	16,000
ES2 10G ADV LM	32,000	32,000
PPP subinterfaces per chassis (See Notes 2 and 3 on page 90.)	64,000	96,000
PPP subinterfaces per line module (ignoring physical interface constraints)		
ES2 4G LM	16,000	16,000
ES2 10G LM	16,000	16,000
ES2 10G ADV LM	32,000	32,000
PPP packet logging		
Aggregate dynamic and static PPP interfaces for which you can log PPP packets per chassis	32	32
PPPoE service name tables		
PPPoE service name tables per chassis	16	16
Service name tags per PPPoE service name table (including one empty service name tag)	17	17

Table 10: Link Layer Maximums (continued)

Feature	E120	E320
PPPoE subinterfaces per chassis	64,000	96,000
(See Notes 2 and 3 on page 90.)		
PPPoE subinterfaces per line module		
ES2 4G LM	16,000	16,000
ES2 10G LM	16,000	16,000
ES2 10G ADV LM	32,000	32,000
Transparent bridging and VPLS		
Bridge groups or VPLS instances per chassis	1024	1024
Bridge interfaces per line module in bridge groups or VPLS instances	8000	8000
Bridge interfaces per chassis in bridge groups or VPLS instances	32,000	32,000
Learned MAC address entries combined for all bridge groups and VPLS instances on a chassis	64,000	64,000

Routing Protocol Maximums

Table 11 lists routing protocol maximums for the E120 router and the E320 router. The following notes are referred to in Table 11:

1. The total set of FTEs can be shared by interfaces, next hops, ECMP sets, VRs, and VRFs. Next-hop FTEs identify the next hop on multiaccess media, such as ATM multipoint, Ethernet, or bridged Ethernet. Each VR or VRF consumes three entries. Each interface, next hop, and ECMP set consumes a single entry. One FTE is reserved for internal use, and the system software limits the number of FTEs used by interfaces to a maximum of 32,000. The remaining FTEs can be shared across the other types.
2. On the E120 router, the SRP-120 and the SRP-320 support a maximum of 64,000 IP network interfaces. On the E320 router, the SRP-320 supports a maximum of 96,000 IP network interfaces. The SRP-100 supports a maximum of 64,000 IP network interfaces.

You can use either all dynamic interfaces or a combination of dynamic and static interfaces to achieve this maximum.

3. These values are subject to limitations on available SRP module memory, which varies according to your router configuration.
4. Depending on your configuration, the router may support more routing table entries or fewer routing table entries than this value. In any case, you can choose to limit the number of routes that can be added to the routing table on a per-VR or per-VRF basis by means of the **maximum routes** command.
5. The maximum number of ANCP adjacencies can be scaled over a maximum of 100 virtual routers. Fewer ANCP adjacencies can be scaled in configurations with more than 100 virtual routers.
6. On the E320 router, you can achieve 32,767 total Martini circuits only over Ethernet interfaces. For all routers, the total Martini circuits can be any combination of external inter-router circuits and internal circuits (local cross-connects).
7. There is no per-VR limit; all multicast routes can be on a single VR or present across multiple VRs.
8. The maximum number of interfaces can be achieved by any combination; for example, two streams each being replicated to 32,768 interfaces; 16,384 streams each being replicated four times; or any other combination.

Table 11: Routing Protocol Maximums

Feature	E120	E320
BFD		
Sessions per line module for ES2 4G LM	100	100
Sessions per line module for all modules other than ES2 4G LM	50	50

Table 11: Routing Protocol Maximums (continued)

Feature	E120	E320
ECMP maximum paths to a destination		
BGP, IS-IS, MPLS, OSPF, RIP	16	16
IPv4 forwarding table entries per chassis (See Note 1 on page 96.)		
	1,048,576	1,048,576
IP network interfaces (IPv4 and IPv6)		
Per chassis (See Note 2 on page 96.)	64,000	96,000
Per ES2 4G LM	16,000	16,000
Per ES2 10G LM	16,000	16,000
Per ES2 10G ADV LM	32,000	32,000
Per ES2 10G Uplink LM	8000	8000
IPv4 routing protocol scaling and peering densities (See Note 3 on page 96.)		
Routing table entries (See Note 4 on page 96.)	500,000	500,000
ANCP Adjacency Scaling (See Note 5 on page 96.)	5000	5000
BGP-4 peering sessions	3000	3000
BGP-4 routes (NLRI)	1,500,000	1,500,000
IP next hops (egress FECs); used to represent the IP addresses of next-hop routers on Ethernet interfaces	1,000,000	1,000,000
MPLS next hops (egress FECs) when graceful restart is <i>not</i> enabled	500,000	500,000
MPLS next hops (egress FECs) when graceful restart is enabled	250,000	250,000
MPLS forwarding entries when graceful restart is <i>not</i> enabled	64,000	64,000
MPLS forwarding entries when graceful restart is enabled	32,000	32,000
IS-IS adjacencies	150	150
IS-IS routes	20,000	20,000
MPLS LDP LSPs when graceful restart is <i>not</i> enabled	10,000	10,000
MPLS LDP LSPs when graceful restart is enabled	5000	5000
MPLS RSVP-TE LSPs when graceful restart is <i>not</i> enabled	10,000	10,000
MPLS RSVP-TE LSPs when graceful restart is enabled	5000	5000
OSPF adjacencies	1000	1000
OSPF routes	25,000	25,000

Table 11: Routing Protocol Maximums (continued)

Feature	E120	E320
IPv6 routing table entries (See Note 3 on page 96.)	100,000	100,000
J-Flow statistics		
J-Flow-enabled VRs and VRFs, in any combination	16	16
Sampled interfaces per VR or VRF	32	32
Total sampled Interfaces per chassis	512	512
Martini circuits for layer 2 services over MPLS		
Total Martini circuits per line module	16,000	16,000
Total Martini circuits per chassis (See Note 6 on page 96.)	16,000	32,767
External Martini circuits per chassis	16,000	32,767
Internal Martini circuits (local cross-connects) per chassis	16,000	32,767
Mobile IP bindings per chassis	–	96,000
Multicast routes (IPv4 and IPv6)		
Forwarding entries [(S,G) pairs] per chassis (See Note 7 on page 96.)	16,384	16,384
Outgoing interfaces per chassis (See Note 8 on page 96.)	65,536	65,536
Response Time Reporter simultaneous operations per VR	500	500
Response Time Reporter maximum tests per chassis (SRP-100 or SRP-320)	–	500
Response Time Reporter maximum tests per virtual router (SRP-100 or SRP-320)	–	100
VRRP VRIDs per line module	See Ethernet VRRP VRIDs per line module on page 94.	See Ethernet VRRP VRIDs per line module on page 94.

Policy and QoS Maximums

Table 12 lists policy and QoS maximums for the E120 router and the E320 router. The following notes are referred to in Table 12:

1. For more information about system resource requirements for nodes, queues, and shadow nodes, see *JUNOS Quality of Service Configuration Guide, Chapter 15, QoS Profile Overview*. QoS is supported on all E Series line modules except for the ES2 10G Uplink LM.
2. For all line modules the maximum number of IP/IPv6 or VLAN policy attachments is determined by the maximum number of interfaces multiplied by the number of attachment resources that are currently used. Attachment resources are only used when you attach the policy.

The line modules support policy attachments based on the following considerations:

- IPv4—Up to 2 ingress policy attachments and 1 egress policy attachment
 - Secure policy—Up to 1 ingress policy attachment and 1 egress policy attachment (ES2 10G LM and ES2 10G ADV LM only)
 - VLANs—Up to 1 ingress policy attachment and 1 egress policy attachment
3. Secure policies are not supported on the ES2 10G Uplink LM. Secure IPv6 policies are not supported on the ES2 10G LM.

Table 12: Policy and QoS Maximums

Feature	E120	E320
QoS queues per line module (See Note 1 on page 99.)	128,000	128,000
QoS profiles configurable per chassis	1000	1000
QoS profile attachments per chassis	96,000	96,000
QoS profile attachments per line module		
ES2 4G LM	16,000	16,000
ES2 10G LM	16,000	16,000
ES2 10G ADV LM	32,000	32,000
QoS scheduler nodes per line module	64,000	64,000
QoS shapers per line module	64,000	64,000
Classification rules per policy	512	512

Table 12: Policy and QoS Maximums (continued)

Feature	E120	E320
Policy classification (CLACL) entries per line module		
ES2 4G LM	256,000	256,000
ES2 10G LM	131, 071	131, 071
ES2 10G ADV LM	131, 071	131, 071
ES2 10G Uplink LM	65,535	65,535
Policy egress interface attachments per line module (See Note 2 on page 99.)		
ES2 4G LM combined IP and IPv6 interface attachments	16,383	16,383
ES2 4G LM combined ATM, GRE, L2TP (LAC only), MPLS, and VLAN interface attachments	16,383	16,383
ES2 10G LM combined IP and IPv6 interface attachments	16,383	16,383
ES2 10G LM VLAN interface attachments	16,383	16,383
ES2 10G ADV LM IP interface attachments	32,000	32,000
ES2 10G ADV LM VLAN interface attachments	32,000	32,000
ES2 10G Uplink LM combined IP and IPv6 interface attachments	16,383	16,383
ES2 10G Uplink LM VLAN interface attachments	8191	8191
Policy ingress interface attachments per line module (See Note 2 on page 99.)		
ES2 4G LM combined IP and IPv6 interface attachments	32,767	32,767
ES2 4G LM combined ATM, GRE, L2TP (LAC only), MPLS, and VLAN interface attachments	16,383	16,383
ES2 10G LM IP interface attachments	16,383	16,383
ES2 10G LM VLAN interface attachments	16,383	16,383
ES2 10G ADV LM IP interface attachments	64,000	64,000
ES2 10G ADV LM VLAN interface attachments	32,000	32,000
ES2 10G Uplink LM IP interface attachments	16,383	16,383

Table 12: Policy and QoS Maximums (continued)

Feature	E120	E320
ES2 10G Uplink LM VLAN interface attachments	8191	8191
Rate limiters (egress) per line module		
ES2 4G LM	64,000	64,000
ES2 10G LM	64,000	64,000
ES2 10G ADV LM	64,000	64,000
ES2 10G Uplink LM	64,000	64,000
Rate limiters (ingress) per line module		
ES2 4G LM	64,000	64,000
ES2 10G LM	64,000	64,000
ES2 10G ADV LM	64,000	64,000
ES2 10G Uplink LM	64,000	64,000
Policy statistics blocks (egress) per line module		
ES2 4G LM	256,000	256,000
ES2 10G LM	256,000	256,000
ES2 10G ADV LM	512,000	512,000
ES2 10G Uplink LM	256,000	256,000
Policy statistics blocks (ingress) per line module		
ES2 4G LM	256,000	256,000
ES2 10G LM	256,000	256,000
ES2 10G ADV LM	512,000	512,000
ES2 10G Uplink LM	256,000	256,000
Parent groups (egress) per line module		
ES2 4G LM	49,151	49,151
ES2 10G LM (internal parent groups only)	8191	8191
ES2 10G ADV LM (internal parent groups only)	8191	8191
ES2 10G Uplink LM (internal parent groups only)	8191	8191

Table 12: Policy and QoS Maximums (continued)

Feature	E120	E320
Parent groups (ingress) per line module		
ES2 4G LM	49,151	49,151
ES2 10G LM (internal parent groups only)	8191	8191
ES2 10G ADV LM (internal parent groups only)	8191	8191
ES2 10G Uplink LM (internal parent groups only)	8191	8191
Software lookup blocks per line module		
ES2 4G LM	16,383	16,383
ES2 10G LM	16,383	16,383
ES2 10G ADV LM	32,000	32,000
ES2 10G Uplink LM	16,383	16,383
Secure policies (for packet mirroring)		
Per chassis	2400	2400
Per line module (See Note 3 on page 99.)	1022	1022

Tunneling Maximums

Table 13 lists tunneling maximums for the E120 router and the E320 router. The following notes are referred to in Table 13:

1. The ES2-S1 Service IOA supports any combination of DVMRP, GRE, and L2TP tunnels up to a maximum of 8000 tunnels; however, no more than 4000 tunnels can be DVMRP or GRE tunnels in any combination.
2. For more information about supported L2TP sessions and tunnels, see *JUNOS Broadband Access Configuration Guide, Chapter 11, L2TP Overview*.

Table 13: Tunneling Maximums

Feature	E120	E320
DVMRP (IP-in-IP) tunnels per chassis	4000	4000
DVMRP (IP-in-IP) tunnels per line module with shared tunnel-server ports provisioned	4000	4000
DVMRP (IP-in-IP) tunnels per ES2-S1 Service IOA (See Note 1 on page 103.)	4000	4000
GRE tunnels per chassis	4000	4000
GRE tunnels per line module with shared tunnel-server ports provisioned	4000	4000
GRE tunnels per ES2-S1 Service IOA (See Note 1 on page 103.)	4000	4000
L2TP sessions per chassis (See Note 2 on page 103.)	60,000	60,000
L2TP sessions per line module with shared tunnel-server ports provisioned (See Note 2 on page 103.)	8000	8000
L2TP sessions per ES2-S1 Service IOA (See Note 2 on page 103.)	16,000	16,000
L2TP tunnels per chassis for SRP-100	16,000	16,000
L2TP tunnels per chassis for SRP-320 with ES2 4G LM	32,000	32,000

Table 13: Tunneling Maximums (continued)

Feature	E120	E320
L2TP tunnels per line module with shared tunnel-server ports provisioned (See Note 2 on page 103.)	8000	8000
L2TP tunnels per ES2-S1 Service IOA (See Note 1 and Note 2 on page 103.)	16,000	16,000

Subscriber Management Maximums

Table 14 lists subscriber management maximums for the E120 router and the E320 router. The following notes are referred to in Table 14:

1. DHCP relay proxy maintains a list of active DHCP clients up to a maximum of 100,000 clients per chassis for all virtual routers. DHCP relay does not maintain a list of DHCP clients.

DHCP relay proxy is notified of DHCP client deletions and subsequently deletes the client's host routes. In contrast, DHCP relay is not notified of DHCP client deletions, so the host routes for deleted clients remain in DHCP relay until you permanently delete them with the **set dhcp relay discard-access-routes** command. A maximum of 100,000 host routes for DHCP clients can be stored for all DHCP relay and DHCP relay proxy instances (that is, for all virtual routers).

2. On the E120 router, the SRP-120 and the SRP-320 support a maximum of 64,000 interfaces.

On the E320 router, the SRP-320 supports a maximum of 96,000 interfaces. The SRP-100 supports a maximum of 64,000 interfaces.

3. For DHCPv6 local server, up to 32,000 subscribers and clients are supported on PPP/ATM and PPPoE/ATM with dynamic interfaces. Interface flapping tests have been qualified for 8000 subscribers and interfaces.

Table 14: Subscriber Management Maximums

Feature	E120	E320
DHCP external server clients (per chassis for all virtual routers; and per virtual router) (See Note 1 on page 105.)	100,000	100,000
DHCP local server (See Note 2 on page 105.)		
Client bindings per chassis	96,000	96,000
Client interfaces per chassis	64,000	96,000
Local address pools per virtual router	4000	4000
IP addresses per local address pool	96,000	96,000
DHCPv6 local server		
Clients (See Note 3 on page 105.)	32,000	32,000

Table 14: Subscriber Management Maximums (continued)

Feature	E120	E320
DHCP relay and relay proxy client		
(See Notes 1 and 2 on page 105.)		
DHCP client host routes for DHCP relay and DHCP relay proxy combined (per chassis for all virtual routers; and per virtual router)	100,000	100,000
DHCP relay proxy clients (per chassis for all virtual routers; and per virtual router)	100,000	100,000
Interfaces (per chassis for all virtual routers; and per virtual router)	64,000	96,000
RADIUS requests		
Concurrent RADIUS authentication requests	32,000	32,000
Concurrent RADIUS accounting requests	32,000	96,000
RADIUS route-download server downloaded routes per chassis	64,000	96,000
Service Manager		
Service definitions	2048	2048
Service sessions (active)	196,608	262,114
Active subscriber sessions	64,000	96,000
SRC Software and SDX Software		
COPS client instances	200	200
SRC clients	200	200
SRC interfaces	48,000	96,000
Subscriber interfaces		
(See Note 2 on page 105.)		
Dynamic subscriber interfaces per chassis	64,000	96,000
Dynamic subscriber interfaces per ES2 4G LM	16,000	16,000
Dynamic subscriber interfaces per ES2 10G LM	16,000	16,000
Dynamic subscriber interfaces per ES2 10G ADV LM	32,000	32,000
Static subscriber interfaces per chassis	64,000	96,000
Static subscriber interfaces per ES2 4G LM	16,000	16,000
Static subscriber interfaces per ES2 10G LM	16,000	16,000
Static subscriber interfaces per ES2 10G ADV LM	32,000	32,000

Appendix B

Module Name Cross-Reference Information

This appendix provides information on the label name, software display name, and model number of ERX modules. This information supplements the *ERX Module Guide*.

- Module Name Cross-Reference Information on page 107

Module Name Cross-Reference Information

Use Table 15 on page 107 to find the label name, software display name, and model number of a module.

Table 15: Module Naming Reference for ERX Routers

Label Name	Software Display Name	Model Number
SRP Modules		
SRP-5G +	SRP-5GPlus	ERX-5G2GEC2-SRP
SRP-10G	SRP-10G	ERX-10G2GEC2-SRP
SRP-40G PLUS	SRP-40G +	ERX-40G2GEC2-SRP
SRP-SE10G	SRP-SE10G	EX3-1GSRP-MOD
Line Modules		
CT3/T3-F0	CT3-12	CT3-12-F0
COCX-F3	UT3F-12	ERX-UT3E3OCX-MOD
cOCX/STMx F0	COC3/COC12	COCX/STMX-F0
OCx/STMx ATM	OC3/OC12-ATM	ERX-O3O12A-MOD
OCx/STMx/DS3-ATM	OC3/OC12/DS3-ATM	ERX-OCXA256M-MOD
OCx/STMx POS	OC3/OC12-POS	ERX-O3O12P-MOD
OCx/STMx POS	OC3/OC12-POS	OC3/OC12-POS
OC48	OC48-POS	ERX-OC48ST16-MOD
GE/FE	GE/FE	ERX-GEFE-MOD
GE/FE	GE/FE	ERX-GEFE256M-MOD
GE-HDE	GE-HDE-8	ERX-HDE-MOD

Table 15: Module Naming Reference for ERX Routers (continued)

Label Name	Software Display Name	Model Number
GE-HDE	GE-HDE-8	ERX-GE-MOD
OC3/STM1 GE/FE	2xOC3-ATM 1xGE I/O	ERX-OCXGE-MOD
Service Modules		
IPSEC SERVICE	IPsec	ERX-IPSECURE-MOD
SERVICE MODULE	SERVICE MODULE	ERX-SERVICE-MOD
I/O Modules		
4xDS3 ATM I/O	DS3-4P I/O	ERX-4T3ATM-IOA
CT3/T3 12 I/O	CT3/T3-12 I/O	T312-F0-F3-I/O
E3-12 FRAME I/O	UE3F-12	E3-12-F3-I/O
OC12 STM4 APS MULTI MODE	OC12-MM-2P I/O	ERX-OC12MM-A-IOA
OC12 STM4 APS SINGLE MODE	OC12-SM-2P-IR I/O	ERX-OC12SM-A-IOA
4X0C3 APS I/O MULTI MODE	OC3(8) MM I/O	ERX-OC3M-APS-IOA
4X0C3 APS I/O SINGLE MODE	OC3(8) SM-IR I/O	ERX-OC3S-APS-IOA
OC48 FRAME APS	OC48-POS I/O	ERX-OC48ST16-IOA
OC12 STM4 I/O LONG HAUL	OC12-SM I/O	OC12-LH-I/O
OC12 STM4 I/O MULTI MODE	OC12-MM I/O	OC12-MM-I/O
OC12 STM4 I/O SINGLE MODE	OC12-SM I/O	OC12-SM-I/O
OC3-4 I/O LONG HAUL	OC3-4LH I/O	OC3-4LH-I/O
OC3-4 I/O MULTI MODE	OC3-4MM I/O	OC3-4MM-I/O
OC3-4 I/O SINGLE MODE	OC3-4SM I/O	OC3-4SM-I/O
cOC12 STM4 F0 I/O MULTI MODE	COC12-MM-1P I/O	COC12F0-MM-I/O
cOC12 STM4 F0 I/O SINGLE MODE	COC12-SM I/O	COC12F0-SM-I/O
cOC12 STM4 LONG HAUL	COC12-LH I/O	ERX-COC12-LH-IOA
cOC3 STM1 F0 I/O MULTI MODE	COC3-4MM I/O	COC3F0-MM-I/O
cOC3 STM1 F0 I/O SINGLE MODE	COC3-4SM I/O	COC3F0-SM-I/O
FE-8 I/O SFP	FE-8 SFP FX I/O	ERX-8FXSFP-IOA
FE-8 I/O	FE-8 I/O	FE-8-I/O
OC3-2 GE APS I/O SFP	OC3-2A GE	ERX-2OC3GE-IOA
GE I/O SFP	GE-SFP I/O	ERX-GIGESFP-IOA
GE-2 SFP I/O	GE-2 I/O	ERX-2GE-IOA
GE-8 I/O	GE-8 I/O	ERX-8GEHDE-IOA

Appendix C

Transferring DSL Line Rate Information from an Access Node to SRC Software

This appendix describes support for collection of updated DSL line rate parameters from an access node and transfer of this information from the Common Open Policy Service (COPS) or SRC client to the COPS server with other COPS messages.

- Configuring the SRC Client to Retrieve DSL Information from Access Nodes on page 109
- Monitoring the Status of Transfer of Updated DSL Line Rate Parameters to the COPS Server on page 112
- JUNOSe Command Reference Guide Update on page 113

Configuring the SRC Client to Retrieve DSL Information from Access Nodes

Beginning with JUNOSe Release 9.3.0, you can retrieve updated DSL line rate information from the Access Node Control Protocol (ANCP) and report this information to the SRC software with corresponding COPS messages. ANCP is also known as Layer 2 Control (L2C). To enable the router that functions as the SRC client to obtain updated line rate parameters from ANCP and transmit them to the COPS server, use the **sscc update-policy-request enable** command in Global Configuration mode. You can configure this setting on a per-virtual-router basis.

In networks with digital subscriber line access multiplexers (DSLAMs), after a connection is established between a subscriber and a routing gateway, the access node or DSLAM obtains the line rate information of the subscriber using a synchronization process. The line rate parameters are transferred in the COPS interface request by using the ANCP topology discovery message to the router that functions as the network access server (NAS). Typically, a COPS interface request is sent from the access node to the SRC client whenever an interface becomes operational.

In JUNOSe Release 9.3.0 and higher-numbered releases, you can configure the SRC client to obtain the line rate details from the access node whenever any change in the values of the parameters occurs. The capability to receive line rate data, when it changes on the access node, is disabled by default on the SRC client.

The access node passes the DSL line rate parameters, whenever they change, to the SRC client. The SRC client appends updated parameters to the COPS messages that it sends to the COPS server or SRC server. A COPS server processes the following topology parameters that it receives from the SRC client in the updated COPS messages:

- junoselpInterfaceMode
- junoselpInterfaceUpstreamRate
- junoselpInterfaceDownstreamRate
- junoselpInterfaceMinimumDataRateUpstream
- junoselpInterfaceMinimumDataRateDownstream
- junoselpInterfaceAttainableDataRateUpstream
- junoselpInterfaceAttainableDataRateDownstream
- junoselpInterfaceMaximumDataRateUpstream
- junoselpInterfaceMaximumDataRateDownstream
- junoselpInterfaceMinimumLowPowerDataRateUpstream
- junoselpInterfaceMinimumLowPowerDataRateDownstream
- junoselpInterfaceMaximumInterleavingDelayUpstream
- junoselpInterfaceActualInterleavingDelayUpstream
- junoselpInterfaceMaximumInterleavingDelayDownstream
- junoselpInterfaceActualInterleavingDelayDownstream
- junoselpInterfaceDSLlinestate

A COPS server that runs an SRC software release earlier than Release 3.0.0 does not support and process the preceding topology parameters that are appended to the COPS messages. Such COPS servers analyze the information, other than the parameters that describe updated DSL line rate details, that they receive in the COPS messages for policy management. Therefore, the COPS-PR operation ensures backward compatibility of the SRC clients with the COPS servers running SRC software releases earlier than Release 3.0.0 by ignoring the received line rate details.

When you configure the **sscc update-policy-request enable** command, a warning message is displayed, prompting you to confirm whether you want to enable the router that functions as the SRC client to forcibly send updated line rate information parameters to the COPS server, which is running a release of SRC software earlier than Release 3.0.0 that is not compatible with the line rate message format.

Even if you confirm the prompt to enable the SRC client to forcibly send updated DSL line rate parameters to the COPS server, the COPS server that is running a release of SRC software earlier than Release 3.0.0 ignores the updated line rate details that it receives and processes only the other information in the COPS messages.

The Policy Information Base (PIB) is modified to extend the JunosIpInterfaceEntry object. ANCP now notifies the SRC software about any change in the ANCP parameters. If this change in rate is greater than 10 percent or a change in mode, SRC software reports this upgrade to the service activation engine (SAE) in SRC version 3.0.0 and later.

sscc update-policy-request enable

- Use to enable updated DSL line rate parameters to be collected from ANCP and transmitted to the COPS server with corresponding COPS messages.
- The SRC client gathers line rate information from the access node and transfers it to the COPS server, both during connection establishment between a subscriber and an access node, and when any of the values of the line rate parameters changes after the connection is built.
- A COPS server that is running SRC software Release 3.0.0 and earlier releases does not support the receipt of updated DSL line rate information from the SRC client. If you configure the SRC client to send updated line rate parameters to the COPS server, regardless of the version of SRC software that it is running, the COPS server ignores the received updated line rate information and processes the other COPS details. Therefore, this feature of processing of updated line rate parameters from ANCP by the SRC client is backward compatible with older versions of SRC software.
- When you enter the **sscc update-policy-request enable** command, a warning message is displayed, prompting you to confirm whether you want to enable the router that functions as the SRC client to forcibly send line rate information parameters to the COPS server, which is running a release of SRC software earlier than Release 3.0.0 that is not compatible with the line rate message format.
- Example

```
host1(config)#sscc update-policy-request enable
```
- Use the **no** version to restore the default behavior, which disables updated line rate parameters to be sent to the COPS server.

Monitoring the Status of Transfer of Updated DSL Line Rate Parameters to the COPS Server

- Purpose** Display whether the SRC client is enabled to retrieve updated DSL line rate details from ANCP and send them to the SRC client with corresponding COPS messages. The command output refers to the SRC client by its former name, SSC client.
- Action** To display the status of transfer of updated line rate parameter details from the SRC client to the COPS server.

The line highlighted in bold is the field added for this feature in the output of this command. The added line specifies whether line rate parameters are sent to the COPS server with the other COPS messages.

```

host1#show sscc info
The SSC Client configured protocols : IP(v4), DHCP(v4), L2TP(LAC)
The SSC Client is currently unconnected
The SSC Client configured servers are:
  Primary: 10.10.2.2:3
  Secondary: 0.0.0.0:0
  Tertiary: 0.0.0.0:0
  Local Source: FastEthernet 0/0, Local Source Address: 10.13.5.61
  The configured transport router is: default
  The configured retry timer is (seconds): 90
The configured update-policy-request is: Enabled
  The connection state is: NoConnection
SSC Client Statistics:
Policy Commands received      0
Policy Commands(List)         0
Policy Commands(Acct)         0
Bad Policy Cmds received      0
Error Policy Cmds received    0
Policy Reports sent           0
Connection Open requests      0
Connection Open completed     0
Connection Closed sent        0
Connection Closed remotely    0
Create Interfaces sent         0
Delete Interfaces sent         0
Active IP Interfaces           2
IP Interface Transitions      0
Synchronizes received         0
Synchronize Complete sent     0
Internal Errors                0
Communication Errors           0
Tokens Seen                    0
Active Tokens                  0
Token Transitions              0
Token Creates Sent             0
Token Deletes Sent             0
Active Addresses               0
Address Transitions            0
Create Addresses Sent          0
Delete Addresses Sent          0
Authentication Successes       0
Authentication Failures        0

```



NOTE: Only the field that has been newly added by this feature in the output of the **show sssc info** command is described here. For a complete version of the descriptions of all the other fields that are displayed in the output of this command, see *JUNOSe Broadband Access Configuration Guide, Chapter 2, Monitoring and Troubleshooting Remote Access*.

JUNOSe Command Reference Guide Update

This section supplements the *JUNOSe Command Reference Guide N to Z*. It describes the new command that enables the E Series router that functions as the SRC client to retrieve changed DSL line rate information from ANCP and report this information to the COPS server.

sscc update-policy-request enable

Description Configures the router to collect updated DSL line rate parameters from an access node using the ANCP topology discovery message and transmit the information to the COPS server with corresponding COPS messages. If you enable this feature, the access node sends line rate parameters not only during connection establishment, but also whenever any of the line rate values changes after the connection is built. The **no** version restores the default, which disables line rate parameters to be sent to the COPS server.



NOTE: When you configure the **sscc update-policy-request enable** command, a warning message is displayed, prompting you to confirm whether you want to enable the router that functions as the SRC client to forcibly send updated line rate information parameters to the COPS server, which is running a release of SRC software earlier than Release 3.0.0 that is not compatible with the line rate message format.

Syntax [no] sssc update-policy-request enable

Mode Global Configuration

Release Information Command introduced in JUNOSe Release 9.3.0.

