

Release Notes (Rev. 1.4)

Juniper Networks NetScreen-Secure Access

IVE Platform version 6.3 R1.1 Build # 13563



Juniper Networks, Inc.
1194 North Mathilda Avenue
Sunnyvale, CA 94089 USA
408 745 2000 or 888 JUNIPER
www.juniper.net

April 19, 2010

Contents

Recommended Operation.....	1
New Features in this Release	3
Upgrading to this Release.....	3
Known Issues/Limitations Fixed in this Release	5
All Secure Access Platforms.....	5
SA 2000 through SA 6500 Items	7
Known Issues and Limitations in this Release	8
All Secure Access Platforms.....	8
SA 2000 through SA 6500 Items	9
Documentation Errata	10
Archived Known Issues and Limitations	11
All Secure Access Platforms.....	11
SA 2000 through SA 6500 Items	29
Supported Platforms	43
Supported NSM releases	44

Recommended Operation

- The Debug Log troubleshooting functionality should only be enabled after consultation with Juniper Networks Support.
- The IVE has an Automatic Version Monitoring feature which notifies Juniper Networks of the software version the IVE is running and the hardware ID of the appliance via an HTTPS request from the Administrator's Web browser upon login to the Admin UI. Juniper Networks collects this data to be able to inform customers about critical security patches they may need. Administrators can enable/disable this functionality by logging into the Admin UI and going to the **Maintenance > System > Options** menu. We strongly recommend that Administrators keep this setting enabled.
- When using W-SAM, Network Connect, or Secure Meeting, we recommend that the admin allow the client to automatically select between the optimized and non-optimized NCP options. This allows clients to use optimized NCP where possible, and to fall back to non-optimized NCP where necessary. (28405)
- Multiple simultaneous sessions from a single client to the same IVE might cause unpredictable behavior and are not supported. This is primarily due to the pre-authentication mechanisms which might conflict between sessions. This caution also applies to situations where an end-user and admin session to a single host occur simultaneously.
- When using an external load balancer and accessing J-SAM, W-SAM, Network Connect, or the Online Meeting functionality, persistence must be employed on the load balancer. This persistence should be based on Source IP or Destination Source, depending on the load balancer being used.
- In order to access IVE resources as links from a non-IVE Web page, a selective rewriting rule for the IVE resources is required. For example, if you would like to include a link to the IVE logout page such as `http://<IVE server>/access/auth/logout.cgi` then you need to create a selective rewriting rule for `http://< IVE server >/*.` (26472)
- If two separate Web browser instances attempt to access different versions of the IVE, the browser may prompt the user to reboot the PC after the NeoterisSetup.cab has been downloaded. Upon closing all browsers and logging in again, the prompt will no longer be displayed. No reboot is required.
- When using the command-line W-SAM ("SAMLancher"), the URL entered must contain the prefix `https://`.
- W-SAM supports client-initiated UDP and TCP traffic by process name, by destination hostname, or by destination address range:port range. Except for Passive FTP, W-SAM only supports protocols that do not embed IP addresses in the header or payload. W-SAM also supports unicast client-initiated UDP.
- Users must launch drive maps through W-SAM in one of the following ways:
 - **NetUse**--At the Command prompt, type: `net use * \server\share /user:username`
 - Right-click on **My Computer > Map Network Drive**, or Explorer-enabled drive mapping. In Windows Explorer, go to **Tools > Map Network Drive**, then select "Connect using a different username".
- When using the W-SAM Access Control List (ACL), administrators should take extra precaution when granting access to hosts. We recommend that administrators use the IP address instead of the hostname. If the hostname is required, for security purposes, administrators should try to include

additional ACLs with the corresponding IP address or IP addresses for that hostname. Reverse DNS lookups are not supported.

- To run Citrix NFuse through W-SAM, you must define a Caching rule to cache launch.asp files. For example, configure the resource policy to “<server name>:80,443/*.launch.asp” and the Caching Option to “Cache (do not add/modify caching headers)”.
- When scripting the use of SAMLauncher.exe, users should provide the -reboot command-line flag so that if the launcher requires a reboot, it happens automatically and does not exit, prompting the user to manually reboot. Note that during a fresh install (with NetBIOS enabled), W-SAM requires a reboot.
- When using Microsoft NetMeeting with W-SAM, hosting a meeting is not supported. There are no problems joining a meeting using Windows 2000. When using Windows XP, however, application sharing does not work as expected. In order for Windows XP users to work around this sharing issue, they must first turn on the “Only you can accept incoming calls” option.
- When using WSAM on Pocket PC, Roaming for IVE sessions should be enabled when being used over GPRS because the IP address of the phone may change.
- When using WSAM on Pocket PC, if you have multiple roles defined, select the option for “Merge settings for all assigned roles” in **Administrators > Admin Realms > [Realm] > Role Mapping**.
- Do not delete the main cluster licensing node. Doing so will lose all cluster licenses.

New Features in this Release

- Please refer to the *What's New* document for details about new features available in this release.

Upgrading to this Release

- Please refer to the Supported Platforms document for important information pertaining platforms supported. Windows 98 SE and Windows NT are not supported on the 5.5 and later releases. The SA1000, SA3000 and SA5000 series platforms are not supported on the 6.1 and later releases.
- Automatic upgrades to this release from the following releases are supported (including from the Legacy Authentication mode):
 - 6.2 R2 Build 13515
 - 6.2 R1 Build 13255
 - 6.1 R4 Build 13437
 - 6.1 R3 Build 13281
 - 6.1 R2 Build 12965
 - 6.1 R1 Build 12821
 - 6.0 R7 Build 13487
 - 6.0 R6 Build 13319
 - 6.0 R5 Build 13073
 - 6.0 R4.3 Build 13075
 - 6.0 R4 Build 12733
 - 6.0 R3.2 Build 13111
 - 6.0 R3.1 Build 12507
 - 6.0 R2 Build 12141
 - 6.0 R1 Build 12023
 - 5.5 R7 Build 13237
 - 5.5 R6 Build 12857
 - 5.5 R5.1 Build 12781
 - 5.5 R4 Build 12129
 - 5.5 R3 Build 12029
 - 5.5 R2.1 Build 11965
 - 5.5 R1 Build 11711
 - 5.4 R6 Build 12025
 - 5.4 R5 Build 11871
 - 5.4 R4 Build 11743
 - 5.4 R3 Build 11621

- 5.4 R2.1 Build 11529
- 5.4 R1 Build 11359
- 5.3 R10 Build 11531
- 5.3 R8 Build 11339
- 5.3 R7 Build 11255
- 5.3 R6.1 Build 11199
- 5.3 R5.3 Build 11159
- 5.3 R4 Build 10769
- 5.3 R3.1 Build 10741
- 5.3 R2.1 Build 10641
- 5.3 R1 Build 10197
- 5.2 R7 Build 11527
- 5.2 R6.1 Build 11167
- 5.2 R5.2 Build 11161
- 5.2 R4.1 Build 10573
- 5.2 R3 Build 10171
- 5.2 R2 Build 9895
- 5.2 R1 Build 9469
- 5.1 R8.2 Build 11163
- 5.1 R8.1 Build 11095
- 5.1 R7 Build 10081
- 5.1 R6 Build 9837
- 5.1 R5 Build 9627
- 5.1 R4 Build 9403
- 5.1 R3 Build 9311
- 5.1 R2 Build 9092
- 5.0 R6 Build 9343
- 5.0 R4 Build 9085
- 5.0 R2 Build 8721
- 5.0 R1 Build 8553
- **Note:** If upgrading from a release which is not listed here, please upgrade to one of the listed releases first, and then upgrade to 6.2 R1.
- If using Beta or Early Access (EA) software, please be sure to roll back to a prior production build and then upgrade to the 6.2 R1 software. (This process enables you to roll back to a production build if ever needed.)

Known Issues/Limitations Fixed in this Release

All Secure Access Platforms

AAA

- User cannot login using ACE authentication after upgrade to 6.3R1. (387880)
- IP Address of Netegrity Siteminder Web Agent, when changed through XML Import, is not validated for correctness (58065).
- Policy trace may show an error message on the lines of “authentication successful to auth server [Unknown Auth Server]” even when authentication succeeds. This is a spurious message and can be ignored (57367).
- Custom Sign-In pages uploaded through XML Import may not work, and IVE may present standard signin page instead of the custom page (57984).
- XML Import of a Realm with the option “When editing, start on Role Mapping page” set to OFF, imports the state of the option incorrectly as set to ON (57244).
- XML Import of a configuration enabling Siteminder Auto Sign In without specifying an Auth Realm succeeds, whereas it should not (58063).
- Some extra configuration options appear in the XML exported configuration of Password Restrictoins for User Realms. These are Primary Password Expiration Warning Days, Secondary Password Expiration Warning Days and Enable Secondary Password Management. Import of such a configuration file works fine. The extra options can be ignored (57992).
- Factory Reset creates System Local configuration with very low password change and warning intervals (58101).
- XML Import/Export of device certificates and code-signing certificates is not supported.
- When CRL download frequency is set to a value higher than 166, XML Import/Export and PushConfig operations fail (57608).
- XML export of SAML SSO Policies does not export Detailed Rules attribute information (57290).
- Novell eDir: Starting with this release, a password policy that allows all grace logins to be consumed by the user is not enforced. The user will always have two grace logins left. This change is made so that users are not confronted with a situation where they login only to discover that they cannot change their password.
- On upgrading from 5.X releases to this release, the name of the Siteminder Auth Server becomes uneditable (51314).
- On XML Import of OCSP responder configuration, IVE displays empty tabs (57609).
- If a realm is XML-edited to change its auth server to point to another server that is of a different type than the one configured on the device (example: LDAP in XML file but Radius on the device), then the import of the XML file may fail. The failure happens if the realm has role-mapping rules containing attributes that are available on the old server but are not applicable on the new server. (57369).
- If the role-mapping rules are exported from an SA device via XML Export and new role-mapping rules are introduced in the exported XML document, then the order of the rules in the XML document is not preserved when this document is later imported into the SA device. The newly introduced rules are added to the bottom on the existing list of role-mapping rules on the target device (58044).

- Under role->UI options when we clear the Background color in Header section, Background color in the sub header section or font color in the sub header section xml export sets all three values to #000000, even though the UI displays default values for the sub header background color and the text color. (58136)
- Safari crashes when an authentication proxy is configured on the client browser. This happens on Mac OS 10.
- The IVE allows XML Import of a new SiteMinder auth server for which Backup Server is not specified, but Failover Mode is set to "Yes" in the imported XML document. As a result of the XML Import operation, the SiteMinder auth server gets created, but if the administrator opens the auth server configuration and clicks on "Save Changes", the following error is seen : "To enable Failover Mode, a Backup Server must be specified". (58436)
- The idle timeout value for the SiteMinder auth server does not get imported correctly via the XML Import operation. The values are transformed incorrectly by the XML Import operation to one-sixtieth the intended value (ie "1" gets imported as 0.0166.."). Moreover, if the administrator clicks on the Save changes button, the following error is seen :

Error AD-86

Invalid Policy Server Idle Timeout.

To workaroud this issue, the administrator needs to configure the correct value for the idle timeout via the admin UI. (58422)

- It is possible to enable the "Automatic Sign-in" checkbox for the SiteMinder auth server via XML Import, even if the auth server is not mapped to any realm. The XML Import goes through successfully, but if the administrator browses to the SiteMinder auth server page in the admin UI and clicks on "Save Changes", the following error is seen :

Error AD-79

Invalid Auto-Logon Realm.

To work around this issue, the administrator is advised to uncheck the "Automatic Sign-in" capability or to map the auth server to a valid realm following the XML Import. (58394)

- Via XML Import, it is possible to create LDAP auth servers by specifying just the auth server name and IP address, but without specifying the port number. Subsequently, when the administrator browses to the LDAP auth server configuration page in the admin UI, error messages are displayed. (58392)
- Through XML Import, it is possible to configure limits restrictions in User Realms such that the sum of the guaranteed minima across the realms exceeds the user license limit. However, when users log in to the system, the correct license checks are enforced. (58000)
- If as part of XML Import, the "Roaming Value", under delegated admin session-options is set to limit-to-subnet, the corresponding netmask value gets set to 0.0.0.0 on the IVE.(57017)
- The administrator is advised against creating a '.Administrators' role in an XML instance document and performing an XML Import of this document into the IVE. Doing so will overwrite the .Administrators settings on the IVE with the settings in the XML document, resulting in unintended modifications to the delegation permissions or other settings associated with the .Administrators role. (58478)
- The "Users", "Meeting" and "Authorization Only Access" Sign-In URL names should be unique. The administrator should not create the same Sign-In URL name with different cases for them in the XML document. (57727)

File Browsing

- After creating a share on Vista or Longhorn, user can not access it through the IVE. (56066)
- When “Prompt for user credentials” is set for windows file share access, instead of prompting for the credentials, SSO is attempted with the last-used credentials. Sometimes this causes AD account lockout. (50001)

Network Connect

- When automatic or manual proxy is set for a NC resource profile XML import mandates having a server address specified. (58432)
- When “Custom DNS settings” is set for a NC resource profile XML import mandates having a primary DNS server specified. (58432)

Maintenance

- The SSL Acceleration checkbox which is available in the IVE admin UI panel System > Maintenance > Options is not available through XML import/export. (56924)
- XML Import may fail if all the configurations (System, User, and IVS) on the target device are removed before the operation. (57651)
- XML Import may fail if all the licenses on the target device are removed before the operation. (57654)

Management Port (SA 6000 and SA 6000-SP only)

- When Management Port setting is done for the first time, the link speed/duplex options are not displayed correctly in the admin UI. The dropdown only shows "AUTO" (48226)

SA 2000 through SA 6500 Items

Secure Meeting

- XML Export and Import retains the Configuration-> Secure Meeting-> upload logs option when it is set to enable. (58116)

Known Issues and Limitations in this Release

All Secure Access Platforms

AAA

- NSM client does not validate the fields Under Configuration->System->Maintenance->External User Records Management. However, import into the device fails if device side validation fails (58882).
- The NSM client does not validate that Guaranteed Maximum users is less than the Minimum value, and that negative values should not be allowed for Minimum and Maximum. (Realm -> Authentication Policies -> Limits) (57987).
- When a local auth server is imported via XML import, the “New Password Must be Different From Previous Password” option comes up checked in the UI even though it was disabled in the original configuration (60003).
- XML Import/Export of Radius Custom Rules is not supported (53548).
- Authentication against Active Directory on Windows Server 2008 is not supported (52705).

Archiving

- While archiving, if the administrator selects the option to clear all logs after archiving the logs are cleared even if there is a failure in archiving. This scenario can occur if the archiving server name or IP address is incorrect or unreachable. (59952)

File Browsing

- The shortcut files created within shared folders on Longhorn server do not get listed. (59800)
- The shortcut files, created for folders in Windows XP SP3 server, are listed but accessing them throws an error. (59801)

NSM support (device issues)

- The administrator is advised against configuring DMI agent settings from the NSM UI and pushing this configuration to the device. This configuration will result in the device DMI agent restarting prematurely without sending an <edit-config> RPC reply to NSM, and NSM will display an “UpdateDeviceFailed” error message. (60058)
- The DMI agent process (dsdmiagent) on the IVE consumes 100% of the CPU if the wrong platform or OS version is entered in NSM as part of the Add Device workflow for that particular device (59346).

NSM support (NSM issues)

- In the NSM UI, the group selector panels titled “Members/Non-Members” map to the panels titled “Available/Selected” or “Available List/Selected List” in the SSL VPN SA or Infranet Controller administration UI. (55674)

- When SSL VPN SA and Infranet Controller device objects are promoted to templates, default values in the device object are not promoted to the template. This behavior is working as designed and is not a defect. (56704)
- Identifier names (names of key fields) in the SSL VPN SA and Infranet Controller configuration, such as the names or realms, roles, sign-in URLs, sign-in pages and so forth, cannot be changed through the NSM UI. This is correct NSM behavior. However, identifier names can be changed through the SSL VPN SA and Infranet Controller Web UI. (57104)
- Selection of multiple objects is not available through the NSM UI, even though this capability is available on the SSL VPN SA and Infranet Controller Web UI in multiple places. (57190)
- The SSL VPN SA and Infranet Controller admin UI allows duplication of objects such as roles or resource profiles. This capability does not exist in the NSM UI. (55527)

System Services

- If the administrator configures virtual ports for the external interface when the external interface is disabled, NSM accepts the configuration without any validation errors. However, when the configuration is pushed to the device, device-side validation fails and the device throws an error, resulting in a failed config update from NSM. (58625)
- When configuring IP address for virtual ports, no validation check is performed on the NSM side. When the configuration is updated to the SA device, an error will be generated if the IP address is invalid. (58627)
- In NSM, administrators will be allowed to edit virtual ports settings from the Passive node, provided the Cluster license is installed on that node. (59215)
- The ARP cache entries cannot be deleted through Serial Console. (59834)
- Through XML Import/Export or NSM, administrators will be able to assign the same IP address of a VLAN to all the nodes in a cluster. This is not correct and will be fixed in the next release. (59667)
- Through XML Import/Export or NSM, an invalid MAC address configured in an ARP cache entry will be accepted. However, during runtime, this ARP entry will not be used. (59608)
- In NSM, when configuring cluster nodes in a template, the Add and Delete buttons for VLAN and virtual ports will be disabled. This is due to the missing of license info in a template. (59290)
- With the kernel change in 6.0 and later, the reporting of the load average in an idle system is different from previous releases; the minimum value at idle will be 1 as the kernel accounts for system related processes. (385631)

XML Import/Export

- It is expected that XML Import of a large configuration will drive up CPU utilization. It is recommended that such operations be performed during maintenance windows. (56761)

SA 2000 through SA 6500 Items

All Client Applications

Log Upload

- Log Upload for Host Checker and Cache Cleaner applications don't work through Firefox with proxy. This includes all versions of Firefox. (59707)

Network Connect

Macintosh Client

- On MAC 10.4, Network Connect log may go up to 10.9MB before the log is rolled over. (59507)
- On Mac platform, if NC is launched, Persistent Session does not work. (60402)

Secure Meeting

- Through NSM, User is able to update Secure Meeting configuration on SA service successfully even if "SMTP Login" and "SMTP Password" are invalid. (59632)

Secure Virtual Workspace (SVW)

- SVW does not work on Vista platform with Java Delivery. Restricted users on Vista platform cannot run SVW. (60060)
- Inside SVW, after selecting "Cancel" on dsSetupApplet, the next time the Warning popup dialog box comes up, you must click "Run" more than once to launch SVW. (60076)
- JSAM configured with Netbios file browsing does not work inside SVW. (60265)
- JSAM does not launched inside SVW on Vista platform. (60267)
- If the filename already exists on the real desktop, then you cannot create a file with the same filename in SVW. (60366)
- SVW doesn't support printers that do not use Windows print spooler. (433090)

Documentation Errata

The description of the Secure Email Client reads:

Secure Email Client option—If you have the Secure Email Client option, the IVE supports the Internet Mail Application Protocol (IMAP4), the Post Office Protocol (POP3), and the Simple Mail Transfer Protocol (SMTP).

The description should also include the following note:

Secure Email Client does not support the roaming session options you can select in Users > User Roles > *Role* > General > Session Options.

The description of the User field when creating a Policy Trace file incorrectly states that you can use a wildcard character (*) in place of a username. This is not supported. The step should read "In the User field, enter the IVE username of the user you want to trace."

Archived Known Issues and Limitations

All Secure Access Platforms

System Status and Logs

- On some Administrator console pages, changing one or more parameters causes multiple log messages to appear in the IVE system log that indicate that all the parameters are changed. However, this occurrence does not result in any incorrect behavior.
- Default filter for logs may be incorrectly set after deleting a custom filter. (31694)
- On the **Preferences > Applications** page for end-users, there are links to uninstall applications even if those applications are not installed or available on the client PC (if they are not using a Windows PC, for example). (22978)
- When switching from Optimized NetScreen Communication Protocol (oNCP) to standard NCP, or vice versa, you must restart all NCP-based communications. This includes W-SAM, Network Connect, and Secure Meeting.
- An Internet Explorer cache problem exists when handling the HTTP No-Cache directive in the Microsoft Internet Explorer Web browser. Web content is sometimes served with the HTTP directives. No-Cache or No-Store browsers should not cache such content. When GZIP compressed content with the No-Cache or No-Store directive is served to Internet Explorer the browser saves a copy of the uncompressed content in its cache. If a user then uses the Back button in their browser, Internet Explorer displays the file from its cache, instead of sending a new request. Internet Explorer only exhibits this problem when the served No-Cache content is compressed. To work around this problem, you can configure the IVE not to compress specific files, directories, or types of content using the URL rules commands. (29133)
- The external port on the administrator Web console may show “Connected” status even though the network cable is not connected. (31987)
- When configuring the size of log file, please do not configure multiple log files to have larger than 250Mbytes as it may cause the system to run out of disk space. (36153)
- The legend may still be displayed on the Central Manager display even though it is disabled in the display setting. (39573)
- “Saving all Logs” only designed for Event, Access, and User logs. It does not include sensor logs and uploaded client logs. (35127)
- There are rare situations in which, after binary import, the log utilization is shown to be -1%. (42183)
- When a VLAN interface is deleted, two log messages are generated. The first log message is redundant, and is missing the VLAN interface name. The second log message is valid and contains the correct VLAN interface name. (34287)
- The default filter setting, under System -> Log/Monitoring -> <log type> -> Filters -> <filter> -> Make default, is not supported through XML Import/Export. (57568)
- Reserved HTTP characters are not supported in log format while creating a log filter. (57063)
- Binary import system and user configuration across incompatible hardware platforms are not supported. For example, exporting a system configuration from an SA6000 machine and importing it to SA4500 machine will result in machine not function correctly. (53885)
- For XML Import/Export, the default value for “Enable GZIP Compression” is machine

dependent. On SA6000, it will be TRUE; otherwise, it is FALSE. (57178)

- Upgrade to 6.2R1 may fail with “Unable to import data” error message if the user configuration is very large. The recommendation is to keep the number of user records within 160K. (56657)

System Services

- License upgrade may not work if the original licenses are installed in 3.x releases. (46110)
- When Custom Cipher Selection is used, the selected ciphers are enforced to the SSL connections from clients. SA will always present “High” ciphers to backend servers when making SSL connections. (47718)
- The "RC4-64-MD5" cipher is no longer supported in "LOW" setting. (48967)
- The current SSL-VPN configuration import functionality does not track any platform specific functionality like SSL Acceleration cards etc. Hence if an Admin were to import the configuration from an IVE platform (SA3000) into an SA6000, SSL crypto acceleration would be disabled as the SA3000 does not have the crypto functionality (38433)

Maintenance

- Cross platform imports should be performed only across compatible platforms. Cross platform imports across unsupported migration paths may result in undefined system behavior. (53885)
- The Node Monitoring setting, under Maintenance -> Troubleshooting-> Monitoring -> Node Monitor, is not supported through XML Import/Export. (56319)
- The System Snapshot options, under Maintenance -> Troubleshooting -> System Snapshot, may not be pushed correctly to target device through Push Config. (57576)

Push Config

- Push Config does not currently support deletion of objects. Through Push Config, the administrator can only change settings for existing objects, or create new objects on the target system. (57332)
- On a source and target SA device, configure the same web ACLs or push them individually from source to target through the Selective Push operation. Then, if the order of the ACLs is changed on the source SA and a second Selective Push operation is performed from the source, the resulting order of the ACLs on the target will differ from that on the source. To work around this issue, the ACLs need to be manually re-ordered on the target following the second Selective Push operation. (57162)
- The following settings are excluded from the Selective Push Config operation: internal port, external port, management port (for SA 6000, SA 6000-SP and SA 6500) and VLAN ports. (54323)
- If Security > Lockout options “rate” and “attempts” are configured to be “4294967295” on one SA device and then pushed to another SA device via Selective Push Config, the resulting value on the target SA device is “2147483647”. (57548)
- Push Config (Full Push) incorrectly clears the DMI Agent settings on the target device. The workaround is for the administrator to re-enter the DMI Agent settings manually on the target after the Push operation has completed. (60373).

XML Import/Export

- Combination of “insert” operation and “create” operation of the same XML element in the XML document won’t work in XML import operation if “insert” operation was executed before “create” operation. To work around this problem, there are two options :

Option 1 : Use the “insert” operation with all the required attributes since “insert” operation will

create the object if it does not exist, or,

Option 2 : Separate the “create” operation and “insert” operations to two different XML documents, and import XML document with “create” operations first, then import XML document with “insert” operations. (55655)

Binary Import/Export

- When an binary configuration import is performed with the option “Import everything except network settings and licenses”, apart from the network settings & licenses, several other settings are excluded from the import, such as : ‘cluster configurations’, ‘certificates’, ‘defined SNMP settings’ and ‘syslog configurations’ (56329)

Administration Tools

- If a serial console troubleshooting tool (such as ping) becomes unresponsive, press CTRL+C to terminate the tool and return to the menu.
- VLAN tags do not show up in the TCPDUMP troubleshooting tool due to hardware acceleration. (28400)

Connectivity

- FIN packets may leak from internal port to external port. However, there are no security ramifications for this activity. (25095)

SNMP

- Snmpwalk does not report NC tunnel interfaces due to performance overhead related with retrieving the corresponding OIDs.
- The iveRebootTrap is not sent if the IVE is rebooted via the serial console. However, an event of severity “Major” is logged in the Event Log. Additionally, if the “Major Log Trap” checkbox is selected on the Log/Monitoring > SNMP page, a major log trap is generated for this event. (41829)
- SNMP MIB walk or the entire IVE MIB is expected to be CPU intensive. The recommendation is to configure the external SNMP monitoring application to bypass the tcpTable in the TCP MIB when walking the IVE MIB.(44894)
- When the SNMP agent is disabled from the admin UI, an admin log is generated stating that the query status has been changed to “off”. However, there is no corresponding event log stating that the operational state of the agent has been changed to “off”. (47205)
- Standard traps as specified in MIB-2 such as linkUp, linkDown, etc are not supported. The administrator is advised to monitor traps specified in the IVE MIB such as netExternalInterfaceUp or netExternalInterfaceDown. (41339)
- System healthcheck reporting via SNMP traps, and system parameters reported via the Admin UI dashboard graphs under System > Status > Overview are not synchronized. As a result, SNMP memUtilNotify and cpuUtilNotify traps can be generated even though the dashboard graphs do not show a spike in memory or CPU utilization. (56817)

Archiving

- The Admin UI will show the following checkboxes unchecked, though they are configured, when Admin logs in with Read-Only right: Archive events log, Archive user access log, Archive admin

access log, Archive NC packet log, Archive Sensors log, and Archive client-side log uploads. This is just a UI presentation issue and not affecting actual archiving functionality. (42548)

AAA

- The upload of custom sign-in pages may some times fail. This occurs rarely. The workaround is to try again, preferably with debug log enabled. (46936).
- The maximum number of combined bookmarks a role can have is ~500. If a role has more than 500 bookmarks, some operations (e.g., delete role, duplicate role) may not work correctly. The workaround is to split a role with a large number of bookmarks into multiple roles. (41557)
- When the user signs in and gets redirected to a custom start page, then the access to that page will be allowed in that session either through a bookmark or browsing toolbar, even though there is no explicit policy to allow access. (38853)
- When specifying a time condition in policy detail rules, the specified time range cannot cross midnight. The workaround is to break the time range into two conditions. (27811)
- Importing the system config does not import SSL Intermediate CA Certs (chains). (21040)
- Web Server SSL Certificates issued by the IPSAC root are not supported by the IVE. SSL Certificates of the Netscape format must include the SSL Server Bit set in the "Netscape Cert Type" extension. Key Usage, Extended Key Usage, and Netscape Cert Type are all required for these certificates to work properly.
- The ACE Next-Pin and New-Token modes do not work properly when using ACE as the secondary login server. (21870)
- The Realm-level option "Enable Password Management" needs to be enabled in order to allow the end-user or administrator to change their password via the "change password at next logon" option (IVE Authentication – user accounts). (22969)
- When using HTTP Basic Auth (in SSO), if a Realm name (not an IVE Realm but an HTTP Auth Realm) is encoded in Shift_JIS, and not UTF_8, the IVE will not properly display it. (15881)
- Accounts that are used for both administrator and end-user access to the IVE may conflict if they use the same username and authentication server. This practice may cause one account to force the other account out of an IVE session when the other logs in. One solution is to duplicate the Authentication server on the IVE so that Admin users login to one Authentication server and end-users login to a duplicate server that point to the same backend system.
- Session Timeout Warning is not supported on handheld devices.
- "Sign Juniper Web Controls" feature will not sign Juniper web controls that are windows executables. On Vista, User Access Control (UAC) prompts may appear for some of these windows executables, and user will see Juniper Networks company name in the UAC prompts. (46687)
- The variable NTDOMAIN[2] does not work. (49917)
- Users are forced to change their passwords when XML-exported System Local user accounts are imported back into the SSLVPN device. This happens only if password management is in force, and if passwords were originally configured to be expired after the lapse of a specified number of days. The work-around is to avoid XML export/import of user accounts and use binary export/import instead. (47476)
- XML Import containing changes to User Roles with insufficient data will succeed leading to inconsistent configuration state (57801).

- IP Address of Netegrity Siteminder Web Agent, when changed through XML Import, is not validated for correctness (58065).
- Policy trace may show an error message on the lines of “authentication successful to auth server [Unknown Auth Server]” even when authentication succeeds. This message can be ignored (57367).
- Custom Sign-In pages uploaded through XML Import may not work, and IVE may present standard signin page instead of the custom page (57984).
- XML Import of a Realm with the option “When editing, start on Role Mapping page” set to OFF, imports the state of the option incorrectly as set to ON (57244).
- XML Import of a configuration enabling Siteminder Auto Sign In without specifying an Auth Realm succeeds, whereas it should not (58063).
- Some extra configuration options appear in the XML exported configuration of Password Restrictions for User Realms. These are Primary Password Expiration Warning Days, Secondary Password Expiration Warning Days and Enable Secondary Password Management. Import of such a configuration file works fine. The extra options can be ignored (57992).
- Factory Reset creates System Local configuration with very low password change and warning intervals (58101).
- XML Import/Export of device certificates and code-signing certificates is not supported.
- When CRL download frequency is set to a value higher than 166, XML Import/Export and PushConfig operations fail (57608).
- XML export of SAML SSO Policies does not export Detailed Rules attribute information (57290).
- Novell eDir: Starting with this release, a password policy that allows all grace logins to be consumed by the user is not enforced. The user will always have two grace logins left. This change is made so that users are not confronted with a situation where they login only to discover that they cannot change their password.
- On upgrading from 5.X releases to this release, the name of the Siteminder Auth Server becomes uneditable (51314).
- On XML Import of OCSP responder configuration, IVE displays empty tabs (57609).
- If a realm is XML-edited to change its auth server to point to another server that is of a different type than the one configured on the device (example: LDAP in XML file but Radius on the device), then the import of the XML file may fail. The failure happens if the realm has role-mapping rules containing attributes that are available on the old server but are not applicable on the new server. (57369).
- On the SA device web admin UI, under Configuration->user realms-><REALM NAME>->Role mapping rules, there are three options: 1. Merge settings of all assigned roles, 2. User must select among the assigned roles, and 3. User must select sets of merged roles assigned by each rule. Of these options, the first one is never exported or imported via XML Export/Import. Instead, the system assumes that the first option applies (ie that it needs to Merge Settings for all Roles) if the second and third options are set to <>false> in the imported XML document (57202).
- If the role-mapping rules are exported from an SA device through XML Export and new role-mapping rules are introduced in the exported XML document, then the order of the rules in the XML document is not preserved when this document is later imported into the SA device. The newly introduced rules are added to the bottom on the existing list of role-mapping rules on the target device (58044).
- Under role->UI options when we clear the Background color in Header section, Background color in the sub header section or font color in the sub header section xml export sets all three values to #000000, even though the UI displays default values for the sub header background color and the text

color. (58136)

- User is unable to login to SA if the hostname has an underscore. (56624)
- The IVE allows XML Import of a new SiteMinder auth server for which Backup Server is not specified, but Failover Mode is set to “Yes” in the imported XML document. As a result of the XML Import operation, the SiteMinder auth server gets created, but if the administrator opens the auth server configuration and clicks on “Save Changes”, the following error is seen : “To enable Failover Mode, a Backup Server must be specified”. (58436)
- The idle timeout value for the SiteMinder auth server does not get imported correctly via the XML Import operation. The values are transformed incorrectly by the XML Import operation to one-sixtieth the intended value (ie “1” gets imported as 0.0166..”). Moreover, if the administrator clicks on the Save changes button, the following error is seen :

Error AD-86

Invalid Policy Server Idle Timeout.

To workaroud this issue, the administrator needs to configure the correct value for the idle timeout via the admin UI. (58422)

- It is possible to enable the “Automatic Sign-in” checkbox for the SiteMinder auth server via XML Import, even if the auth server is not mapped to any realm. The XML Import goes through successfully, but if the administrator browses to the SiteMinder auth server page in the admin UI and clicks on “Save Changes”, the following error is seen :

Error AD-79

Invalid Auto-Logon Realm.

To work around this issue, the administrator is advised to deselect the “Automatic Sign-in” option or to map the auth server to a valid realm following the XML Import. (58394)

- Through XML Import, it is possible to create LDAP auth servers by specifying just the auth server name and IP address, but without specifying the port number. Subsequently, when the administrator browses to the LDAP auth server configuration page in the admin UI, error messages are displayed. (58392)
- In a newly-created delegated admin role, the default delegation settings for user roles or realms in the General > Overview page show “Deny All”. Then, if the administrator navigates to the users > roles or realms tabs, and clicks Save Changes without making any changes and then navigates back to the General > Overview page, the “Deny All” is replaced by “Custom Settings” (58188)
- Through XML Import, it is possible to configure limits restrictions in User Realms such that the sum of the guaranteed minima across the realms exceeds the user license limit. However, when users log in to the system, the correct license checks are enforced. (58000)
- If as part of XML Import, the “Roaming Value” (under delegated admin session-options) is set to limit-to-subnet, the corresponding netmask value is set to 0.0.0.0 on the IVE.(57017)
- The administrator is advised against creating a ‘Administrators’ role in an XML instance document and performing an XML Import of this document into the IVE. Doing so will overwrite the .Administrators settings on the IVE with the settings in the XML document, resulting in unintended modifications to the delegation permissions or other settings associated with the .Administrators role. (58478)
- The “Users”, “Meeting” and “Authorization Only Access” Sign-In URL names should be unique. The administrator should not create the same Sign-In URL name with different cases for them in the XML document. (57727)
- When CRL download frequency is set to a value higher than 166, XML Import/Export and

PushConfig operations fail (57608).

- The "Users", "Meeting" and "Authorization Only Access" Sign-In URL names should be unique. The administrator should not create the same Sign-In URL name with different cases for them in the XML document. (57727)

Password Management

- Password Management must be enabled at the realm level if the Admin wishes to enable password expirations or require a user to change a password at the next log-on.
- When a user's password is expired, and Password Management is NOT enabled for that user's realm, the error message displayed to the end-user shows "account disabled", although this account may not truly be disabled. This will be addressed in a future release. (21654)
- When using Sun One/iPlanet as an Authentication server and enforcing both "password expiration in X days" and "allow password change after Y days", if the user's password is reset (or changed) then the user's profile will have a new password expiration date. However, if the password expiration timeframe is changed (for example from 10 days to 20 days), then the user's profile will still show the old password expiration time. This is a limitation of Sun One/iPlanet to which we adhere.
- AD Domain Controllers synchronize security policy settings every 5 minutes. If a change is made to the security policy, for example "minimum password length", it could take up to 5 minutes before that change propagates to all Domain Controllers. This also applies to the Domain Controller on which the change was originally performed. For more information, please refer to: http://www.microsoft.com/technet/treeview/default.asp?url=/technet/prodtechnol/windowsserver2003/proddocs/standard/lpe_overview.asp.

Client-Side Digital Certificates/Cert-Based Authentication/PKI

- When the SA device is configured to "Accept SSL V2 and V3 and TLS V1 (maximize browser compatibility)" and the browser is set to "Use SSL 2.0" only, then the client authentication using the certificate will fail. The workaround is to check the option "Use SSL 3.0" in the browser as well. (42901)
- Client certificate authentication will fail when the client machine has Windows 2003 SP1 installed. The solution is to install Microsoft hotfix KB931494.
- The IVE does not perform revocation checking on Root CA certificates. If a user tries to login to the IVE using a valid certificate issued by a revoked Root CA, the IVE allows the user to sign in. (28892)
- Certificate users may get an HTTP 500 error if an end-user provides an incorrect password for a private key file when challenged for a client certificate. (13489)
- When using LDAP for a CDP, do not specify port numbers in the CDP Server field. The default port number for LDAP is 389. To use a non-standard port, use Manual CDP configuration. (18578)

If you configure a client-side digital certificate authentication policy for the Realm, and the client's certificate is expired, the user cannot login to the Realm until he is given a valid client certificate. (14922)

Host Checker and Cache Cleaner

- If a "Restricted" user runs Cache Cleaner, they will not be able to clean directories that are in privileged root directories like C:\Program Files\...

- Sometimes when using the Firefox browser, it may go into an indefinite "try again" loop if manual intervention is needed to correct a detected anomaly, such as deleting a file. If this occurs, terminate the browser session and restart again.
- Cache Cleaner is not supported on Windows Mobile Devices and will not load on them. Any realm and role restrictions that require Cache Cleaner will fail (39116).
- Host Checker and Cache Cleaner do not work on Firefox when using Sun JVM 1.4.2_04 for the delivery of the Juniper Setup Applet. (40628)
- Whole Security Confidence Online is not supported on the Vista platforms (42943).
- Host Checker Connection Control is not supported on the Vista Platform (44515).
- Whole Security may perform automatic remediation of an endpoint after the user has been shown the remediation page. In this case the user will need to select "Try Again" on the remediation page to re-evaluate the policies and obtain the appropriate access (47655)
- When using Host Checker functionality on Linux OS platform, "firefox" needs to be available in the system PATH in order for remediation instructions to be displayed (47414)
- Auto remediation for Microsoft Windows Firewall on Vista fails if UAC is ON. (51824)
- Predefined AV/FW policies can perform following remediation automatic but the status is not displayed to the end user. [49050](#)
 - Turning on AV real time protection
 - Turning on Firewall
 - Start the AV scan
 - Download AV signature files
- On Vista platform with Java delivery when both HC and CC is enabled for a realm, HC is not installed (57208)
- On Vista with Protected mode off, java delivery and HC in post-auth, if all HC policy pass, the user sees a sign-in page with authentication failure message (56927)
- On Win Mobile id user selects "do not show remediation for this session" option on the remediation page then there is no way to undo it for the session as "Advanced preferences" page is not available on Win Mobile. (56003)
- While importing config with ESAP with version greater than the active ESAP on IVE if some of the AV/FW/ASW products selected in the newer ESAP are not supported on current active ESAP the import fails. (55903)
- On Mac, after login inactivity period, host checker exits and does not restart if the user logs in from same browser instance. User needs to launch a new browser instance and login. (53946)
- On Linux/Unix MD5 check for Process works only if process is launched using absolute path. (52885)
- Shavlik patch rule admin UI: Sometimes the browser is hung if you add or remove a lot of "specific products". The browser operates normally some time after the java script completes processing.
- Host checker is not supported from WSAM UI launcher on Windows Mobile devices.
- During xml import the credentials used to download the files from staging server for "Virus signature version monitoring" and "Patch Management Info monitoring" under Endpoint Security are not verified. (53497)
- Xml import will fail if predefined OS rule under Endpoint Security does not contain any OS selected or contains only Win9x OS selected which is no more supported. Admin should correct

these OS rules before xml import by adding supported OS in the rule. (56493)

- Host Checker options "Create Host Checker Connection Control" and "Enable: Advanced Endpoint Defense" do not get exported during xml export. They are policies exposed as options as in UI. To achieve equivalent export the policies which are created by enabling these options in admin UI (57573)
- On realm restrictions page, during xml I/E, for all or some policies only "Require and Enforce" option should not be enabled. Along with it "Evaluate Policies" option should also be enabled for correct HC behavior. (57993)
- Xml import fails when host checker policy has custom expression defined.
- If user.cfg binary import is performed on IVE version released before 6.2 then the active ESAP package is corrupted. This followed by upgrade to 6.2 causes predefined rules to malfunction. For instance one of the symptoms will be that in the predefined Antivirus rule names of Antivirus selected in rule won't be displayed on admin UI after upgrade to 6.2. (58298)

To restore active ESAP corrupted in IVE versions prior to 6.2 (due to user.cfg binary import), that ESAP should be deleted and uploaded again on IVE. Only after this is done should the IVE be upgraded to 6.2.

- Inside SVW, after logging in to IVE, if browser is left idle for a while such that the session times out, sign out doesn't close SVW - just logs user out of IVE. (60332)
- On Vista with IE7 if HC and CC are configured on a realm and client side proxy is also configured then HC installation falls back to Java even when ActiveX is enabled (60554)

Internationalization Issues

- When importing a custom HTML Help file for end-users, if the file is encoded in a different language, for example, Shift_JIS, it must be converted to UTF-8 before it is imported by the IVE administrator. (10839)
- The following URL contains a list of characters which are not supported for filenames or folders on Samba Servers: <http://support.biglobe.ne.jp/help/faq/charactor/izonmoji.html>. (14529 and 14348)
- With localized Pocket PCs, such as the Japanese Pocket PC, the locale is not sent in the HTTP header, and thus the IVE is unable to detect which language to return, so English is returned by default. (22041)
- Internet Explorer may truncate Japanese filenames if they are too long. Additionally, some Excel files cannot be saved. More details can be found about this non-IVE issue at: <http://support.microsoft.com/?kbid=816868>. (14496)
- The timestamp function of the IVE may not be in the same format as what is expected when working with the Japanese user interface. The formatting for the IVE is as follows: hh:mm:ss (am|pm) and month/day/year.
- When using Netscape 4.7 and the Japanese language setting, the default font may incorrectly display characters and words on the user interface page. If this occurs, you can change the font setting in the **Fonts** section of the Netscape Preferences, where you can select the option "Netscape should override the fonts specified in the document."
- With Secure Meeting, when using a Japanese language setting on the IVE, Meeting invitations will be sent out using the Japanese template. If these invitations are sent to Yahoo or Hotmail or other Web-based email accounts, some characters or possibly the entire email may not display correctly.
- Special characters such as ①, I, ¥, and ~ are not supported in filenames for UNIX servers.

- Japanese characters are not supported in naming Authentication Servers.
- Filenames using 5c characters such as 表 and 工 will be corrupted and cannot be deleted from UNIX servers.
- Some of the diagnostics content in W-SAM is not localized and will always be displayed in English. (22068)
- In a Host Checker policy, the Admin should enter Registry Settings rule settings in English. (25097)
- Bolded characters in Korean, Chinese, and Japanese Help files may be difficult to read. To fix this problem change your browser's text size to a larger font. For instance, in Internet Explorer 6.0, choose **View > Text Size > Largest**. (29603)
- If you try to print Asian language Help from Firefox on Linux, square characters may appear in the printed Help. To fix the problem, use another browser such as Internet Explorer. (30017)
- Advanced Endpoint Defense: Integrated Malware Protection is only supported in English. (32550)
- End-user help will appear only in English in this release. A translated version of the end-user help will be available in the first maintenance release after the general availability release. (35712)

Adaptive Delivery – AX and Java Installers

Windows Vista additions

- On Windows Vista, when installing the Setup Client application or any other Juniper client application, UAC prompts and Setup dialogs may be hidden in the background. However, when these dialogs appear in the background, they will blink within the user's Start Menu "Dock". Users should pay attention to this when working in a multi-window workspace. (45441)
- If ActiveX control was installed and a user cancels a UAC prompt, JAVA delivery is invoked and it redirects user to setup client download page. (48351)
- Some UAC prompt may not come in foreground during IVE clients' installation. (44753)
- When Juniper Installer Service is installed on a Vista client machine, Juniper setup ActiveX control is installed, however, when a restricted user attempts to download an IVE client for the first time, a "Run Prompt" is shown. (47877)
- When Vodafone Mobile Connect application version 9.1.0.4345 is installed on a Vista machine, it modifies the current user's APPDATA directory from "c:\Users\\AppData\Roaming" to "C:\Documents and Settings\ReleaseEngineer.MACROVISION\Application Data". This is a problem with Vodafone Mobile Connect application. It should not modify user's APPDATA directory. This error behavior of Vodafone Mobile Connect application causes Juniper setup client fails to install correctly. If you see issues with Juniper setup client installation, please check if you have Vodafone Mobile Connect application installed. (49755)

Existing Windows XP/Windows 2K platforms

- User see the following warning message when signing in using the Firefox browser.
A script from "Juniper Networks, Inc." is requesting enhanced abilities that are UNSAFE and could be used to compromise your machine or data.

Firefox will not execute JavaScript that is signed by a certificate whose CA is not already trusted by Firefox. Therefore, this is a safe script. To avoid seeing this message every time the user signs in, the user should check the box "Remember this decision".

The purpose of the script is to allow components such as W-SAM, Network Connect, and Secure

Meeting, to be launched from Firefox. (23824)

- The Java Installer Security patch is present in Release 5.4. When a user updates their client to an SSL-VPN running version 5.4, and then reverts to an older version that doesn't have the security patch, client applications will not load using the Java Installer. Additionally, there will not be any notification to the user due to the non-persistent nature of the applet. (40923)
- Juniper's Installer Service is NOT designed to update the version of ActiveX and Java Installer that is loaded on the client system. The user must go to a web browser and logon using an interactive Web Browser launch to ensure that the updated controls are installed on the client-side.
- When running under Windows Vista, the NC standalone launcher causes the Java installer to load, successfully, in spite of the fact that the ActiveX installer is enabled (56157)
- Java delivery failing in 64 bit XP with "Failed to download the application" error (57681)

All Client Applications

Windows Vista additions

- On Windows Vista, ONLY Version 5.5 and later Juniper client applications are supported. Windows Vista will display a warning: "This program has known incompatibility issues" when a Juniper client version 5.4 and older is attempted to install and/or launch on a Vista platform
- When installing Version 5.4 of the Juniper client package "installerservicesetup.exe" on a Windows Vista platform, the user will incorrectly see a Microsoft UAC prompt as mentioned above. (46180)
- All UAC prompts that display "known incompatibility" warnings incorrectly display application name to be: Juniper Citrix Services Client.

Network Connect

- The Network Connect Client IP address pool user interface requires you to enter IP addresses as ranges, with a maximum of 254 addresses per range. Specify each range on a single line. To specify a larger pool for a specific role, enter multiple IP address ranges. In the future, we will mitigate this by allowing you to enter Network Connect IP address pools with a more standard syntax (for example, IP/netmask). (6378)
- When using RedHat DHCP server, the IP address assigned to a Network Connect user is not released when the user sign out from the Secure Gateway. (26994)
- A User-Agent string sent by a standalone Network Connect login is changed from "NcWin32" to "NcWin32<IEUserAgent>". Any authentication policy based on a user-agent string needs to be reviewed to ensure its accuracy. For example, a previous authentication policy which checks the "NcWin32" user-agent needs to be modified to check "NcWin32*". (37753)
- If Network Connect has been launched from a computer that has an older JVM, the browser hangs. (38269)
- Standalone Network Connect login doesn't support client certificate on a USB smart card. (41272)
- When AES 256 is specified to be the only allowed encryption algorithm on IVE admin console, only Network Connect on Vista supports this configuration. This is not supported by Network Connect running on Windows 2000 and Windows XP. (46060)
- NCP Idle Connection Timeout should be configured to be greater than ESP key lifetime. Otherwise, Network Connect may experience random session disconnect. (46723)
- If NC ACL is created as *.**, Network Connect client fails to connect. (56476)

- Network Connect client send/receive byte count wrap back to zero after it reaches 4GB. This is same for Windows client, MAC client and Linux client. (56829)
- When configuring NC bandwidth of roles, value is validate to ensure that total configured bandwidth of all roles do not exceed the bandwidth configured for the IVE system. However, admin may go back and lower the IVE total NC bandwidth to be less than total of bandwidth configured for all roles. (56413)
- NC access policies applied to a user are not captured in the Policy Tracing logs. (56169)
- IVE doesn't send GARP for an assigned NC client IP if the IP address is not in the same subnet as IVE's internal port. (54054)
- When using Network Connect, if the user signs out from the web page will lead to the error message "Failure to download the Application" when attempting to reconnect via Network Connect. Users that sign out via the Network Connect menu are not affected (57381)
- After a Network Connect Bandwidth Management policy is created, if the Maximum Network Connect Bandwidth of IVE was modified to be smaller than the Maximum Bandwidth configured in the policy, the value saved in the policy is not changed. However, the actual maximum bandwidth of the policy will be limited to the Maximum Network Connect Bandwidth of IVE. (58052)

Macintosh Client

- When a Network Connect tunnel is established on a Mac OS X computer, Network Connect might encounter failures when PING packets with sizes greater than 8000 bytes are sent. This is a limitation of the underlying Mac OS X platform. (24809)
- Network Connect fails to reconnect when a VIP fail-over occurs in an Active/Passive cluster environment if the client is on the same subnet with both nodes of the cluster. (27388)
- When clicking Sign Out from a browser user may see a message "session terminated due to duration restrictions". (47829)
- Client side proxy is not supported MAC OS X 10.2 (47885, 47960)
- Authenticated proxy is not supported on MAC OS earlier than 10.3.9 (49009)
- Microsoft Live communication doesn't work over Network Connect tunnel. (51928)

Linux Client

- Users should not remove the /etc/resolv.conf file while NC is running as it causes the client to terminate. (31037)
- In some situations, when authenticated proxy is used with Network Connect, the proxy takes precedence over the Network Connect route, causing an HTTP resource behind the IVE to be unreachable. (34481, 33938)
- Shortcut keys for localized menu items are not correct. (35672)
- Sometimes a Network Connect tunnel fails to setup when launched from a command line. (38735)
- Auto-uninstall on sign-out is not working. (41010)
- Network Connect client doesn't have reconnect functionality in Linux. (47211)
- To install NC on Ubuntu using the standalone installation package, user has to install RPM on the Ubuntu machine using "alien" first. (55679)

Windows Client

- If a Restricted user has Network Connect installed on their system, Network Connect can only be uninstalled if a user with Admin privileges attempts to run the uninstaller, or the Installer Service is installed and the restricted user uninstalls from the uninstall link under Preferences in the user's IVE homepage. (22200)
- Microsoft has limited API support for parsing a proxy PAC file. If a PAC file located inside the client's PAC, i.e. Internet Explorer's "Use automatic configuration script" is "[file:///C:\myproxy.pac](file:///C:/myproxy.pac)" Network Connect is not able to extract the correct proxy information. (24933)
- There is a known issue with the Network Connect standalone client when a custom start page is enabled. Network Connect does not automatically launch on the client as is expected with the standalone client. (25151, 32269)
- When upgrading the client from prior versions of Network Connect to version 5.0.0 or later, it is important to note that attempting to "uninstall" Network Connect from the Juniper SSL-VPN Web UI will not uninstall older versions of Network Connect. Each version of Network Connect will need to be uninstalled separately. (25958)
- When an existing Network Connect session is established, adding a PCMCIA-enabled Wireless card to a laptop will cause the Network Connect to reconnect. (27522)
- While still installing the Network Connect client, if a user tries to launch Network Connect (for example, from a previously installed version), Network Connect displays an error message "Error opening file for writing". (28143)
- In certain situations, users may get a "Cannot connect to IVE" the first time they launch Network Connect. Subsequent launches will connect without issues. This is due to conflicting software that does not allow Network Connect to bind to the TCP/IP stack properly. (28845)
- Some diagnostic tests in the Advanced View of the Network Connect client may fail on unsupported platforms due to lack of libraries that the tests depend on. (29082)
- When ActiveX is "Disabled," and the Sun JRE 1.4.1 or higher is enabled, signing out of the IVE Web interface will prompt the user to accept the SSL certificate up to two times (32129). Accepting the certificate prompt will successfully log the user out. This affects ALL Windows applications, including W-SAM, Network Connect, Windows Terminal Services, Secure Meeting, Host Checker, and Cache Cleaner
- The Network Connect client fails to launch if Kaspersky 5.0 Pro or 6.0 is installed on the same PC. (33123, 46903)
- Network Connect fails to connect if early versions of Checkpoint Secure client are installed on the same computer. Network Connect supports Checkpoint Secure client R5.5. (33162)
- Network Connect fails to connect when using the VIP on the DX. (34905)
- Network Connect does not support proxy with exception list. (45439)
- When Network Connect is connected to the Secure Gateway externally, an entry is added to the hosts file to point to the external interface of the Secure Gateway. (35774)
- Uninstalling the Network Connect client driver manually causes the Network Connect client to be unable to connect to the IVE. The client driver displays a "Failed to Connect to the Secure Gateway. Reconnect?" message. (35993)
- When running on Windows XP SP1, the Network Connect client has compatibility issues with iPass/Telia if split tunneling is disabled. This is due to Windows XP SP1 system issue. This issue doesn't exist on Windows XP SP2 and later. (36137, 35292)

- If you install the Odyssey client when a Network Connect client is running, the Network Connect client is disconnected. (40159)
- The Network Connect client doesn't support the proxy auto detection configuration. (40061)
- On rare occasions, if Windows is not able to sync with the timer server when the Network Connect client is running, Network Connect may repeatedly display a session timeout message box. (40718)
- On Vista, the Virtual Adapter of Network Connect shows the default gateway as 0.0.0.0. This is because of a Microsoft issue: <http://support.microsoft.com/?id=935269> "The IP address of the default gateway for a dial-up connection in Windows Vista is 0.0.0.0 ". (45131)
- New Secure Gateway Window menu button is not supported on Vista. (45157, 47978)
- In Vista, the Network Connect virtual adapter doesn't show user friendly name. (46345)
- Because Network Connect 64 bit driver is not signed by Microsoft, when Network Connect is installed on a 64-bit Vista machine, user will see a pop up message request permission to install the Juniper signed Network Connect driver. (46654)
- Because Network Connect driver dsNcAdpt.sys is signed by Microsoft release and there has been no changes since release 5.5, until Network Connect driver is signed by Microsoft again on 32-bit machines, dsNcAdpt.sys always shows 5.5 as its file version. (47034)
- "Copy to Log" button on Performance tab doesn't show a copy successful confirmation message. (47959)
- If client machine is shutdown when Network Connect is connected, the client side proxy setting may not be restored properly. (48328)
- If Cisco VPN Client 4.8 is installed on the same client machine, accessing shared folder when Network Connect is running, user may see a blue screen. (48590)
- Network Connect doesn't support Firefox 2.0 on 64 bit Windows 2003. (48598)
- On Firefox 1.0, if client side auth proxy is configured, the security alert displays in the same Firefox window so user has to click on back button to get back to the home page. (48170)
- In 64-bit windows 2003, if launches NC using nclauncher Sign Out from browser may show an error message saying that NC session is timed out. (48602)
- Network Connect is a 32-bit application that has supported to be run in a 6- bit machine. Network Connect client is not a true 64-bit application. (48687)
- Auto-Uninstall of Network Connect client when Network Connect is used by a restricted user is not supported on Windows XP. (48978)
- It's been reported that enable Microsoft TCP Chimney causes performance degradation when accessing Onyx server through Network Connect. (49421)
- When Juniper Installer Service is running, a standard user still can not install Network Connect on a 64-bit Vista because the user is not able to see the Network Connect driver installation pop-up message displayed by Vista. See release notes for bug 46654 for reference. (50097)
- Because Nclauncher and NC standalone application are based on Internet Explorer, Nclauncher and NC standalone application are not aware of proxy that is configured in Firefox. (50205)
 - Occasionally, after Network Connect client is installed using the standalone NC package, dsNcAdpt.inf file is left on the install directory. (56149)
 - On Vista, if the Windows network address is changed or if the network adapter is disabled then enabled after Network Connect client launched once, Network Connect client can't be

launched anymore. This problem doesn't happen on Vista SP1. (56628)

- Due to a Windows issue, user will get NC session timeout error when NC is connected to IVE through proxy with enabled "bypass proxy server for local address." Refer to <http://support.microsoft.com/kb/262981> for details. (57065)
- On a Vista 64-bit machine, nlauncher.exe may fail to launch Network Connect. (57435)
- Network Connect client may fail to connect if Adobe Bonjour software is installed and running. (50808)
- If DisableDHCPMediaSense is disabled, NC displays nc.windows.app.23712 error "The Network Connect session terminated. Do you want to reconnect?" Enable DisableDHCPMediaSense resolves this problem. (54001)
- After launched NC from IE7, if signed out from the browser, and then sign in to IVE again and attempted to download an IVE client from the same IE7 browser, user would receive a message saying "Failed to download the application". (57381)
- In Advanced View, Logs tab, when View All Logs are selected in the drop down box, the Log Content viewer window is empty. When a specific log such as dsNetworkConnect is selected, Log Content viewer will show the proper log entries. (59792)
- When Network Connect client is not connected, on the Diagnostic tab, when click on Start Diagnostics, NC Tunnel shows "Established" even when Network Connect is not connected. (59634)

GINA

- The Network Connect client needs to be installed prior to Windows logon for the GINA launch to occur. We strongly recommend that you do not enable auto-uninstall of Network Connect on sign out for roles where GINA is enabled. (29937)
- To login to the IVE using NC GINA, the user has to use the same IVE IP address / hostname as used by the browser. For example, if IVE has external IP and internal IP addresses, and the client is able to reach the IVE via either of the two IP addresses. If the user uses the IVE's external IP address to login using browser, when using NC GINA the user must use the IVE's external IP address. If the user uses the IVE's internal IP address, the NC tunnel can not be established. (34534)
- GINA/HC: Advanced Endpoint Defense: Integrated Malware Protection detection works only in user context mode and in certain situations as described in the documentation. (34806)
- GINA doesn't support certificate authentication. (36093, 34534)
- If the IVE is not responsive, the GINA login progress screen may freeze for up to 30 seconds. (37299)
- Occasionally, after the user successfully launches Network Connect using the GINA login, the Network Connect icon remains grayed out. (37615/43300)
- When Network Connect is upgraded, the GINA from the upgraded version does not take effect until the user reboots the machine. This is by design. A reboot warning message should be displayed. (38856)
- Network Connect GINA has a compatibility issue with the Odyssey client GINA. There are two workarounds: 1. Disable the Odyssey client GINA to enable the Network Connect GINA to function properly; 2. Enter Machine authentication credentials into the Odyssey Client so that it can authenticate against the Access Point prior to Windows login. (40091)
- GINA logon screen doesn't support domain\user login. (56348)
- Proxy configured for the dial-up connection is not supported with Credential Provider. This issue will

be fixed in 6.2R2(57763)

NC Command Launcher

- If a user is using Microsoft Internet Explorer 6.0 Service Pack 1 and a proxy is configured, the user is not able to launch a New Secure Gateway window from the Network Connect icon menu. This is due to IE 6.0 SP1 problem: <http://support.microsoft.com/?kbid=329802> (38869)
- The Network Connect launcher doesn't support Host Checker and Cache Cleaner in this release. (38876)
- nlauncher –signout doesn't support auto-uninstall Network Connect client option. (55859)
- nlauncher –exit doesn't restore proxy settings. (53009)
- Nlauncher.exe – stop doesn't restore proxy settings. (59915)

Installer Service

- If Encrypted File System is enabled on current user's temp directory, Install Service fails to install. (36569)

Rewriter/Web Applications

- If a web page is sending a POST request to an SSL-enabled webserver that does not have a valid SSL certificate and the IVE is configured to display a warning for invalid server certs then the POST request will not succeed. To workaround this issue, purchase a valid SSL certificate for the webserver or disabled the invalid server certificate warning for end-users. (46806)
- Microsoft Office 2007 XML documents that include references to external files are not rewritten. (Bug 41422)
- The PDF rewriter does not support PDF files that contain 2 objects for the same link. (41572, 44040)
- The PDF rewriter does not support Adobe forms, that is submitting a FORM from within a PDF file is not supported. (37684)
- To support the Oracle Financials application in a clientless manner, the following steps must be taken:
 1. The Oracle application must be configured as a Pass Through Proxy application on the IVE.
 2. The Oracle application must be set to the "Forms Listener Servlet" mode.
 3. If using a self-signed certificate on the IVE then you must follow the steps outlined in <http://www.oratransplant.nl/2005/07/11/using-self-signed-ssl-certificates-with-jinitiator/> or you must upload a production Web server certificate to the IVE (38806).
- PDF files greater than 32 Mb are not supported through the rewriter (38375).
- The IVE does not work with Whole Security Confidence Online version 4.3. It works with Confidence Online version 5.0. (35634)
- Some Java applets (including Citrix Java applets) on Mac OS 10.4 running JVM 1.5 might fail through the IVE rewriter if a production SSL certificate is not installed on the IVE. (29303)
- If using Safari on Mac OS, the browsing toolbar may not show up on Web pages that contain Flash objects and Java applets. (25896)
- When accessing, through the IVE, a Flash Web site that requires Macromedia, the user is not prompted to install the Macromedia application. Therefore, the Flash Web site does not render

properly (26391).

- When accessing Flash content, if the Flash content is generating Actionscript from within Actionscript and that Actionscript is generating links, then it may not work through the rewriter. (38638)
- The “Display Favorites” functionality on the IVE toolbar may not work on Web sites that use iFrames or frames. (27361,24621)
- Checking in of documents in the Documentum Web application is not supported through the Java rewriter.
- Lotus iNotes in offline mode is not supported through the rewriter. (9889)
- When using Siebel 7.5 through the IVE, the user may see ActiveX warning pop-ups. To stop these pop-ups, the user must change their browser security settings. For IE, this can be done by selecting **Tools > Internet Settings > Security > Custom Level** and enabling each of the ActiveX items listed there. (8247)
- Some menus of Siebel 7 are not working. This is only a problem for menu-dependent applications. With Siebel 7.5, the menus work as expected. (9442)
- Lotus Sametime Connect chat functionality is supported only when using Web rewriting and J-SAM. Full Sametime Connect functionality is supported using W-SAM and Network Connect. Users who access Lotus Sametime Connect directly, and need to access it through the IVE, should first remove the ActiveX control from their Internet browser’s cache.
- The native browser on a Symbian handheld device is not supported. (22743)
- On a Symbian handheld device, the toolbar logos may be aligned vertically instead of horizontally. In addition, the icons may appear as text links instead of GIFs. (27381, 27377)
- PowerPoint files may not display properly with Office 2002 in Internet Explorer on Windows 2000. To work around this limitation, administrators should advise end-users to install Microsoft Office 2002 Service Pack 1 and Service Pack 2.
- When "High browser security" is enabled, a user might see a pop-up warning confirming whether or not the Java applet should be downloaded. There is nothing that Juniper Networks can do to suppress this warning message, as it is a function of the browser. (21865)
- When using Internet Explorer 5.5 or 6.0 with compression, HTTP objects will be cached, regardless of the object’s cache settings. This is not a limitation of the IVE, rather an issue specific to Microsoft Internet Explorer and HTTP compression. For more details, please visit: <http://support.microsoft.com/default.aspx?scid=kb;en-us;321722>.
- There are known issues with Microsoft's pop-up blocker being enabled and certain OWA 2003 scripts not being able to run when being accessed through the IVE. Users could see "Script" errors in this case. Juniper Networks recommends that pop-up blockers be disabled and that the user refresh their OWA session after disabling the pop-up blocker. Additionally, pop-up blockers may cause problems with other IVE functions using pop-ups (for example, file uploads, online Help, or the IVE Upgrade Progress window, Dashboard Configuration page, and Server Catalog Configuration pages in the Admin console. (23092)
- With Mozilla Firefox and Netscape, saving files containing Japanese characters may result in garbled file names. (30602)
- HDML used by Openwave browsers is not supported through the rewriter. (28627)
- For OWA 2003 support, the following compression resource policy must be added, **Resource Policies > Web > Compression**, http://<OWA server>:80/exchange/*/?cmd=treehierarchy > Do not compress. (35937)

- The rewriter does not support load balancers that use version 3 session ID Secure Socket Layer (SSL) for client-server stickiness. (35619)
- The JavaScript call `window.createpopup` is not supported with persistent cookies. This call is used in Siebel 7.5. The workaround is to disable persistent cookie for Siebel 7.5. (32044)
- The standard and framed IVE toolbar does not appear in the iNotes application in Safari 1.3. (29926)
- To preserve filenames that contain non-English characters when doing a multiple file download in Windows File Browsing, go to Users > Resource Policies > Files > Options and select the appropriate encoding option. (38304)
- Sending email with attachments fails when accessing Domino version 8 through the rewriter. (57468)
- URL obfuscation does not happen when accessing Domino version 8 via the rewriter. (57537)
- Composing a new email in Domino version 8 via rewriter will be present a secure/insecure warning. (57469)
- When SSO is disabled and the IIS server is setup with Basic or NTML authentication for WebDav Virtual directory only, accessing Webdav through the rewriter the user can not login to the Webdav server with write access. (57083)
- When any PDF file accessed through rewriter is saved, "Danainfo" gets appended to the name of the file. (55946)
- When PDF files containing incorrect offsets are rewritten, memory growth happens. (58097).
- XML import allows creating a Web Resource Profile->OWA 2007 resource profile->Form post SSO, even when user does not specify any POST parameters. (58139)
- Importing XML for Web SSO settings may result in the following error message: "Modification of this attribute is not allowed". This error will occur in the following scenarios:
 1. The `<auth-type>` attribute is not set to "basic-predefined" or "ntlm-predefined", and the `<pre-defined-username>`, `<pre-defined-password-type>`, `<variable-password>`, `<explicit-password>`, or `<domain>` attributes are being modified by the XML import.
 2. The `<auth-type>` attribute is set to "basic-predefined" or "ntlm-predefined" and `<pre-defined-password-type>` is set to "variable", and the `<explicit-password>` attribute is being modified by the XML import.
 3. The `<auth-type>` attribute is set to "basic-predefined" or "ntlm-predefined" and `<pre-defined-password-type>` is set to "explicit", and the `<variable-password>` attribute is being modified by XML import.Note: This problem and related scenarios apply to Web SSO settings in resource policies and web resource profiles. (58256)
- When accessing a file via the rewriter and trying to save it through the right click menu will append string similar to "DanaInfo=10.10.10.10+Design.doc" to the filename. This happens because the right click menu picks up the name from the URL. Saving via the download pop-up will retain the filename without appending any string. (53642)

Pass-Through Proxy Issues

- To use OWA 2007 with Pass Through Proxy, the admin must configure a Selective Rewriting policy for resource `"*/owa/ev.owa?*"` and action set to "Don't rewrite content: Do not redirect to target web server". (46344)
- If the user is using Mozilla Firefox with Pass-Through Proxy (with the IVE port configuration), the IVE may invalidate the user session, thus requiring the user to sign in again.

- When using Lotus iNotes through Pass-Through Proxy, if an XML rewrite is needed, administrators are encouraged to either enable XML rewriting in the Pass-Through Proxy configuration, change the default cache rule from 'No-Store' to 'Unchanged', or add a new cache rule with the IP/hostname of the Lotus Server, path '*', and value 'No-Store'.
- When using Lotus iNotes through Pass-through Proxy clicking on the logout button in Lotus iNotes will logout the user from the IVE. (41825)
- If Pass-through proxy with "Rewrite external links" is configured for OWA or iNotes then links embedded in email messages are not clickable (44053).

Hosted Java Applet Issues

- The Java applet upload feature may not work on Mozilla Firefox 1.6 unless the default cookie settings for the browser are modified. This is because Mozilla Firefox 1.6 does not pass cookies from the browser to the Java applet. To work around this limitation, change the settings to "Enable all cookies" in Mozilla's **Edit > Preferences > Privacy & Security > Cookies** or enable "Include IVE session cookie in URL" in the IVE Admin console. (27353)

File Browsing

- Multiple file download is not supported on Windows Mobile devices. (47026)
- When opening a file in the Japanese locale the URL displayed in the Internet Explorer title bar and the URL bar is garbled. The file when viewed is displayed incorrectly. This is due to a bug in Internet Explorer. (19612).
- Due to a bug in Microsoft Network discovery API NetServerEnum2 IVE will not be able to extract the workgroup information if the master browse server is in a different subnet (43172).
- If Folder name starts with a double-quote (") character, it does not show up in the List of Files to be downloaded. (35408)
- To preserve filenames that contain non-English characters when doing a multiple file download in Windows File Browsing, go to Users > Resource Policies > Files > Options and select the appropriate encoding option. (38304)
- Windows File browsing is not supported if the file shares are on a Vista or Longhorn platform. (56066)
- When downloading multiple files, resource policy matching against file ACLs that don't end with the wildcard will fail. For instance, when downloading \\hostname\file.doc, if the ACL is set to \\hostname*.doc, the resource policy matching will fail. This problem does not occur with single file download. (57288)

SA 2000 through SA 6500 Items

Windows Secure Application Manager

- When using Citrix Terminal Services over Windows Secure Application Manager (WSAM), the Citrix "Session Reliability" feature should be disabled on the Citrix Metaframe clients. There are some complex TCP sequence interactions that are causing the application to break when this feature is enabled (21421)
- When WSAM applications are defined in Application Mode, in some cases, clients might find duplicate entries of this application name being displayed in the **WSAM client > Detailed** tab.
- In order to uninstall W-SAM, the end-user should use the Uninstall link in the UI under **Preferences > Applications**. (20415)
- If the Lotus Notes Background Replicator is used within the Lotus Notes Client with the other

email and database functionality, and the remote user needs access to this functionality through the Secure Access Gateway, Network Connect is required. If Lotus Notes Background Replicator is not used, W-SAM and J-SAM will both work as access methods. There is a chance that this might work in Release 5.0 W-SAM and later versions, but it has not been verified yet. (23346)

- When using WSAM with Checkpoint Secure Remote R56 client, there are known interoperability issues introduced by the Checkpoint product. (34584)
 - If WSAM is installed prior to Checkpoint Secure Remote R56 install, then WSAM will work fine.
 - If WSAM is installed *after* installing Checkpoint Secure Remote R56, WSAM does not work.
 - We have also identified that Checkpoint R60 works fine with WSAM in either scenario listed above. This indicates that there were code changes in Checkpoint 6.0 that resolved this interoperability issue with WSAM and other TDI driver-based clients. We are pursuing this issue with Checkpoint R&D.
- In Release 5.2, Juniper investigated support for DFS File Sharing through W-SAM. However, we have identified that the system needs to trigger Domain Authentication via ICMP/Kerberos, and this functionality is currently not supported. Once Domain Authentication is fully supported through W-SAM, there is a high probability Juniper can make DFS File sharing work. There is no ETA at the moment for supporting Domain Authentication. (30587)
- When the “W-SAM uninstall at exit” option is activated on the server, the user cannot launch W-SAM twice within an authenticated session. Users must sign in to the IVE two separate times—the first one resulting in a de-installation, and the second initiating a reinstallation. (26698)
- When using W-SAM diagnostic tools and the built-in log viewer, we recommend that you make your log level selection first, and then launch/re-launch W-SAM so that the log file can be viewed from the diagnostic utility. (25038)
- Now that the W-SAM client for Windows 2000/XP is built on a TDI-based architecture, only one application (BitGuard Personal Firewall) is known to be incompatible with W-SAM.
- Customers who use Norton Antivirus Personal Edition 2003 and 2004 should be aware of a live update that Symantec has made available to resolve some TDI compatibility issues with other TDI drivers, like the one used by Windows Secure Application Manager (W-SAM). We recommend you run Symantec live update before installing W-SAM. (24285)
- If Auto-Upgrade is disabled on the gateway, and the user has the older version of W-SAM installed on their computer, an error message appears instructing them to uninstall their existing application prior to reinstalling W-SAM. The user must manually re-direct their browser by clicking on the available hyperlink. (27350)
- Restricted users can't install W-SAM using the Stand-alone Installer, even in the presence of the Installer Service. The Installer Service is designed to provide application installation capability for users who are performing a standard Web-based installation from the IVE. (22454)
- If a Windows XP client has the “Fast User Switching” option enabled and is switching between two active user sessions, W-SAM upgrade notifications may get crossed between these active user sessions. (23090)
- If you have the NCP Auto-select option disabled, and answer “No” to the security warning during the load process, W-SAM does not initially launch. There is no additional impact to the user session. (18681)
- The application descriptions of the W-SAM window do not wrap properly, so administrators are encouraged to use short descriptions for the applications they have configured for W-SAM.

- If W-SAM is configured in Host Mode, and the Web browser is configured to go through a proxy to access the IVE, W-SAM is not able to tunnel traffic to the specified hosts. To resolve this issue, users can add the specified hostname to the Web browser proxy exception list. Another approach is to secure all Web browser traffic using Application Mode.
- If Samlauncher.exe is launched from the root directory, such as c:\, start test on diagnostics tab doesn't work. The workaround is to launch Samlauncher.exe from a subdirectory, such as c:\Juniper Networks\. (43617)
- If admin doesn't input any value in "Allowed Server Ports" field, it is interpreted as "*" by WSAM. (42119)
- Enabling client log for WSAM impacts throughput. (44585)
- If WSAM is configured by destination with multiple hostnames corresponding to the same physical IP address, only traffic for the first hostname would be secured. Workaround is to specify IP address in WSAM configuration. (46830)
- WSAM will not provide an option to reconnect in the message box displayed on idle timeout with the IVE. (47417)
- When a user signs out of the IVE on a Firefox browser, if WSAM is still transferring traffic, the user may see a "Session Timeout" message because the timeout message may reach WSAM before a sign out event. (45033)
- In Application mode, WSAM will forward all DNS requests to the Secure Gateway, which in turn forward all packets to internal LAN. (45792)
- Windows Secure Application Manager (WSAM) does not support NetBIOS file browsing on Vista SP1. (56414)
- If standalone WSAM Installer is installed on Vista, then launching of WSAM using IE will not work if JRE is not installed on the PC (54513).
- When using WSAM or Terminal Services to remotely connect to the enterprise network, if you want to access UAC (Juniper Networks' Unified Access Control) protected resources, you need to create a policy in UAC to treat traffic coming from the IVE as an unmanaged device. (52840)

Pocket PC

- Windows SAM options under Users > User Roles > *Select Role* > SAM > Options are not supported on Pocket PC. (45956)
- WSAM doesn't support client auth proxy settings in PAC files thru Firefox. (47769)
- By design, SAM UI sign-in does not support role selection. (44832)
- When using WSAM on the Treo, please disable the manual proxy on the device (46081)
- On a Cingular 8125 device when using WSAM on an ActiveSync connection, samizing access to public internet sites is not working. (48524)
- WSAM does not support two-tier Windows Mobile Smartphone devices. (56737)
- WSAM does not support Windows Live Messenger on Windows Mobile devices. (53871)
- To create application specific WSAM log file for an application already launched before WSAM is installed e.g. repllog.exe, please add the application name to the WSAM debug list and reboot the device. (52924).

FIPS

- If you replace an administrator card using option 10 in the serial console after upgrading a Secure Access Series FIPS appliance, the Security World is modified to use the new administrator card. If you then try to perform a “rollback,” the new administrator card does not work. This is because the “rollback” reverts to the original Security World, which is not yet configured to use the new administrator card. To activate the new administrator card, you must use option 10 on the serial console once again.
- Secure Access Series FIPS does not support automatic time synchronization across cluster nodes. We suggest that you configure your cluster nodes to use the same NTP server to ensure they are synchronized. If the cluster nodes are not synchronized, time-based features (such as Secure Meeting) do not function properly.
- If the HSM module switch is set to I on a FIPS-enabled Secure Access appliance, the machine is in “initialize” mode. Rebooting the appliance during this time reinitializes the server key and invalidates the current server certificate. Administrators must leave the switch at O during normal operation (as per the instructions on the serial console and in the documentation).
- To setup a WAN FIPS Cluster, it is recommended that the devices be configured at one site before sending the unit to the final location as the initial configuration requires the smart cards to be available.
- The FIPS Status LED on the front panel of the SA 4000 FIPS and SA 6000 FIPS product lines is reserved for future use. The device operates correctly under the FIPS specification regardless of the state of the LED.

MSP (IVS/VLAN)

- If a binary system configuration is imported with "include network settings" selected to an IVE with IVSs and VLANs, then existing VLANs will be replaced. This may leave an IVS with no Selected VLANs in its profile. To work around this issue, the IVS root admin must go into each individual IVS and reconfigure the "Selected VLANs" and mark the appropriate VLAN in each IVS as default. In addition, they need to go into each Role within each IVS and click on "Save changes" to ensure that the default VLAN configured for the IVS is correctly reflected in the Role's VLAN/Source IP settings. (41085)
- When an IVS license is added to an IVE that already has the VLAN license installed, the expected behavior is that all existing roles should get unbound from VLANs and access to backend resources via VLANs should fail after addition of IVE license. The actual behavior is that the admin UI presents the roles as being disassociated from their former VLANs, but user access to backend resources continues to work over VLAN interfaces. It takes an IVE reboot for backend access to fail as expected. (48240)

MSP administrator advisories:

- For MSP subscribers with logging requirements that exceed 1MB, the recommendation is to redirect the corresponding IVS logs to a syslog server rather than rely on native logging on the IVE. The syslog server could be a central server across multiple IVS systems, or a dedicated syslog server for a single IVS.
- When a binary system configuration (system.cfg) is imported into an IVE on which IVS's have been configured, the recommended binary import option is “Import everything except network settings and licenses.” This option preserves VLAN interfaces configured on the IVE. The option “Import everything except IP” should be avoided since it will result in overwriting the VLAN

interfaces on the IVE with the VLAN interfaces in the imported file, resulting in a mismatch between the VLANs in the IVS profile settings and the newly imported VLANs in the Network settings. (41085)

Java Secure Application Manager (JSAM)

- On Vista, NetBIOS File browsing does not work through JSAM. (44952)
- For JSAM on Vista, to support applications that require registry modifications, etc/hosts and etc/lmhosts modification, a UAC prompt labeled Juniper JSAM Tool will be displayed to enter admin credentials.
- JSAM fails to exit successfully (JSAM window does not close and hosts file is not restored) when two users use JSAM in the following manner: user A launches JSAM on a timed out session while user B logs into the login window and launches JSAM. (46033)
- The JSAM Autolaunch Policy has been enhanced so that JSAM will auto-launch if the configured URL matches a URL that is requested through the rewriter. Formerly, JSAM would auto-launch only if the URL was accessed from the IVE bookmarks page. The exact URL for which the JSAM is expected to launch should be entered as the resource. Including wildcards in the resource could result in the web page displaying incorrectly. (48851)
- The configuration where the JSAM autolaunch resource policy is the same as a PTP hostname is not supported. (48614)
- The restore system settings operation will not restore the hosts file successfully if you log in as a different user from the one that originally launched JSAM. (25828)
- If WINS server is being used for name server resolution then NetBIOS through JSAM is not supported. (43197)
- Internet Explorer 6.0 with the latest automatic updates does not support the auto-launching of the Citrix application when clicking on a published application through the IVE. This only affects configurations where the published application is accessed through JSAM. To work around this issue,
 - Add the IVE as a trusted site or
 - Go to Tools > Internet options > Security > Custom level button > Downloads. Enable "Automatic Prompting for file downloads". (43061)
- Internet Explorer 7.0 will not automatically launch JSAM when a user clicks on a published application on the Citrix Web Interface page. In order to tunnel Citrix traffic, the user must pre-launch JSAM before clicking on the published application. JSAM can be pre-launched in one of the following ways:
 - Select "Auto-launch Secure Application Manager" under Roles > <role Name> > SAM > Options. JSAM will automatically launch when the user logs into the IVE.
 - Create a Launch JSAM resource policy for IE 7 users. You can use detailed rules functionality to create this policy only for IE 7 users. To create a detailed rule, do the following:
 1. Set the resource to "*".
 2. Under Action, select "Detailed Rules" and click the Detailed Rules link.
 3. Click "New Rule". Under Resources, add the URL for the Citrix Web Interface login page. For example, "http://<Citrix server>/Citrix/MetaFrame/site/login.aspx".
 4. Under conditions, enter userAgent = '*MSIE 7*'. Click Save Changes. (43061)
- When using JSAM within SODA 2.6 (SODA build prior to 2237), the etc/hosts file does not get restored to its original state when JSAM is exited. The etc/hosts file does get restored with SODA

2.5 and with SODA 2.6 builds 2237 and greater. (37486)

- Outlook 2003 and Outlook 2007 are not supported with J-SAM. To work around this issue, use W-SAM or Network Connect. (8251)
- Netscape may lock up on users who close J-SAM. To work around this problem, users can add the following line to their "java.policy" file:

```
grant { permission java.security.AllPermission; };
```
- J-SAM does not automatically launch when Embedded Applications are set to "Auto" in the Citrix Web Interface. To work around this issue, configure J-SAM to launch automatically when user accesses the Citrix Web Interface login page.
- When using W-SAM and J-SAM, if a user has a pop-up blocker, that user may experience problems waiting for SAM to fully load. A pop-up window alerting the customer to accept the SAM plug-in may be waiting in the background behind the Internet browser.
- The application discovery functionality within Citrix Program Neighborhood is supported once port 80 is configured under J-SAM. However, if a user attempts to use the server discovery feature, which does not work through the IVE, and then attempts to use the application discovery again, the application discovery fails. The workaround is to restart Citrix Program Neighborhood. (8665)
- When Auto launch JSAM is configured for a PTP port mode web policy JSAM goes into infinite loop on Mac OS. (57144)
- Mac JSAM fails to upload logs when the user is authenticated to the SA using Siteminder authentication with the following message: "Uploading failed: It appears that you are not logged-in". (57742)
- Auto-Launch JSAM for a PTP URL will cause infinite loop on the client. Workaround is to Auto-Launch JSAM at start of user session.(57144)
- When JSAM is launched in Firefox 2.0.0.12 on Vista, and if UAC mode is on, user would see a message "You do not have permission to change hosts files. Please talk to your system administrator." This is expected behavior because UAC prohibits JAVA applet from changing host files. (55079)

Mac OS Specific J-SAM Items

- On Mac OS X 10.2.X, if the framed toolbar is configured then the JSAM autolaunch policy feature is not supported. (46594)
- When auto-launching J-SAM using Safari (versions prior to 1.2), J-SAM opens a new browser window to display the home page instead of updating the original window that launched J-SAM. This results in two open browser windows. This is due to a limitation in these versions of Safari. (21747)
- On a Mac OS X, the first time J-SAM is launched after rebooting the machine, the launch may fail. This is due to Apple's JVM code behavior. (Apple Bug #3860749) (21746)
- When running J-SAM on a Mac OS X client, if the user clicks "No" on the SSL certificate warning, the user must quit and restart the browser in order to launch J-SAM successfully.
- If the custom company logo image uploaded to the IVE is a .bmp file then the image will not display correctly on the J-SAM window on a Mac OS X using JVM 1.4. (25831)

Hardware

- On the SA6000, avoid hot-plugging RAID drive connect-disconnect-connect sequences that are

faster than 5 minutes. Doing so causes the system to accept the drive as healthy even if the drive has missed updates. (31583)

- After an upgrade, occasionally an SA6000 system could see inconsistent LED behavior where the RAID Status LED blinks in RED and the Hard Disk LED is not lit. This incorrect LED behavior is cosmetic and does not reflect the actual state of the system. It is caused by the fact that the system didn't initialize itself properly during soft reset. A cold restart will fix this problem. (35150)
- If an SA6000 goes from a two-drive configuration to a single-drive configuration (due to drive failure and/or removal) and is rebooted, the machine halts during boot and displays a serial console message similar to the following:

```
Adaptec Embedded SATA HostRAID BIOS V3.1-1 1255
(c) 1998-2004 Adaptec, Inc. All Rights Reserved.
<<< Press <Ctrl><A> for Adaptec RAID Configuration Utility! >>>
Controller #00: HostRAID-ICH5R at PCI Bus:00, Dev:1F, Func:02
Loading Configuration...Done.
Port#00 WDC WD800JD-00LSA0 06.01D06 74.53 GB Healthy
Following SATA device(s) are not present or responding:
Port#1

WARNING !!! Configuration Change(s) detected !!!
Press <Enter> to accept the current configuration or power off
the system and check the drive connections.
```

The user should hit Enter to continue using the machine with a degraded array until a replacement drive can be obtained.

- An SA6000 should NEVER be power-cycled or rebooted while rebuilding. If an SA6000 is rebooted while rebuilding the RAID array, the rebuild operation may never complete. This can be seen from the following BIOS screen on reboot:

```
Adaptec Embedded SATA HostRAID BIOS V3.1-1 1255
(c) 1998-2004 Adaptec, Inc. All Rights Reserved.

<<< Press <Ctrl><A> for Adaptec RAID Configuration Utility! >>>

Controller #00: HostRAID-ICH5R at PCI Bus:00, Dev:1F, Func:02
Loading Configuration...Done.
Port#00 WDC WD800JD-23JNA1 06.01C06 74.53 GB Healthy
Port#01 WDC WD800JD-23JNA1 06.01C06 74.53 GB Healthy

Array #0 - RAID-1 IVE 74.47 GB Building

1 Logical Device(s) Found
```

To recover from this condition, the machine should be fully booted into the IVE. The drive which had been previously replaced should be removed from the unit for 2 minutes and then re-inserted. After the drive is removed and re-inserted the RAID rebuild should proceed normally.

Secure Meeting

- We recommend that you do not upgrade the Meeting while Secure Meeting is running on

Macintosh or Linux machines. If an upgrade is performed during a Secure Meeting, Macintosh and Linux users might not be able to launch the client for a new meeting. This is due to Safari and Mozilla browser behavior related to caching Java applets. The user must close and restart the browser to fix the problem. (22273)

- Safari 1.0 has a bug wherein it does not fully support proxy configurations. As a result, if there is a proxy configured, the meeting client cannot be launched from this browser. We are working with Apple on this issue. (17550)
- Red Hat Linux 9 with Mozilla Firefox 1.6 and SunJVM 1.4 has a problem with NTLM authentication when using ISA proxy server to download the Secure Meeting .jar file. This causes the Secure Meeting client to download incorrectly. (17445)
- When using Mac OS X 10.3.3 and Safari 1.0, if the user clicks "No" on the certificate pop-up, the Secure Meeting client does not install. If the user wishes to try again, they must open a new Safari browser window. (17331)
- On a Windows platform, the meeting client picks up the proxy information from the Internet Explorer browser settings. Therefore, Secure Meeting works on other browsers only if the proxy setting is also configured in Internet Explorer. (17442)
- If the Hide Attendees option is enabled, a "Failed to change roles" message appears when granting annotation permissions to another attendee. (24417)
- In Fit To Window mode, attendees may sometimes see small blocks of mangled images in their Viewer window. (24427)
- A presenter using a Linux client is not supported over slow DSL. (24480)
- On Macintosh and Linux platforms, Fit to Window does not work well when the presenter changes the resolution while presenting. (24543)
- You should not start annotation in a remote control session. (24902)
- A presenter using a Linux client is not supported in a WAN environment. (24985)
- There are attendee viewing issues in a WAN environment with Linux presenting. (24986)
- There is a limitation on the areas where a Linux and Mac presenter can annotate. If the Linux or Mac presenter annotates over the application toolbar at the top or bottom of the screen, then the annotated objects in those areas are not displayed to the viewers. (25555)
- Part of the bottom of the presenter screen is truncated when viewed on a Linux or Mac viewer in Fit to Window mode. (26468)
- The Secure Meeting Toolbar does not work on the Linux KDE window manager if the attendee runs the Viewer in Full Screen mode. (26851)
- If there are no attendees, when a Linux or Macintosh presenter clicks on the Draw icon to enable annotation, the annotation session is not started. The presenter needs to click the Draw icon again after an attendee has joined the meeting. (27403)
- When the Hide Attendees option is enabled, the role information is not displayed next to the attendee name in the Chat window. (30633)
- Auto-scrolling in the viewer window on Mac or Linux can be slow at times. (31353)
- If a presenter starts sharing while the Hide Attendees option has been enabled and the presenter has ongoing private chats with other attendees, then the private chat tabs are disabled on Mac and Linux. On Windows, the private chat tabs are enabled, the presenter can click on them, and those private chat messages will be seen by other attendees. (31456)
- On Windows, auto-scrolling in the viewer window is incorrectly controlled by the auto-scroll

option under the presenter's preferences. Therefore, only when the presenter enables auto-scroll will the attendees on the Windows platform see auto-scrolling in their viewer window. (31602)

- During annotation, auto-scrolling in the viewer window is not working on Mac, Linux, and Windows platforms. (31603, 31604)
- On Windows, the chat messages do not reappear after the user un-hides the messages. (37868)
- Secure Meeting does not launch on Sygate Virtual Desktop if the Secure Meeting client is not already installed on the real desktop. (39413)
- There is an issue with Mozilla 1.6 such that if it is configured with an authenticated proxy, Secure Meeting will not launch. (39857)
- During annotation, the attendee lost the annotations when disconnected and reconnected. (40470)
- In Hide Attendees mode, annotation may not work well for conductor and presenter on Windows. (40869)
- When a Linux or Mac user is presenting and a Windows attendee is the remote controller, if the Windows attendee clicks on the Draw icon, he'll get an incorrect message "Request for control failed". The correct message should be he cannot annotate while sharing control of the presentation. (41217)
- On some Intel iMac systems, the toolbar continuously displays and hides once the toolbar is set to auto-hide. (41469)
- On Mac platform, when the attendee draws past the presenter's screen, vertical lines appear in his Viewer window. (41530)
- On Macintosh and Linux platforms, annotated objects are not scaled properly if attendee enables Fit to Window mode. (41992)
- If two or more attendees select the same annotated object and move it, the object will be move to an unexpected location. (41995)
- In the 6.0 release, the format of the notification email has been updated. In addition, if "Authentication Requirements" is not set to "Require secure gateway authentication", conductor will receive two URLs in the notification email: conductor should sign in to IVE using the "Conductor URL" and send the "Attendee URL" for attendees to join the meeting. (43346)
- During a remote control session involving non-English Windows OS, the characters typed by remote controller on presenter's desktop will not appear correctly. The workaround is for remote controller to select the IME to be language X on the presenter desktop and to select remote controller's own IME to English, then remote controller can type language X's characters into presenter desktop. (44684)
- On Windows platform, there is a delay in remote control in Fit To Window mode. (44708)
- "Select All" does not work in Customize Drawing Permissions window. (45612)
- In 6.0, Secure Meeting under Resource Policies has been moved to the Configuration page. (46969)
- If the remote controller changes the screen resolution on Mac or Linux presenter desktop, the presenter gets an error message "Could not share desktop. Contact your system administrator" and the remote controller gets disconnected. (47724, 21404)
- After the presenter enables "Hide Drawing" during annotation and an attendee on Mac/Linux joins the meeting, he is able to draw even though hide drawing mode is enabled. (47891)
- On Mac with JVM 1.4 or below, users have to point their mouse over the menu item to actually see the update state of the menu item. The workaround is to use JVM 1.5.x. (47924)

- On Vista platform, if the Viewer images are mangled, you can minimize/maximize or close/reopen the Viewer window to refresh the images. (48072)
- On Windows, chat messages are duplicated if the Secure Meeting disconnects and reconnects. (48210)
- On Windows platform, the presenter's "Take Control" button is not enabled if the presenter grants remote control to an attendee via "Controller" button. To take control back, the presenter should select his name and click on "Controller" button. (48212)
- After upgrading to 6.0, using the same browser window, the admin will see a javascript error when he clicks on the Meetings tab under Roles. The workaround is to sign in to IVE again or close and open a new browser. (48777)
- On Windows platform, when attendee enables Fit To Window mode on his Viewer, presenter's mouse cursor will be displayed with "wavy" or "fishbowl" effect as the presenter moves his mouse. (53025)
- If the services are restarted on an Active/Passive cluster, the active meeting clients may have to be re-launched. (50060)
- Attendees invited through the Secure Meeting Outlook Plugin are not listed in the meeting archived file. (53408)
- After presenter on Windows machine enables "Hide Drawing" during annotation, if an attendee joins the meeting, he will see the drawings on his Viewer window even though Hide Drawing mode is enabled. (55518)
- If Symantec's Confidence Online blocks the Secure Meeting client process on the presenter's machine, then attendees will see black screen appearing on their viewers. The presenter must unblock "dsCboxUI.exe" in the "Blocked List" tab in Confidence Online Application. (57020)
- On Mac or Linux, "Pause" sharing does not work. (57186)
- On Vista, the Secure Meeting application is run at medium integrity level. It will not be able to access other applications/processes running at higher integrity level. Therefore, remote controlling those applications/processes running at higher integrity level on a Vista machine will not work. (57667)
- Under Configuration->Secure Meeting, if "Sequential room number with prefix" has an empty room value in the XML document, when the XML document is imported back into SA device, the room value will default to value "room". (58571)
- Meetings that are scheduled on the DST start day and the DST end day are placed on a row that is one hour off from the actual meeting starting time. This is only a display problem. Meetings will start on correct scheduled time. (59607)
- When Outlook plug-in is installed through Firefox, the "User ID" and "Realm" fields are empty in the "Provide server details" page. These fields should be auto populated. (59778)

Secure Virtual Workspace (SVW)

- The Secure Virtual Desktop does not support real time Anti-Virus scan. (34385, 48587)
- When Host Checker remediation is configured for a Secure Virtual Workspace policy, the Try Again button on the end user remediation page will not launch Secure Virtual Workspace again. The workaround is to restart the browser and connect to the IVE again (36682).
- When SVW is configured to start before user authentication the end user will see the message "You do not have permission to login. Please contact your administrator" in the browser on the real desktop. This could be confusing as the end user can login to the IVE from within SVW. To avoid any confusion this message can be altered using the custom sign-in pages by customizing

the message for error code 1025 in SSL.shtml (37021).

- While in the Secure Virtual Workspace, Microsoft Word is DISABLED as a default editor for Microsoft Outlook. The default editor is going to be Wordmail instead of Microsoft Word. (37144)
- Multiple users using the same password to encrypt their SVW workspace on the same host could gain access to the persistent data storage protected by that static password. It is recommended that strong passwords be used when securing their SVW persistent data store on multi-user systems. (37311)
- SVW is configured using Host Checker's policy UI on the SSL-VPN Admin UI. SVW does not work in HC post-authentication mode. As part of Host Checker launch, SVW gets evaluated, and any evaluation of SVW will launch the SVW shell. (37438)
- Microsoft Outlook will work in SVW only when connecting to a Microsoft Exchange server through the MAPI protocol (40877).
- Some applications are single instance by design, such as Acrobat Reader. Because of this limitation, these applications can't be launched in the default desktop and inside SVW simultaneously. (43695)
- Application can not modify Local Machine registry keys inside SVW. Thus, all applications require modification in Local Machine during installation can't be installed inside SVW. If they are previously installed on the client machine, they can be launched inside SVW. (45899)
- When persistent data is configured for SVW, if the machine lost power or crashed (not graceful shutdown), the default desktop background is set to same as SVW desktop background. (51131).
- Attendee does not get a request for control denied message when the presenter denies the request for control. This happens when the presenter is running on Linux or Macintosh. (57161)
- In a Japanese OS, sometimes MS office 2007 can't be launched inside SVW. (56316)
- User may get an error message when viewing property of a file inside SVW. (56310)
- When Microsoft Exchange Outlook application is launched inside SVW, user may see a few error pop up messages. (56558)
- After Host Checker launches SVW, the browser page on real desktop shows "You do not have permission to login. Please contact your administrator." (37021)
- When Yahoo toolbar is installed, once SVW launches, user is switched back to real desktop. This is due to compatibility issue with Yahoo toolbar. User can manually switch back to SVW desktop. (53703)
- When the Google Toolbar is installed, and SVW is launched by a restricted user, IE in SVW launches very slowly. (53706)

System Administration and User Interface

System Status and Logs

- The format of the logs for system-generated events may show () and [], both of which can be ignored, as system events do not have an associated Realm or role name. (22321)
- When the Administrator reduces the maximum size of a log file on the IVE, if the log is already larger than the new maximum size, the log size will show a larger % value on the Status page under "Logging Disk % full". As soon as another log message is generated for that log file, the current log file is archived and a new log file is created. The display is momentarily incorrect due to this change.
- When an Admin IVE session times out (due to inactivity or by reaching the hard limit), the "sign

in again" link may take the Admin to the end-user sign in page instead of the Admin sign-in page. The Admin can simply type the Admin sign-in URL (for example, /admin) to sign back into the IVE Admin Console.

- If the custom Help page is blocked by an Access Control policy, then the standard error page is displayed with a link to "Return to previous page." This link does not work. (26077)
- The Dashboard graphs may not display properly if the IVE system time has been adjusted back too many hours or days in time before the data was recorded. (16920)
- The Web Proxy feature may only be configured for HTTP and HTTPS requests. When the Web Proxy feature is enabled, administrators should make sure to turn off HTTP proxy authentication (407-based) on the Web proxy. The IVE does not respond to 407-based authentication challenges from the Web proxy.
- The IVE no longer automatically enables hardware acceleration when the license is installed that enables the acceleration feature. The administrator must manually activate it on the serial console or Web interface.
- The hardware port status may not be correctly updated when the network port is not connected. (31987)
- The maximum log size of the sensor logs cannot be set when the IVE is upgraded from 5.2 or an earlier release (42185)
- The time to generate a system snapshot will increase dramatically if there are a lot of client connections and the DNS server is unreachable. (46642)
- Periodic snapshots will not be taken if the system configuration is imported without network settings from another SA. The workaround is to disable and then enable the periodic snapshot on the new SA again. (49585)

End-User Interface

- Welcome messages and portal name are displayed even if the greeting is disabled. (22728)
- If HTML tags are used in the notification message then the collapse/expand feature is not available. (22264)

Clustering

- The IVE does not support a common IP address pool for NC for an Active/Active cluster. In A/A NC deployments, the recommendation to the administrator is to split up the NC IP pool into node-specific sub-pools. Further, the administrator is advised to perform static route configuration on the backend router infrastructure in a coordinated fashion, with static routes to each sub-pool pointing to the internal IP address of the hosting cluster node as the next-hop gateway. (32829)
- When log synchronization is not turned on, the nodes that do not have a log archiving server configured will not archive the logs. (26182)
- After a certificate is de-associated with an interface, it must be deleted before the new certificate will be present on the interface. (42351)
- Changing the IP address of a cluster node can sometimes cause the cluster to not converge. (40046)
- When upgrading A/P cluster to 6.1, Admin might need to manually associate the device certificates to cluster internal and external VIPs in order for the device certificate to be presented to the right port. (48608)

- Admin UI will show just one IP address in virtual port configuration page, even though there may be more than one IP address configured for each cluster node. (48643)
- An A/P cluster loses the VIP if one of the nodes is removed from the cluster. (48857)
- Changing VLAN IP to different network could leave the VLAN virtual ports configuration in different network than the underlying VLAN. (48904)
- To migrate system and user configuration from an SA cluster C1 to a replacement cluster C2 with different type of SA machines, follow the steps listed below: (54213)

1. Export the system user and ivs configuration from C1's primary node (PN1).

Note down the following information

- Cluster name – C_Name
 - cluster password - C_Password
 - Name of the node where export was done - PN_Name
 - Internal IP address of PN1 – PN_InternalIP
 - Internal network mask of PN1 - PN_InternalNetmask
 - Internal network gateway of PN1 - PN_InternalGateway
 - Names of all other nodes in the C1 cluster and their internal network IP address, network masks and gateways
2. Shut down the machines in the existing cluster C1.
 3. Bring up one of the new machine (which should already be running a software release 6.1R1 or newer) that will be part of the cluster C2 on the same network to which PN1 was attached. Let's call this machine PN2.
 4. When prompted configure the internal network settings of PN2 to exactly match the internal network settings of PN1 as noted down in Step 2.
 5. Install the new primary licenses on PN2.
 6. Navigate to the Admin UI Clustering tab and click on Create Cluster. Create the cluster C2 using the exact same cluster name and cluster password that were in use at cluster C1. This first cluster node PN2 must also be assigned the name PN_Name as noted down in Step 2.
 7. Navigate to the cluster status page and add the remaining nodes to the cluster configuration. Nodes being added must be assigned exactly the same names that existed in original cluster C1. The internal network settings of the newly added nodes must also exactly match the corresponding settings in the original cluster C. **Do not join the newly added nodes to the cluster C2 yet.**
 8. Import the data exported in step 1 into the new cluster Node PN2.
 - Import the system configuration – pick the option “Import everything (except Device Certificate(s))”
 - Import the device certificates
 - Import user accounts
 - Import any ivs settings
 9. Bring up the remaining new machines, configure the bare minimal internal network settings needed to bring up the machine – the network settings must match what has already been configured in the cluster C2 on node PN2. Do not do make any other configuration changes on

these machines as they will be lost when these machines join the cluster. Do not add licenses on these machines yet.

10. Join the machines brought up in step 9 to the cluster, wait for the cluster status to stabilize.
 11. Install the CL licenses on the newly joined nodes.
- Network settings part of the system configuration exported from a cluster can not be imported into another cluster with a different cluster configuration. To import system configuration including network settings previously exported from a cluster back into the same cluster, the administrator must ensure that the import operation is initiated at the same node from which the system configuration was exported. Note that during the import operation nodes in the cluster will be disabled and enabled internally. In general it is preferable to exclude network settings when importing system configuration in a running cluster. (55054)
 - Cluster may split into two different cluster configurations when adding/joining/deleting a node in a WAN cluster under heavy load. (48743)
 - Administrator will not be able to install any new license on a cluster primary node if all the licenses are deleted first. (56077)

Terminal Services

- In releases prior to 6.0, the "Connect local XXX resources" options defined under Roles > Terminal Services > Options had two functions: first it determined if this option was visible in an end-user bookmark; second it determined whether the local resource would be available for all users of this role. Therefore this role-level option overrode a similar option in the admin bookmark. This behavior has been changed to clarify the use of these options. In 6.0 the role level options determine if this option will be visible in an end-user bookmark. To support this new behavior, the following changes will be made during an upgrade: if a terminal services resource profile is associated with multiple roles and their individual role level settings conflict then these corresponding options in all the bookmarks defined under these roles will be disabled. Therefore it is possible that user in a pre-6.0 release had access to local resources and does not have access after the upgrade to 6.0. If the end-user behavior could vary after an upgrade then the change is logged in the admin access logs. (47028)
- If the user is mapped to two roles, one configured to use CTS to run applications on the Citrix Web Interface (through Citrix WI web resource profile) and the other configured to use JSAM or WSAM to run applications, then IVE will use the CTS client to run the applications on the Citrix Web Interface (45629)
- The Terminal Services feature supports local drive mapping, but cannot support it on Windows 2000 due to a Microsoft limitation. (Windows 2000 does not allow drive mapping via RDP clients.) Until Microsoft establishes a fix, local drive mapping will work only on Win2K3.
- Citrix Java applets will not work on Mac OS X unless a production Web server certificate has been uploaded to the IVE. (25264)
- When creating a Windows or Citrix terminal services session on the SA device, a greater number of color depths are listed than what the RDP or ICA client supports. Please check the client documentation for supported color depths. (41027)
- The Citrix client version 10.2 and 10.0 are 7.8MB and 4.8Mb respectively in size. The user session might hit idle time out for those coming from slow connections while downloading the Citrix client. Customers are advised to use a sufficiently large timeout to avoid this problem (46104)

- From IVE 5.5 onwards, Windows Terminal Services uses mstscax.dll on Windows Vista to launch the terminal services session in both the SSO and non-SSO cases. End users should not remove this DLL from their Windows Vista machines or otherwise Windows Terminal Services will not work (42450)
- Netscape may freeze when users close Secure Terminal Access (STA). To resolve this issue, users can add the following line to their java.policy file:

```
grant { permission java.security.AllPermission; };
```
- Creating a Citrix Terminal Services session using a custom ICA file will not work if there is already a Citrix Terminal Services session in the role that is having the same name for the Custom ICA file. Use a different file name for the ICA file to work around the problem. (41475)
- When using Windows Terminal Services with ThinPrint client on Vista, you need to use ThinPrint client's Vista compatible version. (45748)
- When using Web Citrix resource profile with "launch using CTS" option, the "connect all disconnected sessions" feature may not work at times. (54816)
- When a terminal services profile is duplicated, it does not create the supporting policies (ACL) for the new profile. (56832)
- SSO fails if a domain name contains '-' in the Citrix listed applications. (58240)
- When using Windows or Citrix Terminal Services through IVE, if the secure connection is left idle for 5 minutes, the connection will be terminated automatically. (57836)
- XML export does not export the "Launch Seamless Application" option for a WTS bookmark. This option is under Users->Roles-><ROLE>->Terminal Services->Terminal Services sessions-><WTS Bookmark>. (57191)

Telnet/SSH

- When using Secure Terminal Access (STA), the user must first click in the Java Applet window to set the focus. Then, the user may begin typing and using the Telnet/SSH functionality.
- When using the [Tab] + [Enter] key in IE 7 in a telnet/ssh window, the main telnet/ssh window loses focus. To work around this issue, configure IE to allow the telnet/ssh window to open without an address bar.
 - Choose Tools->Internet Options->Security.
 - Click "Custom level...".
 - Scroll down to the "Miscellaneous" section.
 - Click "Enable" under "Allow websites to open windows without address or status bars". (46143)
- Telnet/ssh window configured with screen size 132*60 and font size 36 pixels does not work well. The stop button is missing and scrolling does not work. (49440)
- Telnet/SSH bookmarks can not have duplicate names. So if older versions have bookmarks with duplicate names created the upgrade process will modify the names to make them unique. Ex: BookmarkA, BookmarkA would become 1-BookmarkA, 2-BookmarkA. (51949)

Supported Platforms

Please see the "Supported Platforms" document posted on the Juniper Networks Support Site (<http://www.juniper.net/support/>) under "IVE OS" for a current list of supported platforms (operating system/browser combinations). Note that some platforms do not completely conform to HTTP standards,

so we have tested IVE functionality with the most common operating system/browser configurations used for the specific functionality. The “Supported Platforms” document summarizes the functionality tested, our testing model, and the supported platforms for the Neoteris IVE.

To open a case or to obtain support information, please visit the Juniper Networks Support Site: <http://www.junipernet/support>.

Supported NSM releases

The 6.3R1.1 release will be manageable via the NSM release 2008.1r2 and later releases. NSM management of 6.3R1.1 via NSM release 2008.1r1 is not supported.