

Release Notes for CBA850 3G/4G/LTE Wireless WAN Bridge

Firmware Version 6.0.2

USB Modems Tested:

- Cradlepoint MC400LE2-SP / Sprint (USA)
- Cradlepoint MC400LPE-AT / AT&T (USA)
- Cradlepoint MC400LPE-GN / T-Mobile, C-Spire, US Cellular (USA); Bell Mobility, Rogers, Telus (Canada)
- Cradlepoint MC400LPE-SP / Sprint (USA)
- Cradlepoint MC400LPE-VZ / Verizon (USA)
- Cradlepoint MC400LP3-EU / EE (UK), Vodafone (UK, Germany), Tele2 (Sweden), Telia (Sweden)
- Franklin U770 (“Sprint Plug-In-Connect Tri-Mode USB Modem”) / Sprint (USA)
- Huawei E3276 / Telus (Canada)
- Huawei E368 (“AT&T USBConnect Force 4G”) / AT&T (USA)
- Netgear AC340U (“AT&T Beam”) / AT&T (USA)
- Netgear AC341U (“NETGEAR® 341U USB Modem”) / Sprint (USA)
*supports Netgear firmware 4.07.01.11 and MR2 firmware 45.04.20.00
- Novatel 551L LTE (“Verizon USB551L”) / Verizon (USA)
- Novatel U620L (“Verizon MiFi® 4G LTE Global USB Modem U620L”) / Verizon (USA)
- Novatel U679 (“4G LTE Novatel Wireless U679 Turbo Stick”) / Bell Mobility (Canada)
- Pantech UML295VW (“Verizon 4G LTE USB Modem UML2954G LTE”) Verizon (USA)
*requires Pantech firmware version L0295VWD821F.B4 or later
- Portsmouth PSA1U1M (“Portsmouth USB Client to Analog Modem Adapter”) / POTS phone providers
- Sierra Wireless 308 USB (“AT&T USBConnect Shockwave”) / AT&T (USA)
- Sierra Wireless 313U (“AT&T USBConnect Momentum 4G”) / AT&T (USA)
- Sierra Wireless 320U (“Telstra USB 4G (Sierra AirCard 320U)”) / Telstra (Australia)
- Sierra Wireless 330U (“4G LTE Sierra Wireless U330 - Turbo Stick”) / Bell Mobility (Canada)
- Sierra Wireless 330U (“LTE Rocket Stick – Sierra Wireless AirCard 330U”) / Rogers (Canada)

- ZTE MF683 (“T-Mobile Rocket 3.0 4G Laptop Stick”) / T-Mobile (USA)