

## Requirements for Importing a Secure Access Device into NSM Through a Reachable Workflow

---

Adhere to the following requirements to import a Secure Access device into NSM through a reachable workflow:

- The inbound DMI connection must be enabled in the Secure Access device.
- SSH port must be configured in the Secure Access device. The default SSH port is 22.
- The DMI agent admin realms must be configured and an admin user must be mapped to a role with full admin privileges.

- Related Topics**
- Adding a Secure Access Device Through a Reachable Workflow
  - Verifying Imported Device Configurations

---

Published: 2009-08-20