

Synchronizing System Clocks

The system clock in the e30 Switch must keep synchronized with the SAE. Make sure that the system clock of the Ellacoya switch does not use daylight savings mode.

- Related Topics**
- Provisioning the IPSCS
 - Integration of the SRC Software and the Ellacoya DPI Platform

