

Midplane Energy Hazard Warning for M Series, MX Series, and T Series Routers



WARNING: High levels of electrical energy are distributed across the router midplane. Be careful not to contact the midplane connectors, or any component connected to the midplane, with any metallic object while servicing components installed in the router.

- Related Topics**
- General Electrical Safety Guidelines and Warnings Electrical Codes for M Series, MX Series, and T Series Routers
 - Grounded Equipment Warning for M Series, MX Series, and T Series Routers
 - Multiple Power Supplies Disconnection Warning for M Series, MX Series, and T Series Routers
 - Power Disconnection Warning for M Series, MX Series, and T Series Routers
 - TN Power Warning for M Series, MX Series, and T Series Routers
-

Published: 2009-08-03