

Create a Physical Loopback

Action To create a physical loopback at the port, connect the transmit port to the receive port.

Meaning When you create and test a physical loopback, you are testing the transmit and receive ports of the PIC. This action is recommended if a field engineer is available to create the physical loop as it provides a more complete test of the PIC.

Published: 2010-01-29