

## Assigning CoS Components to Interfaces (CLI Procedure)

---

After you have defined the following CoS components, you must assign them to logical or physical interfaces. (Only these three types of CoS components get assigned to interfaces.)

- Forwarding classes—Assign only to logical interfaces.
- Classifiers—Assign only to logical interfaces.
- Scheduler maps—Assign to either physical or logical interfaces.

To assign CoS components to interfaces, associate a CoS component (scheduler map named `ethernet-cos-map`) with an interface (`ge-0/0/20`):

**[edit class-of-service interfaces]**

```
user@switch# set ge-0/0/20 scheduler-map ethernet-cos-map
```

### Related Topics

- [Assigning CoS Components to Interfaces \(J-Web Procedure\)](#)
- [Example: Configuring CoS on EX-series Switches](#)
- [Monitoring Interfaces That Have CoS Components](#)
- [Understanding JUNOS CoS Components for EX-series Switches](#)

