

Cabling the CTP Platform Overview

Cabling the CTP platform requires the following main tasks:

1. Familiarize yourself with the module ports, and ensure that you have the cables and wires needed to complete each cabling procedure.
2. Read and understand all safety warnings. (See CTP Safety Guidelines and Warnings.)
3. Connect timing ports.
4. Connect grounding wires to the chassis.
5. Connect the power cables from the power source to the power supply.
6. Connect the interface modules to their appropriate network interface.

- Related Topics**
- CTP Cabling Recommendations
 - Required Tools, Wires, and Cables for the CTP Platform
 - CTP2000 Management Ports
 - Cabling a CTP Interface Module
 - Cabling the CTP Platform for DC Power

Published: 2010-04-18