

Viewing Graphs (C-Web Interface)

You can display graphs for components for which the Activity Monitor has collected data.

To display graphs from the Activity Monitor with the C-Web interface:

1. Click **Graphs**.
2. In the side pane, select the component and the graph that you want to display.

The pane for selecting the time period displayed by the graph appears.

3. Select one of the preset values or enter the time range in the From and To boxes, and click **OK**.

The graphs appear.

- Related Topics**
- Performing Data Collection with the Activity Monitor (C-Web Interface)
 - Viewing Graphs from a Web Page
 - Monitoring Activity on C-series Controllers

