

# Release Notes: Junos<sup>®</sup> OS Release 14.1X53-D10 for the EX Series and QFX Series

Release 14.1X53-D10  
28 October 2014  
Revision 4

## Contents

Junos OS Release Notes for EX Series Switches . . . . .	4
New and Changed Features . . . . .	4
Authentication and Access Control . . . . .	4
Bridging and Learning . . . . .	5
Class of Service . . . . .	7
Infrastructure . . . . .	7
Interfaces and Chassis . . . . .	10
J-Web . . . . .	10
Layer 3 Protocols . . . . .	11
MPLS . . . . .	11
Network Management and Monitoring . . . . .	12
Port Security . . . . .	13
Virtual Chassis and Virtual Chassis Fabric . . . . .	14
Known Behavior . . . . .	14
J-Web . . . . .	14
Multicast Protocols . . . . .	15
Virtual Chassis and Virtual Chassis Fabric . . . . .	15
Known Issues . . . . .	15
Class of Service . . . . .	16
Interfaces and Chassis . . . . .	16
J-Web . . . . .	16
Layer 3 Protocols . . . . .	17
MPLS . . . . .	17
Multicast Protocols . . . . .	17
Network Management and Monitoring . . . . .	17
Port Security . . . . .	17
Virtual Chassis and Virtual Chassis Fabric . . . . .	18

Documentation Updates . . . . .	18
Bridging and Learning . . . . .	18
Migration, Upgrade, and Downgrade Instructions . . . . .	19
Upgrade and Downgrade Support Policy for Junos OS Releases . . . . .	19
Product Compatibility . . . . .	19
Hardware Compatibility . . . . .	20
Junos OS Release Notes for the QFX Series . . . . .	20
New and Changed Features . . . . .	20
Authentication and Access Control . . . . .	21
Bridging and Learning . . . . .	21
High Availability . . . . .	23
Infrastructure . . . . .	23
Interfaces and Chassis . . . . .	26
Layer 3 Features . . . . .	26
MPLS . . . . .	27
Network Management and Monitoring . . . . .	28
OpenFlow . . . . .	29
Open vSwitch Database (OVSDB) . . . . .	29
Security . . . . .	29
Software Installation . . . . .	29
Virtual Chassis and Virtual Chassis Fabric . . . . .	30
VXLAN . . . . .	31
Known Behavior . . . . .	31
Interfaces and Chassis . . . . .	31
MPLS . . . . .	31
OpenFlow . . . . .	32
OVSDB . . . . .	32
Routing Policy and Firewall Filters . . . . .	33
Storage and Fibre Channel . . . . .	33
Traffic Management . . . . .	34
Virtual Chassis and Virtual Chassis Fabric . . . . .	38
Known Issues . . . . .	38
Interfaces and Chassis . . . . .	39
MPLS . . . . .	39
Multicast Protocols . . . . .	39
OVSDB . . . . .	39
Software Installation and Upgrade . . . . .	39
Virtual Chassis and Virtual Chassis Fabric . . . . .	40
VXLAN . . . . .	40
Documentation Updates . . . . .	41
Bridging and Learning . . . . .	41
Network Management and Monitoring . . . . .	41
Migration, Upgrade, and Downgrade Instructions . . . . .	41
Upgrading Software on QFX5100 Standalone Switches . . . . .	41
Performing an In-Service Software Upgrade (ISSU) . . . . .	43
Preparing the Switch for Software Installation . . . . .	43
Upgrading the Software Using ISSU . . . . .	44
Product Compatibility . . . . .	45
Hardware Compatibility . . . . .	45

---

Third-Party Components .....	46
Finding More Information .....	46
Documentation Feedback .....	46
Requesting Technical Support .....	47
Self-Help Online Tools and Resources .....	47
Opening a Case with JTAC .....	47
Revision History .....	48

## Junos OS Release Notes for EX Series Switches

---

These release notes accompany Junos OS Release 14.1X53 for the EX Series. They describe new and changed features, limitations, and known and resolved problems in the hardware and software.

You can also find these release notes on the Juniper Networks Junos OS Documentation webpage, located at <http://www.juniper.net/techpubs/software/junos/>.

- [New and Changed Features on page 4](#)
- [Known Behavior on page 14](#)
- [Known Issues on page 15](#)
- [Documentation Updates on page 18](#)
- [Migration, Upgrade, and Downgrade Instructions on page 19](#)
- [Product Compatibility on page 19](#)

### New and Changed Features

This section describes the new features and enhancements to existing features in Junos OS Release 14.1X53-D10 for the EX Series.

- [Authentication and Access Control](#)
- [Bridging and Learning](#)
- [Class of Service](#)
- [Infrastructure](#)
- [Interfaces and Chassis](#)
- [J-Web](#)
- [Layer 3 Protocols](#)
- [MPLS](#)
- [Network Management and Monitoring](#)
- [Port Security](#)
- [Virtual Chassis and Virtual Chassis Fabric](#)

#### [Authentication and Access Control](#)

---

- **IPv6 for RADIUS AAA (EX3300, EX4200, EX4300, EX4500, and EX8200 switches and EX4300 Virtual Chassis)**—Starting with Junos OS Release 14.1X53-D10, EX3300, EX4200, EX4300, EX4500, and EX8200 switches and EX4300 Virtual Chassis support IPv6, along with the existing IPv4 support, for user authentication, authorization, and accounting (AAA) using RADIUS servers.

RADIUS authentication is a method of authenticating users who attempt to access the router or switch. To use RADIUS authentication on the switch, configure information about one or more RADIUS servers on the network by including one **radius-server** statement at the **[edit system]** hierarchy level for each RADIUS server.

When you configure a source address for each configured RADIUS server, each RADIUS request sent to a RADIUS server uses the specified source address.

- **Authentication**—Specify which source address Junos OS uses when accessing your network to contact an external RADIUS server for authentication. You configure the IPv6 source address for RADIUS authentication at the **[edit system radius-server server-address source-address]** hierarchy level.
- **Accounting**—Specify which source address Junos OS uses when contacting a RADIUS server for sending accounting information. You configure the IPv6 source address for RADIUS authentication at the **[edit system accounting destination radius server server-address source-address]** hierarchy level.

[See [source-address](#).]

### Bridging and Learning

- **RVI support for private VLANs (EX8200 switches and EX8200 Virtual Chassis)**—Starting with Junos OS Release 14.1X53-D10, you can configure a routed VLAN interface (RVI) on an EX8200 switch or EX8200 Virtual Chassis to handle the Layer 3 traffic of intersecondary VLANs (community VLANs and isolated VLANs) in a private VLAN (PVLAN). By using an RVI to handle the routing within the PVLAN, you eliminate the need for an external router with a promiscuous port connection to perform this function.

One RVI serves the entire PVLAN domain regardless of whether the domain consists of one or more switches. After you configure the RVI, Layer 3 packets received by the secondary VLAN interfaces are mapped to and routed by the RVI.

[See [Configuring a Routed VLAN Interface in a Private VLAN \(CLI Procedure\)](#).]

- **Support for private VLANs (EX4300)**—Starting with Junos OS Release 14.1X53-D10, EX4300 switches support private VLANs (PVLANS). PVLANS are useful for restricting the flow of broadcast and unknown unicast traffic and for limiting the known communication between known hosts. PVLANS can be used to help ensure the security of service providers sharing a server farm, or to provide security to subscribers of various service providers sharing a common metropolitan area network.



**NOTE:** An interface can belong to only one PVLAN domain.

[See [Understanding Private VLANs on EX Series Switches](#).]

- **Support for Layer 2 protocol tunneling (EX4300)**—Starting with Junos OS Release 14.1X53-D10, EX4300 switches support Layer 2 protocol tunneling (L2PT). L2PT enables service providers to send Layer 2 protocol data units (PDUs) across the provider's cloud and deliver them to Juniper Networks EX Series Ethernet Switches that are not part of the local broadcast domain. This feature is useful when you want to run Layer 2 protocols on a network that includes switches located at remote sites that are connected across a service provider network. For example, it can help you provide transparent LAN services over a metropolitan Ethernet infrastructure. L2PT operates

under the Q-in-Q tunneling configuration; therefore, you must enable Q-in-Q tunneling before you can configure L2PT.

The Layer 2 protocol to be tunneled can be one of the following: 802.3AH, CDP, LACP, LLDP, MVRP, STP, VTP, GVRP, or VSTP.



**NOTE:** L2PT does not support the following on EX4300 switches:

- **drop-threshold or shutdown-threshold statements**
- **The all option for setting the Layer 2 protocol**
- **802.1X authentication**

[See [Understanding Layer 2 Protocol Tunneling on EX Series Switches](#).]

- **MAC notification (EX4300 and EX4600)**—Starting with Junos OS Release 14.1X53-D10, MAC notification is supported on EX4300 and EX4600 switches. The switches track clients on a network by storing MAC addresses in the Ethernet switching table on the switch. When switches learn or unlearn a MAC address, SNMP notifications can be sent to the network management system at regular intervals to record the addition or removal of the MAC address. This process is known as MAC notification.

The MAC Notification MIB controls MAC notification for the network management system.

The MAC notification interval defines how often these SNMP notifications are sent to the network management system. The MAC notification interval works by tracking all MAC address additions or removals on the switch over a period of time and then sending all tracked MAC address additions or removals to the network management server at the end of the interval.

Enabling MAC notification allows you to monitor the addition and removal of MAC addresses from the Ethernet switching table remotely using a network management system. The advantage of setting a high MAC notification interval is that the amount of network traffic is reduced because updates are sent less frequently. The advantage of setting a low MAC notification interval is that the network management system is better synchronized with the switch.

Two new MIBs related to MAC notification are provided at Junos OS Release 14.1X53-D10. See *Documentation Updates*.

[See [Configuring MAC Notification \(CLI Procedure\)](#).]

- **Default VLAN and multiple VLAN range support (EX4300)**—Starting with Junos OS Release 14.1X53-D10, the default VLAN and multiple VLAN range are supported on EX4300 switches. They provide the ability for the switch to operate as a *plug and play* device and connect to various Ethernet-enabled devices in a small, scaled enterprise network. When the switch boots, a VLAN named **default** is created. The default VLAN is automatically created for the default routing instance named **default-switch**. All interfaces on the switch are automatically configured as access interfaces and are part of the default VLAN.

The default VLAN accepts and forwards untagged packets only and is preconfigured with a VLAN ID (**vlan-id**) of 1. The default VLAN does not support a VLAN ID list (**vlan-id-list**), **vlan-id** set to **all**, or **vlan-id** set to **none**. You can configure the VLAN ID to be another value, but the value must be between 1 and 4093.

Access interfaces that are enabled for VoIP or 802.1X are internally converted to trunk interfaces, so that the interfaces can belong to multiple VLANs. If the interfaces do not belong to a valid VLAN, the interfaces automatically become part of the default VLAN.

You can configure more than one VLAN range, and each range can contain unique VLAN properties.



**NOTE:** Virtual Chassis interfaces cannot be preconfigured to belong to the default VLAN or any other VLAN.



**NOTE:** For interfaces to be part of the default VLAN, you must configure the interfaces to be part of the Ethernet switching family. You can configure Ethernet switching at the [edit interfaces *interface-name* unit family] CLI hierarchy level.

## Class of Service

- **Explicit congestion notification (ECN) support (EX4300)**—Starting with Junos OS Release 14.1X53-D10, ECN marking is supported on EX4300 switches—you enable it for packets in scheduler queues. Explicit congestion notification (ECN) enables end-to-end congestion notification between two endpoints on TCP/IP based networks. The two endpoints are an ECN-enabled sender and an ECN-enabled receiver. ECN must be enabled on both endpoints and on all intermediate devices between the endpoints for ECN to work properly. Any device in the transmission path that does not support ECN breaks the end-to-end ECN functionality.

ECN notifies networks about congestion with the goal of reducing packet loss and delay by making the sending device decrease the transmission rate until the congestion clears, without dropping packets.

To enable ECN, issue the **set class-of-service schedulers *name* explicit-congestion-notification** command.

## Infrastructure

- **Licensing enhancements (EX Series)**—Starting with Junos OS Release 14.1X53-D10, licensing enhancements on EX Series switches enable you to configure and delete license keys in a Junos OS CLI configuration file. The license keys are validated and installed after a successful commit of the configuration file. If a license key is invalid, the commit fails and issues an error message. You can configure individual license keys or multiple license keys by issuing Junos OS CLI commands or by loading the license key configuration contained in a file. All installed license keys are stored in the **/config/license/** directory.

To install an individual license key in the Junos OS CLI, issue the **set system license keys key *name*** command, and then issue the **commit** command.

For example:

```
[edit]
root@switch# set system license keys key "JUNOS_TEST_LIC_FEAT aeaqeb qbmqds
qwwsxe okyvou 6v57u5 zt6ie6 uwl3zh assvnu e2ptl5 soxawy vtfh7k axwnno m5w54j
6z"
root@switch# commit
commit complete
```

To verify that the license key was installed, issue the **show system license** command.

For example:

```
root@switch> show system license
License usage:

Feature name          Licenses used  Licenses installed  Licenses needed  Expiry
-----
sdk-test-feat1       0             1                   0
permanent

Licenses installed:
License identifier: JUNOS_TEST_LIC_FEAT
License version: 2
Features:
  sdk-test-feat1    - JUNOS SDK Test Feature 1
  permanent
```

To install multiple license keys in the Junos OS CLI, issue the **set system license keys key *name*** command, and then issue the **commit** command.

For example:

```
[edit]
root@switch# set system license keys key "key_1"
set system license keys key "key_2"
set system license keys key "key_2"
set system license keys key "key_4"
root@switch# commit
commit complete
```

To verify that the license key was installed, issue the **show system license** command.

To install an individual license key configuration in a file, issue the **cat** command:

For example:

```
[edit]
root@switch%cat license.conf
system {
  license {
    keys {
      key "JUNOS_TEST_LIC_FEAT aeaqeb qbmqds qwwsxe okyvou 6v57u5 zt6ie6
uwl3zh assvnu e2ptl5 soxawy vtfh7k axwnno m5w54j 6z";
    }
  }
}
```

Load and merge the license configuration file.



For example:

```
[edit]
root@switch# load merge license.conf
load complete
```

Issue the **show | compare** command to see the configuration, and then issue the **commit** command.

For example:

```
[edit]
root@switch# show | compare
[edit system]
+ license {
+   keys {
+       key "JUNOS_TEST_LIC_FEAT aeaqeb qbmqds qwwsxe okyvou 6v57u5
zt6ie6 uw13zh assvnu e2pt15 soxawy vtfh7k axwnno m5w54j 6z";
+   }
+ }
[edit]
root@switch# commit
```

To verify that the license key was installed, issue the **show system license** command.

For example:

```
root@switch> show system license
License usage:
```

	Licenses	Licenses	Licenses	Expiry
Feature name	used	installed	needed	
sdk-test-feat1	0	1	0	
permanent				

```

Licenses installed:
License identifier: JUNOS_TEST_LIC_FEAT
License version: 2
Features:
  sdk-test-feat1  - JUNOS SDK Test Feature 1
  permanent
```

To install multiple license keys in a file, issue the **cat** command:

For example:

```
[edit]
root@switch%cat license.conf
system
{
  license
  {
    keys
    {
      key "key_1"
      key "key_2"
      key "key_3"
      ...
      key "key_n"
    }
  }
}
```

Load and merge the license configuration file, and then issue the **commit** command.

For example:

```
[edit]
root@switch# load merge license.conf
load complete
[edit]
root@switch# commit
```

To verify that the license key was installed, issue the **show system license** command.

You can also delete or deactivate individual and multiple license keys in the Junos OS CLI by issuing the **delete system license keys** or **deactivate system license keys** commands. Do not use the **request system license delete** command to delete the license keys.

For example, to issue the **delete system license keys** command:

```
[edit]
root@switch# delete system license keys
root@switch# commit
```

---

## Interfaces and Chassis

- **Support for aggregated Ethernet link protection enhancements (EX4500)**—Starting with Junos OS Release 14.1X53-D10, aggregated Ethernet link protection is enhanced on EX4500 switches to support a collection of Ethernet links within a LAG bundle. Link protection could previously be used to protect a single link within a LAG bundle only. The ability to provide link protection for a collection of links in a LAG bundle is provided using link protection subgroups, which are introduced as part of this feature.

[See [Configuring LACP Link Protection of Aggregated Ethernet Interfaces \(CLI Procedure\)](#).]

---

## J-Web

- **J-Web interface available in two packages (EX2200, EX3200, EX3300, EX4200, EX4300, EX4500, EX4550, EX6200)**—Prior to this release, the J-Web interface was available as a single package as part of Junos OS. Starting with Junos OS Release 14.1X53-D10, the J-Web interface is available in two packages:
  - The Platform package is installed as part of Junos OS, which provides basic functionalities of J-Web. You can use the Platform package to create a basic configuration and maintain your EX Series switch.
  - The Application package is an optionally installable package, which provides complete functionalities of J-Web that enable you to configure, monitor, maintain, and troubleshoot your switch. You must download the Application package and install it over the Platform package on your switch.

For detailed information about the J-Web packages, see [Release Notes: J-Web Application Package Release 14.1X53-A1 for Juniper Networks EX Series Ethernet Switches](#).

- **Browser support enhancements for the J-Web interface (EX2200, EX3200, EX3300, EX4200, EX4300, EX4500, EX4550, EX6200)**—Starting with Junos OS Release 14.1X53-D10, the J-Web interface supports the following browsers:

- Microsoft Internet Explorer versions 9 and 10
- Mozilla Firefox versions 24 through 30
- Google Chrome versions 27 through 36



**TIP:** For best viewing of the J-Web application, set the screen resolution to 1440 X 900.

### Layer 3 Protocols

- **IS-IS protocol (EX3300)**—EX3300 switches now support the Intermediate System-to-Intermediate System (IS-IS) protocol. On EX3300 switches, the IS-IS configuration is available at the **[edit protocols]** hierarchy level.

[See [Layer 3 Protocols Supported on EX Series Switches](#).]

### MPLS

- **Ethernet-over-MPLS (L2 circuit) (EX4600)**—Starting with Junos OS Release 14.1X53-D10, Ethernet-over-MPLS is supported on EX4600 switches. Ethernet-over-MPLS enables you to send Layer 2 Ethernet frames transparently over an MPLS cloud. Ethernet-over-MPLS uses a tunneling mechanism for Ethernet traffic through an MPLS-enabled Layer 3 core. It encapsulates Ethernet protocol data units (PDUs) inside MPLS packets and forwards the packets, using label stacking, across the MPLS network.

This technology has applications in service provider, enterprise, and data center environments. For disaster recovery purposes, data centers are hosted in multiple sites that are geographically distant and interconnected using a WAN network. These data centers require Layer 2 connectivity between them for the following reasons:

- To replicate the storage over Fibre Channel over IP (FCIP). FCIP works only on the same broadcast domain.
  - To run a dynamic routing protocol between the sites.
  - To support high availability clusters that interconnect the nodes hosted in the various data centers.
- **MPLS-based Layer 3 VPNs (EX4600)**—Starting with Junos OS Release 14.1X53-D10, MPLS-based Layer 3 VPNs are supported on EX4600 switches.

Customer networks are private and can use either public addresses or private addresses. When customer networks that use private addresses connect to the public Internet infrastructure, the private addresses might overlap with private addresses being used by other network users. MPLS BGP VPNs solve this problem by adding the route distinguisher prefix to the route.

You can configure the switch as a CE or PE device using Layer 3 MPLS/BGP VPN for interprovider and carrier-of-carrier VPNs. The key difference between interprovider

and carrier-of-carriers VPNs is whether the customer sites belong to the same autonomous system (AS) or to a separate AS:

- Interprovider VPNs—The customer sites belong to different ASs. You need to configure EBGP to exchange the customer's external routes.
- Carrier-of-carriers VPNs—The customer sites belong to the same AS. You need to configure IBGP to exchange the customer's external routes.
- **MPLS LSP protection (EX4600)**—Starting with Junos OS Release 14.1X53-D10, the following types of MPLS LSP protection are supported on EX4600 switches:
  - Fast reroute (FRR)
  - Link protection
  - Node link protection

[ See [MPLS Overview](#).]

### **Network Management and Monitoring**

---

- **Chef for Junos OS (EX4300)**—Starting with Junos OS Release 14.1X53-D10, Chef for Junos OS is supported on EX4300 switches.
- **Puppet for Junos OS (EX4300)**—Starting with Junos OS Release 14.1X53-D10, Puppet for Junos OS is supported on EX4300 switches.
- **Network analytics (EX4300)**—Starting with Junos OS Release 14.1X53-D10, EX4300 switches support the network analytics feature. The network analytics feature provides visibility into the performance and behavior of the data center infrastructure. This feature collects data from the switch, analyzes the data by using sophisticated algorithms, and captures the results in reports. Network administrators can use the reports to help troubleshoot problems, make decisions, and adjust resources as needed. The analytics manager (analyticsm) in the Packet Forwarding Engine collects traffic and queue statistics, and the analytics daemon (analyticd) in the Routing Engine analyzes the data and generates reports. You can enable network analytics by configuring microburst monitoring and high-frequency traffic statistics monitoring.

[See [Network Analytics Overview](#).]

- **Ethernet frame delay measurement (EX2200)**—Starting with Junos OS Release 14.1X53-D10, you can obtain Ethernet frame delay measurements (ETH-DM) on an EX2200 switch. You can configure Operation, Administration, and Maintenance (OAM) statements for connectivity fault management (IEEE 802.1ag) to provide on-demand measurements of frame delay and frame delay variation (jitter). You configure the feature under the `[edit protocols oam ethernet connectivity-fault-management]` hierarchy level.
- **Support for native analyzers and remote port-mirroring capabilities (EX4300)**—Starting with Junos OS Release 14.1X53-D10, native analyzers and remote port mirroring are supported on EX4300 switches. A native analyzer configuration contains both an input stanza and an output stanza in the analyzer hierarchy for mirroring packets. In remote port mirroring, the mirrored traffic is flooded into a remote mirroring VLAN that can be specifically created for the purpose of receiving mirrored

traffic. On EX4300 switches, the analyzer configuration is available under the **[edit forwarding-options]** hierarchy level.

## Port Security

- **IPv6 access security (EX2200 and EX3300)**—Starting with Junos OS Release 14.1X53-D10, the following IPv6 access security features are supported on EX2200 and EX3300 switches: DHCPv6 snooping, IPv6 Neighbor Discovery Inspection, IPv6 source guard, and RA guard. DHCPv6 snooping enables a switch to process DHCPv6 messages between a client and a server and build a database of the IPv6 addresses assigned to the DHCPv6 clients. The switch can use this database, also known as the binding table, to stop malicious traffic. DHCPv6 includes the relay agent Remote-ID option, also known as Option 37, to optionally append additional information to the messages sent by the client towards the server. This information can be used by the server to assign addresses and configuration parameters to the client. IPv6 Neighbor Discovery inspection analyzes neighbor discovery messages sent between IPv6 nodes on the same link and verifies them against the DHCPv6 binding table. IPv6 source guard inspects all IPv6 traffic from the client and verifies the source IPv6 address and source MAC address against the entries in the DHCPv6 binding table. If no match is found, the traffic is dropped. RA guard examines incoming Router Advertisement (RA) messages and decides whether to forward or block them based on statically configured IPv6/MAC address bindings. If the content of the RA message does not match the bindings, the message is dropped.

Starting with this release, Remote-ID (Option-37) is not added by default on when you enable **dhcpv6-snooping**.

You configure DHCPv6 snooping, IPv6 Neighbor Discovery Inspection, and IPv6 source guard at the **[edit ethernet-switching-options secure-access-port vlan *vlan-name*]** hierarchy level. You configure RA guard at the **[edit ethernet-switching-options secure-access-port interface *interface-name*]** hierarchy level.

[See [Port Security Overview](#).]

- **IPv6 access security (EX4300)**—Starting with Junos OS Release 14.1X53-D10, DHCPv6 snooping supports a configuration to optionally append the relay agent Remote ID (Option-37), Interface-ID (Option-18), and Vendor-Class (Option-16) to the DHCPv6 packets sent by a client. You can configure these options under the **[edit vlans *vlan-name* forwarding-options dhcp-security dhcpv6-options]** hierarchy level.
- **Media Access Control Security (MACsec) support for switch to host connections (EX4200, EX4300, and EX4550)**—Starting with Junos OS Release 14.1X53-D10, MACsec is supported on links connecting EX4200, EX4300, and EX4550 switches to host devices, such as phones, servers, personal computers, or other endpoint devices. This feature also introduces MACsec dynamic mode and the ability to retrieve MACsec Key Agreement (MKA) keys from a RADIUS server, which are required to enable MACsec on a switch to host link.

[See [Understanding Media Access Control Security \(MACsec\)](#) .]

## Virtual Chassis and Virtual Chassis Fabric

---

- **Alias support for Virtual Chassis and Virtual Chassis Fabric (VCF) nodes**—Starting with Junos OS Release 14.1X53-D10, an alias can be used to label nodes in a Virtual Chassis and VCF. An alias enables you to more clearly identify a member switch in your Virtual Chassis or VCF by assigning a text label to it. The text label appears alongside the switch's serial number whenever operational commands, such as **show virtual-chassis**, are used to monitor Virtual Chassis status.

[See [aliases](#).]

### Related Documentation

- *New and Changed Features*

## Known Behavior

The following are changes in known behavior in Junos OS Release 14.1X53-D10 for the EX Series.

For the most complete and latest information about known Junos OS defects, use the Juniper Networks online [Junos Problem Report Search](#) application.

- [J-Web](#)
- [Multicast Protocols](#)
- [Virtual Chassis and Virtual Chassis Fabric](#)

### J-Web

---

- In the J-Web interface, you cannot commit some configuration changes in the Ports Configuration page or the VLAN Configuration page because of the following limitations for port-mirroring ports and port-mirroring VLANs:
  - A port configured as the output port for an analyzer cannot be a member of any VLAN other than the default VLAN.
  - A VLAN configured to receive analyzer output can be associated with only one interface.

This is a known software limitation. [PR400814](#)

- In the J-Web interface for EX4500 switches, the Ports Configuration page (Configure > Interfaces > Ports), the Port Security Configuration page (Configure > Security > Port Security), and the Filters Configuration page (Configure > Security > Filters) display features that are not supported on EX4500 switches. This is a known software limitation. [PR525671](#)
- The J-Web interface does not support role-based access control; it supports only users in the super-user authorization class. Therefore, a user who is not in the super-user class, such as a user with view-only permission, is able to launch the J-Web interface and can configure everything, but the configuration fails on the switch, and the switch displays access permission error messages. This is a known software limitation. [PR604595](#)

## Multicast Protocols

- On EX4300 switches, executing the **show igmp snooping membership** CLI command continuously while IGMP groups are being processed results in some groups not being displayed in the output. CPU utilization also increases significantly when this command is executed when there are more than 1000 groups. As a workaround, issue the **show igmp snooping membership** command with filters such as **group** or **interface**. This is a known software limitation. [PR914908](#)

## Virtual Chassis and Virtual Chassis Fabric

- When an EX4300 switch is removed from a Virtual Chassis by deleting the Virtual Chassis port (VCP) connecting the switch to the Virtual Chassis, the EX4300 switch splits from the Virtual Chassis. To add the EX4300 switch back into the Virtual Chassis, enter the **request virtual-chassis reactivate** command to take the switch out of linecard mode and then enter the **request virtual-chassis vc-port set pic-slot slot-number port port-number** command to create the VCP. [PR1013386](#)

### Related Documentation

- [New and Changed Features on page 4](#)
- [Known Behavior on page 14](#)
- [Known Issues on page 15](#)
- [Documentation Updates on page 18](#)
- [Migration, Upgrade, and Downgrade Instructions on page 19](#)
- [Product Compatibility on page 19](#)

## Known Issues

This section lists the known issues in hardware and software in Junos OS Release 14.1X53-D10 for the EX Series.

For the most complete and latest information about known Junos OS defects, use the Juniper Networks online [Junos Problem Report Search](#) application.

- [Class of Service](#)
- [Interfaces and Chassis](#)
- [J-Web](#)
- [Layer 3 Protocols](#)
- [MPLS](#)
- [Multicast Protocols](#)
- [Network Management and Monitoring](#)
- [Port Security](#)
- [Virtual Chassis and Virtual Chassis Fabric](#)

### Class of Service

---

- On EX4550 switches, 128-byte packets are dropped if the CPU is at 97 percent load or greater. Packets of different sizes are not dropped under these conditions. [PR862767](#)

### Interfaces and Chassis

---

- On EX Series switches, if you configure an IPv4 GRE interface on an IPv6 interface, the GRE tunnel might not work properly. Traffic is not forwarded through the tunnel. [PR1008157](#)
- When a transceiver on a QFX5100, QFX3600, QFX3500, or EX4300 switch is removed and reinserted into an interface within 30 seconds after you issued the **set virtual-chassis vc-port set** command to convert the interface into a Virtual Chassis port (VCP), the VCP is not created. [PR1029829](#)
- An EX4600-EM-8F expansion module installed in a QFX5100-24Q switch or an EX4600 switch does not support the 100 mbps speed on the 10-Gigabit Ethernet interfaces. [PR1032257](#)

### J-Web

---

- In the **Maintain > Update J-Web** page, **Select Application package > Update J-Web > local file** does not work in Microsoft IE9 and later releases, due to default security options set on IE9 and later releases. As a workaround, increase the security level by using one of the following methods:

Method 1:

1. Navigate to **Internet Options > Security**.
2. Select the zone **Local intranet**.
3. Click the custom level button.
4. Disable the option **Include local directory Path when uploading file to the server** in the **Settings > miscellaneous** section.
5. Repeat Steps 3 and 4 for the zone **Internet**.



#### Method 2:

- Navigate to **Internet Options > Security > Custom level...** and set **Reset custom settings** to **Medium-High** or **High**. This automatically disables the option **Include local directory Path when uploading file to the server** under the **Settings > miscellaneous** section.

[PR1029736](#)

### Layer 3 Protocols

---

- On EX3300 switches, when there are multiple open Telnet or SSH sessions, the switch might become unresponsive. [PR1029340](#)

### MPLS

---

- FRR convergence times over pseudo interfaces (aggregate) might be larger than over physical interfaces. [PR976737](#)
- For MPLS FRR and L2 circuit, certain scenarios after an ISSU might not work as expected. As a workaround, restart the Packet Forwarding Engine. [PR1016513](#)
- In a scaled configuration for MPLS FRR and L2 circuit, the convergence time for FRR might be higher. For L2 circuit, there might be packet drops. [PR1016146](#)
- In certain scenarios, the pseudowire redundancy feature might not work as expected. [PR1013686](#)

### Multicast Protocols

---

- On an EX4550 switch, if you configure IGMP on all interfaces and create a large number of multicast groups, the maximum scale for IGMP can be achieved on some interfaces, but not on all interfaces. [PR1025169](#)

### Network Management and Monitoring

---

- On EX2200 switches, remote MEP flaps might occur every 30 to 200 seconds because of processing delays and lead to iterator delay measurement statistic resets. All delay system measurements remain valid when this issue occurs. As a workaround, use an iterator count of less than 30. [PR1005819](#)

### Port Security

---

- On an EX4300 switch, a MAC address that is specified as part of a MAC-based VLAN is authenticated on an interface, for example, xe-1/1/1, on which 802.1X authentication in multiple supplicant mode is configured. However, the same MAC address might not be authenticated on another interface, for example, xe-2/1/1, if the MAC address moves to interface xe-2/1/1 from interface xe-1/1/1. [PR1007589](#)
- On an EX2200 or EX3300 Virtual Chassis, when DHCP snooping is enabled and 1000 or more IPv4 and 500 or more IPv6 DHCP bindings occur simultaneously, the software forwarding daemon (sfid) might create a core file. There might be a traffic impact because of the core file creation. [PR1019136](#)

### Virtual Chassis and Virtual Chassis Fabric

---

- On a Virtual Chassis with three EX2200 switch members, if you configure nine link aggregation groups and eight interfaces per LAG bundle, the LACP links might transition down and up continuously. As a workaround, configure eight link aggregation groups and eight interfaces per LAG bundle instead. [PR1030809](#)
- On a mixed Virtual Chassis Fabric (VCF), a Virtual Chassis port (VCP) link between two members might disappear after you perform a nonstop software upgrade (NSSU). The **show virtual-chassis protocol adjacency member** command output shows the state of the VCP link as **Initializing**. [PR1031296](#)

#### Related Documentation

- [New and Changed Features on page 4](#)
- [Known Behavior on page 14](#)
- [Known Issues on page 15](#)
- [Documentation Updates on page 18](#)
- [Migration, Upgrade, and Downgrade Instructions on page 19](#)
- [Product Compatibility on page 19](#)

### Documentation Updates

This section lists changes and errata in Junos OS Release 14.1X53-D10 for the EX Series switches documentation.

- [Bridging and Learning on page 18](#)

#### Bridging and Learning

---

- Two new MIBs related to MAC notification are provided at Junos OS Release 14.1X53-D10:
  - jnxL2aldMacHistoryEntry
  - jnxL2aldMacNotificationMIBGlobalObjects

These MIBs are not yet described in the documentation.

#### Related Documentation

- [New and Changed Features on page 4](#)
- [Known Behavior on page 14](#)
- [Known Issues on page 15](#)
- [Documentation Updates on page 18](#)
- [Migration, Upgrade, and Downgrade Instructions on page 19](#)
- [Product Compatibility on page 19](#)

## Migration, Upgrade, and Downgrade Instructions

This section contains upgrade and downgrade policies for Junos OS for the EX Series. Upgrading or downgrading Junos OS can take several hours, depending on the size and configuration of the network.

For information about software installation and upgrade, see the [Installation and Upgrade Guide](#).

- [Upgrade and Downgrade Support Policy for Junos OS Releases on page 19](#)

---

### Upgrade and Downgrade Support Policy for Junos OS Releases

Support for upgrades and downgrades that span more than three Junos OS releases at a time is not provided, except for releases that are designated as Extended End-of-Life (EEOL) releases. EEOL releases provide direct upgrade and downgrade paths—you can upgrade directly from one EEOL release to the next EEOL release, even though EEOL releases generally occur in increments beyond three releases.

You can upgrade or downgrade to the EEOL release that occurs directly before or after the currently installed EEOL release, or to two EEOL releases before or after. For example, Junos OS Releases 10.0, 10.4, and 11.4 are EEOL releases. You can upgrade from Junos OS Release 10.0 to Release 10.4 or even from Junos OS Release 10.0 to Release 11.4. However, you cannot upgrade directly from a non-EEOL release that is more than three releases ahead or behind. For example, you cannot directly upgrade from Junos OS Release 10.3 (a non-EEOL release) to Junos OS Release 11.4 or directly downgrade from Junos OS Release 11.4 to Junos OS Release 10.3.

To upgrade or downgrade from a non-EEOL release to a release more than three releases before or after, first upgrade to the next EEOL release and then upgrade or downgrade from that EEOL release to your target release.

For more information about EEOL releases and to review a list of EEOL releases, see <http://www.juniper.net/support/eol/junos.html>.

For information on software installation and upgrade, see the [Installation and Upgrade Guide](#).

#### Related Documentation

- [New and Changed Features on page 4](#)
- [Known Behavior on page 14](#)
- [Known Issues on page 15](#)
- [Documentation Updates on page 18](#)
- [Migration, Upgrade, and Downgrade Instructions on page 19](#)
- [Product Compatibility on page 19](#)

## Product Compatibility

- [Hardware Compatibility on page 20](#)

## Hardware Compatibility

---

To obtain information about the components that are supported on the devices, and special compatibility guidelines with the release, see the Hardware Guide for the product.

To determine the features supported on EX Series switches in this release, use the Juniper Networks Feature Explorer, a Web-based application that helps you to explore and compare Junos OS feature information to find the right software release and hardware platform for your network. Find Feature Explorer at:

<http://pathfinder.juniper.net/feature-explorer/>

### Related Documentation

- [New and Changed Features on page 4](#)
- [Known Behavior on page 14](#)
- [Known Issues on page 15](#)
- [Documentation Updates on page 18](#)
- [Migration, Upgrade, and Downgrade Instructions on page 19](#)
- [Product Compatibility on page 19](#)

## Junos OS Release Notes for the QFX Series

---

These release notes accompany Junos OS Release 14.1X53 for the QFX Series. They describe new and changed features, limitations, and known and resolved problems in the hardware and software.

You can also find these release notes on the Juniper Networks Junos OS Documentation webpage, located at <http://www.juniper.net/techpubs/software/junos/>.

- [New and Changed Features on page 20](#)
- [Known Behavior on page 31](#)
- [Known Issues on page 38](#)
- [Documentation Updates on page 41](#)
- [Migration, Upgrade, and Downgrade Instructions on page 41](#)
- [Product Compatibility on page 45](#)

## New and Changed Features

This section describes the new features and enhancements to existing features in Junos OS Release 14.1X53-D10 for the QFX Series. To view the entire set of software information in PDF format, see the [Complete Software Guide for Junos OS for the QFX Series](#).

- [Authentication and Access Control on page 21](#)
- [Bridging and Learning on page 21](#)
- [High Availability on page 23](#)
- [Infrastructure on page 23](#)

- [Interfaces and Chassis on page 26](#)
- [Layer 3 Features on page 26](#)
- [MPLS on page 27](#)
- [Network Management and Monitoring on page 28](#)
- [OpenFlow on page 29](#)
- [Open vSwitch Database \(OVSDb\) on page 29](#)
- [Security on page 29](#)
- [Software Installation on page 29](#)
- [Virtual Chassis and Virtual Chassis Fabric on page 30](#)
- [VXLAN on page 31](#)

---

### Authentication and Access Control

- **IPv6 for RADIUS AAA (QFX5100 switch and Virtual Chassis)**—Starting with Junos OS Release 14.1X53-D10, QFX5100 switches and QFX5100 Virtual Chassis support IPv6, along with the existing IPv4 support, for user authentication, authorization, and accounting (AAA) using RADIUS servers.

RADIUS authentication is a method of authenticating users who attempt to access the router or switch. To use RADIUS authentication on the switch, configure information about one or more RADIUS servers on the network by including one **radius-server** statement at the **[edit system]** hierarchy level for each RADIUS server.

When you configure a source address for each configured RADIUS server, each RADIUS request sent to a RADIUS server uses the specified source address.

- **Authentication**—Specify which source address Junos OS uses when accessing your network to contact an external RADIUS server for authentication. You configure the IPv6 source address for RADIUS authentication at the **[edit system radius-server server-address source-address]** hierarchy level.
- **Accounting**—Specify which source address Junos OS uses when contacting a RADIUS server for sending accounting information. You configure the IPv6 source address for RADIUS authentication at the **[edit system accounting destination radius server server-address source-address]** hierarchy level.

[See [source-address](#).]

---

### Bridging and Learning

- **MAC notification (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, MAC notification is supported on QFX5100 switches. The switches track clients on a network by storing MAC addresses in the Ethernet switching table on the switch. When switches learn or unlearn a MAC address, SNMP notifications can be sent to the network management system at regular intervals to record the addition or removal of the MAC address. This process is known as MAC notification.

The MAC Notification MIB controls MAC notification for the network management system.

The MAC notification interval defines how often these SNMP notifications are sent to the network management system. The MAC notification interval works by tracking all MAC address additions or removals on the switch over a period of time and then sending all tracked MAC address additions or removals to the network management server at the end of the interval.

Enabling MAC notification allows you to monitor the addition and removal of MAC addresses from the Ethernet switching table remotely using a network management system. The advantage of setting a high MAC notification interval is that the amount of network traffic is reduced because updates are sent less frequently. The advantage of setting a low MAC notification interval is that the network management system is better synchronized with the switch.

Two new MIBs related to MAC notification are provided at Junos OS Release 14.1X53-D10. See *Documentation Updates*.

[See [Configuring MAC Notification \(CLI Procedure\)](#).]

- **Default VLAN and multiple VLAN range support (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, the default VLAN and multiple VLAN range are supported on QFX5100 switches. They provide the ability for the switch to operate as a *plug and play* device and connect to various Ethernet-enabled devices in a small, scaled enterprise network. When the switch boots, a VLAN named **default** is created. The default VLAN is automatically created for every routing instance that belongs to a type of **virtual-switch** and for the default routing instance named **default-switch**. All interfaces on the switch are automatically configured as access interfaces and are part of the default VLAN.

The default VLAN accepts and forwards untagged packets only and is preconfigured with a VLAN ID (**vlan-id**) of 1. The default VLAN does not support a VLAN ID list (**vlan-id-list**), **vlan-id** set to **all**, or **vlan-id** set to **none**. You can configure the VLAN ID to be another value, but the value must be between 1 and 4093.

Access interfaces that are VoIP-enabled or 802.1X-enabled are internally converted to trunk interfaces, so that the interfaces can belong to multiple VLANs. If the interfaces do not belong to a valid VLAN, the interfaces automatically become part of the default VLAN.

You can configure more than one VLAN range, and each range can contain unique VLAN properties.



**NOTE:** Virtual Chassis interfaces cannot be preconfigured to belong to the default VLAN or any other VLAN.



**NOTE:** For interfaces to be part of the default VLAN, you must configure the interfaces to be part of the Ethernet switching family. You can configure Ethernet switching at the [edit interfaces *interface-name* unit family] CLI hierarchy level.

---

- **Ethernet ring protection switching (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, Ethernet ring protection switching (ERPS) is supported on QFX5100 switches. ERPS helps achieve high reliability and network stability. Links in the ring never form loops that fatally affect the network operation and services availability.

[See [Understanding Ethernet Ring Protection Switching Functionality](#).]

---

### High Availability

- **Resilient hashing support for link aggregation groups and equal cost multipath routes (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, resilient hashing is now supported by link aggregation groups (LAGs) and equal cost multipath (ECMP) sets.

A LAG combines Ethernet interfaces (members) to form a logical point-to-point link that increases bandwidth, provides reliability, and allows load balancing. Resilient hashing enhances LAGs by minimizing destination remapping when a new member is added to or deleted from the LAG.

Resilient hashing works in conjunction with the default static hashing algorithm. It distributes traffic across all members of a LAG by tracking the flow's LAG member utilization. When a flow is affected by a LAG member change, the packet forwarding engine (PFE) rebalances the flow by reprogramming the flow set table. Destination paths are remapped when a new member is added to or existing members are deleted from a LAG.

Resilient hashing applies only to unicast traffic and supports a maximum of 1024 LAGs, with each group having a maximum of 256 members.

An ECMP group for a route contains multiple next-hop equal cost addresses for the same destination in the routing table. (Routes of equal cost have the same preference and metric values.)

Junos OS uses a hash algorithm to choose one of the next-hop addresses in the ECMP group to install in the forwarding table. Flows to the destination are rebalanced using resilient hashing.

Resilient hashing enhances ECMPs by minimizing destination remapping when a new member is added to or deleted from the ECMP group.

[See [Understanding the Use of Resilient Hashing to Minimize Flow Remapping in Trunk Groups](#).]

---

### Infrastructure

- **Licensing enhancements (QFX Series)**—Starting with Junos OS Release 14.1X53-D10, licensing enhancements on QFX Series switches enable you to configure and delete license keys in a Junos OS CLI configuration file. The license keys are validated and installed after a successful commit of the configuration file. If a license key is invalid, the commit fails and issues an error message. You can configure individual license keys or multiple license keys by issuing Junos OS CLI commands or by loading the license key configuration contained in a file. All installed license keys are stored in the `/config/license/` directory.

To install an individual license key in the Junos OS CLI, issue the **set system license keys key *name*** command, and then issue the **commit** command.

For example:

```
[edit]
root@switch# set system license keys key "JUNOS_TEST_LIC_FEAT aeaqeb qbmqds
qwxsxe okyvou 6v57u5 zt6ie6 uwl3zh assvnu e2ptl5 soxawy vtfh7k axwnno m5w54j
6z"
root@switch# commit
commit complete
```

To verify that the license key was installed, issue the **show system license** command.

For example:

```
root@switch> show system license
License usage:

Feature name          Licenses used  Licenses installed  Licenses needed  Expiry
-----
sdk-test-feat1       0             1                   0
permanent

Licenses installed:
License identifier: JUNOS_TEST_LIC_FEAT
License version: 2
Features:
  sdk-test-feat1    - JUNOS SDK Test Feature 1
  permanent
```

To install multiple license keys in the Junos OS CLI, issue the **set system license keys key *name*** command, and then issue the **commit** command.

For example:

```
[edit]
root@switch# set system license keys key "key_1"
set system license keys key "key_2"
set system license keys key "key_2"
set system license keys key "key_4"
root@switch# commit
commit complete
```

To verify that the license key was installed, issue the **show system license** command.

To install an individual license key configuration in a file, issue the **cat** command:

For example:

```
[edit]
root@switch%cat license.conf
system {
  license {
    keys {
      key "JUNOS_TEST_LIC_FEAT aeaqeb qbmqds qwxsxe okyvou 6v57u5 zt6ie6
uwl3zh assvnu e2ptl5 soxawy vtfh7k axwnno m5w54j 6z";
    }
  }
}
```

Load and merge the license configuration file.



For example:

```
[edit]
root@switch# load merge license.conf
load complete
```

Issue the **show | compare** command to see the configuration, and then issue the **commit** command.

For example:

```
[edit]
root@switch# show | compare
[edit system]
+ license {
+   keys {
+       key "JUNOS_TEST_LIC_FEAT aeaqeb qbmqds qwwsxe okyvou 6v57u5
zt6ie6 uw13zh assvnu e2pt15 soxawy vtfh7k axwnno m5w54j 6z";
+   }
+ }
[edit]
root@switch# commit
```

To verify that the license key was installed, issue the **show system license** command.

For example:

```
root@switch> show system license
License usage:
```

	Licenses	Licenses	Licenses	Expiry
Feature name	used	installed	needed	
sdk-test-feat1	0	1	0	
permanent				

```

Licenses installed:
License identifier: JUNOS_TEST_LIC_FEAT
License version: 2
Features:
  sdk-test-feat1  - JUNOS SDK Test Feature 1
  permanent
```

To install multiple license keys in a file, issue the **cat** command:

For example:

```
[edit]
root@switch%cat license.conf
system
{
  license
  {
    keys
    {
      key "key_1"
      key "key_2"
      key "key_3"
      ...
      key "key_n"
    }
  }
}
```

Load and merge the license configuration file, and then issue the **commit** command.

For example:

```
[edit]
root@switch# load merge license.conf
    load complete
[edit]
root@switch# commit
```

To verify that the license key was installed, issue the **show system license** command.

You can also delete or deactivate individual and multiple license keys in the Junos OS CLI by issuing the **delete system license keys** or **deactivate system license keys** commands. Do not use the **request system license delete** command to delete the license keys.

For example, to issue the **delete system license keys** command:

```
[edit]
root@switch# delete system license keys
root@switch# commit
```

---

## Interfaces and Chassis

- **Fast reboot option (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, you can enhance the reboot time on a QFX5100 by issuing the new **fast-boot** option with the **request system reboot** command (**request system reboot fast-boot**). The switch reboots in such a way as to minimize downtime of network ports by not bringing the network ports down immediately as in the normal reboot option. There is minimal traffic loss while the forwarding device is reprogrammed.

[See [request system reboot](#).]

- **Keep a link up on a multichassis link aggregation group (MC-LAG) when LACP is not configured on one of the MC-LAG peers (QFX5100 switch)**—Junos OS Release 14.1X53-D10 provides connectivity from provider edge devices to customer edge devices when LACP is not configured on a customer edge device. The customer edge device must have one link connected to the provider edge device, though, and multichassis link aggregation must be configured between the provider edge devices in the MC-LAG. You can configure the force-up feature in Link Aggregation Control Protocol (LACP) on the provider edge device for which you need connectivity. Additionally, only one member interface in the aggregated Ethernet interface can be active, otherwise the provider edge device will receive duplicate packets.

[See [Forcing MC-LAG Links or Interfaces with Limited LACP Capability to Be Up](#).]

---

## Layer 3 Features

- **Loop-free alternate (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, QFX5100 switches support loop-free alternates (LFA) to compute backup next hops for IS-IS routes, providing IP fast-reroute capability for IS-IS routes. These routes, with precomputed backup next hops, are preinstalled in the Packet Forwarding Engine, which performs a local repair and switches to the backup next hop when the link for the primary next hop for a particular route is no longer available. With local repair, the

Packet Forwarding Engine can correct a path failure before it receives recomputed paths from the Routing Engine. Local repair reduces the amount of time needed to reroute traffic to less than 50 milliseconds. You can configure loop free alternates (LFA) for IS-IS at the **[edit protocols isis]** hierarchy level.

- **IS-IS support (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, on QFX5100 switches, the IS-IS protocol has extensions to differentiate between different sets of routing information sent between routers and switches for unicast and multicast. IS-IS routes can be added to the RPF table when special features such as traffic engineering and shortcuts are turned on. You configure the feature under the **[edit protocols isis]** hierarchy level.

## MPLS

- **MPLS-based Layer 3 VPNs (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, MPLS-based Layer 3 VPNs are supported on QFX5100 switches.

Customer networks are private and can use either public addresses or private addresses. When customer networks that use private addresses connect to the public Internet infrastructure, the private addresses might overlap with private addresses being used by other network users. MPLS BGP VPNs solve this problem by adding the route distinguisher prefix to the route.

You can configure the switch as a CE or PE using Layer 3 MPLS/BGP VPN for interprovider and carrier-of-carrier VPNs. The key difference between interprovider and carrier-of-carriers VPNs is whether the customer sites belong to the same autonomous system (AS) or to a separate AS:

- Interprovider VPNs—The customer sites belong to different ASs. You need to configure EBGP to exchange the customer's external routes.
- Carrier-of-carriers VPNs—The customer sites belong to the same AS. You need to configure IBGP to exchange the customer's external routes.
- **Ethernet-over-MPLS (L2 circuit) (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, Ethernet-over-MPLS is supported on QFX5100 switches. Ethernet-over-MPLS enables you to send Layer 2 Ethernet frames transparently over an MPLS cloud. Ethernet-over-MPLS uses a tunneling mechanism for Ethernet traffic through an MPLS-enabled Layer 3 core. It encapsulates Ethernet protocol data units (PDUs) inside MPLS packets and forwards the packets, using label stacking, across the MPLS network.

This technology has applications in service provider, enterprise, and data center environments. For disaster recovery purposes, data centers are hosted in multiple sites that are geographically distant and interconnected using a WAN network. These data centers require Layer 2 connectivity between them for the following reasons:

- To replicate the storage over Fibre Channel over IP (FCIP). FCIP works only on the same broadcast domain.
- To run a dynamic routing protocol between the sites.
- To support high availability clusters that interconnect the nodes hosted in the various data centers.

- **MPLS LSP protection (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, the following types of MPLS LSP protection are supported on QFX5100 switches:
  - Fast reroute (FRR)
  - Link protection
  - Node link protection

[ See [MPLS Overview](#).]

### **Network Management and Monitoring**

---

- **Chef for Junos OS (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, Chef for Junos OS is supported on all QFX5100 switches, not just QFX5100 switches that are running Junos OS with automated enhancements for QFX5100 switches.
- **Puppet for Junos OS (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, Puppet for Junos OS is supported on QFX5100 switches that are not running Junos OS with automated enhancements for QFX5100 switches.
- **IEEE 802.3ah (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, QFX5100 switches support the IEEE 802.3ah standard for the Operation, Administration, and Maintenance (OAM) of Ethernet in networks. The standard defines OAM link fault management (LFM). You can configure IEEE 802.3ah OAM LFM on point-to-point Ethernet links that are connected either directly or through Ethernet repeaters. Ethernet OAM provides the tools that network management software and network managers can use to determine how a network of Ethernet links is functioning. You configure the feature under the **[edit protocols oam ethernet]** hierarchy level.

## OpenFlow

---

- **Support for OpenFlow v1.0 and v1.3.1 (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, QFX5100 switches support OpenFlow v1.0 and v1.3.1. OpenFlow v1.0 enables you to control traffic in an existing network by adding, deleting, and modifying flows in the switch. You can configure one OpenFlow virtual switch and one active OpenFlow controller under the **[edit protocols openflow]** hierarchy on each QFX5100 switch in the network.

In addition to the OpenFlow v1.0 functionality, OpenFlow v1.3.1 allows the action specified in one or more flow entries to direct packets to a base action called a group. The purpose of the group action is to further process these packets and assign a more specific forwarding action to them. You can view groups that were added, modified, or deleted from the group table by way of the OpenFlow controller using the **show openflow groups** command. You can view group statistics using the **show openflow statistics groups** command.

OpenFlow v1.0 and v1.3.1 are not supported on MX Series routers or EX9200 switches in Junos OS Release 14.1X53-D10. OpenFlow v1.0 is supported in Junos OS Release 14.1 on these platforms.

[See [Understanding OpenFlow Operation and Forwarding Actions on Devices Running Junos OS.](#)]

## Open vSwitch Database (OVSDB)

---

- **OVSDB support (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, the Junos OS implementation of the Open vSwitch Database (OVSDB) management protocol provides a means through which VMware NSX controllers and QFX5100 switches that support OVSDB can communicate. In an NSX multi-hypervisor environment, NSX version 4.0.3 controllers and QFX5100 switches can exchange control and statistical information via the OVSDB schema for physical devices, thereby enabling virtual machine (VM) traffic from entities in a virtual network to be forwarded to entities in a physical network and vice versa.

You can set up a connection between the QFX5100 management interface (**em0** or **em1**) and an NSX controller.

[See [Setting Up Open vSwitch Database Connections Between Junos OS Devices and Controllers.](#)]

## Security

---

- **Port mirroring to IP address (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, you can send mirrored packets to an IP address over a Layer 3 network (for example, if there is no Layer 2 connectivity to the analyzer device). This feature also enables you to apply an IEEE-1588 timestamp to the mirrored packets.

## Software Installation

---

- **Open Source Python modules supported in automation enhancement (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, these Open Source Python

modules are pre-installed in the `jinstall-qfx-5-flex-x.tgz` software bundle:

- **ncclient**—Facilitates client scripting and application development through the NETCONF protocol.
- **lxml**—Combines the speed and XML feature completeness of the C libraries `libxml2` and `libxslt` with the simplicity of a native Python API.
- **jinja2**—Serves as a fast, secure, designer-friendly templating language.

[See [Overview of Python with QFX5100 Switch Automation Enhancements.](#)]

---

### Virtual Chassis and Virtual Chassis Fabric

- **Alias support for Virtual Chassis and Virtual Chassis Fabric (VCF) nodes**—Starting with Junos OS Release 14.1X53-D10, an alias can be used to label nodes in a Virtual Chassis and VCF. An alias allows you to more clearly identify a member switch in your Virtual Chassis or VCF by assigning a text label to it. The text label appears alongside the switch's serial number whenever operational commands, such as **show virtual-chassis**, are used to monitor Virtual Chassis status.

[See [aliases.](#)]

- **Local link bias support for Virtual Chassis with QFX Series member switches**—Starting with Junos OS Release 14.1X53-D10, Virtual Chassis Local Link Bias is available on Link Aggregation Group (LAG) bundles on QFX3500 Virtual Chassis, QFX3600 Virtual Chassis, and mixed QFX3500 and QFX3600 Virtual Chassis. Virtual Chassis local link bias conserves bandwidth on Virtual Chassis ports (VCPs) by using local links to forward unicast traffic exiting a Virtual Chassis that has a LAG bundle composed of member links on different member switches in the same Virtual Chassis. A local link is a member link in the LAG bundle that is on the member switch that received the traffic. Because traffic is received and forwarded on the same member switch when local link bias is enabled, no VCP bandwidth is consumed by traffic traversing the VCPs to exit the Virtual Chassis using a different member link in the LAG bundle.

[See [Understanding Local Link Bias.](#)]

- **Adaptive load balancing support (Virtual Chassis Fabric)**—Starting with Junos OS Release 14.1X53-D10, adaptive load balancing (ALB) is supported in Virtual Chassis Fabric (VCF). ALB improves traffic management within a VCF by using dynamic load information to make traffic forwarding decisions. ALB introduces a method to better manage extremely large traffic flows—*elephant flows*—by splicing them into smaller flows—*flowlets*—and individually forwarding the flowlets across the VCF to the same destination device over different paths.

[See [Understanding Traffic Flow Through a Virtual Chassis Fabric.](#)]

## VXLAN

- **Layer 2 VXLAN gateway (QFX5100)**—Starting with Junos OS Release 14.1X53-D10, VXLAN is an overlay technology that enables you to stretch Layer 2 connections over an intervening Layer 3 network by encapsulating (tunneling) Ethernet frames in a VXLAN packet that includes IP addresses. You can use VXLAN tunnels to enable migration of virtual machines between servers that exist in separate Layer 2 domains by tunneling the traffic through Layer 3 networks. This functionality enables you to dynamically allocate resources within or between data centers without being constrained by Layer 2 boundaries or being forced to create large or geographically stretched Layer 2 domains. Using VXLANs to connect Layer 2 domains over a Layer 3 network means that you do not need to use STP to converge the topology (so no links are blocked) but can use more robust routing protocols in the Layer 3 network instead.

[See [Understanding VXLANs](#).]

### Related Documentation

- *New and Changed Features*

## Known Behavior

This section lists the limitations in Junos OS Release 14.1X53-D10 and 14.1X53-D15 for the QFX Series.

### Interfaces and Chassis

- On a QFX5100 switch, if you configure MC-LAG, IRB mac sync, and LACP force up, the number of packets received (rx) might be twice the amount sent (tx) from the customer edge to the core. [PR1015655](#)

### MPLS

- A pseudowire is a port-based Layer 2 circuit that emulates a service over a packet switched network (PSN). You can emulate any circuit end to end using a pseudowire. In the event of a link failure on a transit router that hosts a Layer 2 circuit over an RSVP tunnel, the traffic convergence time is approximately 350 milliseconds for a single pseudowire. [PR1016992](#)
- If a pseudowire fails, the switchover from the active pseudowire to the standby/backup pseudowire takes longer than expected. [PR1025899](#), [PR1026336](#)
- If a link failure occurs when multiple LSPs are using a link-protected, fast-rerouted link, the convergence time is proportional to the number of LSPs sharing the protected link. [PR1016146](#), [PR1015806](#)
- On a QFX5100 switch, if an MPLS link is in hot standby mode and a pseudowire switchover is triggered by the event **remote site local interface signaled down**, traffic flowing through the pseudowire is dropped. [PR1027755](#)
- Pseudowire is a port-based Layer 2 circuit that emulates a service over packet switched network (PSN) using only virtual wire. You can emulate any circuit end to end using pseudo-wire. Note that the rewrite configuration on an L2 circuit UNI port is not

persistent after a system reboot. As a workaround, reapply the rewrite configuration after a system reboot. [PR1026701](#), [PR1026683](#)

### OpenFlow

---

- On a QFX5100 switch, a BGP session might go down and come back up repeatedly if an OpenFlow interface receives line-rate traffic that does not match any term and the default action of **packet-in** is applied. [PR892310](#)

### OVSDB

---

- On QFX5100 switches, the amount of time that it takes for other Juniper Networks devices that function as hardware virtual tunnel endpoints (VTEPs) to learn a new MAC address after the first packet is sent from this MAC address is a maximum of 4.5 seconds. (The amount of time depends upon the server configuration on which VMware NSX is running.) During this time, traffic destined for this MAC address is flooded into the VXLAN. [PR962945](#)
- After the connections with NSX controllers are disabled on a Juniper Networks device, interfaces that were configured to be managed by OVSDB continue passing traffic. [PR980577](#)
- If an entity with a particular MAC address is moved so that its traffic is handled by a different Juniper Networks device that functions as a hardware virtual tunnel endpoint (VTEP), this MAC address is not learned by entities served by the new hardware VTEP until the hardware VTEP that previously handled its traffic ages out the MAC address. During this transitional period, traffic destined for this MAC address is dropped. [PR988270](#)
- On QFX5100 switches, an NSX controller occasionally overrides an existing local MAC with a remote MAC of the same address. If the Junos OS hardware VTEP detects such a condition (that is, it receives a remote MAC from the NSX controller that conflicts (matches) with an existing local MAC), the hardware VTEP in a Junos OS network accepts the remote MAC and stops publishing the local MAC to the NSX controller. [PR991553](#)
- On QFX5100 switches, an active path in the OVSDB overlay, which you can view by using the **show ovbdb mac** operational command, does not always match the active path in the Layer 3 network underlay, which you can view by using the **show route** operational command. [PR1015998](#)
- On QFX5100 switches, in NSX Manager, when a logical switch is deleted, the corresponding VXLAN on a QFX5100 switch might not be automatically deleted and might still appear in the output of the **show vlans** command. [PR1024169](#)



## Routing Policy and Firewall Filters

- On QFX Series Virtual Chassis, packets that are generated in the CPU and exit from a non-master FPC port might be subjected to an egress port-based firewall filter (PACL) and be egress filtered, while packets that exit from a master FPC port might not be egress filtered. [PR923659](#)

## Storage and Fibre Channel

- Each Fibre Channel fabric on an FCoE-FC gateway supports a maximum of four Fibre Channel over Ethernet (FCoE) VLAN interfaces.
- The maximum number of logins for each FCoE node (ENode) is in the range of 32 through 2500. (Each ENode can log in to a particular fabric up to the maximum number of configured times. The maximum number of logins is per fabric, so an ENode can log in to more than one fabric and have its configured maximum number of logins on each fabric.)
- The maximum number of FCoE sessions for the switch, which equals the total number of fabric login (FLOGI) sessions plus the total number of fabric discovery (FDISC) sessions, is 2500.
- The maximum number of FIP snooping sessions per QFX3500 switch is 2500.
- When you configure FIP snooping filters, if the filters consume more space than is available in the ternary content-addressable memory (TCAM), the configuration commit operation succeeds even though the filters are not actually implemented in the configuration. Because the commit operation checks syntax but does not check available resources, it appears as if the FIP snooping filters are configured, but they are not. The only indication of this issue is that the switch generates a system log message that the TCAM is full. You must check the system log to find out if a TCAM full message has been logged if you suspect that the filters have not been implemented.
- You cannot use a fixed classifier to map FCoE traffic to an Ethernet interface. The FCoE application type, length, and value (TLV) carries the FCoE priority-based flow control (PFC) information when you use an explicit IEEE 802.1p classifier to map FCoE traffic to an Ethernet interface. You cannot use a fixed classifier to map FCoE traffic to an Ethernet interface because untagged traffic is classified in the FCoE forwarding class, but FCoE traffic must have a priority tag (FCoE traffic cannot be untagged).

For example, the following behavior aggregate classifier configuration is supported:

**[edit class-of-service]**

```
user@switch# set congestion notification profile fcoe-cnp input ieee-802.1 code-point 011 pfc
```

```
user@switch# set interfaces xe-0/0/24 unit 0 classifiers ieee-802.1 fcoe
```

For example, the following fixed classifier configuration is not supported:

**[edit class-of-service]**

```
user@switch# set interfaces xe-0/0/24 unit 0 forwarding-class fcoe
```

- On a QFX Series device, a DCBX interoperability issue between 10-Gigabit Ethernet interfaces on QFX Series devices and 10-Gigabit Ethernet interfaces on another vendor's

devices can prevent the two interfaces from performing DCBX negotiation successfully in the following scenario:

1. On a QFX Series 10-Gigabit Ethernet interface, LLDP is running, but DCBX is disabled.
2. On another vendor's device 10-Gigabit Ethernet interface, both LLDP and DCBX are running, but the interface is administratively down.
3. When you bring another vendor's 10-Gigabit Ethernet interface up by issuing the **no shutdown** command, the device sends DCBX 1.01 (CEE) TLVs, but receives no acknowledge (ACK) message from the QFX Series device, because DCBX is not enabled on the QFX Series device. After a few tries, another vendor's device sends DCBX 1.00 (CIN) TLVs, and again receive no ACK messages from the QFX Series device.
4. Enable DCBX on the QFX Series 10-Gigabit Ethernet interface. The interface sends DCBX 1.01 (CEE) TLVs, but the other vendor's device ignores them and replies with DCBX 1.00 (CIN) TLVs. The other vendor's device does not attempt to send or acknowledge DCBX 1.01 TLVs, only DCBX 1.00 TLVs.

In this case, the QFX Series device ignores the DCBX 1.00 (CIN) TLVs because the QFX Series does not support DCBX 1.00 (the QFX Series supports DCBX 1.01 and IEEE DCBX). The result is that the DCBX capabilities negotiation between the two interfaces fails.

---

### Traffic Management

- On a QFX5100 switch, running **tcpdump** on the console might cause system instability or cause protocols such as STP or LACP to fail. [PR932592](#)
- On a mixed-mode Virtual Chassis Fabric, during a Routing Engine switchover, the system might experience a 200-300 millisecond loss of traffic. [PR964987](#)
- **Access interface CoS support**—CoS on Virtual Chassis access interfaces is the same as CoS on QFX Series access interfaces with the exception of shared buffer settings. All of the documentation for QFX Series CoS on access interfaces applies to Virtual Chassis access interfaces.

Virtual Chassis access interfaces support the following CoS features:

- Forwarding classes—The default forwarding classes, queue mapping, and packet drop attributes are the same as on QFX Series access interfaces:

Default Forwarding Class	Default Queue Mapping	Default Packet Drop Attribute
best-effort (be)	0	drop
fcoe	3	no-loss
no-loss	4	no-loss
network-control (nc)	7	drop
mcast	8	drop

- Packet classification—Classifier default settings and configuration are the same as on QFX Series access interfaces. Support for behavior aggregate, multifield, multidestination, and fixed classifiers is the same as on QFX Series access interfaces.
- Enhanced transmission selection (ETS)—This data center bridging (DCB) feature that supports hierarchical scheduling has the same defaults and user configuration as on QFX Series access interfaces, including forwarding class set (priority group) and traffic control profile configuration.
- Priority-based flow control (PFC)—This DCB feature that supports lossless transport has the same defaults and user configuration as on QFX Series access interfaces, including support for six lossless priorities (forwarding classes).
- Ethernet PAUSE—Same defaults and configuration as on QFX Series access interfaces.
- Queue scheduling—Same defaults, configuration, and scheduler-to-forwarding-class mapping as on QFX Series access interfaces. Queue scheduling is a subset of hierarchical scheduling.
- Priority group (forwarding class set) scheduling—Same defaults and configuration as on QFX Series access interfaces. Priority group scheduling is a subset of hierarchical scheduling.
- Tail-drop profiles—Same defaults and configuration as on QFX Series access interfaces.
- Code-point aliases—Same defaults and configuration as on QFX Series access interfaces.
- Rewrite rules—As on the QFX Series access interfaces, there are no default rewrite rules applied to egress traffic.
- Host outbound traffic—Same defaults and configuration as on QFX Series access interfaces.

The default shared buffer settings and shared buffer configuration are also the same as on QFX Series access interfaces, except that the shared buffer configuration is global and applies to all access ports on all members of the Virtual Chassis. You cannot configure different shared buffer settings for different Virtual Chassis members.

- **Similarities in CoS support on VCP interfaces and QFabric system Node device fabric interfaces**—VCP interfaces support full hierarchical scheduling (ETS). ETS includes:
  - Creating forwarding class sets (priority groups) and mapping forwarding classes to forwarding class sets.
  - Scheduling for individual output queues. The scheduler defaults and configuration are the same as the scheduler on access interfaces.
  - Scheduling for priority groups (forwarding class sets) using a traffic control profile. The defaults and configuration are the same as on access interfaces.
  - No other CoS features are supported on VCP interfaces.



**NOTE:** You cannot attach classifiers, congestion notification profiles, or rewrite rules to VCP interfaces. Also, you cannot configure buffer settings on VCP interfaces. Similar to QFabric system Node device fabric interfaces, you can only attach forwarding class sets and traffic control profiles to VCP interfaces.

The behavior of lossless traffic across 40-Gigabit VCP interfaces is the same as the behavior of lossless traffic across QFabric system Node device fabric ports. Flow control for lossless forwarding classes (priorities) is enabled automatically. The system dynamically calculates buffer headroom that is allocated from the global lossless headroom buffer for the lossless forwarding classes on each 40-Gigabit VCP interface. If there is not enough global headroom buffer space to support the number of lossless flows on a 40-Gigabit VCP interface, the system generates a syslog message.



**NOTE:** After you configure lossless transport on a Virtual Chassis, check the syslog messages to ensure that there is sufficient buffer space to support the configuration.



**NOTE:** If you break out a 40-Gigabit VCP interface into 10-Gigabit VCP interfaces, lossless transport is not supported on the 10-Gigabit VCP interfaces. Lossless transport is supported only on 40-Gigabit VCP interfaces.

- **Differences in CoS support on VCP interfaces and QFabric system Node device fabric interfaces**—Although most of the CoS behavior on VCP interfaces is similar to CoS behavior on QFabric system Node device fabric ports, there are some important differences:

- Hierarchical scheduling (queue and priority group scheduling)—On QFabric system Node device fabric interfaces, you can apply a different hierarchical scheduler (traffic control profile) to different priority groups (forwarding class sets) on different interfaces. However, on VCP interfaces, the schedulers you apply to priority groups are global to all VCP interfaces. One hierarchical scheduler controls scheduling for a priority group on all VCP interfaces.

You attach a scheduler to VCP interfaces using the global identifier (*vcp-\**) for VCP interfaces. For example, if you want to apply a traffic control profile (which contains both queue and priority group scheduling configuration) named *vcp-fcoe-tcp* to a forwarding class set named *vcp-fcoe-fcset*, you include the following statement in the configuration:

```
[edit]
user@switch# set class-of-service interfaces vcp-* forwarding-class-set vcp-fcoe-fcset
output-traffic-control-profile vcp-fcoe-tcp
```

The system applies the hierarchical scheduler *vcp-fcoe-tcp* to the traffic mapped to the priority group *vcp-fcoe-fcset* on all VCP interfaces.

- You cannot attach classifiers, congestion notification profiles, or rewrite rules to VCP interfaces. Also, you cannot configure buffer settings on VCP interfaces. Similar to QFabric system Node device fabric interfaces, you can only attach forwarding class sets and traffic control profiles to VCP interfaces.
- Lossless transport is supported only on 40-Gigabit VCP interfaces. If you break out a 40-Gigabit VCP interface into 10-Gigabit VCP interfaces, lossless transport is not supported on the 10-Gigabit VCP interfaces.
- On a QFX5100 switch, CPU-generated host outbound traffic is forwarded on the network-control forwarding class, which is mapped to queue 7. If you use the default scheduler, the network-control queue receives a guaranteed minimum bandwidth (transmit rate) of 5 percent of port bandwidth. The guaranteed minimum bandwidth is more than sufficient to ensure lossless transport of host outbound traffic.

However, if you configure a scheduler, you must ensure that the network-control forwarding class (or whatever forwarding class you configure for host outbound traffic) receives sufficient guaranteed bandwidth to prevent packet loss.

If you configure a scheduler, we recommend that you configure the network-control queue (or the queue you configure for host outbound traffic if it is not the network-control queue) as a strict-high priority queue. Strict-high priority queues receive the bandwidth required to transmit their entire queues before other queues are served.



**NOTE:** As with all strict-high priority traffic, if you configure the network-control queue (or any other queue) as a strict-high priority queue, you must also create a separate forwarding class set (priority group) that contains only strict-high priority traffic, and apply the strict-high priority forwarding class set and its traffic control profile (hierarchical scheduler) to the relevant interfaces.

- You cannot apply classifiers and rewrite rules to IRB interfaces because the members of an IRB interface are VLANs, not interfaces. You can apply classifiers and rewrite rules to Layer 2 logical interfaces and Layer 3 physical interfaces that are members of VLANs that belong to IRB interfaces.

---

### Virtual Chassis and Virtual Chassis Fabric

- When a Virtual Chassis port (VCP) is added between two QFX5100 member switches that are already interconnected using a VCP, a VCP link aggregation group (LAG) is formed and some multicast packets between the two member switches might be duplicated. [PR1007204](#)
- On a mixed Virtual Chassis Fabric (VCF), control plane packets, including control packets for OSPF or PIM, are not mirrored by the native analyzer when the output port belongs to another member switch. [PR969542](#)
- If a VCF is connected to a Juniper Networks router with a flexible PIC concentrator (FPC) and an xSTP bridge protocol data unit is distributed to the FPC, there might be traffic loss when the FPC is rebooted. [PR990247](#)
- On a mixed-mode VCF, if you perform a nonstop software upgrade (NSSU) and a MAC address is present on the ingress or egress Packet Forwarding Engine, in some cases known Layer 2 unicast traffic might still be flooded over the VLAN. [PR1013416](#)

#### Related Documentation

- [New and Changed Features on page 20](#)
- [Known Behavior on page 31](#)
- [Known Issues on page 38](#)
- [Documentation Updates on page 41](#)
- [Migration, Upgrade, and Downgrade Instructions on page 41](#)
- [Product Compatibility on page 45](#)

### Known Issues

The following issues are outstanding in Junos OS Release 14.1X53-D10. The identifier following the description is the tracking number in our bug database.

For the latest, most complete information about outstanding and resolved issues with the Junos OS software, see the Juniper Networks online software defect search application at <http://www.juniper.net/prsearch>.

- [Interfaces and Chassis](#)
- [MPLS](#)
- [Multicast Protocols](#)
- [OVSDB](#)
- [Software Installation and Upgrade](#)
- [Virtual Chassis and Virtual Chassis Fabric](#)
- [VXLAN](#)

### [Interfaces and Chassis](#)

- On a QFX5100 switch, if you configure MC-LAG with the **force up option**, the FXP might dump a core and generate the following error message: **0x0806b7b8 in panic (format\_string=0x9c72614 "Memory corruption in block %p\n" at ../../src/pfe/platform/fxpc/fxpc\_panic.c:93.** [PR1024354](#)

### [MPLS](#)

- For an L2 circuit on QFX5100 switches, when IS-IS is used as an IGP between CEs connected to an L2 circuit, the CEs fail to form an IS-IS adjacency over the pseudowire. As a workaround, consider using an alternative IGP protocol, such as OSPF. [PR1032007](#)

### [Multicast Protocols](#)

- When an IGMP leave is sent from a host to a QFX5100 switch, one packet per multicast group is dropped during route programming. [PR995331](#)

### [OVSDB](#)

- On QFX5100 switches, in general, Layer 3 routes use per-prefix load balancing without a routing policy that specifies that per-packet load balancing should be used. Note that the default behavior is different for Layer 3 routes for remote VTEP reachability. Layer 3 routes for remote VTEP reachability use per-packet load balancing, which means that load balancing is implemented if there are ECMP paths to the remote VTEP. [PR1018814](#)
- If you enter a **show configuration** command after installing the OVSDB software package (jsdn-i386-release) on a QFX5100 Virtual Chassis or VCF, you see the warning **ddl\_sequence\_number\_match: sequence numbers don't match.** [PR1019087](#)

### [Software Installation and Upgrade](#)

- On a QFX 5100 switch, if a port mirroring analyzer is configured with a VLAN input and you perform an in-service software upgrade (ISSU), the analyzer state is restored after the upgrade. If you later delete the analyzer configuration, mirroring stops but there might be residual harmless stale entries in the hardware. [PR970001](#)

- On a QFX5100 switch, if you perform an ISSU, there might be approximately 2 seconds of IPv4/IPv6 traffic loss during the em0 handoff. [PR985462](#)

### Virtual Chassis and Virtual Chassis Fabric

---

- On a mixed Virtual Chassis Fabric (VCF), a VCP link between two members disappears after you perform a nonstop software upgrade. The **show virtual-chassis protocol adjacency member** command output shows the state of the VCP link as **Initializing**. [PR1031296](#)
- On a non-mixed Virtual Chassis Fabric (VCF), LACP flaps when the switch in the master Routing Engine role is rebooted using the CLI or because of a power cycle. This issue is not experienced after a Routing Engine switchover. As a workaround, configure a slow LACP timeout. [PR1034377](#)

### VXLAN

---

- On QFX5100 switches, the Layer 3 routes that form virtual extensible LAN (VXLAN) tunnels use per-packet load balancing by default, which means that load balancing is implemented if there are ECMP paths to the remote tunnel endpoint. This is different from normal routing behavior in which per-packet load balancing is not used by default. (Normal routing uses per-prefix load balancing by default.) [PR1018814](#)
- On a QFX5100 switch with a VXLAN configured, if you add an interface to the VLAN that the VXLAN is associated with or delete an interface from that VLAN, the switch might drop traffic for devices connected to other interfaces in the same VLAN. [PR1019378](#)
- On a QFX5100 switch configured with a VXLAN and PIM, the (S,G) route for the VXLAN multicast group can get stuck pointing to the pime interface even though the RP has joined the multicast group. This does not affect traffic forwarding for multicast traffic as the forwarding state for the (S,G) route points correctly to the uplink interface to the RP. [PR1023447](#)
- If you perform a graceful Routing Engine switchover in a Virtual Chassis Fabric acting as a VXLAN virtual tunnel endpoint, known unicast traffic might be dropped from the VXLAN. [PR1026408](#)
- If you change the VNIs of all the VXLANs in a QFX 5100 Virtual Chassis Fabric, VXLAN traffic does not converge for some of the VXLANs. [PR1028588](#)

#### Related Documentation

- [New and Changed Features on page 20](#)
- [Known Behavior on page 31](#)
- [Known Issues on page 38](#)
- [Documentation Updates on page 41](#)
- [Migration, Upgrade, and Downgrade Instructions on page 41](#)
- [Product Compatibility on page 45](#)



## Documentation Updates

This section lists the errata or changes in Junos OS Release 14.1X53-D10 documentation for QFX Series.

### Bridging and Learning

- Two new MIBs related to MAC notification are provided at Junos OS Release 14.1X53-D10:
  - `jnxL2aldMacHistoryEntry`
  - `jnxL2aldMacNotificationMIBGlobalObjects`

These MIBs are not yet described in the documentation.

### Network Management and Monitoring

- The Network Management and Monitoring on the QFX Series feature guide at Junos OS Release 14.1X53-D10 erroneously contained topics that applied to QFabric systems but not to QFX Series standalone switches. Those topics have been removed from the guide.

#### **Related Documentation**

- [New and Changed Features on page 20](#)
- [Known Behavior on page 31](#)
- [Known Issues on page 38](#)
- [Documentation Updates on page 41](#)
- [Migration, Upgrade, and Downgrade Instructions on page 41](#)
- [Product Compatibility on page 45](#)

## Migration, Upgrade, and Downgrade Instructions

This section contains the procedure to upgrade Junos OS, and the upgrade and downgrade policies for Junos OS. Upgrading or downgrading Junos OS can take several hours, depending on the size and configuration of the network.

- [Upgrading Software on QFX5100 Standalone Switches on page 41](#)
- [Performing an In-Service Software Upgrade \(ISSU\) on page 43](#)
- [Preparing the Switch for Software Installation on page 43](#)
- [Upgrading the Software Using ISSU on page 44](#)

### Upgrading Software on QFX5100 Standalone Switches

When upgrading or downgrading Junos OS, always use the `jinstall` package. Use other packages (such as the `jbundle` package) only when so instructed by a Juniper Networks support representative. For information about the contents of the `jinstall` package and details of the installation process, see the [Junos OS Installation and Upgrade Guide](#) and [Junos OS Basics](#) in the QFX Series documentation.

The download and installation process for Junos OS Release 14.1X53-D10 is the same as for previous Junos OS releases.

If you are not familiar with the download and installation process, follow these steps:

1. In a browser, go to <http://www.juniper.net/support/downloads/junos.html>.

The Junos Platforms Download Software page appears.

2. In the QFX Series section of the Junos Platforms Download Software page, select the QFX Series platform for which you want to download the software.
3. Select **14.1** in the Release pull-down list to the right of the Software tab on the Download Software page.
4. In the Install Package section of the Software tab, select the QFX Series Install Package for the 14.1 release.

An Alert box appears.

5. In the Alert box, click the link to the PSN document for details about the software, and click the link to download it.

A login screen appears.

6. Log in to the Juniper Networks authentication system using the username (generally your e-mail address) and password supplied by Juniper Networks representatives.
7. Download the software to a local host.
8. Copy the software to the device or to your internal software distribution site.
9. Install the new jinstall package on the device.



**NOTE:** We recommend that you upgrade all software packages out of band using the console, because in-band connections are lost during the upgrade process.

---

Customers in the United States and Canada use the following command:

```
user@host> request system software add  
source/jinstall-qfx-5-14.1X53-D25-domestic-signed.tgz reboot
```

Replace **source** with one of the following values:

- **/pathname**—For a software package that is installed from a local directory on the switch.
- For software packages that are downloaded and installed from a remote location:
  - **ftp://hostname/pathname**
  - **http://hostname/pathname**
  - **scp://hostname/pathname** (available only for Canada and U.S. version)

Adding the **reboot** command reboots the switch after the upgrade is installed. When the reboot is complete, the switch displays the login prompt. The loading process can take 5 to 10 minutes.

Rebooting occurs only if the upgrade is successful.



**NOTE:** After you install a Junos OS Release 14.1 jinstall package, you can issue the **request system software rollback** command to return to the previously installed software.

### Performing an In-Service Software Upgrade (ISSU)

You can use an in-service software upgrade to upgrade the software running on the switch with minimal traffic disruption during the upgrade.



**NOTE:** ISSU is supported in Junos OS Release 13.2X51-D15 and later.

Perform the following tasks:

- [Preparing the Switch for Software Installation on page 43](#)
- [Upgrading the Software Using ISSU on page 44](#)

### Preparing the Switch for Software Installation

Before you begin software installation using ISSU:

- Ensure that nonstop active routing (NSR), nonstop bridging (NSB), and graceful Routing Engine switchover (GRES) are enabled. NSB and GRES enable NSB-supported Layer 2 protocols to synchronize protocol information between the master and backup Routing Engines.

To verify that nonstop active routing is enabled:



**NOTE:** If nonstop active routing is enabled, then graceful Routing Engine switchover is enabled.

```
user@switch> show task replication
Stateful Replication: Enabled
RE mode: Master
```

If nonstop active routing is not enabled (**Stateful Replication is Disabled**), see *Configuring Nonstop Active Routing on Switches* for information about how to enable it.

- Enable nonstop bridging (NSB). See *Configuring Nonstop Bridging on Switches (CLI Procedure)* for information on how to enable it.
- (Optional) Back up the system software—Junos OS, the active configuration, and log files—on the switch to an external storage device with the **request system snapshot** command.

## Upgrading the Software Using ISSU

---

This procedure describes how to upgrade the software running on a standalone switch:

To upgrade the switch using ISSU:

1. Download the software package by following the procedure in the Downloading Software Files with a Browser section in *Upgrading Software*.
2. Copy the software package or packages to the switch. We recommend that you copy the file to the `/var/tmp` directory.
3. Log in to the console connection. Using a console connection allows you to monitor the progress of the upgrade.
4. Start the ISSU:
  - On the switch, enter:

```
user@switch> request system software in-service-upgrade  
/var/tmp/package-name.tgz
```

where *package-name.tgz* is, for example, *jinstall-132\_x51\_vjunos.domestic.tgz*.



**NOTE:** During the upgrade, you will not be able to access the Junos OS CLI.

The switch displays status messages similar to the following messages as the upgrade executes:

```
warning: Do NOT use /user during ISSU. Changes to /user during ISSU may get  
lost!  
ISSU: Validating Image  
ISSU: Preparing Backup RE  
Prepare for ISSU  
ISSU: Backup RE Prepare Done  
Extracting jinstall-qfx-5-13.2X51-D15.4-domestic ...  
Install jinstall-qfx-5-13.2X51-D15.4-domestic completed  
Spawning the backup RE  
Spawn backup RE, index 0 successful  
GRES in progress  
GRES done in 0 seconds  
Waiting for backup RE switchover ready  
GRES operational  
Copying home directories  
Copying home directories successful  
Initiating Chassis In-Service-Upgrade  
Chassis ISSU Started  
ISSU: Preparing Daemons  
ISSU: Daemons Ready for ISSU  
ISSU: Starting Upgrade for FRUs  
ISSU: FPC Warm Booting  
ISSU: FPC Warm Booted  
ISSU: Preparing for Switchover  
ISSU: Ready for Switchover  
Checking In-Service-Upgrade status
```

Item	Status	Reason
FPC 0	Online (ISSU)	
Send ISSU done to chassisd on backup RE		
Chassis ISSU Completed		
ISSU: IDLE		
Initiate em0 device handoff		



**NOTE:** An ISSU might stop instead of abort if the FPC is at the warm boot stage. Also, any links that go down and up will not be detected during a warm boot of the Packet Forwarding Engine (PFE).



**NOTE:** If the ISSU process stops, you can look at the log files to diagnose the problem. The log files are located at `/var/log/vjunos-log.tgz`.

- Log in after the reboot of the switch completes. To verify that the software has been upgraded, enter the following command:

```
user@switch> show version
```

- To ensure that the resilient dual-root partitions feature operates correctly, copy the new Junos OS image into the alternate root partitions of all of the switch:

```
user@switch> request system snapshot slice alternate
```

Resilient dual-root partitions allow the switch to boot transparently from the alternate root partition if the system fails to boot from the primary root partition.

#### Related Documentation

- [New and Changed Features on page 20](#)
- [Known Behavior on page 31](#)
- [Known Issues on page 38](#)
- [Documentation Updates on page 41](#)
- [Migration, Upgrade, and Downgrade Instructions on page 41](#)
- [Product Compatibility on page 45](#)

## Product Compatibility

- [Hardware Compatibility on page 45](#)

### Hardware Compatibility

To obtain information about the components that are supported on the devices, and special compatibility guidelines with the release, see the Hardware Guide for the product.

To determine the features supported on QFX Series switches in this release, use the Juniper Networks Feature Explorer, a Web-based application that helps you to explore and compare Junos OS feature information to find the right software release and hardware platform for your network. Find Feature Explorer at:

<http://pathfinder.juniper.net/feature-explorer/>

- Related Documentation**
- [New and Changed Features on page 20](#)
  - [Known Behavior on page 31](#)
  - [Known Issues on page 38](#)
  - [Documentation Updates on page 41](#)
  - [Migration, Upgrade, and Downgrade Instructions on page 41](#)
  - [Product Compatibility on page 45](#)

## Third-Party Components

---

This product includes third-party components. To obtain a complete list of third-party components, see [Overview for Routing Devices](#).

For a list of open source attributes for this Junos OS release, see [Open Source: Source Files and Attributions](#).

## Finding More Information

---

For the latest, most complete information about known and resolved issues with Junos OS, see the Juniper Networks Problem Report Search application at:

<http://prsearch.juniper.net>.

Juniper Networks Feature Explorer is a Web-based application that helps you to explore and compare Junos OS feature information to find the correct software release and hardware platform for your network. Find Feature Explorer at:

<http://pathfinder.juniper.net/feature-explorer/>.

Juniper Networks Content Explorer is a Web-based application that helps you explore Juniper Networks technical documentation by product, task, and software release, and download documentation in PDF format. Find Content Explorer at:

<http://www.juniper.net/techpubs/content-applications/content-explorer/>.

## Documentation Feedback

---

We encourage you to provide feedback, comments, and suggestions so that we can improve the documentation. You can provide feedback by using either of the following methods:

- Online feedback rating system—On any page at the Juniper Networks Technical Documentation site at <http://www.juniper.net/techpubs/index.html>, simply click the stars to rate the content, and use the pop-up form to provide us with information about your experience. Alternately, you can use the online feedback form at <http://www.juniper.net/techpubs/feedback/>.
- E-mail—Send your comments to [techpubs-comments@juniper.net](mailto:techpubs-comments@juniper.net). Include the document or topic name, URL or page number, and software version (if applicable).

## Requesting Technical Support

---

Technical product support is available through the Juniper Networks Technical Assistance Center (JTAC). If you are a customer with an active J-Care or JNASC support contract, or are covered under warranty, and need postsales technical support, you can access our tools and resources online or open a case with JTAC.

- JTAC policies—For a complete understanding of our JTAC procedures and policies, review the JTAC User Guide located at <http://www.juniper.net/us/en/local/pdf/resource-guides/7100059-en.pdf>.
- Product warranties—For product warranty information, visit <http://www.juniper.net/support/warranty/>.
- JTAC Hours of Operation —The JTAC centers have resources available 24 hours a day, 7 days a week, 365 days a year.

## Self-Help Online Tools and Resources

For quick and easy problem resolution, Juniper Networks has designed an online self-service portal called the Customer Support Center (CSC) that provides you with the following features:

- Find CSC offerings: <http://www.juniper.net/customers/support/>
- Search for known bugs: <http://www2.juniper.net/kb/>
- Find product documentation: <http://www.juniper.net/techpubs/>
- Find solutions and answer questions using our Knowledge Base: <http://kb.juniper.net/>
- Download the latest versions of software and review release notes: <http://www.juniper.net/customers/csc/software/>
- Search technical bulletins for relevant hardware and software notifications: <http://kb.juniper.net/InfoCenter/>
- Join and participate in the Juniper Networks Community Forum: <http://www.juniper.net/company/communities/>
- Open a case online in the CSC Case Management tool: <http://www.juniper.net/cm/>

To verify service entitlement by product serial number, use our Serial Number Entitlement (SNE) tool located at <https://tools.juniper.net/SerialNumberEntitlementSearch/>.

## Opening a Case with JTAC

You can open a case with JTAC on the Web or by telephone.

- Use the Case Management tool in the CSC at <http://www.juniper.net/cm/>.
- Call 1-888-314-JTAC (1-888-314-5822 toll-free in the USA, Canada, and Mexico).

For international or direct-dial options in countries without toll-free numbers, visit us at <http://www.juniper.net/support/requesting-support.html>.

If you are reporting a hardware or software problem, issue the following command from the CLI before contacting support:

```
user@host> request support information | save filename
```

To provide a core file to Juniper Networks for analysis, compress the file with the **gzip** utility, rename the file to include your company name, and copy it to **ftp.juniper.net/pub/incoming**. Then send the filename, along with software version information (the output of the **show version** command) and the configuration, to **support@juniper.net**. For documentation issues, fill out the bug report form located at <https://www.juniper.net/cgi-bin/docbugreport/>.

---

## Revision History

28 October 2014—Revision 4, Junos OS for the EX Series and the QFX Series, Release 14.1X53-D10—Fixed URL in New Features for EX Series

22 October 2014—Revision 3, Junos OS for the EX Series and the QFX Series, Release 14.1X53-D10

17 October 2014—Revision 2, Junos OS for the EX Series and the QFX Series, Release 14.1X53-D10

29 September 2014—Revision 1, Junos OS for the EX Series, Release 14.1X53-D10

Copyright © 2017, Juniper Networks, Inc. All rights reserved.

Juniper Networks, Junos, Steel-Belted Radius, NetScreen, and ScreenOS are registered trademarks of Juniper Networks, Inc. in the United States and other countries. The Juniper Networks Logo, the Junos logo, and JunosE are trademarks of Juniper Networks, Inc. All other trademarks, service marks, registered trademarks, or registered service marks are the property of their respective owners.

Juniper Networks assumes no responsibility for any inaccuracies in this document. Juniper Networks reserves the right to change, modify, transfer, or otherwise revise this publication without notice.