

Juniper Networks® CTPOS Release 9.1R6-6 Software

Published
2025-11-27

RELEASE

Table of Contents

[**About This Guide**](#)

[**Release Highlights**](#)

[**Upgrade Information**](#)

[**Resolved Issues in CTPOS Release 9.1R6-6**](#)

[**Known Issues in CTPOS Release 9.1R6-6**](#)

[**Required Install or Upgrade files**](#)

[**Known Limitations in CTPOS Release 9.1R6-6**](#)

[**Revision History**](#)

About This Guide

This release notes accompany Release 9.1R6-6 of the CTPOS software. They describe device documentation and known problems with the software.

You can also find these release notes on the Juniper Networks CTP software documentation webpage, which is located at [CTP Series Release Notes](#).

Release Highlights

The CTPOS 9.1R6-6 release is supported on CTP151 and CTP2000 Series devices. In this release:

- We have addressed the FPGA mismatch after upgrading to CTPOS 9.2R2.
- We have addressed the Radius issues encountered during guest access.

Upgrade Information

You can upgrade your CTP node from CTPOS 9.1R6-x (where x<6) to CTPOS 9.1R6-6 using acorn package.

You can also upgrade from 9.1R3 and 9.1R5 to 9.1R6-6 using CTPOS acorn package and CTPOS FPGA acorn package.

You can upgrade CTP node by copying the acorn package in `/tmp` folder and run "**upgrade y**".

Alternatively, you can upgrade your CTP node through CTPView using CTPOS complete package from 9.1R6-2 CTPView server.

Example:

```
[root@ctp_device:/tmp]# md5sum acorn_310_9.1R6-6_251106.tgz
a5a6565cb69431f453b487cc4be968d2 acorn_310_9.1R6-6_251106.tgz
[root@ctp_device:/tmp]#
[root@ctp_device:/tmp]# upgrade y
```

Resolved Issues in CTPOS Release 9.1R6-6

The following issues have been resolved in CTPOS Release 9.1R6-6.

- CTPOS version must be accurate regardless of the display methods (Grub, cli menu, cmd -v, etc) [PR 1881491]
- FPGA mismatch is not showing in "sc" output(on CLI display) after upgrade to CTPOS-9.2R2. [PR 1843238]
- CTP151-IM-T1E1-B bricked during upgrade [PR 1887151]
- Radius issues with guest access. [PR 1886710]

Known Issues in CTPOS Release 9.1R6-6

None.

Required Install or Upgrade files

Following files are provided for upgrading the CTPOS software to CTPOS 9.1R6-6:

Table 1:

File	Filename	MD5 Checksum
CTPOS acorn package	acorn_310_9.1R6-6_251106.tgz	a5a6565cb69431f453b487cc4be968d2
CTPOS FPGA acorn package	acorn_310_251031_fpga_150_s2c_t24_S04_T05_2000_s1f_t32_S05_T0A.tgz	7c0c034a924a77187c082809a61bae8d
CTPOS complete package	ctp_complete_9.1R6-6_251106.tgz	b4b7b8cda3cea657281b445f712dd500

Known Limitations in CTPoS Release 9.1R6-6

- None.

Revision History

November 2025—Revision 1—CTPOS Release 9.1R6-6

Juniper Networks, the Juniper Networks logo, Juniper, and Junos are registered trademarks of Juniper Networks, Inc. in the United States and other countries. All other trademarks, service marks, registered marks, or registered service marks are the property of their respective owners. Juniper Networks assumes no responsibility for any inaccuracies in this document. Juniper Networks reserves the right to change, modify, transfer, or otherwise revise this publication without notice. Copyright © 2025 Juniper Networks, Inc. All rights reserved.